

# INTERNATIONAL STANDARD

ISO  
3070-1

Second edition  
1987-06-15



INTERNATIONAL ORGANIZATION FOR STANDARDIZATION  
ORGANISATION INTERNATIONALE DE NORMALISATION  
МЕЖДУНАРОДНАЯ ОРГАНИЗАЦИЯ ПО СТАНДАРТИЗАЦИИ

## Acceptance conditions for boring and milling machines with horizontal spindle — Testing of the accuracy —

### Part 1: Table-type machines

*Conditions de réception des machines à aléser et à fraiser, à broche horizontale — Contrôle de la précision —*

*Partie 1: Machines à montant fixe*

# Acceptance conditions for boring and milling machines with horizontal spindle — Testing of the accuracy —

## Part 1: Table-type machines

### 1 Scope and field of application

This part of ISO 3070 describes, with reference to ISO 230-1, geometrical and practical tests on general purpose and normal accuracy boring and milling machines, horizontal spindle, table type, defined in ISO 3070-0, and the corresponding deviations which apply.

In addition it should be noted that this part of ISO 3070 concerns machines which have both longitudinal and traverse movement of the table, and may include a rotary or indexing table. It will also have a vertical movement of the spindle head, and possibly a facing head.

It deals only with the verification of the accuracy of the machine. It does not apply to the testing of the running of the machine (vibrations, abnormal noises, stick-slip motion of components, etc.) or to machine characteristics (such as speeds, feeds, etc.) which should generally be checked before testing the accuracy.

### 2 Preliminary remarks

**2.1** In this part of ISO 3070, deviations and ranges are expressed in millimetres and inches.

**2.2** To apply this part of ISO 3070, reference should be made to ISO 230-1, especially for installation of the machine before testing, warming up of spindles and other moving parts, description of measuring methods and recommended accuracy of testing equipment.

**2.3** The sequence in which the geometrical tests are given is related to the sub-assemblies of the machine and this in no way

defines the practical order of testing. In order to make the mounting of instruments or gauging easier, tests may be applied in any order.

**2.4** When inspecting a machine, it is not always necessary to carry out all the tests given in this part of ISO 3070. It is up to the user to choose, in agreement with the manufacturer, those tests relating to the properties which are of interest to him, but these tests are to be clearly stated when ordering a machine.

**2.5** Practical tests shall be made with finishing cuts.

**2.6** When establishing the tolerance for a measuring range different from that given in this part of ISO 3070 (see subclause 2.311 in ISO 230-1) it should be taken into consideration that the minimum tolerance value is 0,002 5 mm (0.000 1 in).

NOTE — Rotary table machines are covered by an addendum.

### 3 References

ISO 230-1, *Acceptance code for machine tools — Part 1: Geometric accuracy of machines operating under no-load or finishing conditions*.

ISO 1101, *Technical drawings — Geometrical tolerancing — Tolerancing of form, orientation, location and run-out — Generalities, definitions, symbols, indications on drawings*.

ISO 3070-0, *Acceptance conditions for boring and milling machines with horizontal spindle — Testing of the accuracy — Part 0: General introduction*.

Permissible deviation			Measuring instruments	Observations and references to the ISO 230-1 acceptance code
mm	in			
a) 0,02 up to 1 000	a)  (flat to convex)  Local tolerance:  0,006  over any measuring length of  300	0,000 8 up to 40  0,000 24  12	Precision level, optical or other methods	<p>a) Subclauses 3.11, 3.21, 5.212.21 and 5.212.22</p> <p>Measurements shall be made at a number of positions equally spaced along the length of the bed:</p> <ol style="list-style-type: none"> <li>1) the table shall be placed in the middle of its longitudinal travel and transverse travel;</li> <li>2) the table shall then be placed at the extremities of the longitudinal travel and in the middle of the transverse travel.</li> </ol> <p>The levels may be placed on the table [this is valid for a) and b)].</p>
b) Variation of level  0,02/1 000		0,000 8/40	Precision level and support	b) Subclause 5.412.7
a) 0,02 up to 1 000	a)  up to 40	0,000 8 0,000 4  0,002	Precision level, optical or other methods	<p>a) Subclauses 3.11, 3.21, 5.212.21 and 5.212.22</p> <p>Measurements shall be made at a number of positions equally spaced along the length of the slideways.</p> <p>Levels may be placed on the table [this is valid for a) and b)].</p>
b) Variation of level:  0,03/1 000		0,001 2/40	Precision level and support	b) Subclause 5.412.7
				A level shall be placed transversely on the slideways and measurements taken at a number of positions equally spaced along the length of the slideways. The variation of level measured at any position shall not exceed the permissible deviation.

Permissible deviation		Measuring instruments	Observations and references to the ISO 230-1 acceptance code
mm	in		
0,02 up to 1 000	0,000 8 up to 40	Dial gauge, straightedge and supports or optical methods	<p>Subclause 5.232.1</p> <p>The dial gauge shall be fixed on the middle position of the saddle touching a straightedge laid parallel to the Z axis.</p> <p>The straightedge shall be placed on a fixed part, independent or integral with the machine, and as near as possible to the slideways.</p>
0,006 over any measuring length of 300	0,000 24 12		
For each 1 000 mm (40 in) increase in length beyond 1 000 mm (40 in), add to the corresponding preceding tolerance:			
0,01	0,000 4		
Maximum permissible deviation:			
0,05	0,002		
0,02 up to 1 000	0,000 8 up to 40	Dial gauge, straightedge, supports or optical methods	<p>Subclause 5.232.1</p> <p>The dial gauge shall be fixed on the middle position of the table with the stylus touching a straightedge laid parallel to the Z axis.</p> <p>The straightedge shall be placed on a fixed part, independent or integral with the machine, and as near as possible to the slideways.</p>
0,006 over any measuring length of 300	0,000 24 12		
For each 1 000 mm (40 in) increase in length beyond 1 000 mm (40 in), add to the corresponding preceding tolerance:			
0,01	0,000 4		
Maximum permissible deviation:			
0,05	0,002		
0,04/1 000	0,001 6/40	Dial gauge, straightedge and square	<p>Subclause 5.522.4</p> <p>a) The straightedge shall be set parallel to the table saddle longitudinal movement; then the square shall be placed against the straightedge. The table saddle shall then be locked in the central position.</p> <p>b) The transverse movement of the table shall then be checked.</p> <p>If the spindle can be locked, then the dial gauge may be mounted on it. If the spindle cannot be locked the dial gauge shall be placed on a fixed part of the machine.</p>

Permissible deviation		Measuring instruments	Observations and references to the ISO 230-1 acceptance code
mm	in		
0,03 up to 1 000 (flat to concave)	0,001 2 up to 40	Precision level or straightedge and gauge blocks	<p>Subclauses 5.322 and 5.323</p> <p>Table in its mid-position.</p> <p>Table saddle and table base may be locked in the middle of their travel.</p>
0,02 over any measuring length of 300	0,000 8 12		
For each 1 000 mm (40 in) increase in length beyond 1 000 mm (40 in), add to the corresponding preceding tolerance:			
0,01	0,000 4		
Maximum permissible deviation:			
0,05	0,002		
a) 0,04 up to 1 000 Local tolerance: 0,015 over any measuring length of 300			
a)	0,001 6 up to 40		<p>Subclause 5.232.1 or 5.422.21</p> <p>The stylus of the dial gauge shall be placed approximately in a vertical plane coaxial with the spindle axis.</p>
For each 1 000 mm (40 in) increase in length beyond 1 000 mm (40 in), add to the corresponding preceding tolerance:			
0,01	0,000 4		
Maximum permissible deviation:			
0,06	0,002 4		
b) 0,04 over any measuring length of 1 000			
b)	0,001 6 40	Straightedge and dial gauge	<p>Measurement may be made on a straightedge laid parallel to the table surface. If the table length is greater than 1 600 mm (64 in), carry out the inspection by successive movements of the straightedge.</p> <p>If the spindle can be locked, the dial gauge may be mounted on it. If the spindle cannot be locked, the dial gauge shall be placed on a fixed part of the machine.</p> <p>a) Carry out the test with the transverse movement locked for the table.</p> <p>b) Carry out the test with the longitudinal movement locked for the table saddle.</p>
0,02 for any measuring length of 1 000	0,000 8 40		<p>Subclauses 5.212, 5.212.1, 5.212.3 or 5.232</p> <p>The straightedge may be set directly on the table.</p>
0,03	0,001 2	Straightedge and dial gauge, or gauge blocks, or microscope and taut wire	

Permissible deviation		Measuring instruments	Observations and references to the ISO 230-1 acceptance code
mm	in		
0,03 for a measuring length of 1 000	0,001 2 40	Straightedge, gauge blocks and dial gauge	Subclauses 5.232.1 and 5.422.21 If the spindle can be locked, the dial gauge may be mounted on it; otherwise, it shall be mounted on a fixed part of the machine.
0,04 Maximum permissible deviation:	0,001 6		
a) 0,02 for a measuring length of 500	a) 0,000 8 20	Dial gauge and straightedge or square	Subclause 5.232.1 Carry out the test with the table saddle locked; the table and table base may be locked in mid-position. As an exception to the acceptance code, a square may be used instead of a straight-edge.
b) 0,02 for a measuring length of 500	b) 0,000 8 20		If the spindle can be locked, the dial gauge can be mounted on it. If the spindle cannot be locked, the dial gauge shall be placed on the spindle head of the machine.
a) 0,02/500	a) 0,000 8/20	Dial gauge and square	Subclause 5.522.2 Carry out the test with the table saddle locked; the table base may be locked in mid-position. Lock the spindle head when taking measurements.
b) 0,02/500	b) 0,000 8/20		If the spindle can be locked, the dial gauge can be mounted on it. If the spindle cannot be locked, the dial gauge shall be placed on the spindle head of the machine. The square is placed at the centre of the table.