
**Nuclear energy — Nuclear fuel
technology — Determination of
plutonium in nitric acid solutions by
spectrophotometry**

*Énergie nucléaire — Technologie du combustible nucléaire —
Détermination du plutonium dans les solutions d'acide nitrique par
spectrophotométrie*

iTeh Standards
(<https://standards.iteh.ai>)
Document Preview

ISO 9463:2019

<https://standards.iteh.ai/catalog/standards/iso/15957a54-a6b7-4662-9f3a-cd1e04e9be79/iso-9463-2019>



iTeh Standards
(<https://standards.iteh.ai>)
Document Preview

ISO 9463:2019

<https://standards.iteh.ai/catalog/standards/iso/15957a54-a6b7-4662-9f3a-cd1e04e9be79/iso-9463-2019>



COPYRIGHT PROTECTED DOCUMENT

© ISO 2019

All rights reserved. Unless otherwise specified, or required in the context of its implementation, no part of this publication may be reproduced or utilized otherwise in any form or by any means, electronic or mechanical, including photocopying, or posting on the internet or an intranet, without prior written permission. Permission can be requested from either ISO at the address below or ISO's member body in the country of the requester.

ISO copyright office
CP 401 • Ch. de Blandonnet 8
CH-1214 Vernier, Geneva
Phone: +41 22 749 01 11
Fax: +41 22 749 09 47
Email: copyright@iso.org
Website: www.iso.org

Published in Switzerland

Contents

Page

Foreword	iv
1 Scope	1
2 Normative references	1
3 Terms and definitions	1
4 Principle	1
5 Chemical conditions	1
5.1 Stability of Pu(VI)	1
5.2 Rate of oxidation of Pu(IV) to Pu(VI)	2
5.3 Destruction of the excess oxidant	2
5.4 Comparison of Ce(IV) and Ag(II)	2
5.5 Molar extinction coefficient of Pu(VI)	2
6 Reagents	3
6.1 General	3
6.2 Common reagents for methods using silver oxide or cerium as oxidant	3
6.3 Reagents for method using silver oxide as oxidant	3
6.4 Reagents for method using Ce(IV) as oxidant	3
7 Apparatus	4
8 Test procedure	4
8.1 Preparation of the different solutions	4
8.1.1 Plutonium calibration solution	4
8.1.2 Sample solutions	5
8.2 Spectrophotometer setup	6
8.3 Measurements	6
8.3.1 Background measurement	6
8.3.2 Measurements on the calibration solution	7
8.3.3 Measurements on the sample solution	7
9 Expression of the result	7
9.1 Calculation of the concentration of plutonium in the sample	7
9.2 Reproducibility	8
9.3 Detection limit	8
10 Interferences	8
10.1 Anions	8
10.2 Cations	9
Annex A (informative) Preparation of silver (II) oxide (AgO)	11
Bibliography	12