CEI 61942 (Première édition – 1997) IEC 61942 (First edition – 1997)

Travaux sous tension – Gants et moufles avec protection mécanique

Live working – Gloves and mitts with mechanical protection

CORRIGENDUM 1

Page 10

2 Références normatives

A la page 12, supprimer:

CEI 60410:1973, Plans et règles d'échantillonnage pour les contrôles par attributs

Ajouter les publications suivantes:

CEI 61318:1994, Travaux sous tension – Guide pour les plans d'assurance de la qualité

ISO 2859-1:1999, Règles d'échantillonnage pour les contrôles pai attributs — Partie 1: Procédures d'échantillonnage pour les contrôles lot par lot, indexés d'après le niveau de qualité acceptable (NQA) Page 11

2 Normative references

On page 13, delete:

IEC 60410:1973, Sampling plans and procedures for inspection by attributes

Add the following publications:

IEC 61318:1994, Live working – Guidelines for quality assurance plans

ISO 2859-1:1999, Sampling procedures for inspection by attributes – Part 1: Sampling schemes indexed by acceptance quality limit (AQL) for lot-by-lot inspection

Page 80 Page 81

Annexe C Annex C

C.1 Généralités C.1 General

Premier alinéa First paragraph

Au lieu de: Instead of:

... dans la CEI 60410. ... in IEC 60410.

lire: read:

... dans l'ISO 2859-1. ... in ISO 2859-1.