

Designation: D2633 - 20 D2633 - 21

# Standard Test Methods for Thermoplastic Insulations and Jackets for Wire and Cable<sup>1</sup>

This standard is issued under the fixed designation D2633; the number immediately following the designation indicates the year of original adoption or, in the case of revision, the year of last revision. A number in parentheses indicates the year of last reapproval. A superscript epsilon ( $\varepsilon$ ) indicates an editorial change since the last revision or reapproval.

# 1. Scope\*

- 1.1 These test methods cover procedures for the testing of thermoplastic insulations and jackets used on insulated wire and cable. To determine the test to be made on the particular insulation or jacket compound, refer to the product specification for that type. These test methods do not apply to the class of products known as flexible cords. The electrical tests on insulation and water-absorption tests do not apply to the class of products having a separator between the conductor and the insulation.
- 1.2 These test methods pertain to insulation or jacket material for electrical wires and cables. In many instances the insulation or jacket material cannot be tested unless it has been formed around a conductor or cable. Therefore, tests are done on insulated or jacketed wire or cable in these test methods solely to determine the relevant property of the insulation or jacket material and not to test the conductor or completed cable.
- 1.3 Whenever two sets of values are stated, in different units, the values in the first set are regarded as standard, while the values in parentheses are provided for information only and are not considered standard.
- 1.4 This standard does not purport to address all of the safety concerns, if any, associated with its use. It is the responsibility of the user of this standard to establish appropriate safety, health, and environmental practices and determine the applicability of regulatory limitations prior to use. For specific hazards see Sections Section 4 and 634 and for fire test safety caveats see Test Method D8354.
- 1.5 The These test methods appear in the following sections:

Partial-discharge Ex- 38 to 44

tinction Level Test

Test Method

Section(s)

Test Method

<sup>&</sup>lt;sup>1</sup> These test methods are under the jurisdiction of ASTM Committee D09 on Electrical and Electronic Insulating Materials and are the direct responsibility of Subcommittee D09.07 on Electrical Insulating Materials.

Current edition approved Oct. 1, 2020Jan. 1, 2021. Published Nov. 1, 2020February 2021. Originally approved in 1967. Last previous edition approved in 20132020 as D2633 – 13a.D2633 – 20. DOI: 10.1520/D2633-20:10.1520/D2633-21.

Flammability

# Test Method

Physical Tests of Insu-5 to 16 lation and Jackets (Test Method D8354) Surface Resistivity 69 to 72 Test Surface Resistivity Test Thermal Tests Thermal Tests 72 to 77 Track Resistance Test 83 to 86 Track Resistance Test 78 to 81 U-bend Discharge Test73 to 76 U-bend Discharge Test68 to 71 Vertical Flame Test 63 Water Absorption 52 to 62 Tests. Accelerated

1.6 This international standard was developed in accordance with internationally recognized principles on standardization established in the Decision on Principles for the Development of International Standards, Guides and Recommendations issued by the World Trade Organization Technical Barriers to Trade (TBT) Committee.

# 2. Referenced Documents

# 2.1 ASTM Standards:<sup>2</sup>

D149 Test Method for Dielectric Breakdown Voltage and Dielectric Strength of Solid Electrical Insulating Materials at Commercial Power Frequencies

D150 Test Methods for AC Loss Characteristics and Permittivity (Dielectric Constant) of Solid Electrical Insulation

D257 Test Methods for DC Resistance or Conductance of Insulating Materials

D374/D374M Test Methods for Thickness of Solid Electrical Insulation

D471 Test Method for Rubber Property—Effect of Liquids

D573 Test Method for Rubber—Deterioration in an Air Oven

D638 Test Method for Tensile Properties of Plastics

D1248 Specification for Polyethylene Plastics Extrusion Materials for Wire and Cable

D1711 Terminology Relating to Electrical Insulation

D2132 Test Method for Dust-and-Fog Tracking and Erosion Resistance of Electrical Insulating Materials

D3755 Test Method for Dielectric Breakdown Voltage and Dielectric Strength of Solid Electrical Insulating Materials Under Direct-Voltage Stress

D5025 Specification for Laboratory Burner Used for Small-Scale Burning Tests on Plastic Materials

D5207 Practice for Confirmation of 20-mm (50-W) and 125-mm (500-W) Test Flames for Small-Scale Burning Tests on Plastic Materials

D5423 Specification for Forced-Convection Laboratory Ovens for Evaluation of Electrical Insulation

D8354 Test Method for Flammability of Electrical Insulating Materials Used for Sleeving or Tubing

E29 Practice for Using Significant Digits in Test Data to Determine Conformance with Specifications

2.2 Federal Standard:<sup>3</sup>

PPP-T-45D Federal Specification for Tape; Paper, Gummed (Kraft)

2.3 ICEA Standard:4

T-24-380 Guide for Partial-Discharge Procedure

2.4 UL Standard:<sup>5</sup>

UL 2556 Wire and Cable Test Methods

#### 3. Terminology

- 3.1 Definitions:
- 3.1.1 For definitions of terms used in these test methods, refer to Terminology D1711.
  - 3.2 Definitions of Terms Specific to This Standard:

<sup>&</sup>lt;sup>2</sup> For referenced ASTM standards, visit the ASTM website, www.astm.org, or contact ASTM Customer Service at service@astm.org. For *Annual Book of ASTM Standards* volume information, refer to the standard's Document Summary page on the ASTM website.

<sup>&</sup>lt;sup>3</sup> Available from Standardization Documents Order Desk, Bldg. <sup>4</sup> Section D, 700 Robbins Ave., Philadelphia, PA 19111-5094, Attn: NPODS.

<sup>&</sup>lt;sup>4</sup> Available from The Insulated Cable Engineers Association, Inc. (ICEA), P.O. Box 2694, Alpharetta, GA 30023, http://www.icea.net.

- 3.2.1 aging (act of), n—exposure of material to air or oil at a temperature and a time as specified in the relevant material specification for that material.
  - 3.3 Symbols:
- 3.3.1 kemil = thousands of circular mils.

#### 4. Hazards

- 4.1 High Voltage:
- 4.1.1 (Warning—Lethal voltages are a potential hazard during the performance of this test. It is essential that the test apparatus, and all associated equipment electrically connected to it, be properly designed and installed for safe operation.)
- 4.1.2 Solidly ground all electrically conductive parts which it is possible for a person to contact during the test.
- 4.1.3 Provide means for use at the completion of any test to ground any parts which were at high voltage during the test or have the potential for acquiring an induced charge during the test or retaining a charge even after disconnection of the voltage source.
- 4.1.4 Thoroughly instruct all operators as to the correct procedures for performing tests safely.
- 4.1.5 When making high voltage tests, particularly in compressed gas or in oil, it is possible for the energy released at breakdown to be sufficient to result in fire, explosion, or rupture of the test chamber. Design test equipment, test chambers, and test specimens so as to minimize the possibility of such occurrences and to eliminate the possibility of personal injury. If the potential for fire exists, have fire suppression equipment available. Design test equipment, test chambers, and test specimens so as to minimize the possibility of such occurrences and to eliminate the possibility of personal injury. See 20.1, 27.1, 33.1, 42.1, 48.1, 55.1, 70.165.1, 74.169.1, and 84.179.1.

# PHYSICAL TESTS OF INSULATIONS AND JACKETS

# 5. Scope

#### ASTM D2633-21

- 5.1 Physical tests include determination of the following properties of insulations and jackets: 91e544/astm-d2633-21
- 5.1.1 Thickness,
- 5.1.2 Tensile strength,
- 5.1.3 Ultimate elongation,
- 5.1.4 Accelerated aging,
- 5.1.5 Effects of oil immersion,
- 5.1.6 Accelerated water absorption,
- 5.1.7 Flame test evaluation,
- 5.1.8 Heat shock,
- 5.1.9 Heat distortion, and
- 5.1.10 Cold bend.
- 6. Significance and Use
- 6.1 Physical tests, properly interpreted, provide information with regard to the physical properties of the insulation or jacket. The



physical test values give an approximation of how the insulation will physically perform in its service life. Physical tests provide useful data for research and development, engineering design, quality control, and acceptance or rejection under specifications.

# 7. Sampling

- 7.1 *Number of Samples*—Unless otherwise required by the detailed product specification, sample the wire and cable to do the physical tests other than the tests for insulation and jacket thickness, as follows:
- 7.1.1 For Sizes of Less Than 250 kcmil (127 mm²)—Select one sample for each quantity ordered between 2000 ft (600 m) and 50 000 ft (15 200 m) of wire or cable. Select one additional sample for each additional 50 000 ft thereafter. Do not select a sample from lots of less than 2000 ft.
- 7.1.2 For Sizes of 250 kcmil (127 mm²) and Over—Select one sample for each quantity ordered between 1000 ft (300 m) and 25 000 ft (7600 m) of wire or cable. Select one additional sample for each additional 25 000 ft thereafter. Do not select a sample from lots of less than 1000 ft.
- 7.2 Size of Samples—Choose samples at least 6 ft (2 m) in length when the wire size is less than 250 kcmil (127 mm<sup>2</sup>). Select a sample at least 3 ft (1 m) in length when the wire size is 250 kcmil or larger.

# 8. Test Specimens

8.1 Number of Specimens—From each of the samples selected in accordance with Section 7, prepare test specimens as follows:

iest	Test Specimer
For Determina- tion of Original	3
Tensile Strength	
Elongation	
For Determina- tion of Original	<u>3</u>
Tensile Strength and	!
Ultimate Elor	<u>1-</u>
For Aging	3
For Oil Immer- sion	3

Number of



When only one or two samples are selected, test all three specimens of each sample, and report the average result of each. Otherwise, test one specimen of each three and hold the other two specimens in reserve.

- 8.2 Size of Specimens—When testing wire smaller than 6 AWG (13.3 mm²) which has an insulation thickness less than 0.095 in. (2.41 mm), test the entire specimen cut from the section of the insulation. When testing wire of 6 AWG and larger, or wire smaller than 6 AWG having an insulation thickness greater than 0.095 in., cut specimens approximately square in section, with a cross section not greater than 0.025 in.² (1.6 mm²) from the insulation. If necessary, use a segmented or sector-shaped specimen. Make the test specimens approximately 6 in. (150 mm) long. Take the jacket compound test specimens from the complete wire assembly. Cut the specimens parallel to the axis of the wire. Cut a test specimen (either a segment or sector) with a suitable sharp instrument. Alternatively, use a die to prepare a shaped specimen with a cross-sectional area not greater than 0.025 in.²
- 8.3 *Preparation of Specimens*—Prepare specimens having smooth uncut surfaces. Remove irregularities and corrugations by buffing, planing, or skiving so that the test specimen is smooth and uniform in thickness. Remove reinforcing cords or wires carefully. Do not heat, immerse in water, or subject specimens to any mechanical or chemical treatment not specifically prescribed in these test methods. Additional treatments must be agreed upon by the producer and the purchaser.
- 8.4 Insulation removal is often facilitated by stretching the conductor to the breaking point in a tensile-strength machine, or by cutting the insulation through to the conductor, longitudinally, and carefully removing it.

# 9. Measurement of Thickness of Specimens

- 9.1 Make thickness measurements of the insulation with any type of micrometer reading to 0.001 in. (0.025 mm) and suitable for measurements of this characteristic. See Test Methods D374/D374M for appropriate measuring devices. Apparatus A is preferred, Apparatus C and Apparatus D are acceptable, but Apparatus B is not recommended. The average thickness of the insulation is calculated as one half the difference between the mean of the maximum and minimum diameters over the insulation at one point and the average diameter of the conductor measured at the same point. The minimum thickness of the insulation is calculated as the difference between a measurement made over the conductor plus the thinnest insulation wall, and the diameter of the conductor. (Make the first measurement after slicing off the thicker side of the insulation.) When the wire or cable has a jacket, remove the jacket and determine its minimum and maximum thickness by micrometer measurement. Take the average of these determinations as the average thickness of the jacket.
- 9.2 If the procedures given in 9.1 cannot be followed conveniently, use of an optical micrometer is permitted. https://standards.iteh.a/catalog/standards/sist/dc1cf010-c14f-4749-a567-54cdb291e544/astm-d2633-21
- 9.3 Number of Thickness Measurements—When the lot of wire to be inspected consists of two or fewer coils or reels, make at least one determination of the thickness on each coil or reel. When the lot is greater than two coils or reels and fewer than 20 coils or reels, make at least one determination of the thickness on each of two coils or reels selected at random. For lots greater than 20 coils or reels, randomly select a minimum of 10 % of the coils or reels. Make at least one determination of thickness on each coil or reel selected.

# 10. Physical Test Procedures

- 10.1 Determine the physical properties in accordance with Test Method D638, except as specified in 10.2, 10.3, and 10.4.
- 10.2 Test the specimens at a temperature of 68 to 82 °F (20 to 28 °C).
- 10.3 Mark specimens for all physical tests with gauge marks 1 in. (25 mm) apart. Place a specimen in the jaws of the testing machine. The maximum distance between the jaws is 2 in. (50 mm).
- 10.4 Test insulation or jacketing at a jaw separation speed as specified in Specification D1248 or other applicable product specification.

# 11. Calculation of Area of Specimens

11.1 Calculate the area of a test specimen as follows:

- 11.1.1 When the total cross-section of the insulation is used, calculate the area as the difference between the area of the circle whose diameter is the average outside diameter of the insulation and the area of the conductor. Calculate the area of a stranded conductor from its maximum diameter.
- 11.1.2 Where the specimen is a slice cut from the insulation by a knife held tangent to the wire, and the resulting cross-section of that slice is not a segment of a circle, calculate the area from a direct measurement of the volume or from the specific gravity and the weight of a known length of the specimen having a uniform cross-section.
- 11.1.3 When a portion of a sector of a circle is taken from a large conductor, calculate the area as the thickness times the width. (This applies either to a die cut specimen or one from which all corrugations have been removed.)
- 11.1.4 Determine the dimensions of specimens to be aged before the aging cycle is begun.

#### 12. Aging Test

- 12.1 Age specimens in accordance with Test Method D573, except as specified in 12.2, 12.3, and 12.4.
- 12.2 Use an oven that meets the requirements given in Specification D5423 for Type II ovens.
- 12.3 The product specification defines the test period and temperature of heat aging.
- 12.4 Test the tensile strength and ultimate elongation of the specimens between 16 and 96 h after completion of heat aging. Use the procedure described in Section 11. Perform physical tests on both aged and unaged specimens at the same time.

#### 13. Oil Immersion Test

- 13.1 Oil Immersion Test for Poly(Vinyl Chloride) Insulation and Jacket—Immerse the following test specimens in ASTM Oil No. 2, IRM902, or equivalent, described in Table 1 of Test Method D471, at  $158 \pm 1.8$  °F ( $70 \pm 1$  °C) for 4 h.
- 13.1.1 When using insulated conductors in sizes smaller than 6 AWG (13.3 mm<sup>2</sup>), do not immerse the ends of the specimens.
- 13.1.2 Buffed die-cut specimens of the insulation in sizes 6 AWG (13.3 mm<sup>2</sup>) and larger.
- 13.1.3 Buffed die-cut specimens of the jacket.
- 13.2 After a 4 h exposure period to ASTM Oil No. 2, IRM902, or its equivalent, remove the specimens from the oil. Blot specimens to remove excess oil, and condition at room temperature for a period of 16 to 96 h. Determine the tensile strength and elongation at the same time that the original properties are determined.
- 13.3 Calculations for Tensile Strength and Measurement of Elongation—Base the calculations for tensile strength on the cross-sectional area of the specimen obtained before immersion in the oil. Base the calculation for ultimate elongation on the original distance between the gauge marks applied to the specimen before immersion in the oil.

# 14. Retests

14.1 Any specimens that fail to conform to the values specified for any test, either before or after aging, are required to have two additional specimens retested from the same sample. Failure of the retests indicates nonconformity of the sample to the requirement specified.

# 15. Report

- 15.1 Report the following information:
- 15.1.1 Identification of the wire or cable sampled and tested by manufacturer, lot number if applicable, gauge, sheath type, reel number, length, etc.,



- 15.1.2 Identification of the material sampled and tested by how it was used (insulation, jacket, etc.) and by type (for example, polyethylene as specified in Specification D1248),
- 15.1.3 Date of testing,
- 15.1.4 Name and location of testing laboratory and the person responsible for the testing,
- 15.1.5 Remarks indicating the method or procedure used and the deviation, if any, from the standard procedure,
- 15.1.6 Indication of the variance in test measurements such as high, low, standard deviation, etc., and
- 15.1.7 Minimum, maximum, and average values as applicable and any other information that is appropriate to the test being performed.
- 15.2 The test results shall be reported as calculated or observed values rounded to the nearest unit in the last right hand place of figures used in the wire or cable specification to express the limiting value. (See the rounding method of Practice E29.)

#### 16. Precision and Bias

- 16.1 These test methods have been in use for many years. No statement of precision has been made, and no activity is planned to develop such a statement.
- 16.2 A statement of bias is not possible due to a lack of a standard reference material.

# ELECTRICAL TESTS OF INSULATION

#### 17. Significance and Use

17.1 Electrical tests, properly interpreted, provide information with regard to the electrical properties of the insulation. The electrical test values give an indication as to how the insulation will perform under conditions similar to those observed in the tests. Electrical tests provide useful data for research and development, engineering design, quality control, and acceptance or rejection under specifications.

# 18. Types of Voltage Tests

18.1 Perform voltage withstand tests using either alternating or direct current, or both, applied in accordance with Test Methods D149 and D3755, and as specified in the following sections. Perform the partial discharge, ac voltage, insulation resistance, and dc voltage tests on entire lengths of completed cable.

#### 19. Order of Testing

19.1 Perform the partial discharge, ac voltage withstand, insulation resistance, and dc voltage withstand tests in that order when any of these tests are required. The sequence of other testing is not specified.

# 20. Hazards

20.1 These tests involve the use of high voltages. See Section 4.

# 21. Sampling, Test Specimens, and Test Units

21.1 The specimen is defined in each test method.

#### AC AND DC VOLTAGE WITHSTAND TESTS

#### 22. Significance and Use

22.1 Voltage withstand tests are useful as an indication that the cable is capable of electrically withstanding the intended rated voltage with adequate margin. These tests are normally performed in the factory and are used for product acceptance to specification requirements.

# 23. Apparatus

- 23.1 AC Apparatus—For ac tests, use a voltage source and a means of measuring the voltage that is in conformance with the voltage source and voltage measurement sections of the apparatus section of Test Method D149. Use a power supply having a frequency of 49 to 61 Hz.
- 23.2 *DC Apparatus*—For dc tests, use any source of dc, but if using rectified alternating current, limit the dc ripple to 4 %. Measure the voltage with an electrostatic voltmeter or, in the case of the rectifying equipment, with suitable low-voltage indicators, provided the latter are so connected that their indications are independent of the test load. See Test Method D3755.
- 23.3 Grounded Water Tank—For tests requiring immersion in water, a metal water tank connected to ground or a tank of other material containing a grounded metal plate or bar is required.

# 24. Sampling, Test Specimens, and Test Units

- 24.1 The specimen consists of entire lengths of completed cable.
- 25. Rate of Voltage Application https://standards.iteh.ai)
- 25.1 Increase the applied voltage (from zero unless otherwise specified), at a uniform rate, from the initial value to the specified full test voltage within 60 s.

#### 26. Application of Voltage to Cable

ASTM D2633-21

https://standards.iteh.ai/catalog/standards/sist/dc1cf010-c14f-4749-a567-54cdb291e544/astm-d2633-2

- 26.1 Cables Without Metallic Sheath, Metallic Shield, or Metallic Armor:
- 26.1.1 When single-conductor cables of this type are twisted together into an assembly of two or more conductors without an overall jacket or covering, apply the specified voltage between each conductor and the water. Test such assemblies after immersion for at least 1 h and while still immersed.
- 26.1.2 Test all other single and multiple conductor cables of this type, after immersion in water for at least 6 h and while still immersed.
- 26.1.3 Test each conductor against all other conductors connected to the grounded water tank.
- 26.2 Cables with Metallic Sheath, Metallic Shield, or Metallic Armor:
- 26.2.1 Test all cables of this type with the metallic sheaths, shields, or armors grounded, without immersion in water, at the specified test voltage. For cables having a metallic sheath, shield, or armor over the individual conductor(s), apply the specified test voltage between the conductor and ground. For multiple-conductor cables with nonshielded individual conductors having a metallic sheath, shield, or armor over the cable assembly, apply the specified test voltage between each conductor and all other conductors and ground.

#### 27. Procedure

27.1 Warning (Warning—These tests involve the use of high voltages. See Section 4.—These tests involve the use of high voltages. See Section )4.

27.2 Where the insulation on a single-conductor cable or on individual conductors of a multiple-conductor cable is covered with a thermoplastic jacket, either integral or separate from the insulation, or where the insulation is increased for mechanical reasons, determine the test voltage by the size of the conductor and the rated voltage of the cable and not by the apparent thickness of the insulation.

#### 27.3 AC Tests:

- 27.3.1 Test each insulated conductor for 5 min at the ac withstand voltage given in the applicable product specification. This test is not necessary for non-shielded conductors rated up to 5000 V, if the dc voltage withstand test described in 27.4 is to be performed.
- 27.3.2 Do not apply a starting ac voltage (initial voltage) greater than the rated ac voltage of the cable under test.

#### 27.4 DC Tests:

- 27.4.1 Do not apply a starting dc voltage greater than 3.0 times the rated ac voltage of the cable. The test voltage is permitted to be of either polarity.
- 27.4.2 Upon completion of the insulation resistance test, test each insulated conductor rated for service at 5001 V and above for 15 min at the dc voltage withstand given in the applicable product specification.
- 27.4.3 For cables rated up to 5000 V, upon completion of the insulation resistance test, test each insulated conductor without shielding over the insulation for 5 min at the dc withstand voltage given in the applicable product specification, unless the ac voltage withstand test described in 27.3 was performed.

# 28. Report

# (https://standards.iteh.ai)

- 28.1 Report the following information: Document Preview
- 28.1.1 Manufacturer's name,
- 28.1.2 Manufacturer's lot number, if applicable, ASTM D2633-21
- 28.1.3 Description of the cable construction,
- 28.1.4 Voltage and time of application,
- 28.1.5 Whether or not the cable was immersed in water, and
- 28.1.6 Whether or not the cable withstood the required voltage for the specified time.

#### 29. Precision and Bias

29.1 No statement is made about either the precision or bias of this test since the result merely states whether there is conformance to the criteria for success specified in the procedure.

# INSULATION RESISTANCE TESTS ON COMPLETED CABLE

#### 30. Significance and Use

30.1 The insulation resistance of a cable is primarily a measurement of the volume resistance of the insulating material, although surface resistance across the ends is often significant for short specimens or when atmospheric humidity is high. It is usually desirable for a cable to have a high value of insulation resistance. This test is used for product acceptance to specification requirements, but is also useful for quality control purposes in indicating consistency of manufacture. See Test Methods D257 for a more complete discussion of the significance of insulation resistance tests.

# 31. Apparatus

31.1 *Megohm Bridge*—Use a megohm bridge capable of supplying a constant dc potential from 100 to 500 V. See Test Methods D257.

# 32. Sampling, Test Specimens, and Test Units

32.1 The specimen consists of entire lengths of completed cable.

#### 33. Procedure

- 33.1 Warning (Warning—This test method involves the use of high voltages. See Section 4.—This test involves the use of high voltages. See Section )4.
- 33.2 Unless otherwise specified in the product specification:
- 33.2.1 Perform this test only after performing the completed cable ac voltage withstand tests as specified in 27.3.
- 33.2.2 Perform this test only before performing the completed cable dc voltage withstand tests as specified in 27.4.
- 33.2.3 Perform this test in accordance with Test Methods D257, and as follows:
- 33.2.3.1 Where the voltage withstand tests are made on wire and cable immersed in water, measure the insulation resistance while the cable is still immersed.
- 33.3 Testing:
- 33.3.1 For single conductor cables test between the conductor and its metallic sheath or between the conductor and surrounding water.
- 33.3.2 Multiple-conductor Cables:
- 33.3.2.1 For cables with unshielded conductors, test between each conductor and all other conductors, and between each conductor and the overall sheath or surrounding water.
- 33.3.2.2 For cables having shielded conductors, test between each conductor and its shield.
- 33.3.3 Maintain the temperature of the water between 50 and 85 °F (10 and 30 °C).
- 33.3.4 Connect the conductor of the specimen under test to the negative terminal of the test equipment, and take readings after an electrification of 1 min. On short sections of wire or cable, use a guard circuit to prevent end leakage.
- 33.3.5 When the length of cable under test differs from 1000 ft (305 m), correct the measured value of insulation resistance to  $M\Omega$ -1000 ft by multiplying by the ratio L/1000 (or L/305) where L is the length in feet (or metres).

# 34. Calculation

34.1 Calculate the minimum insulation resistance in M $\Omega$ -1000 ft (305 m) at a temperature of 60 °F (15.6 °C) for each coil, reel, or length of wire or cable as follows:

$$R = K \log_{10} \left( D/d \right) \tag{1}$$

where:

R = minimum insulation resistance, M $\Omega$ -1000 ft (305 m),

K = constant for the grade of insulation, (see 34.1.1),

D = diameter over the insulation, and

d = diameter under the insulation.

- 34.1.1 Obtain the constant K, for the type of insulation in the cable under test, by reference to the product specification.
- 34.1.2 Where a nonconducting separator is applied between the conductor and the insulation, or where an insulated conductor is covered with a nonmetallic jacket, the insulation resistance shall be at least 60 % of that required for the primary insulation based on the thickness of that insulation.
- 34.2 The insulation resistance of wires and cables varies widely with temperature. If the temperature at the time measurement was made differs from 60 °F (15.6 °C), adjust the resistance to that at 60 °F by multiplying the measured value by the proper correction factor from Table 1. Use the coefficient furnished by the manufacturer for the particular insulation and temperature or determine it in accordance with Section 35.

# 35. Determining Temperature Coefficients for Insulation Resistance

- 35.1 Select three specimens, preferably of 14 AWG (2.08 mm<sup>2</sup>) solid wire with a 0.045-in. (1.14 mm) wall of insulation, as representative of the insulation under consideration. Use sufficient length to yield insulation resistance values under 25 000 M $\Omega$ at the lowest water bath temperature.
- 35.2 Immerse the three specimens in a water bath equipped with heating, cooling, and circulating facilities, with the ends of the specimens extended 2 ft (0.6 m) above the surface of the water and properly prepared for minimum leakage. Leave the specimens in the water at room temperature for 16 h before adjusting the bath temperature to 10 °C, or transfer the samples to a 10 °C 10 °C test temperature bath.
- 35.3 Measure the resistance of the conductor at suitable intervals of time until it remains unchanged for at least 5 min. The

TABLE 1 Temperature Correction Factors for Insulation Resistance at 60 °F

Coefficient for 1 °F Temperature °F °C 1.03 1.04 1.05 1.06 1.07 1.08 1.09 1.10 1.11 0.75 0.68 0.56 0.51 0.42 0.38 0.35 10.0 0.62 0.46 0.65 0.39 51 10.6 0.77 0.70 0.59 0.54 0.50 0.46 0.42 0.79 0.73 0.63 0.58 0.54 0.47 0.43 52 11.1 0.68 0.50 53 11.7 0.82 0.76 0.71 0.67 0.62 0.58 0.55 0.51 0.48 0.54 12.2 0.84 0.79 0.75 0.70 0.67 0.63 0.60 0.56 55 12.8 0.87 0.82 0.78 0.75 0.71 0.68 0.65 0.62 0.60 0.74 0.69 0.66 56 13.3 0.89 0.86 0.82 0.76 0.76 0.71 57 13.6 0.92 0.89 0.87 0.84 0.82 0.80 0.78 0.76 0.73 58 14.4 0.94 0.91 0.86 0.85 0.83

1.12 0.32 0.36 0.40 0.45 0.51 0.57 0.64 0.71 0.93 0.90 0.88 0.82 0.80 59 15.0 0.97 0.96 0.96 0.95 0.94 0.93 0.92 0.91 0.90 0.89 1 00 1 00 60 156 1.00 1.00 1.00 1.00 1.00 1 00 1.00 1 00 61 16.1 1.03 1.04 1.05 1.06 1.07 1.08 1.09 1.10 1.11 1.12 62 16.7 1.06 1.08 1.10 1.13 1.15 1.17 1.19 1.21 1.24 1.27 63 17.2 1.09 1.13 1.16 1.19 1.23 1.26 1.30 1.34 1.38 1.42 64 1.26 1.47 1.53 1.58 17.8 1.13 1.17 1.22 1.31 1.36 1.41 65 18.3 1 16 1 22 1 28 1 34 1 40 1 47 1 54 1 62 1 70 1 78 1.27 1.42 1.88 1.98 18.9 1.20 1.35 1.50 1.59 1.69 1.78 67 19.4 1.23 1.32 1.41 1.51 1.62 1.72 1.84 1.96 2.09 2.21 2.31 68 20.0 1.27 1.37 1.48 1.60 1.72 1.86 1.99 2.15 2.48 69 20.6 1.31 1.43 1.55 1.69 1.84 2.00 2.18 2.36 2.57 2.77 70 21.1 1.35 1.48 1.63 1.79 1.97 2.17 2.38 2.60 2.85 3.10 71 21.7 1.39 1.54 1.72 1.90 2.11 2.34 2.59 2.87 3.17 3.48 72 22.2 1.43 1.60 1.80 2.02 2.26 2.53 2.82 3.15 3.52 3.90 73 22.8 1.47 1.67 1.89 2.14 2.42 2.72 3.08 3.46 3.90 4.37 74 23.3 1.52 1.74 1.98 2.27 2.58 2.94 3.35 3.81 4.31 4.88 75 23.9 1.56 1.80 2.08 2.40 2.76 3.18 4.19 4.78 5.47 76 24.4 1.61 1.87 2.19 2.54 2.96 3.43 3.98 4.61 5.30 6.12 25.0 5.88 77 1.66 1 95 2.30 2 70 3.17 3.70 4.34 5.08 6.85 78 25.6 1.71 2.02 2.41 2.86 3.39 4.00 4.78 5.59 6.51 7.68 79 26.1 1.76 2.11 2.53 3.03 3.62 4.33 5.16 6.14 7.27 8.59 2.66 3.21 3.87 6.72 9.65 80 26.7 1.81 2.19 4.67 5.61 8.07 81 27.2 1.87 2.28 2.80 3.40 4.15 5.04 6.12 7.43 8.98 10.8 82 27.8 1.92 2.37 2.94 3.60 4.43 5.45 6.69 8.18 9.92 12.1 83 28.3 1.98 2.47 3.08 3.82 4.73 5.89 7.28 9.00 11.0 13.6 4.05 28.9 2.04 2.57 3.23 5.04 6.35 7.92 9.90 12.2 15.2 84 3.40 4.30 5.42 85 29.4 2.10 2.67 6.84 8.67 10.8 13.5 17.0