



DRAFT INTERNATIONAL STANDARD ISO/DIS 12154

ISO/TC 24/SC 4

Secretariat: DIN

Voting begins on
2012-05-04

Voting terminates on
2012-10-04

INTERNATIONAL ORGANIZATION FOR STANDARDIZATION • МЕЖДУНАРОДНАЯ ОРГАНИЗАЦИЯ ПО СТАНДАРТИЗАЦИИ • ORGANISATION INTERNATIONALE DE NORMALISATION

Determination of density by volumetric displacement — Skeleton density by gas pycnometry

Détermination de la masse volumique par déplacement volumétrique — Masse volumique du squelette mesurée par pycnométrie à gaz

ICS 19.120

ITeH STANDARD PREVIEW
(standards.iteh.ai)
Full standard:
<https://standards.iteh.ai/catalog/standards/sist/626df4e0-7a-4fd2-baf4-6a10e40da564/iso-12154-2014>

To expedite distribution, this document is circulated as received from the committee secretariat. ISO Central Secretariat work of editing and text composition will be undertaken at publication stage.

Pour accélérer la distribution, le présent document est distribué tel qu'il est parvenu du secrétariat du comité. Le travail de rédaction et de composition de texte sera effectué au Secrétariat central de l'ISO au stade de publication.

THIS DOCUMENT IS A DRAFT CIRCULATED FOR COMMENT AND APPROVAL. IT IS THEREFORE SUBJECT TO CHANGE AND MAY NOT BE REFERRED TO AS AN INTERNATIONAL STANDARD UNTIL PUBLISHED AS SUCH.

IN ADDITION TO THEIR EVALUATION AS BEING ACCEPTABLE FOR INDUSTRIAL, TECHNOLOGICAL, COMMERCIAL AND USER PURPOSES, DRAFT INTERNATIONAL STANDARDS MAY ON OCCASION HAVE TO BE CONSIDERED IN THE LIGHT OF THEIR POTENTIAL TO BECOME STANDARDS TO WHICH REFERENCE MAY BE MADE IN NATIONAL REGULATIONS.

RECIPIENTS OF THIS DRAFT ARE INVITED TO SUBMIT, WITH THEIR COMMENTS, NOTIFICATION OF ANY RELEVANT PATENT RIGHTS OF WHICH THEY ARE AWARE AND TO PROVIDE SUPPORTING DOCUMENTATION.

iTeh STANDARD PREVIEW
(standards.iteh.ai)
Full standard:
<https://standards.iteh.ai/catalog/standards/sist/626df4e0-fe7a-4fd2-baf4-6a10e40da564/iso-12154-2014>

Copyright notice

This ISO document is a Draft International Standard and is copyright-protected by ISO. Except as permitted under the applicable laws of the user's country, neither this ISO draft nor any extract from it may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, photocopying, recording or otherwise, without prior written permission being secured.

Requests for permission to reproduce should be addressed to either ISO at the address below or ISO's member body in the country of the requester.

ISO copyright office
Case postale 56 • CH-1211 Geneva 20
Tel. + 41 22 749 01 11
Fax + 41 22 749 09 47
E-mail copyright@iso.org
Web www.iso.org

Reproduction may be subject to royalty payments or a licensing agreement.

Violators may be prosecuted.

Contents

Page

Foreword	iv
Introduction.....	iv
1 Scope	1
2 Normative references	1
3 Terms and definitions	1
4 Symbols and abbreviated terms	2
5 Principle of the method.....	2
6 Apparatus and procedure.....	3
6.1 Apparatus.....	3
6.2 Sample pre-treatment and determination of sample mass	4
6.3 Determination of the solid skeleton volume of the sample	5
6.3.1 Pycnometric measurement	5
6.3.2 Calculation of the skeleton volume of the sample.....	6
6.4 Calculation of skeleton density	6
6.5 Calibration procedure	6
6.5.1 General remarks	6
6.5.2 Calibration of pycnometer configuration 1.....	7
6.5.3 Calibration of pycnometer configuration 2.....	7
7 Test report.....	8
Annex A (informative) Interferences	9
A.1 Improper sample quantity.....	9
A.2 Thermal effects and pressure stability.....	9
A.3 Influence of humidity and adsorbed gases	9
A.4 Leaks.....	9
A.5 Permeable samples	10
A.6 Compressible samples	10
A.7 Thermally sensitive samples.....	10
A.8 High surface area samples.....	10
A.9 Finely ground samples	10
Bibliography.....	11

Foreword

ISO (the International Organization for Standardization) is a worldwide federation of national standards bodies (ISO member bodies). The work of preparing International Standards is normally carried out through ISO technical committees. Each member body interested in a subject for which a technical committee has been established has the right to be represented on that committee. International organizations, governmental and non-governmental, in liaison with ISO, also take part in the work. ISO collaborates closely with the International Electrotechnical Commission (IEC) on all matters of electrotechnical standardization.

International Standards are drafted in accordance with the rules given in the ISO/IEC Directives, Part 2.

The main task of technical committees is to prepare International Standards. Draft International Standards adopted by the technical committees are circulated to the member bodies for voting. Publication as an International Standard requires approval by at least 75 % of the member bodies casting a vote.

Attention is drawn to the possibility that some of the elements of this document may be the subject of patent rights. ISO shall not be held responsible for identifying any or all such patent rights.

ISO 12154 was prepared by Technical Committee ISO/TC 24, *Particle characterization including sieving*, Subcommittee SC 4, *Particle characterization*.

This second/third/... edition cancels and replaces the first/second/... edition (), [clause(s) / subclause(s) / table(s) / figure(s) / annex(es)] of which [has / have] been technically revised.

iTeh STANDARD PREVIEW
(standards.iteh.ai)
Full standard available on
<https://standards.iteh.ai/catalog/standards/sist/628884e0-fe7a-4fd2-baf4-6a10e40da564/iso-12154-2014>

Introduction

The true solid state density of a material is defined as the ratio of the mass to the volume occupied by that mass. Therefore, the contribution to the volume made by pores or internal voids and also interparticle voids (in the case of granulated or highly dispersed samples) must be subtracted when calculating the true density.

If the material has no porosity, the true density can be measured by displacement of any fluid in which the solid remains inert. The accuracy of the method is limited by the accuracy with which the fluid volume can be determined. Usually, however, the pores, cracks, or crevices of the material will not easily be completely penetrated by a displaced liquid. In these instances, the true density can be measured by using a gas as the displaced fluid if the material does not contain closed pores, which cannot be penetrated by the analysis gas. Therefore, the density experimentally determined by gas pycnometry generally is the so called skeleton density of the material which equals the true solid state density only for samples without closed pores.

Apparatus used to measure solid volumes are often referred to as pycnometers or pycnometers after the Greek 'pyknos', meaning thick or dense. With gas pycnometry, materials of irregular shape can be analysed.

Once the volume of solid skeleton of the sample and the sample mass have been determined, the skeleton density is readily calculated.

iTeh STANDARD PREVIEW
(standards.iteh.ai)
Full standard:
<https://standards.iteh.ai/catalog/standards/sist/626df40fe7a-4fd2-baf4-6a10e40da564/iso-12154-2014>

iTeh STANDARD PREVIEW
(standards.iteh.ai)

Full standard:
<https://standards.iteh.ai/catalog/standards/sist/626df4e0-fe7a-4fd2-baf4-6a10e40da564/iso-12154-2014>

Determination of density by volumetric displacement — Skeleton density by gas pycnometry

1 Scope

This standard specifies a method for rapid and efficient determination of the skeleton density of solid material samples of regular or irregular shape whether powdered or in one piece by means of a gas displacement pycnometer.

2 Normative references

The following referenced documents are indispensable for the application of this document. For dated references, only the edition cited applies. For undated references, the latest edition of the referenced document (including any amendments) applies.

ISO 14488, *Particulate materials — Sampling and sample splitting for the determination of particulate properties*

ISO 9277, *Determination of the specific surface area of solids by gas adsorption — BET method*

ISO 15901-3, *Pore size distribution and porosity of solid materials by mercury porosimetry and gas adsorption — Part 3: Analysis of micropores by gas adsorption*

3 Terms and definitions

For the purposes of this document, the following terms and definitions apply.

3.1

density

ratio of the mass of a certain amount of a sample to the volume occupied by that mass

3.2

true solid state density

ratio of the sample mass to the volume of the compact solid skeleton of the sample which excludes the volume of open and closed pores or internal voids and also interparticle voids as in the case of granulated or highly dispersed samples

3.3

skeleton density

ratio between sample mass and the volume of the sample including the volume of closed pores (if present) but excluding the volumes of open pores as well as that of void spaces between particles within the bulk sample

3.4

closed pore

a pore totally enclosed by its walls and hence not interconnecting with other pores and not accessible to fluids

3.5

open pore

a pore not totally enclosed by its walls and open to the surface either directly or by interconnecting with other pores and therefore accessible to fluids

3.6 gauge pressure sensor

because gauge pressure is defined relative to atmospheric conditions, the signal or reading of a gauge pressure sensor is the total pressure minus atmospheric pressure

3.7 absolute pressure sensor

an absolute pressure sensor measures the pressure relative to an absolute vacuum that means the reference is full vacuum (zero pressure)

4 Symbols and abbreviated terms

Table 1 — Symbols

Symbol	Name	Unit
ρ_s	skeleton density	g cm^{-3}
m_s	sample mass	g
V_s	skeleton volume of the sample	cm^3
V_{cell}	sample chamber volume	cm^3
V_{ref}	reference chamber volume	cm^3
V_{cal}	volume of the calibrated reference sample	cm^3
p_1	equilibrated gauge pressure prior to expansion ^a	Pa
p_2	equilibrated gauge pressure after expansion ^a	Pa
p_{A1}	equilibrated gauge pressure before expansion (calibration step A) ^a	Pa
p_{A2}	equilibrated gauge pressure after expansion (calibration step A) ^a	Pa
p_{B1}	equilibrated gauge pressure before expansion (2nd calibration step) ^a	Pa
p_{B2}	equilibrated gauge pressure after expansion (2nd calibration step) ^a	Pa
p_a	pycnometer pressure at start of analysis	Pa
p_i^*	pycnometer absolute gas pressure i ($i = 1, 2, A1, A2, B1, \text{ or } B2$)	Pa
p_i	pycnometer excess gas pressure i ($i = 1, 2, A1, A2, B1, \text{ or } B2$)	Pa

^a gauge pressure (gas excess pressure) p_i is defined as the difference between the absolute pressure p_i^* and the pycnometer pressure p_a at start of analysis, i.e. $p_i = p_i^* - p_a$ (see Subclauses 3.6, 3.7, and 6.3.2.1)

5 Principle of the method

The skeleton density will be determined volumetrically in a gas expansion pycnometer. This technique is based on the displacement of a volume of gas by the solid space. The measurement is performed by expanding gas from one chamber to another (see Figure 1) under isothermal conditions. First, the weight of the dry sample is to be determined and the sample loaded into the sample chamber. The sample chamber then is pressurised to a set value when using the experimental configuration 1 of Figure 1. In a further step, the analysis gas will be expanded into a second chamber, the reference volume. The equilibrated pressures for both steps will be recorded by the instrument. Density is calculated using these values.

For gas pycnometers according to the experimental configuration 2 of Figure 1, the first step consists in pressurising the reference chamber to a set value followed by the expansion into the sample chamber having a lower initial pressure than the set value. It is important for both experimental pycnometer configurations, that every chamber of the pycnometer is at the same pressure p_0 prior to starting the analysis steps (see Clause 6) Furthermore, all parts of the pycnometer must have the same controlled temperature.

The analysis gas of sufficient purity (see Subclause 6.1) must be nonreactive and behave as ideally as possible. Therefore, helium is used for most applications. Another reason for the preferred use of helium as the analysis gas for gas pycnometry is that it is able to penetrate even the smallest pores or cracks of a material.

NOTE 1 Because of its pronounced ability to permeate thin inner walls of samples with closed cells, helium may cause difficulties if permeable samples are to be analyzed. Therefore, as described in Annex A.6, gas pycnometric measurements using helium may be erroneous in the case of organic samples like cellulose and cellular polymers with low density. For density measurements of those samples, the use of alternative inert gases such as nitrogen, argon, or sulfur hexafluoride but also dry air is recommended.

NOTE 2 If the sample contains no closed pores, then the volume measured by gas pycnometry is the true volume. To test the presence of closed pores, after a first density determination the sample can be powdered revealing any possible closed pores accessible to the test gas. An increased density value of the ground sample material indicates closed pores in the original sample.

6 Apparatus and procedure

6.1 Apparatus

- Gas expansion pycnometer with fixed-volume sample chamber [1], [2], [3] (see Figure 1)
- Calibrated reference sample (in general calibration spheres made of stainless steel with known traceable volume)
- Analysis gas, in general helium (see Clause 5) with a minimum purity of 99,996 % (by volume)
- Analytical balance
- Drying oven for pre-treatment of samples preferably with the option of purging during heating or heating in a vacuum

Figure 1 is a schematic diagram of the two principal configurations of automatic gas expansion pycnometers having fixed sample chamber size. Main components of such instruments are two chambers connected by tubes (a sample chamber with a sealed cap for inserting the sample or the calibration spheres and a reference chamber), a pressure-measuring sensor, and three valves. The difference between the pycnometer configurations is in the sequence of the sample chamber and the reference chamber.

Sample volumes of commercially available gas expansion pycnometers vary from 0,1 cm³ to about 500 cm³. This is accomplished either by having fixed-volume sample chambers of different sizes, or by means of volume-filling inserts placed into a sample chamber. These variations in sample chamber volume are necessary because the accuracy of the pycnometric measurement is related to the percent of total capacity the sample material occupies in the sample chamber.