

INTERNATIONAL
STANDARD

ISO/ASTM
51026

First edition
2015-07-15

**Practice for using the Fricke dosimetry
system**

iTeh STANDARD PREVIEW
Pratique pour l'utilisation du système dosimétrique de Fricke
(standards.iteh.ai)

[ISO/ASTM 51026:2015](#)
<https://standards.iteh.ai/catalog/standards/sist/692200df-b3f5-44ab-9526-159f54f82c88/iso-astm-51026-2015>



Reference number
ISO/ASTM 51026:2015(E)

© ISO/ASTM International 2015

iTeh STANDARD PREVIEW (standards.iteh.ai)

[ISO/ASTM 51026:2015](#)

<https://standards.iteh.ai/catalog/standards/sist/692200df-b3f5-44ab-9526-159f54f82c88/iso-astm-51026-2015>

© ISO/ASTM International 2015

All rights reserved. Unless otherwise specified, no part of this publication may be reproduced or utilized in any form or by any means, electronic or mechanical, including photocopying and microfilm, without permission in writing from either ISO at the address below or ISO's member body in the country of the requester. In the United States, such requests should be sent to ASTM International.

ISO copyright office
Case postale 56 • CH-1211 Geneva 20
Tel. +41 22 749 01 11
Fax +41 22 749 09 47
E-mail copyright@iso.org
Web www.iso.org

ASTM International,100 Barr Harbor Drive, PO Box C700,
West Conshohocken, PA 19428-2959, USA
Tel. +610 832 9634
Fax +610 832 9635
E-mail khooper@astm.org
Web www.astm.org

Published in Switzerland

Contents

	Page
1 Scope	1
2 Referenced documents	1
3 Terminology	2
4 Significance and use	2
5 Effect of influence quantities	2
6 Interferences	2
7 Apparatus	3
8 Reagents	3
9 Preparation of dosimeters	3
10 Calibration of the dosimetry system	4
11 Application of dosimetry system	5
12 Minimum documentation requirements	6
13 Measurement uncertainty	6
14 Keywords	6

iTeh STANDARD PREVIEW

(standards.iteh.ai)

[ISO/ASTM 51026:2015](#)

<https://standards.iteh.ai/catalog/standards/sist/692200df-b3f5-44ab-9526-159f54f82c88/iso-astm-51026-2015>

Foreword

ISO (the International Organization for Standardization) is a worldwide federation of national standards bodies (ISO member bodies). The work of preparing International Standards is normally carried out through ISO technical committees. Each member body interested in a subject for which a technical committee has been established has the right to be represented on that committee. International organizations, governmental and non-governmental, in liaison with ISO, also take part in the work. ISO collaborates closely with the International Electrotechnical Commission (IEC) on all matters of electrotechnical standardization.

Draft International Standards adopted by the technical committees are circulated to the member bodies for voting. Publication as an International Standard requires approval by at least 75% of the member bodies casting a vote.

ASTM International is one of the world's largest voluntary standards development organizations with global participation from affected stakeholders. ASTM technical committees follow rigorous due process balloting procedures.

iTeh STANDARD PREVIEW

A project between ISO and ASTM International has been formed to develop and maintain a group of ISO/ASTM radiation processing dosimetry standards. Under this project, ASTM Committee E61, Radiation Processing, is responsible for the development and maintenance of these dosimetry standards with unrestricted participation and input from appropriate ISO member bodies.

<https://standards.iec.ch/catalog/standards/sis/0922000d-03f5-44ab-9526-15954f82c88/iso-astm-51026-2015>

Attention is drawn to the possibility that some of the elements of this document may be the subject of patent rights. Neither ISO nor ASTM International shall be held responsible for identifying any or all such patent rights.

International Standard ISO/ASTM 51026 was developed by ASTM Committee E61, Radiation Processing, through Subcommittee E61.02, Dosimetry Systems, and by Technical Committee ISO/TC 85, Nuclear energy, nuclear technologies and radiological protection.

This first edition cancels and replaces the ASTM E1026-13, which has been technically revised.

Standard Practice for Using the Fricke Dosimetry System¹

This standard is issued under the fixed designation ISO/ASTM 51026; the number immediately following the designation indicates the year of original adoption or, in the case of revision, the year of last revision.

1. Scope

1.1 This practice covers the procedures for preparation, testing and using the acidic aqueous ferrous ammonium sulfate solution dosimetry system to measure absorbed dose to water when exposed to ionizing radiation. The system consists of a dosimeter and appropriate analytical instrumentation. The system will be referred to as the Fricke dosimetry system. The Fricke dosimetry system may be used as either a reference standard dosimetry system or a routine dosimetry system.

1.2 This practice is one of a set of standards that provides recommendations for properly implementing dosimetry in radiation processing, and describes a means of achieving compliance with the requirements of ISO/ASTM Practice [52628](#) for the Fricke dosimetry system. It is intended to be read in conjunction with ISO/ASTM Practice [52628](#).

1.3 The practice describes the spectrophotometric analysis procedures for the Fricke dosimetry system.

1.4 This practice applies only to gamma radiation, X-radiation (bremsstrahlung), and high-energy electrons.

1.5 This practice applies provided the following [52628](#) is satisfied:

1.5.1 The absorbed dose range shall be from 20 to 400 Gy [\(1\)](#).²

1.5.2 The absorbed-dose rate does not exceed 10^6 Gy·s⁻¹ [\(2\)](#).

1.5.3 For radioisotope gamma sources, the initial photon energy is greater than 0.6 MeV. For X-radiation (bremsstrahlung), the initial energy of the electrons used to produce the photons is equal to or greater than 2 MeV. For electron beams, the initial electron energy is greater than 8 MeV.

NOTE 1—The lower energy limits given are appropriate for a cylindrical dosimeter ampoule of 12 mm diameter. Corrections for displacement effects and dose gradient across the ampoule may be required for electron beams [\(3\)](#). The Fricke dosimetry system may be used at lower energies by

¹ This practice is under the jurisdiction of ASTM Committee [E61](#) on Radiation Processing and is the direct responsibility of Subcommittee [E61.02](#) on Dosimetry Systems and is also under the jurisdiction of ISO/TC 85/WG 3.

Current edition approved Feb. 9, 2015. Published June 2015. Originally published as ASTM E1026-84. Last previous ASTM edition E1026 – 13. The present International Standard ISO/ASTM 51026-2015(E) replaces ASTM E1026 – 13.

² The boldface numbers that appear in parentheses refer to a bibliography at the end of this practice.

employing thinner (in the beam direction) dosimeter containers (see ICRU Report 35).

1.5.4 The irradiation temperature of the dosimeter should be within the range of 10 to 60°C.

1.6 *This standard does not purport to address all of the safety concerns, if any, associated with its use. It is the responsibility of the user of this standard to establish appropriate safety and health practices and determine the applicability of regulatory limitations prior to use.*

2. Referenced documents

2.1 ASTM Standards:³

[C912](#) Practice for Designing a Process for Cleaning Technical Glasses

[E170](#) Terminology Relating to Radiation Measurements and Dosimetry

[E18](#) Practice for Dealing With Outlying Observations

[E275](#) Practice for Describing and Measuring Performance of Ultraviolet and Visible Spectrophotometers

[E666](#) Practice for Calculating Absorbed Dose From Gamma or X-Radiation

[E668](#) Practice for Application of Thermoluminescence-Dosimetry (TLD) Systems for Determining Absorbed Dose in Radiation-Hardness Testing of Electronic Devices

[E925](#) Practice for Monitoring the Calibration of Ultraviolet-Visible Spectrophotometers whose Spectral Bandwidth does not Exceed 2 nm

[E958](#) Practice for Estimation of the Spectral Bandwidth of Ultraviolet-Visible Spectrophotometers

2.2 ISO/ASTM Standards:³

[51261](#) Practice for Calibration of Routine Dosimetry Systems for Radiation Processing

[51707](#) Guide for Estimating Uncertainties in Dosimetry for Radiation Processing

[52628](#) Practice for Dosimetry in Radiation Processing

2.3 ISO/IEC Standard:

[ISO/IEC 17025](#) General requirements for the competence of testing and calibration laboratories⁴

³ For referenced ASTM and ISO/ASTM standards, visit the ASTM website, www.astm.org, or contact ASTM Customer Service at service@astm.org. For *Annual Book of ASTM Standards* volume information, refer to the standard's Document Summary page on the ASTM website.

⁴ Available from American National Standards Institute (ANSI), 25 W. 43rd St., 4th Floor, New York, NY 10036, <http://www.ansi.org>.

2.4 International Commission on Radiation Units and Measurements (ICRU) Reports:⁵

ICRU Report 14 Radiation Dosimetry: X Rays and Gamma Rays with Maximum Photon Energies Between 0.6 and 50 MeV

ICRU Report 35 Radiation Dosimetry: Electrons with Initial Energies Between 1 and 50 MeV

ICRU Report 64 Dosimetry of High-Energy Photon Beams based on Standards of Absorbed Dose to Water

ICRU Report 80 Dosimetry Systems for Use in Radiation Processing

ICRU Report 85a Fundamental Quantities and Units for Ionizing Radiation

2.5 Joint Committee for Guides in Metrology (JCGM) Reports:⁶

JCGM 100:2008 GUM 1995, with minor corrections, Evaluation of measurement data – Guide to the expression of uncertainty in measurement

2.6 National Research Council Canada (NRCC):

PIRS-0815 The IRS Fricke Dosimetry System⁷

3. Terminology

3.1 Definitions:

3.1.1 *approved laboratory*—laboratory that is a recognized national metrology institute; or has been formally accredited to ISO/IEC 17025; or has a quality system consistent with the requirements of ISO/IEC 17025.

3.1.1.1 *Discussion*—A recognized national metrology institute or other calibration laboratory accredited to ISO/IEC 17025 should be used in order to ensure traceability to a national or international standard. A calibration certificate provided by a laboratory not having formal recognition or accreditation will not necessarily be proof of traceability to a national or international standard.

3.1.2 *molar linear absorption coefficient* (ϵ_m)—a constant relating the spectrophotometric absorbance (A_λ) of an optically absorbing molecular species at a given wavelength (λ) per unit pathlength (d) to the molar concentration (c) of that species in solution:

$$\epsilon_m = \frac{A_\lambda}{(d \times c)} \quad (1)$$

Unit: $\text{m}^2 \cdot \text{mol}^{-1}$

3.1.3 *radiation chemical yield* ($G(x)$)—quotient of $n(x)$ by $\bar{\epsilon}$, where $n(x)$ is the mean amount of a specified entity, x , produced, destroyed, or changed by the mean energy, $\bar{\epsilon}$, imparted to the matter.

$$G(x) = \left(\frac{n(x)}{\bar{\epsilon}} \right) \quad (2)$$

Unit: $\text{mol} \cdot \text{J}^{-1}$

⁵ Available from International Commission on Radiation Units and Measurements (ICRU), 7910 Woodmont Ave., Suite 400, Bethesda, MD 20841-3095, <http://www.icru.org>.

⁶ Document produced by Working Group 1 of the Joint Committee for Guides in Metrology (JCGM/WG1). Available free of charge at the BIPM website (<http://www.bipm.org>).

⁷ Available from the National Research Council, Ionizing Radiation Standards, Ottawa, Ontario. K1A 0R6.

3.1.4 *reference standard dosimetry system*—dosimetry system, generally having the highest metrological quality available at a given location or in a given organization, from which measurements made there are derived.

3.1.5 *type I dosimeter*—dosimeter of high metrological quality, the response of which is affected by individual influence quantities in a well-defined way that can be expressed in terms of independent correction factors.

3.2 Definitions of other terms used in this standard that pertain to radiation measurement and dosimetry may be found in Terminology E170. Definitions in E170 are compatible with ICRU 85a; that document, therefore, may be used as an alternative reference.

4. Significance and use

4.1 The Fricke dosimetry system provides a reliable means for measurement of absorbed dose to water, based on a process of oxidation of ferrous ions to ferric ions in acidic aqueous solution by ionizing radiation (ICRU 80, PIRS-0815,(4)). In situations not requiring traceability to national standards, this system can be used for absolute determination of absorbed dose without calibration, as the radiation chemical yield of ferric ions is well characterized (see Appendix X3).

4.2 The dosimeter is an air-saturated solution of ferrous sulfate or ferrous ammonium sulfate that indicates absorbed dose by an increase in optical absorbance at a specified wavelength. A temperature-controlled calibrated spectrophotometer is used to measure the absorbance.

5. Effect of influence quantities

5.1 The Fricke dosimeter response (change in optical absorbance) to a given radiation dose is dependent on irradiation temperature and measurement temperature. Thus, corrections may have to be applied for changes to the radiation chemical yield (G) for irradiation temperature and to the molar linear absorption coefficient (ϵ) for measurement temperatures. Both $\epsilon(\text{Fe}^{3+})$ and $G(\text{Fe}^{3+})$ increase with increase in temperature. The subscripts indicate the temperature of irradiation and measurement, as applicable. Both of the temperatures are in $^{\circ}\text{C}$.

$$\epsilon_{T_{\text{meas}}} = \epsilon_{25} [1 + 0.0069 (T_{\text{meas}} - 25)] \quad (3)$$

$$G_{T_{\text{irrad}}} = G_{25} [1 + 0.0012 (T_{\text{irrad}} - 25)] \quad (4)$$

5.2 The radiation chemical yield depends on the type and energy of the radiation employed and, in particular, changes significantly at low photon energies (5).

6. Interferences

6.1 The Fricke dosimeter response is extremely sensitive to impurities in the solution, particularly organic impurities. Even in trace quantities, impurities can cause a detectable change in the observed response. For high accuracy, organic materials shall not be used for any component in contact with the solution, unless it has been demonstrated that the materials do not affect the dosimeter response.

6.2 Traces of metal ions in the irradiated and unirradiated dosimetric solutions can also affect dosimeter response. Therefore, do not use metal in any component in contact with the solutions.

6.3 If flame sealed ampoules are used as the dosimeters, exercise care in filling ampoules to avoid depositing solution in the ampoule neck. Subsequent heating during sealing of the ampoule may cause undesirable chemical change in the dosimetric solution remaining inside the ampoule neck. For the same reason, exercise care to avoid heating the body of the ampoule during sealing.

6.4 Thermal oxidation (as indicated by an increase in optical absorbance), in the absence of radiation, is a function of ambient temperature. At normal laboratory temperatures (about 20 to 25°C), this effect may be significant if there is a long period of time between solution preparation and photometric measurement. This interference is discussed further in 9.3.

6.5 The dosimetric solution is somewhat sensitive to ultraviolet light and should be kept in the dark for long-term storage. No special precautions are required during routine handling under normal laboratory lighting conditions, but strong UV sources such as sunlight should be avoided.

7. Apparatus

7.1 For the analysis of the dosimetric solution, use a high-precision spectrophotometer capable of measuring absorbance values up to 2 with an uncertainty of no more than $\pm 1\%$ in the region of 300 nm. Use a quartz cuvette with 5- or 10 mm pathlength for spectrophotometric measurement of the solution. The cuvette capacity must be small enough to allow it to be thoroughly rinsed by the dosimeter solution and still leave an adequate amount of that solution to fill the cuvette to the appropriate level for the absorbance measurement. For dosimeter ampoules of less than 2 mL, this may require the use of semi-microcapacity cuvettes. Other solution handling techniques, such as the use of micro-capacity flow cells, may be employed provided precautions are taken to avoid cross-contamination. Either control the temperature of the dosimetric solution during measurement at $25 \pm 0.5^\circ\text{C}$, or determine the solution temperature during the spectrophotometric analysis and correct the measured absorbance to 25°C using Eq 3.

7.2 Use borosilicate glass or equivalent chemically-resistant glass to store the reagents and the prepared dosimetric solution. Clean all apparatus thoroughly before use (see Practice C912).

7.2.1 Store the cleaned glassware in a clean, dust-free environment. For extreme accuracy, bake the glassware in vacuum at 550°C for at least 1 h (6).

7.2.2 As an alternative method to baking the glassware, the dosimeter containers (for example, ampoules) may be filled with the dosimetric solution and irradiated to a dose of at least 500 Gy. When a container is needed, pour out the irradiated solution, rinse the container at least three times with unirradiated solution and then refill with the dosimetric solution to be irradiated. The time between filling, irradiation and measurement should be as short as practical, preferably no more than a few hours. Refer to Note 2.

7.3 Use a sealed glass ampoule or other appropriate glass container to hold the dosimetric solution during irradiation.

NOTE 2—To minimize errors due to differences in radiation absorption properties between the container material and the Fricke solution, it is possible to use plastic containers (for example, PMMA or polystyrene) to hold Fricke solution. However, the interferences discussed in Section 6 may result in a reduction in accuracy. To reduce these problems, the plastic containers may be conditioned by irradiating them filled with dosimetric solution to approximately 500 Gy. The containers should then be thoroughly rinsed with unirradiated solution before use.

8. Reagents

8.1 *Purity of Reagents*—Reagent grade chemicals shall be used. Unless otherwise indicated, all reagents shall conform to the specifications of the Committee on Analytical Reagents of the American Chemical Society (or equivalent) where such specifications are available.⁸ Other grades may be used, provided it is first ascertained that the reagent is of sufficient high purity to permit its use without lessening the accuracy of the measurements. Methods of obtaining higher purity of chemicals exist (for example, crystallization or distillation), but are not discussed here.

8.2 *Purity of Water*—Water purity is very important since water is the major constituent of the dosimetric solution, and therefore, may be the prime source of contamination. The use of double-distilled water from coupled all-glass and silica stills or water from a high-quality commercial purification unit capable of achieving Total Oxidizable Carbon (T.O.C.) content below 5 ppb is recommended. Use of deionized water is not recommended.

NOTE 3—Double-distilled water distilled from an alkaline permanganate (KMnO_4) solution (2 g KMnO_4 plus 5 g sodium hydroxide (NaOH) in 2 L of distilled water) has been found to be adequate for routine preparation of the dosimetric solution. High purity water is commercially available from some suppliers. Water labelled HPLC (high pressure liquid chromatography) grade is usually sufficiently free of organic impurities to be used in this practice.

8.3 Reagents:

- 8.3.1 *Ferrous Ammonium Sulfate*— $(\text{NH}_4)_2\text{Fe}(\text{SO}_4)_2 \cdot 6\text{H}_2\text{O}$.
- 8.3.2 *Sodium Chloride* (NaCl).
- 8.3.3 *Sulfuric Acid* (H_2SO_4).

9. Preparation of dosimeters

9.1 Prepare dosimetric solution:

9.1.1 Dissolve 0.392 g of ferrous ammonium sulfate, $(\text{NH}_4)_2\text{Fe}(\text{SO}_4)_2 \cdot 6\text{H}_2\text{O}$, and 0.058 g of sodium chloride, NaCl , in 12.5 mL of 0.4 mol·L⁻¹ sulfuric acid, H_2SO_4 . Dilute to 1 L in a volumetric flask with air-saturated 0.4 mol·L⁻¹ sulfuric acid at 25°C . To make 0.4 M solution, use 41.0 g of 96.7 % sulfuric acid plus water to make 1 L of solution.

NOTE 4—Sodium chloride is used to reduce any adverse effects on the response of the dosimeter due to trace organic impurities.

⁸ *Reagent Chemicals, American Chemical Society Specifications*, American Chemical Society, Washington, DC. For suggestions on the testing of reagents not listed by the American Chemical Society, see *Analalr Standards for Laboratory Chemicals*, BDH Ltd, Poole, Dorset, U.K., and the *United States Pharmacopeia and National Formulary*, U.S. Pharmaceutical Convention, Inc. (USPC), Rockville, MD.

9.1.2 If the final solution is not yet air-saturated, it should be done. Shaking of the solution is normally sufficient to achieve this. Alternatively, bubble high-purity air through the solution, taking care to avoid any possible organic contamination of the air. The oxygen concentration in air-saturated solution is adequate to ensure the dosimeter's linear response up to 400 Gy. Store the dosimetric solution in clean borosilicate glass containers in the dark.

9.2 The dosimetric solution has the following concentrations: 1×10^{-3} mol·L⁻¹ ferrous ammonium sulfate; 1×10^{-3} mol·L⁻¹ sodium chloride; and 0.4 mol·L⁻¹ sulfuric acid.

9.3 The dosimetric solution will slowly oxidize at room temperature resulting in an increase in the optical absorbance of the unirradiated solution. If the solution has not been used for some time, measure the absorbance of the unirradiated solution, as described in 10.4. If the absorbance of a 10-mm pathlength sample is greater than 0.1, do not use that solution. Prepare a fresh batch of solution to replace it.

NOTE 5—Oxidation of the solution at room temperature can be significantly reduced by refrigerating the solution, but refrigeration may also change the oxygen concentration.

9.4 Rinse the dosimeter containers (ampoules or other types) at least three times with the dosimetric solution before filling them for irradiation. Even with careful rinsing, there will always be solution remaining; subsequent rinsing will help mitigate this effect.

9.5 Fill clean containers with the dosimetric solution. If flame sealing the dosimeters, observe the precautions in 16.3(15954182c88/ISO/ASTM 51026-2015).

9.6 An alternative method of preparation using concentrated stock solution is described in Appendix X1. Each dilution made from the stock solution should be treated as a separate batch for the purposes of calibration.

10. Calibration of the dosimetry system

10.1 Prior to use, the dosimetry system (consisting of a specific batch of dosimeters and specific measurement instruments) shall be calibrated in accordance with the user's documented procedure, that specifies details of the calibration and quality assurance requirements. This calibration shall be repeated at regular intervals to ensure that the accuracy of the absorbed dose measurement is maintained within required limits. Calibration methods are described in ISO/ASTM Practice 51261.

NOTE 6—The quality of the Fricke dosimetry system is potentially high if prepared and used correctly and it is capable of dose determination using published ϵ or G values, or the value of their product. However, doses determined in this way cannot be considered traceable to national or international standards without additional evidence, such as comparison with known traceable standards. For completeness, details of this method are given in Appendix X3, but it is not recommended in situations where traceability to national or international standards is a regulatory requirement.

10.2 *Calibration Irradiation of Dosimeters*—Irradiation is a critical component of the calibration of the dosimetry system.

10.2.1 When the Fricke dosimeter is used in a reference standard dosimetry system, calibration irradiations shall be

performed at an approved laboratory, as defined in 3.1.1, and have demonstrable traceability to nationally or internationally recognized standards.

10.2.2 When the Fricke dosimeter is used in a routine dosimetry system, the calibration irradiation may be performed in accordance with 10.2.1, or at a production or research irradiation facility together with reference- or transfer-standard dosimeters from a system that has measurement traceability to nationally or internationally recognized standards.

10.2.3 Specify the calibration dose in terms of absorbed dose to water.

10.2.4 For calibration with photons, the Fricke dosimeter shall be irradiated under conditions that approximate electron equilibrium.

10.2.5 When using an electron beam for irradiation, locate the dosimeters in a well-characterized position within the radiation field.

10.2.6 Ensure that the radiation field within the volume occupied by the dosimeters is as uniform as possible. The variation in dose rate within this volume should be known, and be within acceptable limits for the uncertainty of calibration required.

10.2.7 The dosimeter shall be calibrated in a radiation field of the same type and energy as that in which it is to be used, unless evidence is available to demonstrate equivalence of response.

10.2.8 Calibrate each batch of dosimeters prior to use.

10.2.9 Separate five dosimeters from the remainder of the batch and do not irradiate them. Use them in determining A_0 (see 10.5.1).

10.2.10 Control (or monitor) the temperature of the dosimeters during irradiation. Calculate or measure the mean irradiation temperature of each dosimeter to an accuracy of $\pm 2^\circ\text{C}$, or better.

10.2.11 Use a set of at least three dosimeters for each absorbed dose value.

10.2.12 Irradiate these sets of dosimeters to at least five known dose values covering the range of utilization in order to determine the calibration curve for the dosimetry system.

10.3 *Measurement Instrument Calibration and Performance Verification*—For the calibration of the instruments, and for the verification of instrument performance between calibrations, see ISO/ASTM Practice 51261 and instrument-specific operating manuals.

10.3.1 Check the wavelength scale of the spectrophotometer and establish its accuracy. The emission spectrum from a low-pressure mercury arc lamp can be used for this purpose. Such a lamp may be obtained from the spectrophotometer manufacturer or other scientific laboratory instrument suppliers. Other appropriate wavelength standards are holmium oxide filters or solutions. For more details, see Practices E275, E925, and E958.

NOTE 7—For example, holmium oxide solutions in sealed cuvettes for use in the wavelength region of 240 to 650 nm are available as certified wavelength standards (SRM 2034).⁹

⁹ Available from the National Institute of Standards and Technology (NIST), Gaithersburg, MD 20899.

10.3.2 Check the accuracy of the photometric (absorbance) scale of the spectrophotometer, especially in the ultraviolet region before and after each set of measurements. Certified absorbance standard filters or solutions are available for this purpose.

NOTE 8—Solutions such as SRM 931f and SRM 935 (7) and metal-on-quartz filters such as SRM 2031⁹ are examples of absorbance standards. Note that SRM 935 is a pure chemical that must be diluted by the user.

10.4 Measurement:

10.4.1 Set the spectral bandwidth of the spectrophotometer at no more than 2 nm. Determine the optimum wavelength of the absorbance peak of the solution by making a spectral scan of an irradiated sample. The optimum wavelength is the wavelength that corresponds to the maximum absorbance value and should be between 302 nm and 305 nm. This peak is fairly broad, and the optimum wavelength will vary depending on the quality of the spectrophotometer. Set the wavelength at the peak and leave it there for the subsequent measurements.

10.4.2 Set the balance of the spectrophotometer to zero with only air (no cuvette) in the light path(s).

10.4.3 Fill a clean cuvette (or flow cell) of 5 to 10 mm pathlength with distilled water. Carefully wipe off any liquid on the exterior surfaces of the cuvette. Measure and record the absorbance. See **Note 9**.

NOTE 9—Inadequate rinsing of the cuvette (or flow cell) between dosimeter solutions can lead to errors due to solution carryover (cross-contamination). Techniques for minimizing this effect are discussed in Ref (7). Micropipettes or Hamilton dispensers are recommended for the rinsing procedure. It is not meaningful to attempt to determine the quality of the water from absorbance measurements of water since pure water has an absorbance of approximately 0.0002 at 303 nm. The loss of light due to reflection from the cuvette surfaces will increase the absorbance. ¹⁵ ISO/ASTM 51026:2015

10.4.4 Empty the water from the cuvette (or flow cell) and rinse it at least twice with the solution from an ampoule, or other container. Discard the rinse solution and fill to the appropriate level with more solution from the same container. Carefully wipe off any solution on the exterior surfaces of the cuvette. Place the cuvette in the sample holder of the spectrophotometer and measure the absorbance as soon as the instrument reading has stabilized. If necessary, correct the absorbance for temperature during measurement (see 7.1). The temperature correction should be applied to the measured absorbance after subtraction of the absorbance of the cell containing water (10.4.3). It is important to read the absorbance of each dosimeter at the same elapsed time after putting it in the spectrophotometer light beam. This is necessary because the absorbance increases slowly with time while the dosimeter is in the light beam (probably due to oxidation of the solution by the UV light). Repeat this procedure for all unirradiated and irradiated solutions.

10.4.5 Check the spectrophotometer zero after each measurement using only air in the light path(s). Measure the unirradiated solution before and after the irradiated solutions are read. Periodically during the measurement process, remeasure the absorbance of a distilled water to detect any contamination of the cuvette (or flow cell) and take appropriate corrective actions if required.

10.5 Analysis:

10.5.1 Calculate the mean absorbance of the unirradiated dosimeters, A_0 (see 10.2.9). Calculate the net absorbance, ΔA , for each irradiated dosimeter by subtracting A_0 from its absorbance (A_1), as follows:

$$\Delta A = A_1 - A_0 \quad (5)$$

10.5.2 Correct the measured net absorbance ΔA to the net absorbance expected for an irradiation temperature of 25°C using the formula:

$$\Delta A_{25} = \Delta A / (1 + 0.0012 (T_{irrad} - 25)) \quad (6)$$

10.5.3 Prepare a calibration curve by plotting the corrected ΔA values versus absorbed dose, D . Fit the data by means of a least-squares method with an appropriate analytical form that provides a best fit to the data. The data for these Fricke dosimeters should fit a first (or at the high end of the dose range a second) order polynomial of the form:

$$\Delta A_{25} = b_0 + b_1 D + b_2 D^2 \quad (7)$$

10.5.4 As a guide, the value of b_1 should be approximately 0.00360 Gy⁻¹ for absorbance measurements made in a 10 mm pathlength optical cell.

NOTE 10—Computer software is available commercially for performing least-squares fits of data with polynomials or other analytical forms. Further information on mathematical methods for handling calibration data is given in ISO/ASTM Practice 51261.

10.5.5 The calibration curve should tend towards $\Delta A = 0$ at zero dose. An appreciable ΔA intercept value is indicative of contamination of the dosimetric solution with impurities.

NOTE 11—Impure solutions may exhibit a linear response in terms of ΔA versus dose, but with an enhanced radiation chemical yield (G). A useful method to check the purity of Fricke solution is to compare the dosimetric response (ΔA) of irradiated Fricke solution with and without NaCl (all other aspects of the preparation remaining the same). If the solutions are pure, the difference in response of solutions with and without NaCl should be less than 0.5 %.

10.5.6 Compare the net absorbance values of a given calibration with those expected based on the value of b_1 given in 10.5.4 and the appropriate optical path length. For cobalt-60 radiation, agreement should be within ± 2 % if the dosimetric solutions were properly prepared and all associated analysis equipment was properly calibrated. Agreement of the dosimetric response values from batch to batch over the useful range of the system should be within ± 1 %.

10.5.7 Estimate the reproducibility (precision) of the individual dosimeter results either from the results of replicate measurements or from the statistics of the least-squares fit to the data. The reproducibility, expressed as one standard deviation, should not exceed 0.002 absorbance for an optical pathlength of 10 mm. Suspected data outliers should be tested using statistical procedures such as those found in Practice E178.

11. Application of dosimetry system

11.1 For most applications, use a minimum of two dosimeters for each dose measurement. The number of dosimeters required for the measurement of absorbed dose on or within a material is determined by the reproducibility associated with