

### SLOVENSKI STANDARD SIST EN IEC 61098:2024

01-maj-2024

Instrumenti za zaščito pred sevanjem - Vgrajeni monitorji osebne površinske kontaminacije (IEC 61098:2023)

Radiation protection instrumentation - Installed personnel surface contamination monitors (IEC 61098:2023)

Strahlenschutz-Messgeräte - Fest installierte Personenkontaminationsmonitore (IEC 61098:2023)

Instrumentation pour la radioprotection - Moniteurs fixes pour la surveillance de la contamination de surface du personnel (IEC 61098:2023)

Ta slovenski standard je istoveten z: EN IEC 61098:2024

ICS:

13.280 Varstvo pred sevanjem Radiation protection

17.240 Merjenje sevanja Radiation measurements

SIST EN IEC 61098:2024 en

# iTeh Standards (https://standards.iteh.ai) Document Preview

SIST EN IEC 61098:2024

https://standards.iteh.ai/catalog/standards/sist/51c8dd53-cfad-415f-a103-80c18d3bb30a/sist-en-jec-61098-2024

### EUROPEAN STANDARD NORME EUROPÉENNE FUROPÄISCHE NORM

**EN IEC 61098** 

February 2024

ICS 13.280; 17.240

Supersedes EN 61098:2007

#### **English Version**

# Radiation protection instrumentation - Installed personnel surface contamination monitors (IEC 61098:2023)

Instrumentation pour la radioprotection - Moniteurs fixes pour la surveillance de la contamination de surface du personnel (IEC 61098:2023)

Strahlenschutz-Messgeräte - Fest installierte Personenkontaminationsmonitore (IEC 61098:2023)

This European Standard was approved by CENELEC on 2024-01-22. CENELEC members are bound to comply with the CEN/CENELEC Internal Regulations which stipulate the conditions for giving this European Standard the status of a national standard without any alteration.

Up-to-date lists and bibliographical references concerning such national standards may be obtained on application to the CEN-CENELEC Management Centre or to any CENELEC member.

This European Standard exists in three official versions (English, French, German). A version in any other language made by translation under the responsibility of a CENELEC member into its own language and notified to the CEN-CENELEC Management Centre has the same status as the official versions.

CENELEC members are the national electrotechnical committees of Austria, Belgium, Bulgaria, Croatia, Cyprus, the Czech Republic, Denmark, Estonia, Finland, France, Germany, Greece, Hungary, Iceland, Ireland, Italy, Latvia, Lithuania, Luxembourg, Malta, the Netherlands, Norway, Poland, Portugal, Republic of North Macedonia, Romania, Serbia, Slovakia, Slovenia, Spain, Sweden, Switzerland, Türkiye and the United Kingdom.

#### SIST EN IEC 61098:2024

https://standards.iteh.ai/catalog/standards/sist/51c8dd53-cfad-415f-a103-80c18d3bb30a/sist-en-iec-61098-202



European Committee for Electrotechnical Standardization Comité Européen de Normalisation Electrotechnique Europäisches Komitee für Elektrotechnische Normung

CEN-CENELEC Management Centre: Rue de la Science 23, B-1040 Brussels

### EN IEC 61098:2024 (E)

### **European foreword**

This document (EN IEC 61098:2024) consists of the text of IEC 61098:2023 prepared by IEC/SC 45B "Radiation protection instrumentation" of IEC/TC 45 "Nuclear instrumentation".

The following dates are fixed:

- latest date by which this document has to be implemented at national level by publication of an identical national standard or by endorsement
  - (dop) 2025-01-22
- latest date by which the national standards conflicting with this document have to be withdrawn
- (dow) 2027-01-22

This document supersedes EN 61098:2007 and all of its amendments and corrigenda (if any).

Attention is drawn to the possibility that some of the elements of this document may be the subject of patent rights. CENELEC shall not be held responsible for identifying any or all such patent rights.

Any feedback and questions on this document should be directed to the users' national committee. A complete listing of these bodies can be found on the CENELEC website.

### **Endorsement notice**

The text of the International Standard IEC 61098:2023 was approved by CENELEC as a European Standard without any modification.

In the official version, for Bibliography, the following note has to be added for the standard indicated:

ISO 11929 (series) NOTE Approved as EN ISO 11929 (series) 03-80c18d3bb30a/sist-en-iec-61098-2024

# Annex ZA (normative)

# Normative references to international publications with their corresponding European publications

The following documents are referred to in the text in such a way that some or all of their content constitutes requirements of this document. For dated references, only the edition cited applies. For undated references, the latest edition of the referenced document (including any amendments) applies.

NOTE 1 Where an International Publication has been modified by common modifications, indicated by (mod), the relevant EN/HD applies.

NOTE 2 Up-to-date information on the latest versions of the European Standards listed in this annex is available here: www.cencenelec.eu.

<u>Publication</u>	<u>Year</u>	<u>Title</u>	EN/HD	<u>Year</u>
IEC 60050-395	-	International Electrotechnical Vocabulary - Part 395: Nuclear instrumentation: Physical phenomena, basic concepts, instruments, systems, equipment and detectors	-	-
IEC 61000-4-2	-	Electromagnetic compatibility (EMC) - Part 4- 2: Testing and measurement techniques - Electrostatic discharge immunity test	EN 61000-4-2	-
IEC 61000-4-3	- (	Electromagnetic compatibility (EMC) - Part 4-3: Testing and measurement techniques - Radiated, radio-frequency, electromagnetic field immunity test	EN IEC 61000-4-3	-
IEC 61000-4-5	-	Electromagnetic compatibility (EMC) - Part 4-5: Testing and measurement techniques - Surge immunity test	EN 61000-4-5	-
IEC 61000-4-6	catalog	Electromagnetic compatibility (EMC) - Part 4-6: Testing and measurement techniques - Immunity to conducted disturbances, induced by radio-frequency fields	0c18d3bb30a/sist-e	n-iec-61098-2024
IEC 61000-4-8	-	Electromagnetic compatibility (EMC) - Part 4-8: Testing and measurement techniques - Power frequency magnetic field immunity test	EN 61000-4-8	-
IEC 61000-4-12	-	Electromagnetic Compatibility (EMC) - Part 4- 12: Testing and measurement techniques - Ring wave immunity test	EN 61000-4-12	-
IEC 62706	-	Radiation protection instrumentation - Environmental, electromagnetic and mechanical performance requirements	-	-
ISO 8769	2020	Measurement of radioactivity - Alpha-, beta- and photon emitting radionuclides - Reference measurement standard specifications for the calibration of surface contamination monitor	EN ISO 8769	2022

# iTeh Standards (https://standards.iteh.ai) Document Preview

SIST EN IEC 61098:2024

https://standards.iteh.ai/catalog/standards/sist/51c8dd53-cfad-415f-a103-80c18d3bb30a/sist-en-jec-61098-2024



**IEC 61098** 

Edition 3.0 2023-02

# INTERNATIONAL STANDARD

# NORME INTERNATIONALE



Radiation protection instrumentation – Installed personnel surface contamination monitors

Instrumentation pour la radioprotection – Moniteurs fixes pour la surveillance de la contamination de surface du personnel

https://standards.iteh.ai/catalog/standards/sist/51c8dd53-cfad-415f-a103-80c18d3bb30a/sist-en-iec-61098-202

INTERNATIONAL ELECTROTECHNICAL COMMISSION

COMMISSION ELECTROTECHNIQUE INTERNATIONALE

ICS 13.280: 17.240 ISBN 978-2-8322-6527-7

Warning! Make sure that you obtained this publication from an authorized distributor.

Attention! Veuillez vous assurer que vous avez obtenu cette publication via un distributeur agréé.

### CONTENTS

F	OREWO	RD	6
1	Scop	e	8
2	Norm	native references	8
3	Term	s, definitions, units and symbols	9
	3.1	Terms and definitions	
	3.2	Units	14
	3.3	Symbols (see Table 1)	15
4	Class	sification of monitors	16
	4.1	According to type of radiation to be measured	16
	4.2	According to body surface being monitored	
	4.3	According to background compensation method	
5	Desig	gn characteristics	
	5.1	Positioning of the person being monitored	
	5.2	Size of the person being monitored	
	5.3	Hand monitoring facilities	
	5.4	Foot monitoring facilities	
	5.5	Body monitoring facilities	
	5.6	Frisker	
	5.7	Visual display	
	5.7.1	For the user	18
	5.7.2		18
	5.8	Audible indicators	18
	5.9	Audible indicators	18
	5.10	Ease of decontamination	
	5.11	Detectors used	
	5.12	Seismic consideration	19
lattra qui / 6	Perfo	ormance requirements and test procedures	19
https://si	6.1	General test procedure	19
	6.1.1	Nature of tests	19
	6.1.2	Tests performed under standard test conditions	19
	6.1.3	Tests performed with variation of influence quantities	19
	6.1.4	Type F influence test	20
	6.1.5	Type S influence test	20
	6.2	Functionality test	20
	6.2.1	General	20
	6.2.2	Pre-test	20
	6.2.3	Post-test	21
	6.3	Statistical fluctuations	21
	6.4	Reference sources	21
	6.5	Requirements for use of gas flow detectors	22
7	Radia	ation measurement characteristics	22
	7.1	Variation of response with source position	22
	7.1.1	General	22
	7.1.2	For clothing or the body	22
	7.1.3	For hand monitoring	27
	7.1.4	For foot monitoring	28

7.2       Background.       33         7.2.1       General.       33         7.2.2       Subtraction of pre-determined background       33         7.2.3       Simultaneous subtraction of determined background       33         7.2.5       Gamma monitoring systems       34         7.3       Detection limit (DL)       34         7.3.1       General       34         7.3.2       For clothing or body       36         7.3.3       The effective instrument efficiency at the specific operating point       36         7.3.3       The feffective instrument efficiency at the specific operating point       36         7.3.5       For foot monitoring       37         7.3.5       For for foot monitoring       37         7.4       Variation of response with energy       38         7.4.1       General       38         7.4.2       Beta       38         7.4.3       Alpha       40         7.4.4       General       40         7.5.2       Gamma radiation       41         7.5.1       General       41         7.5.2       Gamma radiation (for lapha contamination monitoring assemblies)       42         7.6.1       Requirements	7.1.5	Contamination measurement of cloth or body by friskers	30
7.2.2       Subtraction of pre-determined background       .33         7.2.3       Simultaneous subtraction of determined background       .33         7.2.5       Gamma monitoring systems       .34         7.3       Detection limit (DL)       .34         7.3.1       General       .34         7.3.2       For clothing or body       .36         7.3.3       The effective instrument efficiency at the specific operating point       .36         7.3.4       For hand monitoring       .37         7.3.5       For foot monitoring       .37         7.3.6       For frisker monitoring       .38         7.4       Variation of response with energy       .38         7.4.1       General       .38         7.4.2       Beta       .38         7.4.3       Alpha       .40         7.5.4       General       .40         7.5.1       General       .41         7.5.2       Camma radiation       .42         7.5.3       Alpha radiation (for beta and gamma contamination monitoring assemblies)       .42         7.5.1       General       .42         7.6.1       Requirements       .42         7.6.2       Method of test       .43	7.2 B	ackground	33
7.2.3       Simultaneous subtraction of determined background       .33         7.2.4       No background subtraction       .33         7.2.5       Gamma monitoring systems       .34         7.3       Detection limit (DL)       .34         7.3.1       General       .34         7.3.2       For clothing or body       .36         7.3.3       The effective instrument efficiency at the specific operating point       .36         7.3.4       For hand monitoring       .37         7.3.5       For for brisker monitoring       .37         7.3.6       For frisker monitoring       .38         7.4       Variation of response with energy       .38         7.4.1       General       .38         7.4.2       Beta       .38         7.4.3       Alpha       .40         7.5.4       General       .40         7.5.5.1       General       .41         7.5.2       Gamma radiation       .42         7.5.3       Alpha radiation (for beta and gamma contamination monitoring assemblies)       .42         7.5.4       Beta or gamma radiation (for alpha contamination monitoring assemblies)       .42         7.6       Linearity of indication       .42	7.2.1	General	33
7.2.4       No background subtraction       .33         7.2.5       Gamma monitoring systems       .34         7.3       Detection limit (DL)       .34         7.3.1       General       .34         7.3.2       For clothing or body       .36         7.3.3       The effective instrument efficiency at the specific operating point       .36         7.3.4       For hand monitoring       .37         7.3.5       For foot monitoring       .37         7.3.6       For frisker monitoring       .38         7.4       Variation of response with energy       .38         7.4.1       General       .38         7.4.2       Beta       .38         7.4.3       Alpha       .40         7.4.4       Gamma       .40         7.5.1       General       .41         7.5.2       Gamma radiation       .42         7.5.3       Alpha radiation (for beta and gamma contamination monitoring assemblies)       .42         7.5.4       Beta or gamma radiation (for alpha contamination monitoring assemblies)       .42         7.5.1       Beta or gamma radiation (for alpha contamination monitoring assemblies)       .42         7.6.       Linearity of indication       .42	7.2.2	Subtraction of pre-determined background	33
7.2.4       No background subtraction       .33         7.2.5       Gamma monitoring systems       .34         7.3       Detection limit (DL)       .34         7.3.1       General       .34         7.3.2       For clothing or body       .36         7.3.3       The effective instrument efficiency at the specific operating point       .36         7.3.4       For hand monitoring       .37         7.3.5       For foot monitoring       .37         7.3.6       For frisker monitoring       .38         7.4       Variation of response with energy       .38         7.4.1       General       .38         7.4.2       Beta       .38         7.4.3       Alpha       .40         7.4.4       Gamma       .40         7.5.1       General       .41         7.5.2       Gamma radiation       .42         7.5.3       Alpha radiation (for beta and gamma contamination monitoring assemblies)       .42         7.5.4       Beta or gamma radiation (for alpha contamination monitoring assemblies)       .42         7.5.1       Beta or gamma radiation (for alpha contamination monitoring assemblies)       .42         7.6.       Linearity of indication       .42	7.2.3	Simultaneous subtraction of determined background	33
7.3       Detection limit (DL)       34         7.3.1       General       34         7.3.2       For clothing or body       36         7.3.3       The effective instrument efficiency at the specific operating point       36         7.3.4       For hand monitoring       37         7.3.5       For fost monitoring       38         7.3.6       For frisker monitoring       38         7.4.1       General       38         7.4.2       Beta       38         7.4.3       Alpha       40         7.4.4       Gamma       40         7.5       Response to other ionising radiations       41         7.5.1       General       41         7.5.2       Gamma radiation       42         7.5.3       Alpha radiation (for beta and gamma contamination monitoring assemblies)       42         7.5.4       Beta or gamma radiation (for alpha contamination monitoring assemblies)       42         7.6       Linearity of indication       42         7.6.1       Requirements       42         7.6.2       Method of test       43         7.7.1       General       43         7.7.2       Requirements       43         8.	7.2.4	•	
7.3       Detection limit (DL)       34         7.3.1       General       34         7.3.2       For clothing or body       36         7.3.3       The effective instrument efficiency at the specific operating point       36         7.3.4       For hand monitoring       37         7.3.5       For fost monitoring       38         7.3.6       For frisker monitoring       38         7.4.1       General       38         7.4.2       Beta       38         7.4.3       Alpha       40         7.4.4       Gamma       40         7.5       Response to other ionising radiations       41         7.5.1       General       41         7.5.2       Gamma radiation       42         7.5.3       Alpha radiation (for beta and gamma contamination monitoring assemblies)       42         7.5.4       Beta or gamma radiation (for alpha contamination monitoring assemblies)       42         7.6       Linearity of indication       42         7.6.1       Requirements       42         7.6.2       Method of test       43         7.7.1       General       43         7.7.2       Requirements       43         8.	7.2.5	Gamma monitoring systems	34
7.3.1 General       34         7.3.2 For clothing or body.       36         7.3.3 The effective instrument efficiency at the specific operating point       36         7.3.4 For hand monitoring.       37         7.3.5 For foot monitoring.       38         7.4 Variation of response with energy.       38         7.4 Variation of response with energy.       38         7.4.1 General       38         7.4.2 Beta.       38         7.4.3 Alpha       40         7.4.4 Gamma.       40         7.5.1 General       41         7.5.2 Gamma radiation       42         7.5.3 Alpha radiation (for beta and gamma contamination monitoring assemblies)       42         7.5.4 Beta or gamma radiation (for alpha contamination monitoring assemblies)       42         7.6.1 Linearity of indication       42         7.6.2 Method of test       43         7.7.1 General       43         7.7.2 Requirements       43         8.0 Verload protection       43         8.1 Requirements       43         8.2 Method of test       43         9 Availability       44         9.1 Varrup time       44         9.2 Power failure       44         10.1 General       44<	7.3 D		
7.3.2       For clothing or body.       36         7.3.3       The effective instrument efficiency at the specific operating point.       36         7.3.4       For hand monitoring.       37         7.3.5       For foot monitoring.       38         7.4       Variation of response with energy.       38         7.4.1       General.       38         7.4.2       Beta.       38         7.4.3       Alpha.       40         7.5       Response to other ionising radiations.       41         7.5.1       General.       41         7.5.2       Gamma radiation.       42         7.5.3       Alpha radiation (for beta and gamma contamination monitoring assemblies).       42         7.5.4       Beta or gamma radiation (for alpha contamination monitoring assemblies).       42         7.6.1       Requirements.       42         7.6.2       Method of test.       43         7.7.1       General.       43         7.7.2       Requirements.       42         7.7.3       Method of test.       43         8       Overload protection.       43         8.1       Requirements.       43         8.2       Method of test.       43			
7.3.3       The effective instrument efficiency at the specific operating point       36         7.3.4       For hand monitoring       37         7.3.5       For foot monitoring       38         7.3.6       For frisker monitoring       38         7.4.1       General       38         7.4.1       General       38         7.4.2       Beta       38         7.4.3       Alpha       40         7.5       Response to other ionising radiations       41         7.5.1       General       41         7.5.2       Gamma radiation (for beta and gamma contamination monitoring assemblies)       42         7.5.4       Beta or gamma radiation (for alpha contamination monitoring assemblies)       42         7.6       Linearity of indication       42         7.6.1       Requirements       42         7.6.2       Method of test       43         7.7       Alarm threshold       43         7.7.1       General       43         7.7.2       Requirements       43         8       Overload protection       43         8.1       Requirements       43         8.2       Method of test       43         9.1	7.3.2		
7.3.4       For hand monitoring       37         7.3.5       For foot monitoring       38         7.4       Variation of response with energy       38         7.4.1       General       38         7.4.2       Beta       38         7.4.3       Alpha       40         7.4.4       Gamma       40         7.5.1       General       41         7.5.2       Gamma radiation       42         7.5.3       Alpha radiation (for beta and gamma contamination monitoring assemblies)       42         7.5.4       Beta or gamma radiation (for alpha contamination monitoring assemblies)       42         7.6.1       Requirements       42         7.6.1       Requirements       42         7.6.2       Method of test       43         7.7.1       General       43         7.7.2       Requirements       43         8       Overload protection       43         8.1       Requirements       43         8.2       Method of test       43         9       Availability       44         9.1       Warm-up time       44         9.2       Power failure       44         10.2	7.3.3	,	
7.3.5       For foot monitoring       37         7.3.6       For frisker monitoring       38         7.4       Variation of response with energy       38         7.4.1       General       38         7.4.2       Beta       38         7.4.3       Alpha       40         7.5.4       Gamma       40         7.5. Response to other ionising radiations       41         7.5.1       General       41         7.5.2       Gamma radiation (for beta and gamma contamination monitoring assemblies)       42         7.5.4       Beta or gamma radiation (for alpha contamination monitoring assemblies)       42         7.6       Linearity of indication       42         7.6.1       Requirements       42         7.6.2       Method of test       43         7.7.1       General       43         7.7.2       Requirements       43         8       Overload protection       43         8.1       Requirements       43         8.2       Method of test       43         9       Availability       44         9.1       Warm-up time       44         9.2       Power failure       44			
7.3.6       For frisker monitoring.       38         7.4       Variation of response with energy.       38         7.4.1       General       38         7.4.2       Beta       38         7.4.3       Alpha       40         7.4.4       Gamma       40         7.5       Response to other ionising radiations       41         7.5.1       General       41         7.5.2       Gamma radiation (for beta and gamma contamination monitoring assemblies)       42         7.5.3       Alpha radiation (for beta and gamma contamination monitoring assemblies)       42         7.5.4       Beta or gamma radiation (for alpha contamination monitoring assemblies)       42         7.6.1       Requirements       42         7.6.2       Method of test       43         7.7       Alarm threshold       43         7.7.1       General       43         7.7.2       Requirements       43         8       Overload protection       43         8.1       Requirements       43         8.2       Method of test       43         8.1       Requirements       44         9.1       Warm-up time       44         9.2		_	
7.4       Variation of response with energy       38         7.4.1       General       38         7.4.2       Beta       38         7.4.3       Alpha       40         7.5       Response to other ionising radiations       41         7.5.1       General       41         7.5.2       Gamma radiation       42         7.5.3       Alpha radiation (for beta and gamma contamination monitoring assemblies)       42         7.5.4       Beta or gamma radiation (for alpha contamination monitoring assemblies)       42         7.6       Linearity of indication       42         7.6.1       Requirements       42         7.6.2       Method of test       43         7.7.1       General       43         7.7.2       Requirements       43         7.7.3       Method of test       43         8       Overload protection       43         8.1       Requirements       43         8.2       Method of test       43         9       Availability       44         9.1       Warm-up time       44         9.2       Power failure       44         10.1       General       44 <tr< td=""><td></td><td></td><td></td></tr<>			
7.4.1 General       38         7.4.2 Beta       38         7.4.3 Alpha       40         7.4.4 Gamma       40         7.5 Response to other ionising radiations       41         7.5.1 General       41         7.5.2 Gamma radiation (for beta and gamma contamination monitoring assemblies)       42         7.5.3 Alpha radiation (for beta and gamma contamination monitoring assemblies)       42         7.5.4 Beta or gamma radiation (for alpha contamination monitoring assemblies)       42         7.6 Linearity of indication       42         7.6.1 Requirements       42         7.6.2 Method of test       43         7.7.1 General       43         7.7.2 Requirements       43         7.7.3 Method of test       43         8 Overload protection       43         8.1 Requirements       43         8.2 Method of test       43         9 Availability       44         9.1 Warm-up time       44         9.2 Power failure       44         10.1 General       44         10.2 Ambient temperature       44         10.1 Requirements       44         10.2 Method of test       45         10.4 Atmospheric pressure       45 <td></td> <td></td> <td></td>			
7.4.2       Beta       38         7.4.3       Alpha       40         7.5.4       Gamma       40         7.5.5       Response to other ionising radiations       41         7.5.1       General       41         7.5.2       Gamma radiation       42         7.5.3       Alpha radiation (for beta and gamma contamination monitoring assemblies)       42         7.5.4       Beta or gamma radiation (for alpha contamination monitoring assemblies)       42         7.6.1       Requirements       42         7.6.1       Requirements       42         7.6.2       Method of test       43         7.7       Alarm threshold       43         7.7.1       General       43         7.7.2       Requirements       43         8       Overload protection       43         8.1       Requirements       43         8.2       Method of test       43         9       Availability       44         9.1       Warm-up time       44         9.2       Power failure       44         10.1       General       44         10.2       Ambient temperature       44         10.2.1		· · · · · · · · · · · · · · · · · · ·	
7.4.3       Alpha       40         7.4.4       Gamma       40         7.5       Response to other ionising radiations       41         7.5.1       General       41         7.5.2       Gamma radiation       42         7.5.3       Alpha radiation (for beta and gamma contamination monitoring assemblies)       42         7.5.4       Beta or gamma radiation (for alpha contamination monitoring assemblies)       42         7.6       Linearity of indication       42         7.6.1       Requirements       42         7.6.2       Method of test       43         7.7       Alarm threshold       43         7.7.1       General       43         7.7.2       Requirements       43         8       Overload protection       43         8.1       Requirements       43         8.2       Method of test       43         9       Availability       44         9.1       Warm-up time       44         9.2       Power failure       44         10.1       General       44         10.2       Ambient temperature       44         10.2.1       Requirements       44			
7.4.4       Gamma       .40         7.5       Response to other ionising radiations       .41         7.5.1       General       .41         7.5.2       Gamma radiation (for beta and gamma contamination monitoring assemblies)       .42         7.5.4       Beta or gamma radiation (for alpha contamination monitoring assemblies)       .42         7.6       Linearity of indication       .42         7.6.1       Requirements       .42         7.6.2       Method of test       .43         7.7       Alarm threshold       .43         7.7.1       General       .43         7.7.2       Requirements       .43         8       Overload protection       .43         8.1       Requirements       .43         8.2       Method of test       .43         9       Availability       .44         9.1       Warm-up time       .44         9.2       Power failure       .44         10.1       General       .44         10.2       Ambient temperature       .44         10.2       Ambient temperature       .44         10.2       Ambient temperature       .44         10.3       Relative humidity			
7.5       Response to other ionising radiations       .41         7.5.1       General       .41         7.5.2       Gamma radiation       .42         7.5.3       Alpha radiation (for beta and gamma contamination monitoring assemblies)       .42         7.5.4       Beta or gamma radiation (for alpha contamination monitoring assemblies)       .42         7.6       Linearity of indication       .42         7.6.1       Requirements       .42         7.6.2       Method of test       .43         7.7       Alarm threshold       .43         7.7.1       General       .43         7.7.2       Requirements       .43         8       Overload protection       .43         8.1       Requirements       .43         8.2       Method of test       .43         9       Availability       .44         9.1       Warm-up time       .44         9.2       Power failure       .44         10.1       General       .44         10.2       Ambient temperature       .44         10.2.1       Requirements       .44         10.2.2       Method of test       .44         10.3.1       Requirements			
7.5.1       General       41         7.5.2       Gamma radiation       42         7.5.3       Alpha radiation (for beta and gamma contamination monitoring assemblies)       42         7.5.4       Beta or gamma radiation (for alpha contamination monitoring assemblies)       42         7.6       Linearity of indication       42         7.6.1       Requirements       42         7.6.2       Method of test       43         7.7.1       General       43         7.7.2       Requirements       43         7.7.3       Method of test       43         8       Overload protection       43         8.1       Requirements       43         8.2       Method of test       43         9       Availability       44         9.1       Warm-up time       44         9.2       Power failure       44         10.1       General       44         10.2       Ambient temperature       44         10.2.1       Requirements       44         10.2.2       Method of test       45         10.3.1       Requirements       45         10.3.2       Method of test       45			
7.5.2       Gamma radiation       42         7.5.3       Alpha radiation (for beta and gamma contamination monitoring assemblies)       42         7.5.4       Beta or gamma radiation (for alpha contamination monitoring assemblies)       42         7.6       Linearity of indication       42         7.6.1       Requirements       42         7.6.2       Method of test       43         7.7       Alarm threshold       43         7.7.1       General       43         7.7.2       Requirements       43         8       Overload protection       43         8.1       Requirements       43         8.2       Method of test       43         9.1       Warm-up time       44         9.1       Warm-up time       44         9.2       Power failure       44         10.1       General       44         10.2       Ambient temperature       44         10.2.1       Requirements       44         10.2.2       Method of test       45         10.3.1       Requirements       45         10.3.2       Method of test       45         10.3.2       Method of test       45 <td></td> <td>·</td> <td></td>		·	
7.5.3       Alpha radiation (for beta and gamma contamination monitoring assemblies)       42         7.5.4       Beta or gamma radiation (for alpha contamination monitoring assemblies)       42         7.6       Linearity of indication       42         7.6.1       Requirements       42         7.6.2       Method of test       43         7.7       Alarm threshold       43         7.7.1       General       43         7.7.2       Requirements       43         8       Overload protection       43         8.1       Requirements       43         8.2       Method of test       43         9       Availability       44         9.1       Warm-up time       44         9.2       Power failure       44         10.1       General       44         10.2       Ambient temperature       44         10.2.1       Requirements       44         10.2.2       Method of test       44         10.3.1       Requirements       45         10.3.2       Method of test       45         10.4       Atmospheric pressure       45			
assemblies)			42
7.5.4       Beta or gamma radiation (for alpha contamination monitoring assemblies)       42         7.6       Linearity of indication       42         7.6.1       Requirements       42         7.6.2       Method of test       43         7.7       Alarm threshold       43         7.7.1       General       43         7.7.2       Requirements       43         8       Overload protection       43         8.1       Requirements       43         8.2       Method of test       43         9       Availability       44         9.1       Warm-up time       44         9.2       Power failure       44         10.1       General       44         10.2       Ambient temperature       44         10.2.1       Requirements       44         10.2.2       Method of test       44         10.3       Relative humidity       45         10.3.1       Requirements       45         10.3.2       Method of test       45         10.4       Atmospheric pressure       45	7.5.3		42
assemblies)	751		42
7.6       Linearity of indication       42         7.6.1       Requirements       42         7.6.2       Method of test       43         7.7       Alarm threshold       43         7.7.1       General       43         7.7.2       Requirements       43         8       Overload protection       43         8.1       Requirements       43         8.2       Method of test       43         9       Availability       44         9.1       Warm-up time       44         9.2       Power failure       44         10       Environmental requirements       44         10.1       General       44         10.2       Ambient temperature       44         10.2.1       Requirements       44         10.2.2       Method of test       44         10.3       Relative humidity       45         10.3.1       Requirements       45         10.4       Atmospheric pressure       45	7.5.4		42
7.6.1       Requirements       42         7.6.2       Method of test       43         7.7       Alarm threshold       43         7.7.1       General       43         7.7.2       Requirements       43         8.0       Overload protection       43         8.1       Requirements       43         8.2       Method of test       43         9       Availability       44         9.1       Warm-up time       44         9.2       Power failure       44         10       Environmental requirements       44         10.1       General       44         10.2       Ambient temperature       44         10.2.1       Requirements       44         10.2.2       Method of test       44         10.3       Relative humidity       45         10.3.1       Requirements       45         10.4       Atmospheric pressure       45	7.6 L	inearity of indication 0.011 ment Provided	42
7.6.2       Method of test       43         7.7       Alarm threshold       43         7.7.1       General       43         7.7.2       Requirements       43         7.7.3       Method of test       43         8.1       Requirements       43         8.2       Method of test       43         9       Availability       44         9.1       Warm-up time       44         9.2       Power failure       44         10.       Environmental requirements       44         10.2       Ambient temperature       44         10.2.1       Requirements       44         10.2.2       Method of test       44         10.3       Relative humidity       45         10.3.1       Requirements       45         10.3.2       Method of test       45         10.4       Atmospheric pressure       45			
7.7       Alarm threshold.       43         7.7.1       General       43         7.7.2       Requirements       43         8.0       Overload protection       43         8.1       Requirements       43         8.2       Method of test       43         9       Availability       44         9.1       Warm-up time       44         9.2       Power failure       44         10       Environmental requirements       44         10.1       General       44         10.2       Ambient temperature       44         10.2.1       Requirements       44         10.2.2       Method of test       44         10.3       Relative humidity       45         10.3.1       Requirements       45         10.3.2       Method of test       45         10.4       Atmospheric pressure       45			
7.7.1 General       43         7.7.2 Requirements       43         7.7.3 Method of test       43         8 Overload protection       43         8.1 Requirements       43         8.2 Method of test       43         9 Availability       44         9.1 Warm-up time       44         9.2 Power failure       44         10 Environmental requirements       44         10.1 General       44         10.2 Ambient temperature       44         10.2.1 Requirements       44         10.2.2 Method of test       44         10.3 Relative humidity       45         10.3.1 Requirements       45         10.3 Wethod of test       45         10.4 Atmospheric pressure       45			
7.7.2       Requirements       43         7.7.3       Method of test       43         8       Overload protection       43         8.1       Requirements       43         8.2       Method of test       43         9       Availability       44         9.1       Warm-up time       44         9.2       Power failure       44         10       Environmental requirements       44         10.1       General       44         10.2       Ambient temperature       44         10.2.1       Requirements       44         10.2.2       Method of test       44         10.3       Relative humidity       45         10.3.1       Requirements       45         10.3.2       Method of test       45         10.4       Atmospheric pressure       45			
7.7.3       Method of test.       43         8       Overload protection       43         8.1       Requirements       43         8.2       Method of test       43         9       Availability       44         9.1       Warm-up time       44         9.2       Power failure       44         10       Environmental requirements       44         10.1       General       44         10.2       Ambient temperature       44         10.2.1       Requirements       44         10.2.2       Method of test       44         10.3       Relative humidity       45         10.3.1       Requirements       45         10.3.2       Method of test       45         10.4       Atmospheric pressure       45			
8 Overload protection       43         8.1 Requirements       43         8.2 Method of test       43         9 Availability       44         9.1 Warm-up time       44         9.2 Power failure       44         10 Environmental requirements       44         10.1 General       44         10.2 Ambient temperature       44         10.2.1 Requirements       44         10.2.2 Method of test       44         10.3 Relative humidity       45         10.3.1 Requirements       45         10.3.2 Method of test       45         10.4 Atmospheric pressure       45			
8.1       Requirements       43         8.2       Method of test       43         9       Availability       44         9.1       Warm-up time       44         9.2       Power failure       44         10       Environmental requirements       44         10.1       General       44         10.2       Ambient temperature       44         10.2.1       Requirements       44         10.2.2       Method of test       44         10.3       Relative humidity       45         10.3.1       Requirements       45         10.3.2       Method of test       45         10.4       Atmospheric pressure       45			
8.2       Method of test       43         9       Availability       44         9.1       Warm-up time       44         9.2       Power failure       44         10       Environmental requirements       44         10.1       General       44         10.2       Ambient temperature       44         10.2.1       Requirements       44         10.2.2       Method of test       44         10.3       Relative humidity       45         10.3.1       Requirements       45         10.3.2       Method of test       45         10.4       Atmospheric pressure       45			
9 Availability       44         9.1 Warm-up time       44         9.2 Power failure       44         10 Environmental requirements       44         10.1 General       44         10.2 Ambient temperature       44         10.2.1 Requirements       44         10.2.2 Method of test       44         10.3 Relative humidity       45         10.3.1 Requirements       45         10.3.2 Method of test       45         10.4 Atmospheric pressure       45		•	
9.1       Warm-up time       44         9.2       Power failure       44         10       Environmental requirements       44         10.1       General       44         10.2       Ambient temperature       44         10.2.1       Requirements       44         10.2.2       Method of test       44         10.3       Relative humidity       45         10.3.1       Requirements       45         10.3.2       Method of test       45         10.4       Atmospheric pressure       45			
9.2 Power failure       44         10 Environmental requirements       44         10.1 General       44         10.2 Ambient temperature       44         10.2.1 Requirements       44         10.2.2 Method of test       44         10.3 Relative humidity       45         10.3.1 Requirements       45         10.3.2 Method of test       45         10.4 Atmospheric pressure       45	9 Availat	oility	44
10 Environmental requirements       44         10.1 General       44         10.2 Ambient temperature       44         10.2.1 Requirements       44         10.2.2 Method of test       44         10.3 Relative humidity       45         10.3.1 Requirements       45         10.3.2 Method of test       45         10.4 Atmospheric pressure       45	9.1 V	Varm-up time	44
10.1 General       44         10.2 Ambient temperature       44         10.2.1 Requirements       44         10.2.2 Method of test       44         10.3 Relative humidity       45         10.3.1 Requirements       45         10.3.2 Method of test       45         10.4 Atmospheric pressure       45	9.2 P	Power failure	44
10.2 Ambient temperature       44         10.2.1 Requirements       44         10.2.2 Method of test       44         10.3 Relative humidity       45         10.3.1 Requirements       45         10.3.2 Method of test       45         10.4 Atmospheric pressure       45	10 Enviror	nmental requirements	44
10.2.1 Requirements       44         10.2.2 Method of test       44         10.3 Relative humidity       45         10.3.1 Requirements       45         10.3.2 Method of test       45         10.4 Atmospheric pressure       45	10.1 G	General	44
10.2.1 Requirements       44         10.2.2 Method of test       44         10.3 Relative humidity       45         10.3.1 Requirements       45         10.3.2 Method of test       45         10.4 Atmospheric pressure       45			
10.2.2 Method of test.       44         10.3 Relative humidity       45         10.3.1 Requirements       45         10.3.2 Method of test.       45         10.4 Atmospheric pressure       45		·	
10.3 Relative humidity       45         10.3.1 Requirements       45         10.3.2 Method of test       45         10.4 Atmospheric pressure       45	-	·	
10.3.1 Requirements       45         10.3.2 Method of test       45         10.4 Atmospheric pressure       45	_		
10.3.2 Method of test			
10.4 Atmospheric pressure		·	
•			
		·	

11.1	General	45
11.2	Vibration test	45
11.2.	1 Requirements	45
11.2.	2 Method of test	46
11.3	Mechanical shock	46
11.3.	1 Requirements	46
11.3.	2 Method of test	46
12 Powe	r and electromagnetic compatibility	46
12.1	Voltage and frequency	46
12.2	Electromagnetic compatibility	
12.2.	1 General	47
12.2.	2 Electrostatic discharge	47
12.2.	Radio-frequency (RF) Immunity	47
12.2.		
12.2.		
12.2.	·	
12.2.	•	
12.2.		
	ge	
	mentation	
14.1	Certificate	
14.1		
	Operation and maintenance manual  Operational instructions	51
14.3 14.4	Type test report	51
	informative) Explanation of the derivation of detection limit formula	
A.1		56
A.2	In a case of taking into account a change in the background value between the background measurement and the contamination measurement	59
A.3	In a case of achieving background compensation simultaneously	
	informative) Phantoms for testing the body effect for gamma contamination	-iec-61
	itors	63
в.1	General	
B.2	Phantoms building blocks	
B.3	Range of phantoms	
	informative) Characterization of the error due to the background attenuation	54
	ly	65
C.1	General	
C.2	Standard background case	
C.2.1		
C.2.2	'	
C.2.3	•	
C.2.4	•	
C.2.4	Increased background case	
C.3 C.3.1		
C.3.2	•	
C.3.3	·	
C.3.4	•	
	informative) Characterization of the response to a carried gamma source	
D.1	General	68

D.2 Test procedure	68
Bibliography	70
Figure 1 – Vertical position of radiation source	24
Figure 2 - Response curve composition by source pos	sition25
Figure 3 – Centre planes of the detection volume	26
Figure 4 – Detector for hand monitoring	28
Figure 5 – Detector for foot monitoring	30
Figure 6 – Frisker (clothes)/Overhead detector	32
Figure B.1 – Size of slices	63
Figure B.2 – Assembled phantoms	64
Figure D.1 – Source positions for the head	68
Figure D.2 – Source positions for the body	69
Figure D.3 – Source positions for the legs	69
Table 1 – Symbols and abbreviate terms	15
Table 2 – Emission frequency range	48
Table 3 – Reference and standard test conditions	52
Table 4 – Tests performed under standard test conditi	ons52
Table 5 – Tests performed with variation of influence of	quantities54
Table 5 – Tests performed with variation of influence of Table 6 – Test and sources	55
Table B.1 – Sizes of the set of phantoms	rds iteh ai) 64

### Document Preview

SIST EN IEC 61098:2024

https://standards.iteh.ai/catalog/standards/sist/51c8dd53-cfad-415f-a103-80c18d3bb30a/sist-en-iec-61098-2024

### INTERNATIONAL ELECTROTECHNICAL COMMISSION

# RADIATION PROTECTION INSTRUMENTATION – INSTALLED PERSONNEL SURFACE CONTAMINATION MONITORS

### **FOREWORD**

- 1) The International Electrotechnical Commission (IEC) is a worldwide organization for standardization comprising all national electrotechnical committees (IEC National Committees). The object of IEC is to promote international co-operation on all questions concerning standardization in the electrical and electronic fields. To this end and in addition to other activities, IEC publishes International Standards, Technical Specifications, Technical Reports, Publicly Available Specifications (PAS) and Guides (hereafter referred to as "IEC Publication(s)"). Their preparation is entrusted to technical committees; any IEC National Committee interested in the subject dealt with may participate in this preparatory work. International, governmental and non-governmental organizations liaising with the IEC also participate in this preparation. IEC collaborates closely with the International Organization for Standardization (ISO) in accordance with conditions determined by agreement between the two organizations.
- 2) The formal decisions or agreements of IEC on technical matters express, as nearly as possible, an international consensus of opinion on the relevant subjects since each technical committee has representation from all interested IEC National Committees.
- 3) IEC Publications have the form of recommendations for international use and are accepted by IEC National Committees in that sense. While all reasonable efforts are made to ensure that the technical content of IEC Publications is accurate, IEC cannot be held responsible for the way in which they are used or for any misinterpretation by any end user.
- 4) In order to promote international uniformity, IEC National Committees undertake to apply IEC Publications transparently to the maximum extent possible in their national and regional publications. Any divergence between any IEC Publication and the corresponding national or regional publication shall be clearly indicated in the latter.
- 5) IEC itself does not provide any attestation of conformity. Independent certification bodies provide conformity assessment services and, in some areas, access to IEC marks of conformity. IEC is not responsible for any services carried out by independent certification bodies.
- 6) All users should ensure that they have the latest edition of this publication.
- 7) No liability shall attach to IEC or its directors, employees, servants or agents including individual experts and members of its technical committees and IEC National Committees for any personal injury, property damage or other damage of any nature whatsoever, whether direct or indirect, or for costs (including legal fees) and expenses arising out of the publication, use of, or reliance upon, this IEC Publication or any other IEC Publications.
- 8) Attention is drawn to the normative references cited in this publication. Use of the referenced publications is 098-2024 indispensable for the correct application of this publication.
  - 9) Attention is drawn to the possibility that some of the elements of this IEC Publication may be the subject of patent rights. IEC shall not be held responsible for identifying any or all such patent rights.

IEC 61098 has been prepared by subcommittee 45B: Radiation protection instrumentation, of IEC technical committee 45: Nuclear instrumentation. It is an International Standard.

This third edition cancels and replaces the second edition published in 2003. This edition constitutes a technical revision.

This edition includes the following significant technical changes with respect to the previous edition:

- a) Title is modified.
- b) As an alternative of small area sources, area sources are added to be used for methods of test with respect to the variation of response with source position, effective instrument efficiency, detection limit (DL), and variation of response with energy.
- c) Detection limit (DL) complies with the ISO 11929 series.
- d) Descriptions of influence quantities of type F and type S are added.
- e) Consistency with IEC 62706 is promoted for environmental requirements, mechanical requirements, electromagnetic compatibility and methods of test.
- f) Descriptions of overhead detectors are added.

- g) Descriptions of friskers are added with respect to the hand and foot monitoring.
- h) Figures are made easier to understand the relation between the detector position and the response, and the positional relation between the detector surface and the source.

The text of this International Standard is based on the following documents:

Draft	Report on voting
45B/1020/FDIS	45B/1026/RVD

Full information on the voting for its approval can be found in the report on voting indicated in the above table.

The language used for the development of this International Standard is English.

This document was drafted in accordance with ISO/IEC Directives, Part 2, and developed in accordance with ISO/IEC Directives, Part 1, ISO/IEC Directives and IEC Supplement, available at www.iec.ch/members\_experts/refdocs. The main document types developed by IEC are described in greater detail at www.iec.ch/standardsdev/publications.

The committee has decided that the contents of this document will remain unchanged until the stability date indicated on the IEC website under webstore.iec.ch in the data related to the specific document. At this date, the document will be

- reconfirmed,
- withdrawn,
- replaced by a revised edition, or https://standards.iteh.ai)
- amended

IMPORTANT - The "colour inside" logo on the cover page of this document indicates that it contains colours which are considered to be useful for the correct understanding of its contents. Users should therefore print this document using a colour printer.

### RADIATION PROTECTION INSTRUMENTATION – INSTALLED PERSONNEL SURFACE CONTAMINATION MONITORS

### 1 Scope

This document applies to contamination monitors that include warning assembles and meters used for the monitoring of radioactive contamination on the surface of personnel whether they be clothed or not. The document is applicable only to that type of equipment where the user stays at the monitor. It is not applicable to the user passes quickly through the monitor. It is also not applicable to any peripheral equipment which can be associated with a particular type of equipment such as small article monitors. Probes (friskers) for measuring clothes or body by the person under monitoring or someone else are included in this document. The probes (friskers) are always connected to the monitor.

This document is applicable to the monitoring of the whole body (including the head), hands and feet, but parts of this document can be used for monitors designed for the monitoring of radioactive contamination on the hands and/or feet only. This document does not include tritium measurement.

This document is applicable to:

- installed personnel monitor (all clauses applicable);
- transportable personnel monitor (all clauses applicable);
- monitor for monitoring the hands (see the following clauses and subclauses: 2, 3, 4, 5, 6, 7.1.3, 7.2, 7.3.4, 7.4.2.2 b), 7.4.3, 7.4.4.1, 7.4.4.2, 7.4.4.3 b), 7.5, 7.6, 7.7, 8, 9, 10, 11, 12, 13 and 14);
- monitor for monitoring the feet (see the following clauses and subclauses: 2, 3, 4, 5, 6, 7.1.4, 7.2, 7.3.5, 7.4.2.2 c), 7.4.3, 7.4.4.1, 7.4.4.2, 7.4.4.3 c), 7.5, 7.6, 7.7, 8, 9, 10, 11, 12, 13 and 14); and
- monitor for monitoring the hands and feet (including probe (frisker) for whole body measurement) (see the following clauses and subclauses: 2, 3, 4, 5, 6, 7.1.3, 7.1.4, 7.1.5, 098-2024 7.2, 7.3.4, 7.3.5, 7.3.6, 7.4.2.2 b), 7.4.2.2 c), 7.4.2.2 d), 7.4.3, 7.4.4.1, 7.4.4.2, 7.4.4.3 b), 7.4.4.3 c), 7.4.4.3 d), 7.5, 7.6, 7.7, 8, 9, 10, 11, 12, 13 and 14).

The object of this document is to define mechanical and operational characteristics, minimum performance characteristics and general test procedures for personnel monitors.

#### 2 Normative references

The following documents are referred to in the text in such a way that some or all of their content constitutes requirements of this document. For dated references, only the edition cited applies. For undated references, the latest edition of the referenced document (including any amendments) applies.

IEC 60050-395, International Electrotechnical Vocabulary (IEV) – Part 395: Nuclear instrumentation – Physical phenomena, basic concepts, instruments, systems, equipment and detectors, available at www.electropedia.org

IEC 61000-4-2, Electromagnetic compatibility (EMC) – Part 4-2: Testing and measurement techniques – Electronic discharge immunity test.

IEC 61000-4-3, Electromagnetic compatibility (EMC) - Part 4-3: Testing and measurement techniques - Radiated, radio-frequency, electromagnetic field immunity test