

ISO/~~DIS~~**FDIS** 21771-2:2025(en)

ISO/TC 60

Secretariat: ANSI

Date: 2025-02-1805-06

Cylindrical involute gears and gear pairs — ~~—~~ **==**

Part 2:
Calculation and measurement of tooth thickness and backlash

~~Engrenages~~**Roues et engrenages** cylindriques en développante de cercle — ~~—~~ **==**

Partie 2: Calcul et ~~Mesure~~**mesurage** de l'épaisseur l'épaisseur de dent et du jeu de battement

FDIS stage

© ISO ~~2024~~2025

All rights reserved. Unless otherwise specified, or required in the context of its implementation, no part of this publication may be reproduced or utilized otherwise in any form or by any means, electronic or mechanical, including photocopying, or posting on the internet or an intranet, without prior written permission. Permission can be requested from either ISO at the address below or ISO's member body in the country of the requester.

ISO copyright office
CP 401 • Ch. de Blandonnet 8
CH-1214 Vernier, Geneva
Phone: + 41 22 749 01 11
~~Email~~E-mail: copyright@iso.org
Website: www.iso.org

Published in Switzerland

iTeh Standards (<https://standards.iteh.ai>) Document Preview

ISO/FDIS 21771-2

<https://standards.iteh.ai/catalog/standards/iso/861da4f1-daa6-49da-9846-3274d5f3869e/iso-fdis-21771-2>

Contents

Foreword.....	Error! Bookmark not defined.
Introduction.....	Error! Bookmark not defined.
1 Scope	Error! Bookmark not defined.
2 Normative references	Error! Bookmark not defined.
3 Terms, definition and symbols.....	Error! Bookmark not defined.
3.1 Terms and definitions.....	Error! Bookmark not defined.
3.2 Symbols and definitions.....	Error! Bookmark not defined.
3.3 Units and conventions	Error! Bookmark not defined.
4 Application.....	Error! Bookmark not defined.
4.1 General	Error! Bookmark not defined.
4.2 Datum surfaces and the datum axis.....	Error! Bookmark not defined.
4.3 Gear tooth thickness specification systems.....	Error! Bookmark not defined.
4.4 Gear tooth thickness measurement methods	Error! Bookmark not defined.
4.5 Reporting of gear tooth thickness	Error! Bookmark not defined.
4.6 Measurement diameter versus contact diameter	Error! Bookmark not defined.
4.7 Gear geometry calculations	Error! Bookmark not defined.
5 Measurement by pitch (index)	Error! Bookmark not defined.
5.1 Principle of measurement.....	Error! Bookmark not defined.
5.2 Underlying assumptions and limitations	Error! Bookmark not defined.
5.3 Advantages and disadvantages of measurement by pitch.....	Error! Bookmark not defined.
5.4 Selection of measurement diameter	Error! Bookmark not defined.
6 Measurement with a master gear on a double flank tester	Error! Bookmark not defined.
6.1 Principle of measurement.....	Error! Bookmark not defined.
6.2 Underlying assumptions and limitations	Error! Bookmark not defined.
6.3 Advantages and disadvantages of double flank radial composite measurement.....	Error! Bookmark not defined.
6.4 Master gear design considerations	Error! Bookmark not defined.
6.5 Skew angle for double flank testing.....	Error! Bookmark not defined.
6.6 Calculation of tight mesh centre distance limits for crossed axis gears.....	Error! Bookmark not defined.
6.7 Tight mesh centre distance limits for parallel axis gears:.....	Error! Bookmark not defined.
6.8 Product gear test radius limits from tight mesh centre distance limits.....	Error! Bookmark not defined.
6.9 Axis related normal tooth thickness from double flank test results.....	Error! Bookmark not defined.
7 Measurement with a master gear on a single flank tester	Error! Bookmark not defined.
7.1 Principle of measurement.....	Error! Bookmark not defined.
7.2 Underlying assumptions and limitations	Error! Bookmark not defined.
7.3 Advantages and disadvantages of single flank composite measurement.....	Error! Bookmark not defined.
7.4 Master gear design considerations	Error! Bookmark not defined.
7.5 Axis related tooth thickness from single flank test results.....	Error! Bookmark not defined.
8 Span measurement	Error! Bookmark not defined.
8.1 Principle of measurement.....	Error! Bookmark not defined.
8.2 Underlying assumptions and limitations	Error! Bookmark not defined.
8.3 Advantages and disadvantages of span measurement.....	Error! Bookmark not defined.
8.4 Span measurement limits.....	Error! Bookmark not defined.
8.5 Number of teeth spanned	Error! Bookmark not defined.

8.6	Angle of rock.....	Error! Bookmark not defined.
8.7	Tooth thickness from span measurement.....	Error! Bookmark not defined.
8.8	Measurement diameter.....	Error! Bookmark not defined.
9	Measurement using three ball span device	Error! Bookmark not defined.
9.1	Principle of measurement.....	Error! Bookmark not defined.
9.2	Underlying assumptions and limitations	Error! Bookmark not defined.
9.3	Advantages and disadvantages of three ball span device measurement.....	Error! Bookmark not defined.
9.4	Number of teeth spanned	Error! Bookmark not defined.
9.5	Selection of the ball diameter	Error! Bookmark not defined.
9.6	Calculations with specified ball diameter	Error! Bookmark not defined.
9.7	Normal tooth thickness from a measurement using a three ball span device.....	Error! Bookmark not defined.
10	Measurement over or between balls or pins.....	Error! Bookmark not defined.
10.1	Principle of measurement	Error! Bookmark not defined.
10.2	Underlying assumptions and limitations.....	Error! Bookmark not defined.
10.3	Advantages and disadvantages of over balls or pins measurement	Error! Bookmark not defined.
10.4	Selection of the ball or pin diameter.....	Error! Bookmark not defined.
10.5	Calculations with specified ball or pin diameter (symmetric pressure angles)	Error! Bookmark not defined.
10.6	Gears with asymmetric pressure angles	Error! Bookmark not defined.
10.7	Measurement over one ball or pin	Error! Bookmark not defined.
10.8	Measurement over two balls or pins	Error! Bookmark not defined.
10.9	Two pin transverse measurement on helical gear, odd number of teeth.....	Error! Bookmark not defined.
10.10	Free pin measurement over two pins, helical gear, odd number of teeth.....	Error! Bookmark not defined.
10.11	Transverse plane measurement method over three balls or pins.....	Error! Bookmark not defined.
10.12	Axial plane three pin method	Error! Bookmark not defined.
11	Measurement with measuring blocks.....	Error! Bookmark not defined.
11.1	Principle of measurement	Error! Bookmark not defined.
11.2	Underlying assumptions and limitations.....	Error! Bookmark not defined.
11.3	Advantages and disadvantages of using blocks	Error! Bookmark not defined.
11.4	Measuring block sets	Error! Bookmark not defined.
11.5	Measurement limits for blocks	Error! Bookmark not defined.
11.6	Tooth thickness from block measurements.....	Error! Bookmark not defined.
12	Chordal measurement.....	Error! Bookmark not defined.
12.1	General.....	Error! Bookmark not defined.
12.2	Measurements with a gear tooth calliper (in the normal plane)	Error! Bookmark not defined.
12.3	Chordal measurement with an optical device (in the transverse plane).....	Error! Bookmark not defined.
12.4	Chordal measurement with a coordinate measurement machine	Error! Bookmark not defined.
13	Backlash in parallel axis and crossed axis gear pairs	Error! Bookmark not defined.
13.1	General.....	Error! Bookmark not defined.
13.2	Factors that influence backlash.....	Error! Bookmark not defined.

13.3	Backlash for parallel axis gears in the axis related system	Error! Bookmark not defined.
13.4	Backlash for parallel axis gears in the non-datum related system	Error! Bookmark not defined.
13.5	Backlash in crossed axis gears	Error! Bookmark not defined.
13.6	Other potential influences on backlash	Error! Bookmark not defined.
13.7	Ways to express backlash	Error! Bookmark not defined.
13.8	Variations in backlash	Error! Bookmark not defined.
	(informative) Tooth thickness measurement using analytical machines	Error! Bookmark not defined.
	(informative) Establishing tooth thickness specifications in the non-datum related system	Error! Bookmark not defined.
	(informative) Establishing tooth thickness specifications in the axis related system	Error! Bookmark not defined.
	(informative) Calculation method for the inverse involute function	Error! Bookmark not defined.
	(informative) Example calculations	Error! Bookmark not defined.
	Bibliography	Error! Bookmark not defined.

Foreword	iii
1 Scope	1
2 Normative references	1
3 Terms, symbols, and definitions	1
3.1 Terms and definitions	1
3.1.1 Backlash	8
3.1.2 Ball	8
3.1.3 Addendum, h_a	9
3.1.4 Chordal addendum, h_{cy}	9
3.1.5 Chordal radius, r_{cy}	9
3.1.6 Datum axis	9
3.1.7 Tip involute limit diameter, d_{tli}	10
3.1.8 Root involute limit diameter, d_{rli}	10
3.1.9 Working pitch diameter	10
3.1.10 Rack tool	10
3.1.11 Reference plane	10
3.1.12 Manufacturing profile shift coefficient, minimum, x_{E-} and maximum, x_{E+}	10
3.1.13 Pin	10
3.1.14 Rack reference line	10
3.1.15 Master gear test radius	11
3.1.16 Product gear test radius	11
3.1.17 Tight mesh	11
3.1.18 Normal tooth thickness, s_{at} , s_{yn} , s_{bn}	11
3.1.19 Normal rack tooth thickness, s_{ar} , s_{yn}	11
3.1.20 Transverse tooth thickness, s_t , s_{yt} , s_{bt}	11
3.1.21 Transverse rack tooth thickness, s_r , s_{yt}	11
3.1.22 Chordal tooth thickness, s_{cy}	12
3.1.23 Axis related tooth thickness	12
3.1.24 Non-datum related tooth thickness	12
3.1.25 Total radial composite deviation, F_{dt}	12
3.1.26 Total radial composite tolerance, F_{dtT}	12

3.1.27 Calculation diameter, d	12
3.2 Symbols and definitions	12
3.3 Units and conventions	12
3.3.1 Units	12
3.3.2 Conventions	12
4 Application	12
4.1 General	12
4.2 Datum surfaces and the datum axis	13
4.3 Gear tooth thickness specification systems	13
4.3.1 Types of tooth thickness specification systems	13
4.3.2 Non-datum related tooth thickness	13
4.3.3 Axis related tooth thickness	13
4.3.4 Relationship between the measurement methods and specification systems	14
4.3.5 Mean tooth thickness	14
4.4 Gear tooth thickness measurement methods	14
4.5 Reporting of gear tooth thickness	15
4.6 Measurement diameter versus contact diameter	16
4.7 Gear geometry calculations	16
4.7.1 Use of radians or degrees	16
4.7.2 Reference diameter	16
4.7.3 Transverse pressure angle	17
4.7.4 Lead angle	17
4.7.5 Normal tooth thickness from manufacturing profile shift coefficient	17
4.7.6 Base diameter	17
4.7.7 Base helix angle	17
4.7.8 Normal pitch at the reference diameter	17
4.7.9 Normal pitch at calculation diameter d	17
4.7.10 Normal base pitch	18
4.7.11 Lead of a helical gear	18
4.7.12 Axial pitch	18
4.7.13 The involute function	18
4.7.14 Helix angle at calculation diameter d	18
4.7.15 Transverse pressure angle at calculation diameter d	18
4.7.16 Tooth thickness calculations	18
4.7.17 Space width calculations	20
5 Measurement by pitch or index	22
5.1 Principle of measurement	22
5.2 Underlying assumptions and limitations	22
5.3 Advantages and disadvantages of measurement by pitch	22
5.4 Selection of measurement diameter	22
6 Measurement with a master gear on a double flank tester	23
6.1 Principle of measurement	23
6.1.1 Main principles	23
6.1.2 Tight mesh centre distance	27
6.1.3 Product gear test radius	27
6.1.4 Total radial composite deviation	27
6.2 Underlying assumptions and limitations	27
6.3 Advantages and disadvantages of double flank radial composite measurement	28
6.4 Master gear design considerations	29
6.4.1 Criteria for proper meshing	29

6.4.2	Additional recommendations	29
6.5	Skew angle for double flank testing	30
6.5.1	General	30
6.5.2	Skew angle for parallel axis gear pairs	30
6.5.3	Skew angle for crossed axis gear pairs	33
6.6	Calculation of tight mesh centre distance limits for crossed axis gears	34
6.6.1	Preliminary calculations	34
6.6.2	Tight mesh centre distance limits for crossed axis gears	35
6.7	Tight mesh centre distance limits for parallel axis gears	35
6.7.1	General	35
6.7.2	For the non-datum related system	36
6.7.3	For the axis related system	36
6.7.4	Differences between axis related and non-datum related systems	36
6.8	Product gear test radius limits from tight mesh centre distance limits	35
6.8.1	General	35
6.8.2	Master gear test radius	35
6.8.3	Product gear test radius limits	36
6.9	Axis related normal tooth thickness from double flank test results	35
6.9.1	General	35
6.9.2	Crossed axis external gear axis related tooth thickness from test results	35
6.9.3	Parallel axis gear axis related tooth thickness	36
7	Measurement with a master gear on a single flank tester	37
7.1	Principle of measurement	37
7.2	Underlying assumptions and limitations	37
7.3	Advantages and disadvantages of single flank composite measurement	38
7.4	Master gear design considerations	38
7.5	Axis related tooth thickness from single flank test results	38
8	Span measurement	38
8.1	Principle of measurement	38
8.2	Underlying assumptions and limitations	40
8.3	Advantages and disadvantages of span measurement	40
8.4	Span measurement limits	41
8.5	Number of teeth spanned	41
8.5.1	Limitations	41
8.5.2	Maximum and minimum number of teeth spanned	41
8.6	Angle of rock	43
8.7	Tooth thickness from span measurement	44
8.8	Measurement diameter	45
9	Measurement using three ball span device	45
9.1	Principle of measurement	45
9.2	Underlying assumptions and limitations	45
9.3	Advantages and disadvantages of three ball span device measurement	46
9.4	Number of teeth spanned	46
9.5	Selection of the ball diameter	46
9.6	Calculations with specified ball diameter	47
9.7	Normal tooth thickness from a measurement using a three ball span device	48
10	Measurement over or between balls or pins	48
10.1	Principle of measurement	48
10.2	Underlying assumptions and limitations	50
10.3	Advantages and disadvantages of over balls or pins measurement	51
10.4	Selection of the ball or pin diameter	51
10.4.1	General	51