



Designation: **D6850—13** **D6850 – 18**

Standard Guide for QC of Screening Methods in Water¹

This standard is issued under the fixed designation D6850; the number immediately following the designation indicates the year of original adoption or, in the case of revision, the year of last revision. A number in parentheses indicates the year of last reapproval. A superscript epsilon (ϵ) indicates an editorial change since the last revision or reapproval.

1. Scope*

1.1 This guide covers general considerations for the ~~Quality Control~~ quality control (QC) practices for use with screening methods for organic and inorganic constituents in water. Methods are provided by various standard setting bodies, governmental agencies, as well as many domestic and international manufacturers.

1.2 This guide provides general QC procedures that are applicable to a broad range of screening methodologies. These procedures help to ensure the quality of data that is generated. Additional, method-specific or project specific requirements may be necessary. This guide also includes general considerations regarding proper utilization of screening methods.

1.3 The values stated in SI units are to be regarded as standard. No other units of measurement are included in this standard.

1.4 *This standard does not purport to address all of the safety concerns, if any, associated with its use. It is the responsibility of the user of this standard to establish appropriate ~~safety~~ safety, health, and health environmental practices and determine the applicability of regulatory limitations prior to use.*

1.5 *This international standard was developed in accordance with internationally recognized principles on standardization established in the Decision on Principles for the Development of International Standards, Guides and Recommendations issued by the World Trade Organization Technical Barriers to Trade (TBT) Committee.*

2. Referenced Documents

2.1 *ASTM Standards:*²

[D1129 Terminology Relating to Water](#)

[D1193 Specification for Reagent Water](#)

[D4840 Guide for Sample Chain-of-Custody Procedures](#)

[D5172 Guide for Documenting the Standard Operating Procedures Used for the Analysis of Water](#)

[D5847 Practice for Writing Quality Control Specifications for Standard Test Methods for Water Analysis](#)

[D5905 Practice for the Preparation of Substitute Wastewater](#)

3. Terminology

3.1 ~~Definitions—Definitions:~~ For definitions of terms used in this guide, refer to Terminology [D1129](#) and Practice [D5847](#).

3.1.1 For definitions of terms used in this standard, refer to Terminology [D1129](#) and Practice [D5847](#).

3.2 *Definitions of Terms Specific to This Standard:*

3.2.1 *action level, n*—a concentration of the analyte of concern at which some further action is required or suggested.

3.2.2 *batch, n*—a set (group) of samples analyzed along with QC samples; the quality of the sample-set's results is indicated by the results from the QC samples.

3.2.2.1 *Discussion—*

The number of samples in the batch is defined by the task group responsible for the method. See Practice [D5847](#) for definition and discussion of batch and batch size.

3.2.3 *false negative, n*—a negative response for a sample that contains the target analyte(s) at or above the stated action level.

¹ This guide is under the jurisdiction of ASTM Committee [D19](#) on Water and is the direct responsibility of Subcommittee [D19.05](#) on Inorganic Constituents in Water. Current edition approved ~~Aug. 1, 2013~~ May 1, 2018. Published ~~August 2013~~ May 2018. Originally approved in 2003. Last previous edition approved in ~~2008~~ 2013 as ~~D6850 – 03 (2008)~~ D6850 – 13. DOI: ~~10.1520/D6850-13~~ 10.1520/D6850-18.

² For referenced ASTM standards, visit the ASTM website, www.astm.org, or contact ASTM Customer Service at service@astm.org. For *Annual Book of ASTM Standards* volume information, refer to the standard's Document Summary page on the ASTM website.

*A Summary of Changes section appears at the end of this standard

3.2.4 *false positive, n*—a positive response for a sample that contains the target analyte(s) below the stated action level.

3.2.5 *qualitative method, n*—a validated method that detects presence or absence of an analyte at a specified screening limit.

3.2.6 *screening limit, n*—the concentration of analyte that can be determined with a given certainty.

3.2.6.1 *Discussion*—

The task group responsible for the method establishes the value of the screening limit.

3.2.7 *screening method, n*—a method that is used to separate or categorize samples.

3.2.7.1 *Discussion*—

An example would be a method that provides results that would be used to separate samples into: (1) those that contain an analyte and (2) those that do not contain an analyte above or below a specified action level.

3.2.8 *semi-quantitative method Type 1, n*—a method whose results are given in specified, discrete concentration ranges.

3.2.8.1 *Discussion*—

Two types of examples of this method would include semi-quantitative immunoassays or test strips. The cutoff concentration of the ranges has been predefined.

3.2.9 *semi-quantitative method Type 2, n*—a method whose results are reported as a single number along with the stated uncertainty.

3.2.9.1 *Discussion*—

The uncertainty will be reported as (standard deviation of x at a concentration of y). The values of x and y can be established from the Initial Demonstration of Performance study.

4. Significance and Use

4.1 Screening methods are often used to determine the presence or absence of a specific analyte, groups of analytes, classes of compounds or other indicators of chemical compounds in order to determine if further analysis or action is necessary. The determination whether to proceed with further action is useful in reducing the number of negative results for which the screening method serves as a surrogate.

4.2 The use of screening methods, whether to generate qualitative or semi-quantitative results, is increasingly becoming a useful tool for regulatory monitoring, process control, and site characterization. The appropriate use of a screening method, or any other method for that matter, is dependent upon the Data Quality Objectives (DQOs) that are defined by the user of the data.

4.3 Persons responsible for assessing the quality of the data generated by the use of screening methods should have detailed Quality Control (QC) guidelines by which to assess data quality.

5. Consideration for Selection of an Appropriate Screening Method

5.1 The screening method chosen must be appropriate for the Action Level of the project.

5.2 The chosen screening method must allow for the necessary number of samples to be run in a timely manner, not to exceed the storage limits of the sample as defined by the method.

5.3 Many screening methods will give a positive result for several compounds or class of compounds. It must be determined if a more specific method is necessary to eliminate these positive results.

5.4 It is essential that an appropriate documentation system be established. A Standard Operating Procedure (SOP) for the screening method containing the appropriate QC elements from this guide must be available. See Guides **D4840** and **D5172** for information on establishing a SOP for a method.

5.5 Issues relating to timeliness of sample collection and analysis should be considered when selecting an appropriate screening method. For example, for analyses that must be run immediately following sample collection, a method capable of being run in the field may be necessary.

5.6 When selecting a field screening method, considerations must be given to the expected field conditions. Factors such as humidity, power requirements, temperature, effects of ambient lighting, etc., must be addressed.