



Designation: C1508 – 18

Standard Test Method for Determination of Bromine and Chlorine in UF₆ and Uranyl Nitrate by X-Ray Fluorescence (XRF) Spectroscopy¹

This standard is issued under the fixed designation C1508; the number immediately following the designation indicates the year of original adoption or, in the case of revision, the year of last revision. A number in parentheses indicates the year of last reapproval. A superscript epsilon (ϵ) indicates an editorial change since the last revision or reapproval.

1. Scope

1.1 This method covers the determination of bromine (Br) and chlorine (Cl) in uranium hexafluoride (UF₆) and uranyl nitrate solution. The method as written covers the determination of bromine in UF₆ over the concentration range of 0.2 to 8 $\mu\text{g/g}$, uranium basis. The chlorine in UF₆ can be determined over the range of 4 to 160 $\mu\text{g/g}$, uranium basis. Higher concentrations may be covered by appropriate dilutions. The detection limit for Br is 0.2 $\mu\text{g/g}$ uranium basis and for Cl is 4 $\mu\text{g/g}$ uranium basis.

1.2 The values stated in SI units are to be regarded as the standard.

1.3 *This standard may involve hazardous materials, operations and equipment. This standard does not purport to address all of the safety concerns, if any, associated with its use. It is the responsibility of the user of this standard to establish appropriate safety, health, and environmental practices and determine the applicability of regulatory limitations prior to use.*

1.4 *This international standard was developed in accordance with internationally recognized principles on standardization established in the Decision on Principles for the Development of International Standards, Guides and Recommendations issued by the World Trade Organization Technical Barriers to Trade (TBT) Committee.*

2. Referenced Documents

2.1 *ASTM Standards:*²

[C761 Test Methods for Chemical, Mass Spectrometric, Spectrochemical, Nuclear, and Radiochemical Analysis of Uranium Hexafluoride](#)

[C787 Specification for Uranium Hexafluoride for Enrichment](#)

¹ This test method is under the jurisdiction of ASTM Committee C26 on Nuclear Fuel Cycle and is the direct responsibility of Subcommittee C26.05 on Methods of Test.

Current edition approved June 1, 2018. Published June 2018. Originally approved in 2001. Last previous edition approved in 2011 as C1508 – 01 (2011). DOI: 10.1520/C1508-18.

² For referenced ASTM standards, visit the ASTM website, www.astm.org, or contact ASTM Customer Service at service@astm.org. For *Annual Book of ASTM Standards* volume information, refer to the standard's Document Summary page on the ASTM website.

[C788 Specification for Nuclear-Grade Uranyl Nitrate Solution or Crystals](#)

[C859 Terminology Relating to Nuclear Materials](#)

[D1193 Specification for Reagent Water](#)

3. Terminology

3.1 *Definitions:*

3.1.1 For definitions of terms relating to the nuclear fuel cycle, refer to Terminology [C859](#).

4. Summary of Test Method

4.1 A sample of hydrolyzed UF₆ (uranyl fluoride) or uranyl nitrate solution is treated with sodium nitrite to reduce oxidized forms of bromine and chlorine (bromates and chlorates) to their respective halide ions. Addition of silver nitrate precipitates the silver halides. Spike recoveries can be improved by the addition of potassium iodide causing coprecipitation of the halides. The halides are collected on filter paper and are analyzed by X-ray fluorescence using two different crystal/detector systems.

5. Significance and Use

5.1 The method is designed to show whether or not the tested materials meet the specifications as given in Specifications [C787](#) and [C788](#).

6. Interferences

6.1 Plastic equipment must be used throughout the method for uranyl fluoride as the hydrofluoric acid in the uranyl fluoride leaches chloride from glassware causing a high bias.

6.2 Low recoveries may occur as the precipitate can be difficult to transfer quantitatively to the filter paper. A surfactant can be added (optional step) to minimize the adhesion of the precipitate to the walls of the beakers and the funnel.

7. Apparatus

7.1 *X-Ray Spectrometer*, appropriate for the intended use.

7.2 *Plastic Vacuum Filtration Apparatus*, for 47 mm diameter filter paper.

7.3 *Filter Paper*, 0.45 micron, 47 mm diameter.³

7.4 *Beakers*, polypropylene, 250 mL.

7.5 *Stirring Rods*, plastic or Teflon.

7.6 *X-ray Sample Support, Rings*. Inner diameter approximately 40 mm.

8. Reagents

8.1 *Purity of Reagents*—Reagent grade chemicals shall be used in all tests. Unless otherwise indicated, it is intended that all reagents conform to the specifications of the Committee on Analytical Reagents of the American Chemical Society, where such specifications are available.⁴ Other grades may be used, provided it is first ascertained that the reagent is of sufficiently high purity to permit its use without lessening the accuracy of the determination.

8.2 *Purity of Water*—Unless otherwise indicated, references to water shall be understood to mean reagent water conforming to Specification D1193, Type I.

8.3 *Ammonium Hydroxide*, NH₄OH, concentrated, specific gravity 0.90.

8.4 *Ammonium Hydroxide Solution*, 1 + 3 (3.7 M). Dilute 1 part NH₄OH with 3 parts water.

8.5 *Surfactant*, bromine and chlorine free.⁵ (Optional).

8.6 *Surfactant Solution*, 1 + 999. Add 1 mL of surfactant to approximately 1 litre of water. (Optional).

8.7 *Nitric Acid*, HNO₃, concentrated, specific gravity 1.42.

8.8 *Nitric Acid Solution*, 1 + 999 (0.016 M). Add 1 mL of concentrated HNO₃ to approximately 200 mL of water. Add 1 mL of the surfactant (8.6). (Optional). Dilute to 1 litre.

8.9 *Sodium Nitrite*, NaNO₂.

8.10 *Sodium Nitrite Solution*, 2 g/L. Dissolve 1 g of sodium nitrite in water and dilute to 500 mL. Prepare fresh immediately before use.

8.11 *Silver Nitrate*, AgNO₃.

8.12 *Silver Nitrate Solution*, 2 g/L. Dissolve 2 g of silver nitrate in water and dilute to 1 litre. Keep away from light in an opaque bottle. The solution should be made fresh weekly. Silver is an RCRA listed hazardous waste. Make up only as much of this solution as required to minimize excess waste.

8.13 *Potassium Bromide*, KBr.

8.14 *Bromide Solution*, 500 mg Br/L. Dissolve 0.1861 g of KBr (dried at 110°C for 1 hour) in water and dilute to 250 mL in a volumetric flask.

8.15 *Sodium Chloride*, NaCl.

8.16 *Sodium Chloride Solution*, 1000 mg Cl/L. Dissolve 1.648 g NaCl (dried at 110° C for 1 hour) in water and dilute to 1 litre in a volumetric flask.

8.17 *Spike Solution*, 5 mg Br/L, 100 mg Cl/L. Transfer 10 mL of 500 mg Br/L solution into a 1 litre volumetric flask by pipette. Transfer 100 mL of 1000 mg Cl/L into the flask by pipette. Dilute to volume.

8.18 *Potassium Iodide*, KI. (Optional).

8.19 *Potassium Iodide Solution*, (Optional), 1g I/L. Dissolve 0.131 g potassium iodide in water and dilute to 100 mL. The solution should be prepared weekly.

9. Standard Preparation

9.1 Pipette the following aliquots of spike solution (from 8.17) into polypropylene beakers. 0 mL, 1 mL, 2 mL, 5 mL, 10 mL. The aliquots represent 0µg Br, 5µg Br, 10µg Br, 25µg Br, 50µg Br and 0µg Cl, 100µg Cl, 200µg Cl, 500µg Cl, 1000µg Cl.

9.2 Add 70 mL water to each beaker.

9.3 Follow steps 10.3 – 10.8 at the same time as the samples.

10. Procedure

10.1 Transfer a known aliquot of uranyl fluoride solution (prepared following Test Methods C761) or uranyl nitrate that contains a known amount of uranium, approximately 5 g, with a plastic graduated cylinder into a polypropylene beaker containing 70 mL water.

NOTE 1—Recommend cleaning all laboratory equipment with ammonium hydroxide solution (8.4) prior to use.

10.2 Follow laboratory QA practices and run the necessary duplicates, spikes and controls with the samples. Use the solution prepared in 8.17 for the spikes.

NOTE 2—2 mL and 4 mL spike aliquots were found to be reasonable volumes.

10.3 Add 0.5 mL of potassium iodide solution to each sample and standard. (Optional step).

10.4 Add 4 mL of surfactant solution 8.6. (Optional step).

10.5 Add 10 mL of sodium nitrite solution to each sample and standard. Stir each solution with a dedicated plastic stirring rod and allow to stand for a minimum of 2 minutes.

TABLE 1 Suggested X-Ray Settings

	Bromine	Chlorine
Line	K _a	K _a
Crystal	LiF 200 (Lithium fluoride)	PE (Tetrakis(hydroxymethyl)-methane)
Detector	Scintillation	Flow
Order	1	1
X-ray tube	Rhodium	Rhodium
Tube voltage (kV)	45	45
Tube Amperage (mA)	45	75
Counting Time (s)	40	40

³ The filter must be Cl and Br free. Millipore membrane filter type HABP (www.millipore.com) has been successfully used. An alternate is 15A from S.C.B, BP6, RN86, 07130 Soyons France. Any other equivalent is acceptable.

⁴ *Reagent Chemicals, American Chemical Society Specifications*, American Chemical Society, Washington, DC. For suggestions on the testing of reagents not listed by the American Chemical Society, see *Analar Standards for Laboratory Chemicals*, BDH Ltd., Poole, Dorset, U.K., and the *United States Pharmacopeia and National Formulary*, U.S. Pharmacopeial Convention, Inc. (USPC), Rockville, MD.

⁵ Triton X-100, Rohm and Haas, has been successfully used.