

## CORRIGENDUM 2

Page 8

### 1.2 Références normatives

*Supprimer:*

CEI 410:1973, *Plans et règles d'échantillonnage pour les contrôles par attributs*

*Ajouter les publications suivantes:*

CEI 61318:1994, *Travaux sous tension – Guide pour les plans d'assurance de la qualité*

ISO 2859-1:1999, *Règles d'échantillonnage pour les contrôles par attributs – Partie 1: Procédures d'échantillonnage pour les contrôles lot par lot, indexés d'après le niveau de qualité acceptable (NQA)*

#### 1.3.1 Termes définis selon les CEI 50(151) et CEI 410

*Au lieu de:*

... et CEI 410

*lire:*

... et CEI 61318

Page 10

#### 1.3.1.6 défaut mineur

*Au lieu de:*

(voir 2.1.3, CEI 410).

*lire:*

(voir 2.6 de la CEI 61318).

Page 9

### 1.2 Normative references

*Delete:*

IEC 410:1973, *Sampling plans and procedures for inspection by attributes*

*Add the following publications:*

IEC 61318:1994, *Live working – Guidelines for quality assurance plans*

ISO 2859-1:1999, *Sampling procedures for inspection by attributes – Part 1: Sampling schemes indexed by acceptance quality limit (AQL) for lot-by-lot inspection*

#### 1.3.1 Terms defined in accordance with IEC 50(151) and IEC 410

*Instead of:*

... and IEC 410

*read:*

... and IEC 61318

Page 11

#### 1.3.1.6 minor defect

*Instead of:*

(see 2.1.3, IEC 410).

*read:*

(see 2.6 of IEC 61318).