

Designation: E313 – 20

Standard Practice for Calculating Yellowness and Whiteness Indices from Instrumentally Measured Color Coordinates¹

This standard is issued under the fixed designation E313; the number immediately following the designation indicates the year of original adoption or, in the case of revision, the year of last revision. A number in parentheses indicates the year of last reapproval. A superscript epsilon (ε) indicates an editorial change since the last revision or reapproval.

1. Scope

1.1 This practice provides numbers that correlate with visual ratings of yellowness or whiteness of white and nearwhite or colorless object-color specimens, viewed in daylight by an observer with normal color vision. White textiles, paints, and plastics are a few of the materials that can be described by the indices of yellowness or whiteness calculated by this practice.

1.2 For a complete analysis of object colors, by a specified observer and under a specified illuminant, use of three parameters is required. For near-white specimens, however, it is often useful to calculate single-number scales of yellowness or whiteness. This practice provides recommended equations for such scales and discusses their derivations and uses, and limits to their applicability (see also Ref $(1)^2$).

1.3 The values stated in SI units are to be regarded as standard. No other units of measurement are included in this standard.

1.4 This standard does not purport to address all of the safety concerns, if any, associated with its use. It is the responsibility of the user of this standard to establish appropriate safety, health, and environmental practices and determine the applicability of regulatory limitations prior to use.

1.5 This international standard was developed in accordance with internationally recognized principles on standardization established in the Decision on Principles for the Development of International Standards, Guides and Recommendations issued by the World Trade Organization Technical Barriers to Trade (TBT) Committee.

2. Referenced Documents

- 2.1 ASTM Standards:³
- D1535 Practice for Specifying Color by the Munsell System D1729 Practice for Visual Appraisal of Colors and Color
- Differences of Diffusely-Illuminated Opaque Materials D1925 Test Method for Yellowness Index of Plastics (Withdrawn 1995)^{4,5}
- E284 Terminology of Appearance
- E308 Practice for Computing the Colors of Objects by Using the CIE System
- E805 Practice for Identification of Instrumental Methods of Color or Color-Difference Measurement of Materials
- E991 Practice for Color Measurement of Fluorescent Specimens Using the One-Monochromator Method
- E1164 Practice for Obtaining Spectrometric Data for Object-Color Evaluation
- E1247 Practice for Detecting Fluorescence in Object-Color Specimens by Spectrophotometry
- E1331 Test Method for Reflectance Factor and Color by Spectrophotometry Using Hemispherical Geometry
- E1345 Practice for Reducing the Effect of Variability of Color Measurement by Use of Multiple Measurements
- E1347 Test Method for Color and Color-Difference Mea-
- surement by Tristimulus Colorimetry E1348 Test Method for Transmittance and Color by Spec-
- trophotometry Using Hemispherical Geometry
- E1349 Test Method for Reflectance Factor and Color by Spectrophotometry Using Bidirectional (45°:0° or 0°:45°) Geometry
- E1360 Practice for Specifying Color by Using the Optical Society of America Uniform Color Scales System
- E1499 Guide for Selection, Evaluation, and Training of Observers

¹ This practice is under the jurisdiction of ASTM Committee E12 on Color and Appearance and is the direct responsibility of Subcommittee E12.04 on Color and Appearance Analysis.

Current edition approved May 1, 2020. Published May 2020. Originally approved in 1967. Last previous edition approved in 2015 as $E313 - 15^{e1}$. DOI: 10.1520/E0313-20.

² The boldface numbers in parentheses refer to the list of references at the end of this practice.

³ For referenced ASTM standards, visit the ASTM website, www.astm.org, or contact ASTM Customer Service at service@astm.org. For *Annual Book of ASTM Standards* volume information, refer to the standard's Document Summary page on the ASTM website.

⁴ The last approved version of this historical standard is referenced on www.astm.org.

⁵ Replaced by Section 6 of E313.

E1541 Practice for Specifying and Matching Color Using the Colorcurve System (Withdrawn 2007)⁴

3. Terminology

3.1 Terms and definitions in Terminology E284 are applicable to this practice.

3.2 Definitions:

3.2.1 *perfect reflecting diffuser*, n—ideal reflecting surface that neither absorbs nor transmits light, but reflects diffusely, with the radiance of the reflecting surface being the same for all reflecting angles, regardless of the angular distribution of the incident light.

3.2.2 *whiteness*, *n*—the attribute of color perception by which an object color is judged to approach the preferred white.

3.2.3 *whiteness index, WI, n*—a number, computed by a given procedure from colorimetric data, that indicates the degree of departure of an object color from that of a preferred white.

3.2.4 *yellowness*, *n*—the attribute of color perception by which an object color is judged to depart from colorless or a preferred white toward yellow.

3.2.5 *yellowness index, YI, n*—a number, computed by a given procedure from colorimetric or spectrophotometric data, that indicates the degree of departure of an object color from colorless or from a preferred white, toward yellow.

3.2.5.1 *Discussion*—Negative values of *YI* denote departure toward blue.

3.3 Definitions of Terms Specific to This Standard:

3.3.1 *near white, n*—a color having a Munsell value greater than 8.3 (luminous reflectance factor Y = 63) and Munsell chroma no greater than 0.5 for *B* hues, 0.8 for *Y* hues, and 0.3 for all other hues.

3.3.2 *preferred white*, *n*—color of a white standard used as the basis for calculating indices of whiteness or yellowness as the departure of the color of the specimen from that of the preferred white; *in this practice*, the perfect reflecting diffuser.

4. Summary of Practice

4.1 The calculations described in this practice assume that specimens have been measured according to Practices E1164 and E308 and one of the Test Methods E1331, E1347, E1348, or E1349, depending on the type of specimen and measuring instrument used (see also Practice E805).

4.2 This practice takes as a starting point for the calculations CIE tristimulus values X, Y, and Z for one of the CIE standard observers and one of the CIE standard or recommended illuminants of daylight quality. Such tristimulus values are available by use of modern color measuring instruments.

4.3 Equations for the preferred methods of calculating *YI* and *WI* are described in Sections 6 and 7, respectively. Equations for calculating other quantities used as indices of yellowness or whiteness are given in Appendix X1 and Appendix X2, respectively.

5. Significance and Use

5.1 This practice should be used only to compare specimens of the same material and same general appearance. For example, a series of specimens to be compared should have generally similar gloss, texture, and (if not opaque) thickness, and translucency.

5.2 For yellowness measurement, this practice is limited to specimens having dominant wavelength in the range 570 to 580 nm, or Munsell hue approximately 2.5GY to 2.5Y. For whiteness measurement, this practice is limited to specimens having Munsell value greater than 8.3 (CIE *Y* greater than 65) and Munsell chroma no greater than 0.5 for *B* hues, 0.8 for *Y* hues, and 0.3 for all other hues (see 3.3.1).

5.3 The combination of measurement and calculation leading to indices of yellowness or whiteness is a psychophysical process, that is, the procedures specified are designed to provide numbers correlating with visual estimates made under specified typical observing conditions. Because visual observing conditions can vary widely, users should compare calculated indices with visual estimates to ensure applicability. Some standards addressing the visual estimation of color and color difference are Practices D1535, D1729, E1360, and E1541, and Guide E1499.

5.4 This practice does not cover the preparation of specimens, a procedure that may affect significantly the quantities measured. In general, specimens should be prepared and presented for measurement in the manner that is standard for the test being performed. Select enough specimens or specimen areas to provide an average result that is representative of each sample to be tested. See Practice E1345.

6. Yellowness Index

6.1 This section contains the calculation of the currently recommended Yellowness Index. The historical background of this Yellowness Index is given in Appendix X1. Alternative Yellowness Indices are given in Appendix X2.

6.2 *Calculation of Yellowness Index (YI)*—YI can be calculated for either Illuminant C or D65, and either the CIE 1931 standard colorimetric observer (2°), or the CIE 1964 standard colorimetric observer (10°).

6.2.1 Use Eq 1 to calculate Yellowness Index (YI):

$$YI = 100(C_X X - C_Z Z)/Y$$
(1)

where X, Y, Z are the measured tristimulus values of the specimen calculated for either Illuminant C or D65, and either the CIE 1931 standard colorimetric observer (2°), or the CIE 1964 standard colorimetric observer (10°); and coefficients C_X and C_Z are selected from Table 1 for the chosen illuminant and observer.

TABLE 1 Coefficients for Yellowness Index Equation (1)

	CIE Standard Illuminant and Standard Observer						
Quantity	C, 1931	D ₆₅ , 1931	C, 1964	D ₆₅ , 1964			
$\overline{C_X}$	1.2769	1.2985	1.2871	1.3013			
C_Z	1.0592	1.1335	1.0781	1.1498			

7. Whiteness Index

7.1 This section contains the calculations of the currently recommended Whiteness Index. The historical background of this Whiteness Index in given in Appendix X3. Alternative measures of Whiteness are given in Appendix X4.

7.2 CIE Equations—The equations for whiteness recommended in this practice were derived and published (2) by the CIE. Two equations are given, one for the whiteness index WIand another for a tint index T. Their coefficients are given in Table 2. The CIE gave coefficients for both standard observers and III. D65; those for the 1931 observer and III. C were taken from the American Association of Textile Chemists and Colorists (AATCC) method for WI(3); and those for the 1964 observer and III. C and III. D50 were estimated by Subcommittee E12.04. Those for III. C and III. D50 and both observers are unofficial and should be used for in-house comparisons only.

7.2.1 Equation for Whiteness Index WI:

$$WI = Y + (WI, x) (x_n - x) + (WI, y) (y_n - y)$$
(2)

where *Y*, *x*, *y* are the luminance factor and the chromaticity coordinates of the specimen; x_n and y_n are the chromaticity coordinates for the CIE standard illuminant and source used; and *WI*, *x* and *WI*, *y* are numerical coefficients.

Values for all these except those measured for the specimen are given in Table 2.

7.2.2 Equation for Tint Index T:

$$T = T, x (x_n - x) - T, y (y_n - y)$$
 (3)

where the symbols have meanings analogous to those in 7.2.1.

7.3 *Notes and Restrictions to the CIE Equations*—The CIE notes the following regarding the use of equations for *WI* and *T*:

7.3.1 The application of the equations is restricted to specimens that are called "white" commercially, that are similar in color and fluorescence, and that are measured on the same instrument at about the same time. Under these conditions their use should give relative, but not absolute, evaluations of whiteness that are adequate for commercial use.

7.3.2 The higher the value of *WI*, the greater is the indicated whiteness. The more positive the value of *T*, the greater is the indicated greenish tint of the specimen; the more negative the value of *T*, the greater is its reddish tint. Lines of equal *T* are approximately parallel to the line of dominant wavelength 466 nm. For the perfect reflecting diffuser, WI = 100 and T = 0.

TABLE 2 Coefficients for the Equations for CIE Whiteness Index and Tint

Value		CIE Standard Illuminant and Observer						
	C, 31	D ₅₀ , 31	D ₆₅ , 31	C, 64	D ₅₀ , 64	D ₆₅ , 64		
$\overline{X_n}$	0.3101	0.3457	0.3127	0.3104	0.3477	0.3138		
Уn	0.3161	0.3585	0.3290	0.3191	0.3595	0.3310		
WI, x	800	800	800	800	800	800		
WI, y	1700	1700	1700	1700	1700	1700		
Т, х	1000	1000	1000	900	900	900		
Т, у	650	650	650	650	650	650		

7.3.3 Equal differences in *WI* or *T* do not always represent equal perceptual differences in whiteness or tint, respectively.

7.3.4 These equations should be used only for specimens with 40 < WI < (5Y - 280) and -4 < T < +2.

8. Apparatus

8.1 *Color Measuring Instrument*—Spectrophotometer or tristimulus (filter) colorimeter, capable of producing CIE tristimulus values and chromaticity coordinates for either CIE standard observer and the desired CIE standard illuminants of daylight quality, for a CIE recommended geometry. The instrument should meet the manufacturer's requirements for calibration.

8.1.1 If the specimens are known or suspected to be fluorescent (see Practice E1247), the choice of instrument optical geometry can affect the measurement results. When hemispherical (integrating sphere) geometry is used for measuring fluorescent specimens, the spectral power distribution of the illuminating system may be altered by the reflected and emitted power from the specimen. The use of bidirectional geometry is therefore preferable. In addition, follow the requirements of Practice E991 with respect to the spectral output of the instrument illuminator.

8.2 *Standards*—The primary standard of reflectance shall be the perfect reflecting diffuser. Instrument standards calibrated in terms of the perfect reflecting diffuser or the perfect transmitting diffuser shall be used in standardizing the instrument.

9. Procedure

9.1 Operate the color measuring instrument according to the manufacturer's instructions for standardization and measurement. Refer to Practices E308 and E1164 and, according to the instrument type and geometry, Test Method E1331, E1347, E1348, or E1349.

9.1.1 In addition to the standards required or furnished by the manufacturer, it is desirable to measure periodically one or more system verification standards with known values of yellowness or whiteness.

9.2 If not carried out automatically by the instrument, print, display, or store values of *X*, *Y*, *Z*, *x*, *y* for the specimens for use in calculations.

9.2.1 Make as many repeat measurements as required (refer to Practice E1345) and average the resulting values of *X*, *Y*, *Z*, *x*, *y*. Use the averaged values in calculations.

10. Calculations

10.1 As required, calculate for each specimen the value of YI by Eq 1, of WI by Eq 2, and of T by Eq 3.

10.1.1 Refer to Appendix X2 and Appendix X4 for other equations used in the past for calculating indices of yellowness and whiteness. Such equations may be used if desired, but the resulting values will in all probability differ from those obtained by use of the recommended equations of this practice.

11. Report

11.1 The report shall include the following information:

11.1.1 Manufacturer, model, geometry, and any further identification required for the instrument used,

11.1.2 Illuminant(s) and observer(s) for which data are reported,

11.1.3 Specimen identifications for each measurement,

11.1.3.1 If multiple measurements were made of a single specimen and set of conditions, number of measurements,

11.1.4 Indices of yellowness, whiteness, and tint as required, and

11.1.5 Special considerations including the following:

11.1.5.1 If the specimens were fluorescent, details of the instrument light source as required in Practice E991, and

11.1.5.2 If the specimens were transparent or translucent, the thickness of each specimen.

11.2 It is good practice for the report to include the following information:

11.2.1 Measured values of X, Y, Z for each measurement, and

11.2.1.1 If multiple measurements were made of a single specimen and set of conditions, average values of X, Y, Z.

12. Keywords

12.1 color; colorimetric analysis; color/light; instrumental measurement; reflectance; reflectivity; whiteness indexes; yellowness indexes

iTeh Standards (https://standards.iteh.ai) Document Preview

<u>ASTM E313-20</u>

https://standards.iteh.ai/catalog/standards/sist/448572b1-fde6-4c37-b827-df5e0687d843/astm-e313-20