



Designation: E77 – 14 (Reapproved 2021)

Standard Test Method for Inspection and Verification of Thermometers¹

This standard is issued under the fixed designation E77; the number immediately following the designation indicates the year of original adoption or, in the case of revision, the year of last revision. A number in parentheses indicates the year of last reapproval. A superscript epsilon (ϵ) indicates an editorial change since the last revision or reapproval.

This standard has been approved for use by agencies of the U.S. Department of Defense.

1. Scope

1.1 This test method covers visual and dimensional inspection and test for scale accuracy to be used in the verification of liquid-in-glass thermometers as specified in Specifications E1 and E2251. However, these procedures may be applied to other liquid-in-glass thermometers.²

NOTE 1—The use of NIST SP250-23² is recommended.

1.2 **Warning**—Mercury has been designated by many regulatory agencies as a hazardous substance that can cause serious medical issues. Mercury, or its vapor, has been demonstrated to be hazardous to health and corrosive to materials. Use caution when handling mercury and mercury-containing products. See the applicable product Safety Data Sheet (SDS) for additional information. The potential exists that selling mercury or mercury-containing products, or both, is prohibited by local or national law. Users must determine legality of sales in their location.

1.3 *This standard does not purport to address all of the safety concerns, if any, associated with its use. It is the responsibility of the user of this standard to establish appropriate safety, health, and environmental practices and determine the applicability of regulatory limitations prior to use.*

1.4 *This international standard was developed in accordance with internationally recognized principles on standardization established in the Decision on Principles for the Development of International Standards, Guides and Recommendations issued by the World Trade Organization Technical Barriers to Trade (TBT) Committee.*

¹ This test method is under the jurisdiction of ASTM Committee E20 on Temperature Measurement and is the direct responsibility of Subcommittee E20.05 on Liquid-in-Glass Thermometers and Hydrometers.

Current edition approved May 1, 2021. Published June 2021. Originally approved in 1949. Last previous edition approved in 2014 as E77 – 14^{ε1}. DOI: 10.1520/E0077-14R21.

² “Liquid-in-Glass Thermometer Calibration Service,” *NIST Special Publication 250-23*, 1988. Available from U.S. Government Printing Office, Superintendent of Documents, 732 N. Capitol St., NW, Washington, DC 20401-0001, <http://www.access.gpo.gov>.

2. Referenced Documents

2.1 *ASTM Standards*:³

E1 Specification for ASTM Liquid-in-Glass Thermometers
E344 Terminology Relating to Thermometry and Hydrometry

E2251 Specification for Liquid-in-Glass ASTM Thermometers with Low-Hazard Precision Liquids

3. Terminology

3.1 *Definitions*:

3.1.1 The definitions given in Terminology E344 apply. Some that are considered essential to this standard are given below.

3.1.2 *calibration, n*—of a thermometer or thermometric system, the set of operations that establish, under specified conditions, the relationship between the values of a thermometric quantity indicated by a thermometer or thermometric system and the corresponding values of temperature realized by standards.

3.1.2.1 *Discussion*—(1) The result of a calibration permits either the assignment of values of temperature to indicated values of thermometric quantity or determination of corrections with respect to indications. (2) A calibration may also determine other metrological properties such as the effect of influence quantities. (3) The result of a calibration may be communicated in a document such as a calibration certificate or a calibration report. (4) The term *calibration* has also been used to refer to the result of the operations, to representations of the result, and to the actual relationship between values of the thermometric quantity and temperature.

3.1.3 *complete-immersion thermometer, n*—a liquid-in-glass thermometer, not specified in ASTM documents, designed to indicate temperature correctly when the entire thermometer is exposed to the temperature being measured.

³ For referenced ASTM standards, visit the ASTM website, www.astm.org, or contact ASTM Customer Service at service@astm.org. For *Annual Book of ASTM Standards* volume information, refer to the standard’s Document Summary page on the ASTM website.

3.1.4 *partial-immersion thermometer, n*—a liquid-in-glass thermometer designed to indicate temperature correctly when the bulb and a specified part of the stem are exposed to the temperature being measured.

3.1.5 *total-immersion thermometer, n*—a liquid-in-glass thermometer designed to indicate temperature correctly when just that portion of the thermometer containing the liquid is exposed to the temperature being measured.

3.2 *Definitions of Terms Specific to This Standard:*

3.2.1 *reference point, n*—a temperature at which a thermometer is checked for changes in the bulb volume.

3.2.2 *verification, n*—the process of testing a thermometer for compliance with specifications.

3.2.3 *verification temperatures, n*—the specified temperatures at which thermometers are tested for compliance with scale error limits.

3.2.4 Other descriptions of terms relating to thermometers are included in Sections 3 and 17 of Specification E1.

4. Significance and Use

4.1 The test method described in this standard will ensure that the thermometers listed in Specifications E1 and E2251 will indicate temperatures within the maximum scale errors listed, be compatible with the apparatus, and serve the purpose for which they were designed.

4.2 Thermometers that do not pass the visual and dimensional inspection tests may give erroneously high or low temperature readings, or may not fit into existing equipment used in ASTM methods. For accurate temperature measurements the scale readings of the thermometer should be verified as described in this test method.

5. Apparatus

5.1 *Graduated Metal Scales or Templates*—Maximum and minimum specified linear dimensions are measured with graduated metal scales and templates on which lines are ruled at suitable distances from reference points corresponding to the maximum and minimum values of the several specified dimensions.

5.2 *Micrometers and Ring Gauges*—Specified diameters of ASTM thermometers are checked using micrometers, or more conveniently with ring gauges consisting of metal plates in which holes have been formed corresponding to the maximum and minimum values of the several specified dimensions. The thickness of such gauges should approximate the diameters of the holes to minimize errors resulting from the axis of the thermometer stem being other than normal to the plane of the gauge. When specified, diameters may also be checked with conventional snap gauges having plane parallel working faces.

5.3 *Comparators*—Comparators are required for verification of scale accuracy of liquid-in-glass thermometers. Suitable types are described in Appendix X1.

5.4 *Primary Standard Thermometer*—The primary standard thermometer in the range from –183 to 630 °C (–297 to 1166 °F) is the platinum-resistance thermometer. Temperatures are not measured directly with this instrument. Its electrical

resistance is determined by comparison with a standard resistor, using a potentiometer, a Kelvin-type double bridge, or a Wheatstone bridge, (preferably of the Mueller type) or an AC resistance bridge. Temperatures may then be calculated using suitable resistance-temperature equations. In order that it shall be satisfactory for such use, the thermometer should meet the requirement that the ratio of resistances at the steam and ice points shall be greater than 1.3925. More complete information on the construction and use of primary standard thermometers may be obtained from NIST SP250-22.⁴

5.5 *Secondary Standard Thermometers*—Secondary standard thermometers are more suitable for routine work, and may be of various types as described below. They are simpler to use than a primary standard thermometer with its accessory equipment, the latter being capable of an order of precision and accuracy far in excess of that attainable with liquid-in-glass thermometers. The choice of a secondary standard will be governed by various factors. The following criteria should, in so far as possible, be satisfied: The standard should be a calibrated thermometer of equal or preferably higher sensitivity than the thermometer to be verified, and it should be capable of giving results of an equal or preferably higher order of accuracy and also of an equal or preferably higher order of reproducibility or precision. Scale corrections should always be applied in the use of these standards. Secondary standards may be of the following types.

5.5.1 *Direct-reading Resistance Thermometers*—Direct-reading resistance thermometers are available commercially, are very convenient to use, and have the advantage over the primary type that temperature indications are given directly in the instrument reading. They should be completely recalibrated every 6 to 12 months, depending upon the temperatures of usage. Ice points should be taken every three months.

5.5.2 *Liquid-in-glass Thermometers*—Liquid-in-glass thermometers, when used as secondary standards, may be classified into two groups, those intended for testing general purpose total or partial-immersion thermometers, and those for testing special use partial-immersion thermometers.

5.5.2.1 *Total-immersion Thermometers*—In the case of general purpose total-immersion thermometers, the sensitivity of the thermometers to be tested will govern the choice of standard. For thermometers graduated in 1, 2, or 5° divisions, a set of well-made thermometers will be adequate when calibrated and used with applicable corrections. For fractionally graduated thermometers a calibrated set of the following thermometers is recommended. Specifications for these ASTM Precision Thermometers appear in Specification E1.

| ASTM Thermometer Number | Range | Celsius | Divisions | Length, mm |
|-------------------------|--------|---------|-----------|------------|
| 62C | –38 to | +2 °C | 0.1 °C | 380 |
| 63C | –8 to | +32 °C | 0.1 °C | 380 |
| 64C | 25 to | 55 °C | 0.1 °C | 380 |

⁴ “Platinum Resistance Thermometer Calibrations,” NIST Special Publication NIST Special Publication 250-22. Available from U.S. Government Printing Office, Superintendent of Documents, 732 N. Capitol St., NW, Washington, DC 20401-0001, <http://www.access.gpo.gov>.

| ASTM Thermometer Number | Range | Celsius | Divisions | Length, mm |
|-------------------------|--------|---------|-----------|------------|
| 65C | 50 to | 80 °C | 0.1 °C | 380 |
| 66C | 75 to | 105 °C | 0.1 °C | 380 |
| 67C | 95 to | 155 °C | 0.2 °C | 380 |
| 68C | 145 to | 205 °C | 0.2 °C | 380 |
| 69C | 195 to | 305 °C | 0.5 °C | 380 |
| 70C | 295 to | 405 °C | 0.5 °C | 380 |

| ASTM Thermometer Number | Range | Fahrenheit | Divisions | Length, mm |
|-------------------------|--------|------------|-----------|------------|
| 62F | -36 to | +35 °F | 0.2 °F | 380 |
| 63F | 18 to | 89 °F | 0.2 °F | 380 |
| 64F | 77 to | 131 °F | 0.2 °F | 380 |
| 65F | 122 to | 176 °F | 0.2 °F | 380 |
| 66F | 167 to | 221 °F | 0.2 °F | 380 |
| 67F | 203 to | 311 °F | 0.5 °F | 380 |
| 68F | 293 to | 401 °F | 0.5 °F | 380 |
| 69F | 383 to | 581 °F | 1.0 °F | 380 |
| 70F | 563 to | 761 °F | 1.0 °F | 380 |

The foregoing set is calibrated for total immersion. With the exception of the first two, each thermometer is provided with an auxiliary scale including 0 °C (32 °F), thus providing means for checking at a fixed point, which should be done each time the thermometer is used. The change in ice-point reading should then be applied to all readings. It is only necessary to have a liquid-in-glass thermometer completely calibrated one time. Recalibration is performed as described in 6.3.8.

5.5.2.2 Partial-immersion Thermometers—General purpose partial-immersion thermometers, as commonly listed in manufacturers' catalogs according to their own specifications, are normally bought and sold without specification of the temperatures of the emergent column for the various temperature indications of the thermometers. In such cases, verification is usually carried out for the emergent column temperatures prevailing with the verification equipment being employed.

5.5.2.3 Special Use Partial-immersion Thermometers—Special use partial-immersion thermometers, such as those covered in Specification E1, have specified emergent mercury columns or stem temperatures. These thermometers can be used as standards to calibrate other thermometers similar in all details of construction above the immersion point, but may differ below the immersion point to the extent of including an auxiliary ice point scale.

5.6 Engraving Date on ASTM Thermometers—If a thermometer's specification was changed, the year that it was changed is engraved on the back of the thermometer after the ASTM designation. For example, "12C-98."

6. Procedure

6.1 Visual Inspection:

6.1.1 Gas Bubbles and Separations—Gas bubbles are readily detected and are more likely to occur in shipment than during service. No method has been discovered that will entirely prevent such displacement of the gas. If bubbles are observed in the bulb, they can generally be removed by cooling the bulb with dry ice or other convenient coolant until all the liquid is drawn into the bulb. Gentle tapping of the thermometer while held upright will cause the bubbles to rise to the surface. It is very important that, if the bulb is cooled in this

process below the freezing point of the liquid, care should be exercised to warm the stem sufficiently during the melting process so that no solidification occurs in the stem; otherwise the bulb may burst or the capillary may split internally because of the expansion forces generated in the bulb.

6.1.1.1 If a mercury separation is observed in the stem, several different ways are suggested for joining the columns, depending on the construction of the thermometer and the type of separation. If a small portion of the liquid has separated at the top of the column and the thermometer is provided with an expansion chamber, the liquid usually can be joined by carefully and slowly heating the bulb until the separated portion is driven into the expansion chamber. Never heat the bulb in an open flame. When the column itself follows into the chamber, the separated portion usually will join onto the main column. A slight tapping of the thermometer against the palm of the hand will facilitate this joining. This method should not be employed for high-temperature thermometers (above 260 °C or 500 °F), because the heating of the bulb, which is necessary to drive the liquid into the expansion chamber, may overheat the glass and either break the bulb, because of the pressure of the gas, or destroy the accuracy of the thermometer by expanding the bulb. Thermometers that have a contraction chamber below the lowest graduation are likely to develop separations either in the chamber or above it. It is frequently possible to join such separations by cooling the thermometer so that the separated portion as well as the main column both stand in the chamber. Tapping the tube against the hand or the bulb on a soft spongy material, such as a rubber stopper, usually will bring the liquid together. For more stubborn separations it may be necessary to cool the bulb in dry ice to a point low enough to bring all of the liquid into the bulb itself. By softly tapping on a soft spongy material or against the hand it usually is possible to bring the liquid together in the bulb. The bulb should be allowed to warm up slowly. The liquid should emerge into the bore with no separation.

6.1.1.2 In organic-liquid-filled thermometers distillation may occur, with subsequent condensation of the colorless parent liquid in the upper part of the thermometer. Such thermometers should always be inspected for these separations, which can be repaired by the procedures described above. If the thermometer has an expansion chamber that is observed to be filled with liquid, the column can be reunited by very careful heating of the chamber to drive the liquid into the bore where it can be rejoined to the main body as described above.

6.1.1.3 Organic liquids as used in thermometers, in contrast to mercury, wet the glass. Sufficient time should always be allowed for drainage to occur, particularly when using or verifying such thermometers below 0 °C (32 °F). It is frequently a good practice to immerse only the bulb of the thermometer. This keeps the viscosity of the liquid in the capillary low and aids in hastening drainage.

6.1.2 Globules of Liquid—Globules of liquid in the stem, which result from mechanical separation, can normally be rejoined by heating the bulb until the liquid column merges with the globules. If such globules appear to unite and then reappear on cooling the bulb, they are indicative of oxidation

of the mercury or the presence of obstructions in the bore, and should result in rejection of the thermometer.

6.1.3 *Foreign Matter*—Foreign matter in the bore can sometimes be detected with the unaided eye, but it is generally convenient to use a magnifying glass of low power for this examination. A magnifier of 10× is recommended for visual examination. The most common types of foreign matter which should be cause for rejection are glass chips, particles of dirt or lint, oxide of mercury (either red, yellow, or black), products of glass weathering commonly called white deposit, and stones or iron spots traceable to faulty glass fabrication.

6.1.3.1 Where a specific gas is specified to be used as filling above the liquid, any other gas present may be treated as foreign matter. The most common example is the use of air instead of nitrogen in mercury-in-glass thermometers, which may have been introduced by accident or in violation of the specifications. The presence of air can readily be detected by visual inspection under slight magnification (2× to 5×). The mercury will oxidize and will show as dull, moist, or will show a red oxide.

6.1.4 *Glass Faults*—Glass faults may be of various types. Any stones or striae that distort the bore or its appearance should be cause for rejection. Strains in the glass as observed with a polarized light strain gauge near enlargements in the stem or bore, or at the top of the thermometer, are detrimental. If so, severe fire cracks may later occur. Strains near the bulb are indicative of incomplete glass stabilization and are particularly objectionable in thermometers for use above 150 °C (302 °F).

6.2 *Dimensional Inspection:*

6.2.1 Determine compliance with lineal dimensional specifications by comparison of the thermometer with the appropriate scale or template described in 5.1. In the case of diameter measurements, the bulb or other portions of the thermometer being tested should not enter the smaller of the holes in the ring gauge (see 5.2), or fail to enter the larger of the holes. In the case of ASTM thermometers, the diameter limits apply over the entire length of the section of the thermometer being tested.

6.2.2 Inspect the thermometers for uniformity of graduation spacing. Normally, the effect of taper in the capillary or nonlinearity in the expansion characteristics of organic liquids is manifested by a gradual change in the spacing of the graduations. Discontinuities in the spacing are evidence of faulty graduating. Inspection for uniformity of spacing can generally be accomplished by eye, but for greater accuracy a pair of dividers may be used to advantage. Adjust the dividers to extend over 10 or 20 graduations, and successive intervals can be intercompared rapidly. Where marked changes in spacing are noted, it is well to include in the verification several temperatures in that region.

6.3 *Verification of Scale Accuracy:*

6.3.1 *Reading Thermometers to Avoid Parallax*—The error due to parallax may be eliminated by taking care that the reflection of the scale can be seen in the mercury thread, and by adjusting the line of sight so that the graduation of the scale nearest the meniscus exactly hides its own image; the line of sight will then be normal to the stem at that point. In reading thermometers, account must be taken of the fact that the lines

are of appreciable width. The best practice is to consider the position of the lines as defined by their middle parts.

6.3.2 *Depth of Immersion for Total-immersion Thermometers*—Although by definition total-immersion thermometers should have the bulb and stem containing the mercury immersed both in use and in verification, it is frequently inconvenient to do so. If any portion of the stem containing mercury is exposed, the emergent mercury column correction should be determined. No correction need be applied if it is found to be less than one fifth of the verification error; otherwise, the proper correction should be applied. In some instances total-immersion thermometers may be used under conditions of complete immersion. With thermometers such as the kinematic-viscosity thermometer 30F, a significant error will be introduced unless the thermometer is verified under the same conditions as those in use. This is due to the effect of increased gas pressure above the column producing a distortion of the bulb.

6.3.3 *Depth of Immersion for Partial-immersion Thermometers*—Thermometers of this type shall be verified by one of the methods described in 6.3.7.2, 6.3.7.3, and 6.3.7.4 using the appropriate comparators. If the thermometer is of the general-purpose type, it should be verified by immersion to the specified depth and the readings compared with those of the secondary standard.

6.3.4 *Verification at Ice Point:*

6.3.4.1 Select clear pieces of ice or ice made from distilled or pure water. Discard any cloudy or unsound portions. Rinse the ice with distilled water and shave or crush into small pieces, avoiding direct contact with the hands or any chemically unclean objects. Fill the Dewar vessel with the crushed ice and add sufficient distilled, preferably precooled, water to form a slush, but not enough to float the ice. As the ice melts it will be necessary to drain off some of the water and add more crushed ice. Insert the thermometer, packing the ice gently about the stem, to a depth approximately one scale division below the 0 °C (32 °F) gradation.

6.3.4.2 After at least 3 min have elapsed, tap the stem gently and observe the reading. Successive readings taken at least 1 min apart should agree within one tenth of a division. It may be necessary to repack the ice around the thermometer because of melting.

6.3.5 *Verification at Steam Point:*

6.3.5.1 If the range of the thermometer is such that the ice point is not included, the steam point at 100 °C (212 °F) can be used. For a description of the equipment and techniques best suited to the purpose, reference may be made to NIST SP250-23.²

6.3.6 *Verification of Total-immersion and General Use Partial-immersion Thermometers at Temperatures Other Than Fixed Points:*

6.3.6.1 Determine the ice point of the primary or secondary standard and the thermometer to be tested as described in 6.3.4. If the secondary standard is of the liquid-in-glass type, it should be held at room temperature for at least 72 h before this determination unless the ice point was originally determined immediately after heating to a specified temperature. The thermometer to be tested should be treated in similar manner.

6.3.6.2 Insert the thermometer to be tested and the standard in the thermometer holder, and adjust the temperature of the comparator to a value approximately 5 °C (10 °F) below the verification temperature. It may be advantageous to use two secondary standard liquid-in-glass thermometers, since observational errors of the standard may then be readily detected. Apply sufficient heat to raise the temperature at a slow uniform rate. At the verification point the rate should not exceed one scale division in 3 to 10 min. Fulfillment of this requirement will ensure that any exposed portion of the stem will have attained thermal equilibrium before readings are taken.

6.3.6.3 When the proper rate of temperature rise has been established, read the thermometers in the following order at equal time intervals: standard, thermometer or thermometers to be tested, standard, thermometers to be tested in reverse order, standard. The average of the first and third readings of the standard should agree with the second. A comparison of differences in successive readings will also indicate if the rate of rise has been uniform.

6.3.6.4 Calculate the average readings for all thermometers. Apply the appropriate corrections to the reading of the standard. Calculate the corrections to be applied to the thermometers under test.

6.3.6.5 For verification purposes, one series of readings is usually sufficient. If the thermometer is being calibrated, check determinations should be made. The results of each of at least three series should agree with the mean of the series within plus or minus one tenth of a division.

6.3.6.6 Unless otherwise specified, tests should be made not less than 40 nor more than 100 divisions apart throughout the range of the thermometer.

6.3.6.7 Comparisons may be made at constant temperature in preference to the use of slowly rising temperatures. Such a procedure is satisfactory if the bath temperature does not vary more than the precision of reading and if the thermometer is jarred, as by tapping, before taking a reading in order to overcome any sticking of the mercury to the glass. Such tapping is particularly important with thermometers having a capillary diameter of the order of 0.1 mm or less and may be employed to advantage in the rising temperature method of test as well. Sufficient time should elapse before taking readings to ensure that all portions of the thermometer have attained thermal equilibrium. This is particularly important at test temperatures remote from room temperatures.

6.3.7 Verification of Partial-immersion Thermometers With Specified Stem Temperatures:

6.3.7.1 Partial-immersion thermometers having specified stem temperatures, such as those in Specification E1, can be verified in one of three ways.

6.3.7.2 One method involves comparison of the thermometers at total immersion with total-immersion standards. The number of degrees of scale, which will be in the emergent column when in actual use, shall then be measured. From these data the corrections under the specified emergent column temperatures may then be calculated (7.2). In the case of organic liquid-filled thermometers such as ASTM Low Cloud and Pour, 6 °C and 6 °F, the coefficient of expansion of the liquid should be obtained by experiment or from the manufac-

turer in order to perform these computations. This method has the advantage that the standard may be selected to have greater sensitivity than the thermometer being tested, thus increasing the accuracy of measurement.

6.3.7.3 A second method, which is the one best suited to large-quantity testing, involves comparison of the thermometers with standards similar in all details of construction above the immersion point, but may differ below the immersion point to the extent of including an auxiliary ice-point scale. Such thermometers, when completely calibrated, as by the National Institute of Standards and Technology, may then be employed indefinitely for verification purposes if periodic ice-point checks are made. The particular field of application of this second method is evidenced by the fact that many of the ASTM thermometers include the ice point in the specified range, but the following fractionally graduated thermometers are not provided with an ice-point scale:

Paraffin Wax Melting Point: 14C, 14F

High Softening Point: 16C, 16F

Saybolt Viscosity: 17C, 17F, 18C, 18F, 19C, 19F, 20C, 20F, 21C, 21F, 22C, 22F, 77F to 81F, 108F, 109F

Engler Viscosity: 23C, 24C, 25C

Stability Test of Soluble Nitrocellulose: 26C

Turpentine Distillation: 27C

Aniline Point: 34C, 34F, 35C, 35F

Solvents Distillation: 38C, 39C, 40C, 41C, 42C, 102C, 103C, 104C, 105C, 106C, 107C

Stormer Viscosity: 49C

Gas Calorimeter Inlet: 50F

Gas Calorimeter Outlet: 51F

Congealing Point: 54F

Petrolatum Melting Point: 61C, 61F

Antifreeze Freezing Point: 76F

Solidification Point: 91C to 96C, 100C, 101C, 102C

Tar Acids Distillation: 111C

Brookfield 122C, 123C, 124C, 125C

The ice point was omitted from the above listed thermometers as a matter of necessity. In order to supply an ice point, when not included in the range of the thermometer, it is necessary to blow an enlargement or contraction chamber below the first graduation to take care of the volume of mercury between the ice point and this first graduation. This contraction chamber may introduce an error in the readings unless it is entirely immersed in or is at the same temperature as the medium the temperature of which is to be measured. This immersion requirement may be difficult if not impossible to attain in the apparatus in which the thermometers are used. Such limitations of space prevented the inclusion of ice points in the above group of thermometers. However, by increasing the lengths of the thermometers, ice-point scales can be incorporated in the thermometers to be used as standards. For those in the group that are partial immersion, the dimensions above the immersion point should be as prescribed in the specifications for the corresponding ASTM thermometer. For the total-immersion thermometers this requirement may be waived.

6.3.7.4 A third method uses total-immersion standards, measuring stem temperature of the emergent liquid column in the partial-immersion thermometer with a Faden thermometer or small auxiliary thermometers. With this data, stem temperature adjustments can be made. See NIST SP250-23² for additional details.

6.3.8 *Recalibrate by Checking Changes in Bulb Volume:*

6.3.8.1 The verification procedure described above can be used to obtain corrections for the calibration of thermometers.

6.3.8.2 Small changes in the volume of the thermometer bulb during use, especially significant for large bulb and relatively short range thermometers graduated in fractional degrees, may occur, even though the thermometer has been carefully annealed or aged, and will result in changes in the indications as well as the corrections. Usually the bulb contracts slowly, and, as a result, the thermometer will read higher after it has been placed in service. Less frequently the bulb expands and the thermometer will read lower after use.

6.3.8.3 Two procedures are followed for using the ice point to determine the change in bulb volume and to recalibrate a liquid-in-glass thermometer. One method requires that the thermometer remain at approximately room temperature for 72 h before the ice point is taken. The other method stipulates that the ice point reading be taken immediately or within a definitely stated short period of time after heating to the test temperature. Changes in the corrections of the thermometer may be observed by determining the changes in the ice point by either method.

6.3.8.4 Record the ice-point reading and compare it with the previous reading. If the ice-point reading is found to be higher or lower than the ice-point reading of the previous calibration, readings at all other temperatures will be correspondingly increased or decreased. If the method involving the taking of the ice point immediately after heating to a specified temperature is used, such as with most kinematic viscosity thermometers, a note should appear in the table of corrections for the thermometer as follows:

NOTE 2—The tabulated corrections apply for the condition of immersion indicated, provided the ice-point reading taken after heating to ___ for not fewer than 3 min is ___. If the ice-point reading (taken in not fewer than 2 min and not more than 1 h after removal of the thermometer from the heated bath) is found to be higher (or lower) than stated, all other readings will be higher (or lower) to the same extent.

6.3.8.5 When the thermometers are first received, make a monthly check of the ice point. Later these time intervals may be lengthened if the changes are found to be insignificant.

6.3.8.6 High-quality liquid-in-glass thermometers require only one complete calibration in their lifetime, and it is possible to avoid the usual requirement for complete recalibration of the instrument by the recalibration of a single previously calibrated temperature. The need for recalibration of properly manufactured liquid-in-glass thermometers is due to the gradual relaxation of residual mechanical strains in the glass that have a significant effect on the volume of the bulb. The recalibration of a single point provides a reliable indication

of the effect of this change in volume and provides a means for the accurate adjustment of the remainder of the scale.⁵

7. Treatment of Data

7.1 From the corrections at the ice point and the other verification temperatures, a table of corrections can be prepared for each thermometer. If the thermometer is to be used frequently at temperatures other than those of calibration, a correction curve will be found more convenient than interpolation from a table. In such a curve the corrections are plotted against the temperature readings.

7.2 Where corrections are to be calculated for emergent columns, the following equation shall be used:

$$\text{Emergent stem correction} = kn(T - t) \quad (1)$$

where:

- k = differential expansion coefficient of the liquid and the glass of which the thermometer is made; for Celsius mercury-in-glass thermometers the value of k is 0.00016, for Fahrenheit mercury-in-glass thermometers it is 0.00009, for Celsius organic liquid-in-glass thermometers it is 0.001, and for Fahrenheit organic liquid-in-glass thermometers it is 0.0006,
- n = number of degrees emergent from the bath,
- T = temperature of the bath, and
- t = average temperature of the liquid column of n degrees.

7.2.1 The use of more accurate values of k is not justified, because of the uncertainty of the true average temperature of the liquid thread not exposed to the temperature being measured.

7.2.2 For emergent columns of partial-immersion thermometers, where the column temperature is other than specified in Table 2 of Specification E1, calculate the correction to the observed reading as follows:

$$\text{Emergent stem correction} = kn(t_s - t_o) \quad (2)$$

where:

- k = same as in 7.2,
- n = the number of scale degrees from the immersion mark to the top of the mercury column. The ungraduated length between the immersion mark and the first graduation on the scale shall be evaluated in terms of scale degrees and be included,
- t_s = temperature specified in Table 2 of Specification E1, and
- t_o = observed average temperature of the liquid column of n degrees.

7.3 The limit of precision to which the corrections at the calibration temperatures shall be recorded, to which correction tables or charts shall be made, or to which any temperature measured by the thermometer shall be reported, is a measure of the sensitivity of the thermometer and is generally described by the phrase, *corrections stated to*.

⁵ Wise, Jacquelyn, "A Procedure for the Effective Recalibration of Liquid-in-Glass Thermometers," *NIST Special Publication 819*, 1991. Available from U.S. Government Printing Office, Superintendent of Documents, 732 N. Capitol St., NW, Washington, DC 20401-0001, <http://www.access.gpo.gov>.

7.4 The limit of reliability of any temperature measurement made with a calibrated thermometer after all corrections, determined as carefully as possible, have been applied is termed the *uncertainty in degree* of the thermometer.

7.5 For compliance with specifications, the errors in the temperature indications of ASTM thermometers being verified shall not exceed the *scale errors* as expressed in Table 1 of Specification E1. Unless otherwise expressed, it is understood that such thermometers are to be used without application of corrections.

8. Precision and Bias

8.1 No statement is made about either precision or bias of Test Method E77 for visual and dimensional inspection since the results merely state whether there is conformance to the criteria for success or failure specified in the procedure.

8.2 Precision of Verification of Scale Accuracy

8.2.1 It is not practicable to specify the precision of the verification of the scale accuracy because of the wide variety of thermometers listed in Specification E1. Of the 129 different kinds of liquid-in-glass thermometers, they are all either for use at total immersion or partial immersion.

8.2.2 The verification of total-immersion thermometers will produce more repeatable results because the temperature of the stem containing the mercury is at the same temperature as the bulb, when the thermometer is immersed correctly. The temperature of the emergent stem of partial-immersion thermometers can vary depending on the temperature of the environment and this will affect the repeatability of the data obtained. The method used for measuring the temperature of the emergent mercury column, when stem-temperature measurements are made, has an effect on the repeatability of the data. Generally, total-immersion thermometers have an uncertainty of approximately ten times better than partial-immersion thermometers.

8.2.3 Most thermometers contain mercury as the actuating liquid. Some thermometers, especially those for use at temperatures below $-56\text{ }^{\circ}\text{C}$ ($-69\text{ }^{\circ}\text{F}$), use an organic liquid. Unlike mercury, the organic liquid will wet the wall of the capillary. Adequate time must be given for complete drainage to occur. This can take up to 1 h and can have an influence on the precision of the measurement. Thermometers containing organic fluids are less accurate than those containing mercury or mercury thallium.

8.2.4 Thermometers are graduated in intervals of 0.01° , 0.02° , 0.05° , 0.1° , 0.2° , 0.5° , 1.0° , 2.0° , and 5.0° . The ability to read these thermometers will have an influence on the precision of the measurements. If the thermometers are read with a telescope, thermometers graduated in intervals of 0.01° or 0.02° can be read to the nearest 0.001° ; in 0.05° or 0.1° to the nearest 0.005° ; in 0.2° to the nearest 0.01° ; in 0.5° or 1.0° to the nearest 0.05° ; in 2.0° to the nearest 0.1° ; and in 5.0° to the nearest 0.5° .

8.2.5 Each laboratory can determine the precision of the verification of scale accuracy or the calibration of liquid-in-glass thermometers using the above information as a guideline. A statistical analysis of data collected on the various types of thermometers verified could be used to obtain a value for the random error.

8.3 Bias

8.3.1 Like precision, it is very difficult to determine a bias statement for the verification of the scale accuracy because of the systematic error from the choice of standard used and the gradients in the comparators in each laboratory.

8.3.2 If a standard platinum resistance thermometer is used as the standard, it can be capable of reproducing temperatures to approximately 0.001 to $0.003\text{ }^{\circ}\text{C}$. If total-immersion liquid-in-glass thermometers, such as the ASTM set of $62\text{ }^{\circ}\text{C}$ ($62\text{ }^{\circ}\text{F}$) through $70\text{ }^{\circ}\text{C}$ ($70\text{ }^{\circ}\text{F}$), are used as standards, the uncertainty at the calibration points will range from $0.03\text{ }^{\circ}\text{C}$ ($0.05\text{ }^{\circ}\text{F}$) to $0.5\text{ }^{\circ}\text{C}$ ($1.0\text{ }^{\circ}\text{F}$). The uncertainty of partial-immersion thermometers will range from approximately $0.3\text{ }^{\circ}\text{C}$ ($0.5\text{ }^{\circ}\text{F}$) to $2.0\text{ }^{\circ}\text{C}$ ($3.0\text{ }^{\circ}\text{F}$). This uncertainty will be less if special use partial-immersion thermometers are used as standards where the readings are adjusted for a specified stem temperature. In all cases the average of two standard liquid-in-glass thermometers will give a more accurate value of the temperature of the medium of the comparator.

8.3.3 The error due to gradients in the comparators must be determined in each laboratory. These gradient errors will usually increase where comparisons are made in comparators at higher temperatures.

8.3.4 The precision and bias for the verification of scale accuracy must be calculated for each laboratory. An example of how this can be done is shown in NIST SP250-23.²

9. Keywords

9.1 calibration; liquid-in-glass thermometers; mercury separation; organic liquids; verification