Household and similar electrical appliances - Safety -

Part 2-3: Particular requirements for electric irons

CORRIGENDUM 1

19 Abnormal operation

19.1 Replace the text of the modification by the following.

The tests of 19.2 and 19.3 are not carried out. The test of 19.5 is only carried out on separate boilers of **steam irons**.

June 2002