# Standard Test Methods for Determination of Nickel, Vanadium, and Iron in Crude Oils and Residual Fuels by Inductively Coupled Plasma (ICP) Atomic Emission Spectrometry<sup>1</sup>

This standard is issued under the fixed designation D 5708; the number immediately following the designation indicates the year of original adoption or, in the case of revision, the year of last revision. A number in parentheses indicates the year of last reapproval. A superscript epsilon  $(\epsilon)$  indicates an editorial change since the last revision or reapproval.

#### 1. Scope

- 1.1 These test methods cover the determination of nickel, vanadium, and iron in crude oils and residual fuels by inductively coupled plasma (ICP) atomic emission spectrometry. Two different test methods are presented.
- 1.2 Test Method A (Sections 7-11 and 18-22)—ICP is used to analyze a sample dissolved in an organic solvent. This test method uses oil-soluble metals for calibration and does not purport to quantitatively determine or detect insoluble particulates.
- 1.3 Test Method B (Sections 12-22)—ICP is used to analyze a sample that is decomposed with acid.
- 1.4 The concentration ranges covered by these test methods are determined by the sensitivity of the instruments, the amount of sample taken for analysis, and the dilution volume. A specific statement is given in Note 4. Typically, the low concentration limits are a few tenths of a mg/kg. Precision data are provided for the concentration ranges specified in Section 21.
- 1.5 The values stated in SI units are to be regarded as the standard. The values given in parentheses are provided for information only.
- 1.6 This standard does not purport to address all of the safety concerns, if any, associated with its use. It is the responsibility of the user of this standard to establish appropriate safety and health practices and determine the applicability of regulatory limitations prior to use.

#### 2. Referenced Documents

- 2.1 ASTM Standards:
- D 1193 Specification for Reagent Water<sup>2</sup>
- D 1548 Test Method for Vanadium in Navy Special Fuel Oil<sup>3</sup>
- D 4057 Practice for Manual Sampling of Petroleum and Petroleum Products<sup>4</sup>
- <sup>1</sup> This test method is under the jurisdiction of ASTM Committee D02 on Petroleum Products and Lubricants and is the direct responsibility of Subcommittee D02.03.0B on Spectrometric Methods.
- Current edition approved Nov. 10, 2000. Published December 2000. Originally published as D 5708 95. Last previous edition D 5708 95a.
  - <sup>2</sup> Annual Book of ASTM Standards, Vol 11.01.
  - <sup>3</sup> Annual Book of ASTM Standards, Vol 05.01.
  - <sup>4</sup> Annual Book of ASTM Standards, Vol 05.02.

- D 4177 Practice for Automatic Sampling of Petroleum and Petroleum Products<sup>4</sup>
- D 5185 Test Method for the Determination of Additive Elements, Wear Metals, and Contaminants in Used Lubricating Oils by Inductively Coupled Plasma Atomic Emission Spectrometry<sup>5</sup>
- D 6299 Practice for Applying Statistical Quality Assurance Techniques to Evaluate Analytical Measurement System Performance<sup>6</sup>

#### 3. Summary of Test Method

- 3.1 Test Method A—Approximately 10 g of the sample are dissolved in an organic solvent (Warning—Combustible. Vapor is harmful.) to give a specimen solution containing 10 % (m/m) of sample. The solution is nebulized into the plasma, and the intensities of the emitted light at wavelengths characteristic of the analytes are measured sequentially or simultaneously. The intensities are related to concentrations by the appropriate use of calibration data.
- 3.2 Test Method B—One to 20 g of sample are weighed into a beaker and decomposed with concentrated sulfuric acid (Warning—Poison. Causes severe burns. Harmful or fatal if swallowed or inhaled.) by heating to dryness. Great care must be used in this decomposition because the acid fumes are corrosive and the mixture is potentially flammable. The residual carbon is burned off by heating at 525°C in a muffle furnace. The inorganic residue is digested with nitric acid (Warning—Poison. Causes severe burns. Harmful or fatal if swallowed or inhaled.), evaporated to incipient dryness, dissolved in dilute nitric acid, and made up to volume. The solution is nebulized into the plasma of an atomic emission spectrometer. The intensities of light emitted at characteristic wavelengths of the metals are measured sequentially or simultaneously. These intensities are related to concentrations by the appropriate use of calibration data.

#### 4. Significance and Use

4.1 These test methods cover, in single procedures, the determination of Ni, V, and Fe in crude oils and residual oils. These test methods complement Test Method D 1548, which

<sup>&</sup>lt;sup>5</sup> Annual Book of ASTM Standards, Vol 05.03.

<sup>&</sup>lt;sup>6</sup> Annual Book of ASTM Standards, Vol 05.04.



covers only the determination of vanadium.

4.2 When fuels are combusted, vanadium present in the fuel can form corrosive compounds. The value of crude oils can be determined, in part, by the concentrations of nickel, vanadium, and iron. Nickel and vanadium, present at trace levels in petroleum fractions, can deactivate catalysts during processing. These test methods provide a means of determining the concentrations of nickel, vanadium, and iron.

#### 5. Purity of Reagents

- 5.1 Reagent grade chemicals shall be used in all tests. Unless otherwise indicated, it is intended that all reagents conform to the specifications of the Committee on Analytical Reagents of the American Chemical Society where such specifications are available. Other grades may be used, provided it is first ascertained that the reagent is of sufficiently high purity to permit its use without lessening the accuracy of the determination.
- 5.2 When determining metals at concentrations less than 1 mg/kg, use ultra-pure reagents.
- 5.3 *Purity of Water*—Unless otherwise indicated, reference to water shall be understood to mean reagent water conforming to Type II of Specification D 1193.

#### 6. Sampling and Sample Handling

- 6.1 The objective of sampling is to obtain a sample for testing purposes that is representative of the entire quantity. Thus, take samples in accordance with the instructions in Practice D 4057 or D 4177. Do not fill the sample container more than two-thirds full.
- 6.2 Prior to weighing, stir the sample and manually shake the sample container. If the sample does not readily flow at room temperature, heat the sample in a drying oven at 80°C or at another safe temperature.

## TEST METHOD A— ICP WITH AN ORGANIC SOLVENT SPECIMEN SOLUTION

#### 7. Apparatus

- 7.1 Inductively Coupled Plasma Atomic Emission Spectrometer—Either a sequential or simultaneous spectrometer, equipped with a quartz torch and radio-frequency generator to form and sustain the plasma, is suitable.
- 7.2 Nebulizer—The use of a high-solids nebulizer is optional but strongly recommended. This type of nebulizer minimizes the probability of clogging. A concentric glass nebulizer can also be used.
- 7.3 Peristaltic Pump—This pump is required for non-aspirating nebulizers and optional for aspirating nebulizers. The pump must achieve a flow rate in the range of 0.5 to 3 mL/min. The pump tubing must be able to withstand at least a

- 6 h exposure to the solvent. Fluoroelastomer copolymer tubing is recommended.<sup>8</sup>
- 7.4 *Specimen Solution Containers*, glass or plastic vials or bottles with screw caps and a capacity of between 50 to 100 mL. One hundred millilitre glass bottles are satisfactory.

#### 8. Reagents

- 8.1 *Dilution Solvent*—Mixed xylenes, *o*-xylene, tetralin and mixed paraffin-aromatic solvents are satisfactory. Solvent purity can affect analytical accuracy when the sample contains low concentrations (typically, a few mg/kg) of the analytes.
  - 8.2 Mineral Oil—A high-purity oil such as U.S.P. white oil.
- 8.3 *Organometallic Standards*—Pre-prepared multielement concentrates containing 100 mg/kg concentrations of each element are satisfactory.<sup>8</sup>
- 8.4 *Quality Control (QC) Samples*, preferably are portions of one or more liquid petroleum materials that are stable and representative of the samples of interest. These QC samples can be used to check the validity of the testing process as described in Section 19.

#### 9. Preparation of Standards and Specimens

- 9.1 *Blank*—Prepare a blank by diluting mineral oil with dilution solvent. The concentration of mineral oil must be 10 % (m/m). Mix well.
- 9.2 Check Standard—Using organometallic standards, mineral oil, and dilution solvent, prepare a check standard to contain analyte concentrations approximately the same as expected in the specimens. The concentration of oil in the check standard must be 10 % (m/m).
- 9.3 *Test Specimen*—Weigh a portion of well-mixed sample into a container and add sufficient solvent to achieve a sample concentration of 10 % (m/m). Mix well.
- 9.4 Working Standard—Prepare an instrument calibration standard that contains 10 mg/kg each of vanadium, nickel, and iron. Combine the organometallic standard, dilution solvent and, if necessary, mineral oil so that the oil content of the calibration standard is 10 % (m/m).
- 9.5 *Quality Control (QC) Samples*—Weigh a portion of the well-mixed QC sample into a container and add sufficient solvent to achieve a sample concentration of 10 % (m/m).

#### 10. Preparation of Apparatus

- 10.1 Consult the manufacturer's instructions for the operation of the ICP instrument. This test method assumes that good operating procedures are followed. Design differences between instruments make it impractial to specify required parameters.
- 10.2 Assign the appropriate operating parameters to the instrument taskfile so that the desired analytes can be determined. Parameters include: (1) element, (2) analytical wavelength, (3) background correction wavelengths (optional), (4) interelement correction factors (refer to 10.3), (5) integration time of 1 to 10 s, (6) two to five consecutive repeat integrations. Suggested wavelengths are listed in Table 1.
- 10.3 Spectral Interferences—Check all spectral interferences expected for the analytes. If interference corrections are

<sup>&</sup>lt;sup>7</sup> Reagent Chemicals, American Chemical Society Specifications, American Chemical Society, Washington, DC. For suggestions on the testing of reagents not listed by the American Chemical Society, see Analar Standards for Laboratory Chemicals, BDH Ltd., Poole, Dorset, U.K., and the United States Pharmacopeia and National Formulary, U.S. Pharmacopeial Convention, Inc. (USPC), Rockville, MD.

<sup>&</sup>lt;sup>8</sup> Viton (a trademark owned by E. I. duPont de Nemours) has been found satisfactory. An equivalent can be used.



TABLE 1 Elements Determined and Suggested Wavelengths

Note 1—These wavelengths are suggestions and do not represent all possible choices.<sup>A</sup>

Element	Wavelength, nm
Iron	259.94, 238.20
Nickel	231.60, 216.56
Vanadium	292.40, 310.22

<sup>A</sup>Winge, R. K., Fassel, V. A., Peterson, V. J., and Floyd, M. A., Inductively Coupled Plasma Atomic Emission Spectroscopy: An Atlas of Spectral Information, Elsevier, NY, 1985.

necessary, follow the manufacturer's operating guide to develop and apply correction factors.

- 10.3.1 Spectral interferences can usually be avoided by judicious choice of analytical wavelengths. If spectral interferences cannot be avoided, the necessary corrections should be made using the computer software supplied by the instrument manufacturer or by using the empirical method described in Test Method D 5185.
- 10.4 Consult the instrument manufacturer's instructions for operating the instrument with organic solvents.
- 10.5 During instrument warm-up, nebulize the blank solution. Inspect the torch for carbon build-up. When carbon build-up occurs, replace the torch and adjust the operating conditions to correct the problem.
- 10.5.1 Carbon build-up within the torch can be caused by improperly adjusted argon flow rates, improper solution flow rates, and positioning the torch injector tube too close to the load coil. Carbon deposits can invalidate a calibration and extinguish the plasma.

#### 11. Calibration and Analysis

- 11.1 Using the blank and working standard, perform a two-point calibration at the beginning of the analysis of <u>each</u> batch of specimens. Additional working standards can be used, if desired.
- 11.2 Use the check standard to determine if the calibration for each analyte is accurate. When the result obtained on the check standard is not within  $\pm 5$  % of the expected concentration for each analyte, take corrective action and repeat the calibration.
- 11.3 Analyze the specimens in the same manner as the calibration standards (that is, same integration time, plasma conditions, and so forth). Calculate concentrations by multiplying the concentration determined for the test specimen solution by the dilution factor. Calculation of concentrations can be performed manually or by computer when such a feature is available.
- 11.4 When the measured intensities for the test specimen solution exceed the corresponding intensities for the working standard, either ensure that the calibration curve is linear to the concentration of the element in the test specimen solution or dilute the test specimen solution with the blank solution and reanalyze.
- 11.5 Analyze the check standard after every fifth specimen. If any result is not within 5 % of the expected concentration, take corrective action, repeat the calibration, and reanalyze the specimen solutions back to the previous acceptable check standard analysis.

11.6 The use of spectral background correction is highly recommended, particularly when the test specimen solutions contain low concentrations of the analytes (typically less than 1 mg/kg). When concentrations are low, background changes, which can result from variability in the compositions of test specimen solutions, can affect the accuracy of the analysis. Background correction minimizes errors due to variable background intensities.

### TEST METHOD B— ICP AFTER ACID DECOMPOSITION OF SAMPLE

#### 12. Apparatus

- 12.1 Refer to 7.1-7.4.
- 12.2 Sample Decomposition Apparatus (optional)—This apparatus is shown in Fig. 1. It consists of a high-silica or borosilicate 400-mL beaker for the specimen, an air bath (Fig. 2) that rests on a hot plate, and a 250-watt infrared lamp supported 1 in. above the air bath. A variable transformer controls the voltage applied to the lamp.
- 12.3 Glassware, high-silica or borosilicate 400-mL beakers, volumetric flasks of various capacities, and pipettes of various capacities. When determining concentrations below 1 mg/kg, all glassware must be thoroughly cleaned and rinsed with water.
- 12.4 Electric Muffle Furnace, capable of maintaining 525  $\pm$  25°C and sufficiently large to accommodate 400-mL beakers. The capability of an oxygen bleed is advantageous and optional.
  - 12.5 Steam Bath (optional).
  - 12.6 Temperature Controlled Hot Plate (optional).

#### 13. Reagents

- 13.1 Aqueous Standard Solutions, individual aqueous standards with 1000 mg/L concentrations of vanadium, nickel, and iron.
  - 13.2 Nitric Acid, concentrated nitric acid, HNO<sub>3</sub>.




FIG. 1 Decomposition Apparatus