AMERICAN SOCIETY FOR TESTING AND MATERIALS 100 Barr Harbor Dr., West Conshohocken, PA 19428 Reprinted from the Annual Book of ASTM Standards. Copyright ASTM

# Standard Test Method for Annealing Point and Strain Point of Glass by Fiber Elongation<sup>1</sup>

This standard is issued under the fixed designation C 336; the number immediately following the designation indicates the year of original adoption or, in the case of revision, the year of last revision. A number in parentheses indicates the year of last reapproval. A superscript epsilon ( $\epsilon$ ) indicates an editorial change since the last revision or reapproval.

This standard has been approved for use by agencies of the Department of Defense.

 $\epsilon^1$  Note—Section 12 was added editorially in September 1995.

## 1. Scope

- 1.1 This test method covers the determination of the annealing point and the strain point of a glass by measuring the viscous elongation rate of a fiber of the glass under prescribed condition.
- 1.2 The annealing and strain points shall be obtained by following the specified procedure after calibration of the apparatus using fibers of standard glasses having known annealing and strain points, such as those specified and certified by the National Institute of Standards and Technology (NIST)<sup>2</sup> (see Appendix X1).
- 1.3 This standard does not purport to address all of the safety concerns, if any, associated with its use. It is the responsibility of the user of this standard to establish appropriate safety and health practices and determine the applicability of regulatory limitations prior to use.

## 2. Referenced Documents

2.1 ASTM Standards:

C 338 Test Method for Softening Point of Glass<sup>3</sup>

C 598 Test Method for Annealing Point and Strain Point of Glass by Beam Bending<sup>3</sup>

# 3. Definitions

3.1 *annealing point*—that temperature at which internal stresses in a glass are substantially relieved in a matter of minutes.<sup>4,5,6</sup> During a test in accordance with the requirements of this method, the viscous elongation rate is measured by a

suitable extensometer while the specimen fiber is cooling at a rate of  $4 \pm 1$ °C/min. The elongation rate at the annealing point is approximately 0.14 mm/min for a fiber of 0.65-mm diameter.<sup>6</sup>

- 3.2 annealing range—the range of glass temperature in which stresses in glass articles can be relieved at a commercially desirable rate. For purposes of comparing glasses, the annealing range is assumed to correspond with the temperatures between the annealing point (AP) and the strain point (StP).
- 3.3 strain point—that temperature at which the internal stresses in a glass are substantially relieved in a matter of hours. The strain point is determined by extrapolation of the annealing point data and is the temperature at which the viscous elongation rate is 0.0316 times that observed at the annealing point.

## 4. Significance and Use

4.1 This test method provides data useful for (1) estimating stress release, (2) the development of proper annealing schedules, and (3) estimating setting points for seals. Accordingly, its usage is widespread throughout manufacturing, research, and development. It can be utilized for specification acceptance.

## 5. Apparatus

- 5.1 Furnace—The furnace shall be 368-mm ( $14\frac{1}{2}$ -in.) long and approximately 114 mm ( $4\frac{1}{2}$  in.) in diameter and shall contain a copper core 305 mm (12 in.) long and 29 mm ( $1\frac{1}{8}$  in.) in outside diameter, with inside diameter of 5.6 mm ( $7\frac{1}{32}$  in.). It shall be constructed substantially as shown in Fig. 1.
- 5.1.1 Such a furnace will cool naturally at approximately 4°C (7°F)/min at 500°C (932°F) and at a rate exceeding 3°C (5.5°F)/min at 400°C (752°F).
- 5.2 Temperature Measuring and Indicating Instruments— For the measurement of temperature there shall be provided a thermocouple, preferably platinum-platinum rhodium, inserted in the upper side hole of the copper core, as indicated in Fig.

<sup>&</sup>lt;sup>1</sup> This test method is under the jurisdiction of ASTM Committee C-14 on Glass and Glass Products and is the direct responsibility of Subcommittee C14.04 on Physical and Mechanical Properties.

Current edition approved Oct. 25, 1971. Originally published as C  $336-54\,\mathrm{T}$ . Last previous edition C 336-69.

<sup>&</sup>lt;sup>2</sup> National Institute of Standards and Technology Publication 260.

<sup>&</sup>lt;sup>3</sup> Annual Book of ASTM Standards, Vol 15.02.

<sup>&</sup>lt;sup>4</sup> Littleton, J. T., and Roberts, E. H., "A Method for Determining the Annealing Temperature of Glass," *Journal of the Optical Society of America*, Vol 4, 1920, p. 224

<sup>&</sup>lt;sup>5</sup> Lillie, H. R., "Viscosity of Glass Between the Strain Point and Melting Temperature," *Journal of American Ceramic Society*, Vol 14, 1931, p. 502; "Re-Evaluation of Glass Viscosities at Annealing and Strain Points," *Journal of American Ceramic Society*, Vol 37, 1954, p. 111.

<sup>&</sup>lt;sup>6</sup> McGraw, D. A. and Babcock, C. L., "Effect of Viscosity and Stress Level on Rate of Stress Release in Soda-Lime, Potash-Barium and Borosilicate Glasses," *Journal of the American Ceramic Society*, Vol 42, 1959, p. 330.




FIG. 1 Apparatus for Determination of Annealing Point and Strain Point of Glass

1, so that its junction is located midway in the length of the core. The thermocouple wire shall not be allowed to directly contact the copper; this can be ensured by placing a 6-mm (1/4-in.) length of ceramic tube in the bottom of the hole ahead of the couple. The cold junction of the thermocouple shall be maintained in an ice bath during tests.

H---Diatomaceous earth

Stainless steel support disk

/--Sample fiber

- 5.2.1 The temperature-indicating instrument, preferably a potentiometer, shall be of such quality and sensitivity as to permit reading the thermocouple emf to an amount corresponding to 0.1°C (0.2°F), equivalent to about 1 µV for a platinum couple or to about 4 µV for a base-metal couple.
- 5.2.2 Provision shall be made for reading temperatures accurately at predetermined moments. One means of accomplishing this is to maintain the potentiometer setting at an electromotive force corresponding to a known temperature, near the annealing point and inferring the temperature from the deflection of a sensitive galvanometer, previously calibrated for the purpose. It is convenient to adjust the galvanometer shunt to a sensitivity of about 3°C (5.5°F)/cm of deflection and to somewhat less than critical damping. This technique for reading temperature changes is one of the preferred methods;

in the following sections it will be assumed that this technique has been used, although any other equally sensitive and precise method of following the temperature of the thermocouple may be used.

- 5.3 Furnace Control—Suitable means shall be provided for idling the furnace, controlling its heating rate, and, in the case of very hard glasses, limiting the cooling rate to not more than 5°C (9°F)/min. A variable transformer is a convenient device for this purpose. The transformer can also be employed as a switch for interrupting the furnace current.
- 5.4 Device for Measuring Elongation—The means of observing the rate of elongation of the fiber should be such as to indicate reliably over a range of about 6-mm (1/4-in.) change in fiber length with an uncertainty not greater than about 0.01 mm (0.0004 in.). A convenient method is shown in Fig. 1, where the arm of the optical lever, N, bears upon a platform, L, incorporated in the loading linkage. The fulcrum of the lever should be mounted on a rigid (but height-adjustable) member, substantially free of vibration. With an optical lever arm about 38 mm (1½ in.) long and a scale distance of about 1 m (40 in.), the multiplying factor is about 50. Readings can be made to 0.5