Standard Test Method for Determination of the Cloud Point of Oil¹


This standard is issued under the fixed designation D 5551; the number immediately following the designation indicates the year of original adoption or, in the case of revision, the year of last revision. A number in parentheses indicates the year of last reapproval. A superscript epsilon (ϵ) indicates an editorial change since the last revision or reapproval.

1. Scope

- 1.1 This test method covers the determination of the cloud point of oils used in the softening and stuffing of leather and in the manufacture of fat liquors and other softening and stuffing compounds. This test method was derived from Test Methods D 97 and D 2500.
- 1.2 The values stated in SI units are to be regarded as the standard. The values given in parentheses are for information only.
- 1.3 This standard does not purport to address all of the safety concerns, if any, associated with its use. It is the responsibility of the user of this standard to establish appropriate safety and health practices and determine the applicability of regulatory limitations prior to use.

2. Referenced Documents

- 2.1 ASTM Standards:
- D 97 Test Methods for Pour Point of Petroleum Oils²
- D 2500 Test Method for Cloud Point of Petroleum Oils²
- E 1 Specification for ASTM Thermometers³



Note 1—All dimensions in millimetres. FIG. 1 Apparatus for Cloud Point Test

3. Terminology

3.1 *cloud point*—that temperature, expressed as a multiple of 1°C (2°F), at which a cloud or haze of wax crystals appears at the bottom of the test jar when the oil is cooled under prescribed conditions.

4. Significance and Use

4.1 This test method is intended to determine the cloud point of oils used in the softening and stuffing of leather, as well as those used in the manufacture of products for such purpose. The cloud point of oils is measured for the purpose of quality assurance.

5. Apparatus

5.1 *Test Jar*, clear cylindrical glass, flat bottom, 30- to 33.5-mm inside diameter, and 115- to 125-mm height. To indicate sample height the jar should be marked with a line 54

\pm 3 mm above the inside bottom.

5.2 *Thermometers*, having ranges shown below and conforming to the requirements prescribed in Specification E 1 for thermometers:

		Thermometer Number	
	Temperature		
Thermometer	Range	ASTM	IP
High cloud and pour	-38 to +50°C	5C	1C
Low cloud and pour	-80 to +20°C	6C	2C
Melting point	+32 to +127°C	61C	63C

- 5.2.1 Since separation of liquid column thermometers occasionally occurs and may escape detection, thermometers should be checked immediately prior to the test and used only if they prove accurate within \pm 1°C (for example, ice point).
- 5.3 *Cork*, to fit the test jar, bored centrally for the test thermometer.
- 5.4 *Jacket*, metal or glass, watertight, cylindrical, flat bottom, 115 mm in depth, 42- to 50-mm inside diameter. It must be supported firmly in a vertical position in the cooling bath of 5.7 so that not more than 25 mm projects out of the cooling medium.
- 5.5 *Disk*, cork or felt, 6 mm thick, to fit loosely inside the jacket.
- 5.6 Gasket, to fit snugly around the outside of the test jar and loosely inside the jacket. The gasket may be made of

¹ This test method is under the jurisdiction of ASTM Committee D-31 on Leather and is the direct responsibility of Subcommittee D31.08 on Fats and Oils. This test method was developed in cooperation with the American Leather Chemists Assn. (Method H 18-1957).

Current edition approved May 15, 1995. Published July 1995. Originally published as D 5551-94. Last previous edition D 5551-94.

² Annual Book of ASTM Standards, Vol 05.01.

³ Annual Book of ASTM Standards, Vol 14.03.