



**SLOVENSKI STANDARD**  
**SIST EN 24943:1997**

**01-december-1997**

---

**Kemična analiza železovih zlitin - Določevanje bakra - Plamenska atomska absorpcijska spektrometrična metoda (ISO 4943:1985)**

Chemical analysis of ferrous metal - Determination of copper content - Flame atomic absorption spectrometric method (ISO 4943:1985)

Chemische Analyse des Eisen- und Stahlwerkstoffes - Ermittlung des Kupfergehalts - Flammenatomabsorptionsspektrometrisches Verfahren (ISO 4943:1985)

Analyse chimique des matériaux sidérurgiques - Détermination de la teneur en cuivre - Méthode par spectrométrie d'absorption atomique dans la flamme (ISO 4943:1985)

[https://standards.iteh.ai/catalog/standards/sist/60694605-0b41-4610-](https://standards.iteh.ai/catalog/standards/sist/60694605-0b41-4610-a463-c2ccb128efcd/sist-en-24943-1997)

**Ta slovenski standard je istoveten z: EN 24943:1990**

---

**ICS:**

77.040.30      Kemijska analiza kovin      Chemical analysis of metals

**SIST EN 24943:1997**      **en**

**iTeh STANDARD PREVIEW**  
**(standards.iteh.ai)**

SIST EN 24943:1997

<https://standards.iteh.ai/catalog/standards/sist/60694605-0b41-4610-a463-c2ccb128efcd/sist-en-24943-1997>

EUROPEAN STANDARD

EN 24 943

NORME EUROPEENNE

EUROPAISCHE NORM

March 1990

UDC 669.1:543.422:546.56

Key words: steels, cast iron chemical analysis, determination of content, copper, atomic absorption spectrophotometry, flame photometry

## English version

Chemical analysis of ferrous metal - Determination of copper content - Flame atomic absorption spectrometric method (ISO 4943:1985)

Analyse chimique des matériaux sidérurgiques - Détermination de la teneur en cuivre - Méthode par spectrométrie d'absorption atomique dans la flamme (ISO 4943:1985)

Chemische Analyse des Eisen- und Stahlwerkstoffes - Ermittlung des Kupfergehaltes - Flammenatomabsorptionsspektrometrisches Verfahren (ISO 4943:1985)

This European Standard was accepted by CEN on 1989-11-27 and is identical to the ISO standard as referred to. CEN members are bound to comply with the requirements of the CEN/CENELEC Common Rules which stipulate the conditions for giving this European Standard the status of a national standard without any alteration.

Up-to-date lists and bibliographical references concerning such national standards may be obtained on application to the CEN Central Secretariat or to any CEN member.

This European Standard exists in three official versions (English, French, German). A version in any other language made by translation under the responsibility of a CEN member into its own language and notified to CEN Central Secretariat has the same status as the official versions.

CEN members are the national standards organizations of Austria, Belgium, Denmark, Finland, France, Germany, Greece, Iceland, Ireland, Italy, Luxembourg, Netherlands, Norway, Portugal, Spain, Sweden, Switzerland and United Kingdom.

CEN

European Committee for Standardization  
Comité Européen de Normalisation  
Europäisches Komitee für Normung

Central Secretariat: rue Bréderode 2, B-1000 Brussels

(c) CEN 1990 Copyright reserved to all CEN members

Ref. No. EN 24943:1990 E

### Brief History

On the proposal of the Technical Committee ECISS/TC 20 "Methods of chemical analysis" the Coordinating Commission (COCOR) of the European Committee for Iron and Steel Standardization (ECISS) decided in November 1986 to submit the International Standard

ISO 4943 - 1985      Steel and cast iron -- Determination of copper content -- Flame atomic absorption spectrometric method

to the Formal Vote.

This European Standard was adopted by CEN on 1989-11-27

According to the Common CEN/CENELEC Rules, being part of the Internal Regulations of CEN, the following countries are bound to implement this European Standards: Austria, Belgium, Denmark, Finland, France, Germany, Greece, Iceland, Ireland, Italy, Luxembourg, Netherlands, Norway, Portugal, Spain, Sweden, Switzerland and United Kingdom.

### Statement

The text of the International Standard ISO 4943, edition 1, 1985 was approved by CEN as a European Standard without any modification.

---

# International Standard



# 4943

---

INTERNATIONAL ORGANIZATION FOR STANDARDIZATION • МЕЖДУНАРОДНАЯ ОРГАНИЗАЦИЯ ПО СТАНДАРТИЗАЦИИ • ORGANISATION INTERNATIONALE DE NORMALISATION

---

## Steel and cast iron — Determination of copper content — Flame atomic absorption spectrometric method

*Aciers et fontes — Dosage du cuivre — Méthode par spectrométrie d'absorption atomique dans la flamme*

First edition — 1985-12-15

**ITeH STANDARD PREVIEW**  
**(standards.iteh.ai)**

[SIST EN 24943:1997](#)

<https://standards.iteh.ai/catalog/standards/sist/60694605-0b41-4610-a463-c2ccb128efcd/sist-en-24943-1997>

---

UDC 669.13/14 : 543.422 : 546.56

Ref. No. ISO 4943-1985 (E)

**Descriptors** : steels, cast iron, chemical analysis, determination of content, copper, atomic absorption method.

## Foreword

ISO (the International Organization for Standardization) is a worldwide federation of national standards bodies (ISO member bodies). The work of preparing International Standards is normally carried out through ISO technical committees. Each member body interested in a subject for which a technical committee has been established has the right to be represented on that committee. International organizations, governmental and non-governmental, in liaison with ISO, also take part in the work.

Draft International Standards adopted by the technical committees are circulated to the member bodies for approval before their acceptance as International Standards by the ISO Council. They are approved in accordance with ISO procedures requiring at least 75 % approval by the member bodies voting.

International Standard ISO 4943 was prepared by Technical Committee ISO/TC 17, *Steel*.

Users should note that all International Standards undergo revision from time to time and that any reference made herein to any other International Standard implies its latest edition, unless otherwise stated.

# Steel and cast iron — Determination of copper content — Flame atomic absorption spectrometric method

## 1 Scope and field of application

This International Standard specifies a method for the determination of copper in steel and cast iron by means of flame atomic absorption spectrometry.

The method is applicable to copper contents in the range 0,004 to 0,5 % (*m/m*).

## 2 Reference

ISO/R 377, *Selection and preparation of samples and test pieces for wrought steel*.

## 3 Principle

Dissolution of a test portion in a mixture of hydrochloric, nitric and perchloric acids.

Spraying of the solution into an air-acetylene flame. Spectrometric measurement of the atomic absorption of the 324,7 nm spectral line emitted by a copper hollow cathode lamp.

## 4 Reagents

During the analysis, unless otherwise stated, use only reagents of recognized analytical grade and having a very low copper content, and only distilled water or water of equivalent purity.

If possible, use only freshly prepared distilled or de-ionized water.

**4.1 Iron of high purity,**  
copper content < 0,000 5 % (*m/m*).

### 4.2 Hydrochloric acid-nitric acid mixture.

Mix three parts by volume of hydrochloric acid ( $\rho$  about 1,19 g/ml), one part by volume of nitric acid ( $\rho$  about 1,40 g/ml), and two parts by volume of water.

Prepare this mixture immediately before use.

### 4.3 Hydrochloric acid-nitric acid-perchloric acid mixture.

Mix 20 ml of hydrochloric acid ( $\rho$  about 1,19 g/ml) with 55 ml of nitric acid ( $\rho$  about 1,40 g/ml) and 75 ml of perchloric acid ( $\rho$  about 1,54 g/ml).

NOTE Perchloric acid ( $\rho$  about 1,67 g/ml) may also be used. 100 ml of perchloric acid ( $\rho$  about 1,54 g/ml) is equivalent to 79 ml of perchloric acid ( $\rho$  about 1,67 g/ml).

### 4.4 Copper, standard solution.

**4.4.1 Stock solution,** corresponding to 1 g of Cu per litre.

Weigh, to the nearest 0,000 1 g, 1,000 0 g of high purity copper [ $> 99,95$  % (*m/m*) Cu].

Transfer to a 400 ml beaker and dissolve in 25 ml of nitric acid ( $\rho$  about 1,40 g/ml, diluted 1 + 4). Cover with a watch-glass. When dissolution is complete, evaporate on a water-bath until the onset of crystallization. Dissolve the residue in water, cool, transfer to a 1 000 ml one-mark volumetric flask, dilute to the mark and mix.

**4.4.2 Standard solution,** corresponding to 20 mg of Cu per litre.

Transfer 20,0 ml of the stock solution (4.4.1) into a 1 000 ml one-mark volumetric flask, dilute to the mark and mix.

1 ml of this standard solution contains 20  $\mu$ g of Cu.

Prepare this standard solution immediately before use.

## 5 Apparatus

Ordinary laboratory apparatus, and

### 5.1 Atomic absorption spectrometer.

A copper hollow cathode lamp; supplies of air and acetylene sufficiently pure to give a steady clear fuel-lean flame, free from water and oil, and free from copper.

## ISO 4943-1985 (E)

The atomic absorption spectrometer used will be satisfactory if after optimization according to 7.3.4 the limit of detection and characteristic concentration are in reasonable agreement with the values given by the manufacturer and it meets the precision criteria given in 5.1.1.

### 5.1.1 Minimum precision

Calculate the standard deviation of 10 measurements of the absorbance of the most concentrated calibration solution. The standard deviation shall not exceed 1,0 % of the mean absorbance.

Calculate the standard deviation of 10 measurements of the absorbance of the least concentrated calibration solution (excluding the zero member). The standard deviation shall not exceed 0,5 % of the mean absorbance of the most concentrated calibration solution.

It is also desirable that the instrument should conform to the additional performance requirements given in 5.1.1.1 to 5.1.1.3.

#### 5.1.1.1 Characteristic concentration

The characteristic concentration for copper in a matrix similar to the final test portion solution shall be better than 0,10 µg of Cu per millilitre.

#### 5.1.1.2 Limit of detection

This is defined as twice the standard deviation of 10 measurements of the absorbance of a solution containing the appropriate element of a concentration level selected to give an absorbance just above that of the zero member.

The limit of detection of copper in a matrix similar to the final test portion solution shall be better than 0,15 µg of Cu per millilitre.

#### 5.1.1.3 Graph linearity

The slope of the calibration graph covering the top 20 % of the concentration range (expressed as a change in absorbance) shall not be less than 0,7 times the value of the slope for the bottom 20 % of the concentration range (expressed as a change in absorbance) determined in the same way.

For instruments with automatic calibration using two or more standards, it shall be established prior to the analysis, by obtaining absorbance readings, that the above requirements for graph linearity are fulfilled.

## 5.2 Ancillary equipment.

A strip chart recorder and/or digital readout device is recommended to evaluate the criteria in 5.1.1 and for all subsequent measurements.

Scale expansion can be used until the noise observed is greater than the read-out error and is always recommended for absorbances below 0,1. If scale expansion has to be used and the instrument does not have the means to read the value of the scale

expansion factor, the value can be calculated by measuring a suitable solution with and without scale expansion and simply dividing the signal obtained.

## 6 Sampling

Carry out sampling in accordance with ISO/R 377 or appropriate national standards for cast iron.

## 7 Procedure

**WARNING — Perchloric acid vapour may cause explosions in the presence of ammonia, nitrous fumes or organic matter in general.**

Ensure that the spray system and drainage system are washed free from perchloric acid after use.

NOTE — All glassware shall first be washed in hydrochloric acid (ρ about 1,19 g/ml, diluted 1 + 1), then in water. The quantity of copper present in the beakers and flasks can be checked by measuring the absorption of the distilled water introduced into the glassware after the acid wash.

### 7.1 Test portion

Weigh, to the nearest 0,001 g, approximately 0,5 g of the test sample.

### 7.2 Blank test

Parallel with the determination and following the same procedure, carry out a blank test using the same quantities of all the reagents.

## 7.3 Determination

### 7.3.1 Preparation of the test solution

Place the test portion (7.1) in a 250 ml beaker. Add, in small portions, 20 ml of the hydrochloric acid-nitric acid-perchloric acid mixture (4.3), cover the beaker with a watch-glass and heat gently until solvent action ceases. Evaporate until dense white fumes of perchloric acid appear. Continue fuming for 1 min at such a temperature as to maintain a steady reflux of white perchloric acid fumes on the walls of the beaker.

NOTE — For samples not readily soluble in the hydrochloric acid-nitric acid-perchloric acid mixture (4.3), first dissolve in 10 ml of the hydrochloric acid-nitric acid mixture (4.2) before adding the 20 ml of the hydrochloric acid-nitric acid-perchloric acid mixture (4.3).

Allow to cool, add 25 ml of water and heat gently to dissolve salts. Cool again and transfer quantitatively to a 100 ml one-mark volumetric flask. Dilute to the mark and mix.

Filter by decantation through a dry medium filter paper to remove any residue or precipitate, for example graphite, silica or tungstic acid, and collect the filtrate in a dry beaker after discarding the first runnings.



If the expected copper content of the test sample exceeds 0,1 % (m/m), the solution shall be diluted as follows.

Transfer 20,0 ml of the solution to a 100 ml one-mark volumetric flask, dilute to the mark and mix.

NOTE — If the solution has to be diluted to give the test solution, the blank test (7.2) must be diluted in the same way.

### 7.3.2 Preparation of the calibration solutions

Place  $10 \pm 0,01$  g of the iron (4.1) in a 1 litre beaker. Add in small portions 400 ml of the hydrochloric acid-nitric acid-perchloric acid mixture (4.3) and heat gently until dissolved.

When dissolution is complete, evaporate until dense white fumes of perchloric acid appear. Continue fuming for 1 min at such a temperature as to maintain a steady reflux of white perchloric acid fumes on the walls of the beaker.

Allow to cool, add 100 ml of water and heat gently to dissolve salts. Cool again and transfer the solution quantitatively to a 500 ml one-mark volumetric flask. Dilute to the mark and mix.

#### 7.3.2.1 Copper content < 0,1 % (m/m)

Transfer a series of 25,0 ml aliquots of the iron solution (7.3.2) to 100 ml one-mark volumetric flasks. Add to the flasks from a pipette or burette respectively 0 (the zero member); 2,5; 5,0; 10,0; 15,0; 20,0; and 25,0 ml of the copper standard solution (4.4.2). Dilute to the mark and mix.

#### 7.3.2.2 Copper content 0,1 to 0,5 % (m/m)

Transfer a series of 5,0 ml aliquots of the iron solution (7.3.2) to 100 ml one-mark volumetric flasks. Add to the flasks from a pipette or burette respectively 0 (the zero member); 2,5; 5,0; 10,0; 15,0; 20,0; and 25,0 ml of the copper standard solution (4.4.2). Dilute to the mark and mix.

NOTE — 1 ml of the copper standard solution (4.4.2), diluted to 100 ml is equivalent to 0,004 % (m/m) Cu in the case of 7.3.2.1 and 0,02 % (m/m) Cu in the case of 7.3.2.2.

### 7.3.3 Adjustment of atomic absorption spectrometer

See table 1.

Table 1

Type of lamp	Copper hollow cathode
Wavelength	324,7 nm
Flame	Air-acetylene slightly lean flame adjusted for maximum copper response
Lamp current	Follow manufacturer's recommendations
Bandwidth	Follow manufacturer's recommendations

In the absence of the bandwidth recommendations mentioned in table 1 the following guideline is suggested :

copper 324,7 nm — bandwidth within the range 0,3 to 1,0 nm

NOTE — The manufacturer's recommendations should be closely followed and particular attention is drawn to the following safety points :

- the explosive nature of acetylene, and regulations concerning its use;
- the need to shield the eyes of the operator from ultraviolet radiation by means of tinted glass;
- the need to keep the burner head clear of deposits caused by perchloric salts, etc. A badly clogged burner may cause a flashback;
- make sure that the liquid trap is filled with water.

### 7.3.4 Optimizing the atomic absorption spectrometer settings

Follow the manufacturer's instructions for preparing the instrument for use.

When the current to the lamp, the wavelength and the flow of gas have been adjusted and the burner lit, spray water until the indication has stabilized.

Set the absorbance value at zero using the zero member (7.3.2.1 or 7.3.2.2).

Choose a damping setting or integration time to give a signal steady enough to fulfil the precision requirements (5.1.1).

Adjust the flame to be slightly lean and the burner height to about 1 cm below the light path. Spraying alternately the calibration solution at highest concentration, and the zero member, adjust the gas flow and burner position (horizontally, vertically and rotationally) until the difference in absorbance between the calibration solutions is at a maximum. Check that the spectrometer is set accurately on the required wavelength.

Evaluate the criteria of 5.1.1 to ensure that the instrument is suitable for the determination.

### 7.3.5 Spectrometric measurements

Set the scale expansion so that the calibration solution of highest concentration gives nearly full scale deflection. Aspirate the calibration solutions in ascending order repetitively until each gives the specified precision, thus showing that the instrument has achieved stability. Select two calibration solutions, one having an absorbance just lower than the test portion solution and one just higher. Aspirate these first in ascending order, then in descending order, with the test solution as the middle solution, in each case measuring the absorption in relation to water. Aspirate the complete range of calibration solutions again.

It is recognized that these procedures cannot be followed with automatic instruments which accept two calibration solutions only. In this case it is suggested that the two "sandwiching" solutions should not be used for the primary calibration but should be analysed alternately with the test solution.