

SLOVENSKI STANDARD SIST EN 1149-1:2006

01-december-2006

Nadomešča:

SIST EN 1149-1:1998

Varovalna obleka - Elektrostatične lastnosti - 1. del: Preskusna metoda za merjenje površinske upornosti

Protective clothing - Electrostatic properties - Part 1: Test method for measurement of surface resistivity

Schutzkleidung - Elektrostatische Eigenschaften - Teil 1: Prüfverfahren für die Messung des Oberflächenwiderstandes (standards.iteh.ai)

Vetements de protection - Propriétés <u>électrostatiques</u> - Partie 1: Méthode d'essai pour la résistivité de surfacettps://standards.itch.ai/catalog/standards/sist/129de17b-5ad8-4cb1-a895-75cb0c2065e1/sist-en-1149-1-2006

Ta slovenski standard je istoveten z: EN 1149-1:2006

ICS:

13.340.10 Varovalna obleka Protective clothing

SIST EN 1149-1:2006 en

SIST EN 1149-1:2006

iTeh STANDARD PREVIEW (standards.iteh.ai)

<u>SIST EN 1149-1:2006</u> https://standards.iteh.ai/catalog/standards/sist/129de17b-5ad8-4cb1-a895-75cb0c2065e1/sist-en-1149-1-2006 EUROPEAN STANDARD NORME EUROPÉENNE EUROPÄISCHE NORM EN 1149-1

June 2006

ICS 13.340.01

Supersedes EN 1149-1:1995

English Version

Protective clothing - Electrostatic properties - Part 1: Test method for measurement of surface resistivity

Vêtements de protection - Propriétés électrostatiques -Partie 1: Méthode d'essai pour la résistivité de surface Schutzkleidung - Elektrostatische Eigenschaften - Teil 1: Prüfverfahren für die Messung des Oberflächenwiderstandes

This European Standard was approved by CEN on 24 May 2006.

CEN members are bound to comply with the CEN/CENELEC Internal Regulations which stipulate the conditions for giving this European Standard the status of a national standard without any alteration. Up-to-date lists and bibliographical references concerning such national standards may be obtained on application to the Central Secretariat or to any CEN member.

This European Standard exists in three official versions (English, French, German). A version in any other language made by translation under the responsibility of a CEN member into its own language and notified to the Central Secretariat has the same status as the official versions.

CEN members are the national standards bodies of Austria, Belgium Cyprus, Czech Republic, Denmark, Estonia, Finland, France, Germany, Greece, Hungary, Iceland, Ireland, Italy, Latvia, Lithuania, Luxembourg, Malta, Netherlands, Norway, Poland, Portugal, Romania, Slovakia, Slovenia, Spain, Sweden, Switzerland and United Kingdom.

SIST EN 1149-1:2006

https://standards.iteh.ai/catalog/standards/sist/129de17b-5ad8-4cb1-a895-75cb0c2065e1/sist-en-1149-1-2006



EUROPEAN COMMITTEE FOR STANDARDIZATION COMITÉ EUROPÉEN DE NORMALISATION EUROPÄISCHES KOMITEE FÜR NORMUNG

Management Centre: rue de Stassart, 36 B-1050 Brussels

Cont	ents	Page
Forewo	ord	3
Introduction		4
1	Scope	5
2	Normative references	5
3	Terms and definitions	5
4	Test method	5
4.1	Principle	
4.2	Apparatus	5
4.2.1	Electrodes	5
4.2.2	Flat base plate	5
4.2.3	Ohmmeter	6
4.2.4	Cleaning agent	6
4.3	Specimen and conditioning	
4.3.1	Pre-treatment	6
4.3.2	Specimen or garment	
4.3.3	Conditioning and testing atmosphere Conditioning atmosphere Condit	6
4.4	Procedure II Ell STANDARD FREVIEW	6
4.4.1	CleaningInsulation test of the flat base plate	6
4.4.2		
4.4.3	Testing	7
4.4.4	Test setup SIST EN 1149-12006	8
4.5	Calculation and expression of results at alog/standards/sist/129de17b-5ad8-4ch1-a895-	9
5	75cb0c2065e1/sist-en-1149-1-2006	
Annex	A (informative) Significant technical changes between this European Standard and the previous edition	10
Annex	ZA (informative) Relationship between this European Standard and the Essential Requirements of EU Directive 89/686/EEC relating to Personal Protective Equipment	11

Foreword

This document (EN 1149-1:2006) has been prepared by Technical Committee CEN/TC 162 "Protective clothing including hand and arm protection and lifejackets", the secretariat of which is held by DIN.

This European Standard shall be given the status of a national standard, either by publication of an identical text or by endorsement, at the latest by December 2006, and conflicting national standards shall be withdrawn at the latest by December 2006.

This document supersedes EN 1149-1:1995.

This document has been prepared under a mandate given to CEN by the European Commission and the European Free Trade Association, and supports essential requirements of EU Directive(s).

For relationship with EU Directive(s), see informative Annex ZA, which is an integral part of this document.

EN 1149 consists of the following parts, under the general title "Protective clothing – Electrostatic properties":

- Part 1: Test method for measurement of surface resistivity
- Part 2: Test method for measurement of the electrical resistance through a material (vertical resistance)
- Part 3: Test methods for measurement of charge decay
- Part 5: Performance requirements¹ SIST EN 1149-1:2006

According to the CEN/CENELEC Internal Regulations, the national standards organizations of the following countries are bound to implement this European Standard: Austria, Belgium, Cyprus, Czech Republic, Denmark, Estonia, Finland, France, Germany, Greece, Hungary, Iceland, Ireland, Italy, Latvia, Lithuania, Luxembourg, Malta, Netherlands, Norway, Poland, Portugal, Romania, Slovakia, Slovenia, Spain, Sweden, Switzerland and United Kingdom.

-

¹ This document is under development.

Introduction

This European Standard is part of a series of test methods and requirements for electrostatic properties of protective clothing. Different parts are necessary, because of the various fields of application and materials. The method of this European Standard is most appropriate for materials for which the electrostatic dissipative behaviour is based on surface conductivity. It determines resistance over short distances and may not be appropriate for evaluating full garments.

iTeh STANDARD PREVIEW (standards.iteh.ai)

<u>SIST EN 1149-1:2006</u> https://standards.iteh.ai/catalog/standards/sist/129de17b-5ad8-4cb1-a895-75cb0c2065e1/sist-en-1149-1-2006

1 Scope

This European Standard specifies a test method for materials intended to be used in the manufacturing of electrostatic dissipative protective clothing (or gloves) to avoid incendiary discharge. This test method is not applicable for materials to be used in the manufacturing of protection clothing or gloves against mains voltages.

2 Normative references

The following referenced documents are indispensable for the application of this document. For dated references, only the edition cited applies. For undated references, the latest edition of the referenced document (including any amendments) applies.

EN 340:2003, Protective clothing — General requirements

3 Terms and definitions

For the purposes of this document, the following terms and definitions apply.

3.1

surface resistance iTeh STANDARD PREVIEW

resistance in ohm (Ω) as determined by using specified electrodes placed on the surface of the material (standards.iteh.ai)

3.2

surface resistivity

resistance in ohm (Ω) between opposite edges of a square of the material along the surface of the material

NOTE The surface resistivity is independent of the electrode dimensions and is calculated by multiplying the measured surface resistance by an appropriate factor.

4 Test method

4.1 Principle

The specimen is placed on an insulating base plate and an electrode assembly is rested on the specimen. A DC potential is applied to the electrode assembly and the resistance of the fabric is measured.

4.2 Apparatus

4.2.1 Electrodes

The electrodes shall consist of a cylindrical and an annular electrode which are arranged concentrically with each other. The electrodes made of stainless steel are shown in Figure 1. The insulation resistance between the inner and the outer electrode shall be not less than $10^{14} \Omega$ when determined in accordance with the method described in 4.4.2.

4.2.2 Flat base plate

A flat base plate shall consist of insulating material of surface resistivity not less than 10^{14} Ω (see 4.4.2), of a thickness between 1 mm and 10 mm and it shall be larger than the overall dimensions of the electrode. This plate is used as a support for the specimen during the measurement, and is rested in turn on an earthed conducting surface, e.g. metal plate.

4.2.3 Ohmmeter

Ohmmeter with a range of $10^5 \Omega$ to $10^{14} \Omega$;

and an accuracy of $\pm 5 \%$ for $\leq 10^{12} \Omega$ and

 $\pm 20 \%$ for > $10^{12} \Omega$.

4.2.4 Cleaning agent

Use an appropriate cleaning agent, e.g. propan-2-ol or ethanol.

WARNING — Propan-2-ol and ethanol are highly flammable and harmful to health. Avoid breathing the vapour and contact with skin, eyes and clothing.

4.3 Specimen and conditioning

4.3.1 Pre-treatment

The specimen shall be pre-treated according to the manufacturer's instructions including the number of cleaning cycles or otherwise undergo five cycles of cleaning according to 5.4 of EN 340:2003.

NOTE This pre-treatment is superfluous for garments not intended for cleaning (e.g. for single use garments).

4.3.2 Specimen or garment iTeh STANDARD PREVIEW

Five test specimens shall be cut each of size between the overall dimensions of the electrodes and of the base plate either from the roll material or cut from the garment. If an uncut garment shall be tested, then measurements shall be made at five different suitable places on the garment. The specimen shall not contain seams. Handle the specimens only at the edges to avoid contamination 17b-5ad8-4cb1-a895-

The specimens shall be from the same production lots of the materials that have been used for the manufacture of the delivery sample of the protective clothing.

4.3.3 Conditioning and testing atmosphere

The specimen shall be conditioned for at least 24 h prior to testing and shall be tested in the following atmosphere:

air temperature: (23 ± 1) °C; relative humidity: (25 ± 5) %.

NOTE The surface resistance of materials can depended to a large degree on relative humidity. The lower the relative humidity the higher the surface resistance.

4.4 Procedure

4.4.1 Cleaning

Clean the lower surfaces of the electrodes and the upper surface of the base plate by wiping with a paper tissue which has been moistened with one of the cleaning agents (see 4.2.4).

The electrodes shall be dried to the air.

4.4.2 Insulation test of the flat base plate

Carry out a blank test using the procedure given in 4.4.3 but with no specimen in position. Calculate the resistivity of the insulating material and check that it meets the requirements of 4.2.2.

4.4.3 Testing

Place the test specimen on the base plate with the surface to be tested uppermost and rest the electrode assembly on top of the specimen. Connect the electrodes as shown in Figure 1.

Apply a potential of (100 ± 5) V and after (15 ± 1) s determine the resistance using the ohmmeter. If the resistance is less than $10^5 \Omega$ an appropriate low voltage may be applied and shall be mentioned in the test report.

If necessary, resistances of below $10^5 \Omega$ may be determined by measuring the current through a suitable ammeter connected in series with the specimen and calculating the ratio of the applied potential to the current.

Repeat this procedure on the four other test specimens or on four different places on the garment.

iTeh STANDARD PREVIEW (standards.iteh.ai)

<u>SIST EN 1149-1:2006</u> https://standards.iteh.ai/catalog/standards/sist/129de17b-5ad8-4cb1-a895-75cb0c2065e1/sist-en-1149-1-2006