

Designation: A 623 – 03

### Standard Specification for Tin Mill Products, General Requirements<sup>1</sup>

This standard is issued under the fixed designation A 623; the number immediately following the designation indicates the year of original adoption or, in the case of revision, the year of last revision. A number in parentheses indicates the year of last reapproval. A superscript epsilon ( $\epsilon$ ) indicates an editorial change since the last revision or reapproval.

This standard has been approved for use by agencies of the Department of Defense.

#### 1. Scope

1.1 This specification covers a group of common requirements which, unless otherwise specified in the purchase order or in an individual specification, shall apply to tin mill products.

1.2 In case of any conflict in requirements, the requirements of the purchase order, the individual material specification, and this general specification shall prevail in the sequence named.

NOTE 1—A complete metric companion to Specification A 623 has been developed—Specification A 623M; therefore no metric equivalents are presented in this specification.

1.3 The following safety caveat pertains to Annex A3 through Annex A10 of this specification: *This standard does not purport to address all of the safety concerns, if any, associated with its use. It is the responsibility of the user of this standard to establish appropriate safety and health practices and determine the applicability of regulatory limitations prior to use.* 

#### 2. Referenced Documents

2.1 ASTM Standards:

- ASTM A of a
- A 370 Test Methods and Definitions for Mechanical Testing of Steel Products<sup>2</sup>
- A 700 Practices for Packaging, Marking, and Loading Methods for Steel Products for Domestic Shipment<sup>3</sup>
- A 987 Test Method for Measuring Shape Characteristics of Tin Mill Products<sup>4</sup>
- D 1125 Test Methods for Electrical Conductivity and Resistivity of Water<sup>5</sup>
- E 18 Test Methods for Rockwell Hardness and Rockwell Superficial Hardness of Metallic Materials<sup>6</sup>

- $E\,112$  Test Methods for Determining the Average Grain  $\rm Size^6$
- 2.2 U.S. Military Standards:
- MIL-STD-129 Marking for Shipment and Storage<sup>7</sup>
- MIL-STD-163 Steel Mill Products, Preparation for Marking and Storage<sup>7</sup>
- 2.3 U.S. Federal Standard:
- Fed. Std. No. 123 Marking for Shipment (Civil Agencies)<sup>7</sup>

#### 3. Terminology

3.1 Definitions:

3.1.1 *base box*, n—a unit of area equivalent to 112 sheets 14 by 20 in. or 31 360 in.<sup>2</sup> (217.78 ft<sup>2</sup>) (see Annex A1).

3.1.2 base weight, n—a term used to describe the thickness of tin mill products. The designated base weight multiplied by a factor of 0.00011 is the nominal decimal thickness, in inches of the material. Although it is customary industry-wide to use the term "pound" (for example, 75 lb), following the base weight designation, base weight is correctly used only to define nominal material thickness, and is not a measure of the weight of a base box.

3.1.3 *black plate*, *n*—light-gage, low-carbon, cold-reduced steel intended for use in the untinned state or for the production of other tin mill products. It is supplied only in a dry or oiled condition.

3.1.4 *box annealing*, *n*—a process involving slow heating of coils to a subcritical temperature, holding, and cooling therefrom, to soften the strip and relieve stresses produced during cold reduction. It is accomplished in a sealed container. By introducing and maintaining an inert or slightly reducing atmosphere during the cycle, a relatively bright surface is obtained.

3.1.5 bright finish, n—a surface that has a melted tin coating.

3.1.6 *bundle*, *n*—a unit containing two or more packages of a cut size, supported by a platform, generally consisting of ten or more packages. (Also commonly referred to as a multiple-package lift containing two or more packages.)

Copyright © ASTM International, 100 Barr Harbor Drive, PO Box C700, West Conshohocken, PA 19428-2959, United States

<sup>&</sup>lt;sup>1</sup> This specification is under the jurisdiction of ASTM Committee A01 on Steel, Stainless Steel, and Related Alloys and is the direct responsibility of Subcommittee A01.20 on Tin Mill Products.

Current edition approved September 10, 2003. Published November 2003. Originally approved in 1968. Last previous edition approved in 2002 as A 623 - 02a.

<sup>&</sup>lt;sup>2</sup> Annual Book of ASTM Standards, Vol 01.03.

<sup>&</sup>lt;sup>3</sup> Annual Book of ASTM Standards, Vol 01.05.

<sup>&</sup>lt;sup>4</sup> Annual Book of ASTM Standards, Vol 01.06.

<sup>&</sup>lt;sup>5</sup> Annual Book of ASTM Standards, Vol 11.01.

<sup>&</sup>lt;sup>6</sup> Annual Book of ASTM Standards, Vol 03.01.

<sup>&</sup>lt;sup>7</sup> Available from Standardization Documents Order Desk, Bldg. 4 Section D, 700 Robbins Ave., Philadelphia, PA 19111-5094, Attn: NPODS.

3.1.7 *burr*, *n*—metal displaced beyond the plane of the surface by slitting or shearing (see 9.1.7 and 9.2.6).

3.1.8 *camber*, n—the greatest deviation of a coil edge from a straight line. The measurement is taken on the concave side and is the perpendicular distance from a straight line to the point of maximum deviation (see 9.1.9 and 9.2.7).

3.1.9 *chemical treatment, electrolytic tin plate, n*—a passivating chemical treatment applied to the surface of electrolytic tin plate to stabilize the plate surface characteristics compatible with a specified end use (see Annex A8 and Annex A10).

3.1.10 *chemically treated steel*, *n*—light-gage, low-carbon, cold-reduced steel that has a passivating or chemical treatment applied to the surface to provide rust resistance or retard underfilm corrosion, or both.

3.1.11 *cold reduction*—the process of reducing the thickness of the strip cold, generally accomplished by one rolling through a series of four-high mills arranged in tandem.

3.1.12 *continuous annealing*—a process consisting of passing the cold-reduced strip continuously and in a single thickness through a series of vertical passes within a furnace consisting of heating, soaking, and cooling zones to soften the strip and relieve stresses produced during cold reduction. An inert or slightly reducing atmosphere is maintained in the furnace to obtain a relatively bright strip.

3.1.13 *differentially coated tin plate*—electrolytic tin plate with a different weight of tin coating on each surface.

3.1.14 *double-reduced plate*—plate given a second major cold reduction following annealing.

3.1.15 *electrolytic chromium-coated steel*—light-gage, lowcarbon, cold-reduced steel on which chromium and chromium oxides have been electrodeposited.

3.1.16 *electrolytic tin plate*—light-gage, low-carbon, cold-reduced steel on which tin has been electrodeposited by an acid or alkaline process.

3.1.16.1 *J Plate*—electrolytic tin plate, No. 50 or heavier tin coating, with improved corrosion performance for some galvanic detinning food products as specified in the table following 3.1.16.2 and as measured by the Special Property Tests for Pickle Lag (*PL*) (see Annex A3), Iron Solution Values (*ISV*) (see Annex A5), Tin Crystal Size (*TCS*) (see Annex A4). The alloy layer is normally light in color, characteristic of the acid tinning process.

3.1.16.2 *K Plate*—electrolytic tin plate, No. 50 or heavier tin coating, with improved corrosion performance for some galvanic detinning food products as specified in the following table and as measured by the Special Property Tests for Pickle Lag (*PL*) (see Annex A3), Iron Solution Value (*ISV*) (see Annex A5), Tin Crystal Size (*TCS*) (see Annex A4), and Alloy Tin Couple (*ATC*) (see Annex A6) and Aerated Media Polarization (AMP) (see Annex A9).

Special Propertie	es Aims
Pickle Lag	10 s max
Iron Solution Value	20 µg Iron max
Tin Crystal Size	ASTM No. 9 or larger
Alloy Tin Couple <sup>A</sup>	0.12 µA/cm <sup>2</sup> max

 $^A$  Good mill practice has demonstrated the ability to average 0.05  $\mu\text{A/cm}^2$  or less over an extended period of production.

3.1.16.3 The production of J Plate and K Plate require special processing and testing. In order to receive J Plate or K Plate, this requirement must be specified on the order.

3.1.17 *length dimension*—the longer dimension of a cut size.

3.1.18 *lot*—each 20 000 sheets or part thereof or the equivalent in coils, of an item in a specific shipment having the same order specifications.

3.1.19 *matte finish*—a surface that has an unmelted tin coating, generally on a shot-blast finish (SBF) base steel.

3.1.20 *mechanical designation*—an arbitrary number to designate Rockwell hardness and ultimate tensile strength characteristics for double-reduced plate (see 8.2).

3.1.21 *oiling*—a lubricant film applied to both surfaces of the plate.

3.1.22 package—a unit quantity of 112 sheets.

3.1.23 *passivating treatment*—a surface chemical treatment (see 3.1.9).

3.1.24 *ratio*—the number of base boxes in a package of a given size (see 3.1.1 and Annex A1).

3.1.25 *Rockwell hardness test*—a test for determining hardness (see Annex A2).

3.1.26 *rolling width*—the dimension of the sheet perpendicular to the rolling direction.

3.1.27 *single-reduced plate*—plate produced with one major cold reduction.

3.1.28 *steel Type D*—base-metal steel aluminum killed, sometimes required to minimize severe fluting and stretcherstrain hazards or for severe drawing applications (see Table 1).

3.1.29 *steel Type L*—base-metal steel, low in metalloids and residual elements, sometimes used for improved internal corrosion resistance for certain food-product containers (see Table 1).

3.1.30 *steel Type MR*—base-metal steel, similar in metalloid content to Type L but less restrictive in residual elements, commonly used for most tin mill products (see Table 1).

3.1.31 *surface appearance*—visual characteristics determined primarily by the steel surface finish. For electrolytic tin plate, the appearance is also influenced by the weight of coating and by melting or not melting the tin coating.

TABLE 1 Chem	ical Requirements	for Tin	Mill Products
--------------	-------------------	---------	---------------

Element	Cast	Composition, m	iax %
Element	Type D	Type L	Type MR
Carbon	0.12	0.13	0.13
Manganese	0.60	0.60	0.60
Phosphorus	0.020	0.015	0.020
Sulfur	0.03	0.03	0.03
Silicon <sup>A,B</sup>	0.020	0.020	0.020
Copper	0.20	0.06	0.20
Nickel	0.15	0.04	0.15
Chromium	0.10	0.06	0.10
Molybdenum	0.05	0.05	0.05
Aluminum <sup>C</sup>	0.20	0.10	0.20
Other elements, each	0.02	0.02	0.02

 $^{A}\!When$  steel produced by the silicon killed method is ordered, the silicon maximum may be increased to 0.080 %.

<sup>b</sup>When strand cast steel produced by the aluminum killed method is ordered or furnished, the silicon maximum may be increased to 0.030 % when approved by the purchaser.

<sup>C</sup>Types L and MR may be supplied as non-killed or killed which would respectively be produced without and with aluminum additions. Minimum aluminum level for Type D is usually 0.02 %.

3.1.32 *surface finishes*—steel surface finishes for tin mill products imparted by the finishing-mill work rolls. These may be either ground or blasted-roll finishes.

3.1.33 *temper designation*—an arbitrary number to designate a Rockwell hardness range for single-reduced products which indicates the forming properties of the plate (see Section 8 and Tables 2 and 3).

3.1.34 *temper mill*—a mill for rolling basemetal steel after annealing to obtain proper temper, flatness, and surface finish. It may consist of one stand or two stands arranged in tandem.

3.1.35 *tin coating weight*—the weight of tin applied to the steel surface, usually stated as pounds per base box, distributed evenly over both surfaces of a base box, the total coated area being 62 720 in.<sup>2</sup> Thus 0.25 lb/bb has a nominal weight of 0.125 lb on each of the two surfaces. Frequently, the coating is referred to as a designation number, and the decimal point is omitted. Thus, 0.25 lb/bb is 25.

3.1.35.1 For differentially coated tin plate, twice the nominal coating weight on each side is designated, usually by the number method; hence, 10/25 designates the nominal weight of 0.05 lb/bb on one side and 0.125 lb/bb on the other side.

3.1.36 *vapor vacuum deposition*—the condensation and solidification of the metal or metal containing vapors, under high vacuum, to form deposits onto a steel surface.

3.1.37 *width dimension*—the shorter dimension of a cut size.

#### 4. Base Metal

4.1 The steel shall be made by the open-hearth, electricfurnace, or basic-oxygen process.

#### TABLE 2 Temper Designations and Hardness Values Single-Reduced Tin Mill Products — Box Annealed

NOTE 1—Thinner plate (0.0083 in. ordered thickness and lighter) is normally tested using the Rockwell 15T scale and the results converted to the Rockwell 30T scale (see Annex A2 and Table A2.1).

Temper Desig-	Rockwell Hardne All Thicknesses		Characteristics and Typical
nation	Nominal	Range	End Uses
T-1 (T49)	49	45–53	soft for drawing parts such as nozzles, spouts, and oil filter shells
T-2 (T53)	53	49–57	moderately soft for drawing shallow parts such as rings, plugs, and pie pans
T-3 (T57)	57	53–61	fairly stiff for parts such as can ends and bodies, closures, and crown caps
T-4 (T61)	61	57–65	increased stiffness for can ends and bodies, crown caps, and large closures

 $^{A}\text{These}$  ranges are based on the use of the diamond spot anvil and a  $1\!\!\!/_{16}$  in. hardened steel ball indenter.

#### TABLE 3 Temper Designations and Hardness Values Single-Reduced Tin Mill Products—Continuously Annealed

NOTE 1—Thinner plate (0.0083-in. ordered thickness and lighter) is normally tested using the Rockwell 15T scale and the results converted to the Rockwell 30T scale (see Annex A2 and Table A2.1).

Temper Designation	Rockwell Hard All Thickness		Characteristics and Typical
Designation	Nominal	Range	End Oses
T-1	49	45–53	soft for drawing parts such as nozzles, spouts, and oil filter shells
T-2	53	49–57	moderately soft for drawing shallow parts such as rings, plugs, and pie pans
T-3 (T57)	57	53–61	moderate stiffness for parts such as can ends and bodies, closures, and crown caps
T-4 (T61)	61	57–65	increased stiffness for can ends, drawn (and ironed) can bodies, and large closures
T-5 (T65)	65	61–69	moderately high stiffness for can ends and bodies

<sup>A</sup> These ranges are based on the use of the diamond spot anvil and a ¼<sub>16</sub> in. hardened steel ball indenter. Test Conditions:

1. For referee purposes, samples of blackplate, unreflowed ETP, and ECCS shall be aged prior to testing by holding at  $400^{\circ}$ F for 10 min.

2. The hardness test area on material produced with SBF or equivalent rolls shall be sanded smooth on both surfaces.

3. To avoid incorrect results due to the cantilever effect, samples shall have an area no larger than 4 in.<sup>2</sup> and the point of testing shall be no more than  $\frac{1}{2}$  in. off the center of the samples.

#### 5. Chemical Composition

5.1 The steel shall conform to the chemical composition requirements as prescribed in Table 1 except as otherwise agreed upon between the manufacturer and the purchaser.

#### 6. Cast or Heat Analysis

6.1 For Type D, MR, and L an analysis of each heat of steel shall be made by the supplier to determine the percentage of carbon, manganese, phosphorus, sulfur, silicon, and residual elements shown in Table 1. Other elements, unless agreed upon between the manufacturer and the purchaser, individually shall not exceed 0.02 %, maximum and while not necessarily analyzed are dependent on the suppliers' practices and controls.

#### 7. Product Analysis

7.1 Rimmed or capped steels are characterized by a lack of uniformity in their chemical composition, and for this reason, product analysis is not technologically appropriate unless misapplication is clearly indicated.

#### 8. Mechanical Requirements

8.1 *Single-Reduced Tin Mill Products, Temper*—The term *temper* when applied to single-reduced tin mill products summarizes a combination of interrelated mechanical properties. No single mechanical test can measure all the various factors which contribute to the fabrication characteristics of the material. The Rockwell 30T hardness value is a quick test which serves as a guide to the properties of the plate. This test forms the basis for a system of temper designations as shown in Tables 2 and 3. A given temper shall have hardness values

Test conditions:

<sup>1.</sup> For referee purposes, samples of blackplate, unreflowed ETP, and ECCS shall be aged prior to testing by holding at 400°F for 10 min.

<sup>2.</sup> The hardness test area on material produced with SBF or equivalent rolls shall be sanded smooth on both surfaces.

<sup>3.</sup> To avoid incorrect results due to the cantilever effect, samples shall have an area no larger than 4 in.<sup>2</sup> and the point of testing shall be no more than  $\frac{1}{2}$  in. off the center of the samples.

meeting the limits shown. The mechanical properties of continuously annealed plate and batch annealed plate of the same Rockwell 30T temper designation are not identical. It is important to keep in mind that the Rockwell 30T test does not measure all the various factors which contribute to the fabrication characteristics of the plate.

8.2 Double-Reduced Tin Mill Products, Mechanical Characteristics—No test or group of tests have been developed that adequately predict the fabricating performance of double-reduced tin mill products. Designations for mechanical properties showing typical applications are arranged in generally ascending level of strength as shown in Table 4.

8.3 Rockwell testing shall be in accordance with the latest revision of Test Methods and Definitions A 370 and Test Methods E 18 (see Annex A2).

#### 9. Permissible Variation in Dimensions

#### 9.1 Dimensional Characteristics, Coils:

9.1.1 Thickness, Method for Determination—When the purchaser wishes to make tests to ascertain compliance with the requirements of this specification for thickness of an item in a specific shipment of tin mill products in coils having the same order specification, the following procedure shall be used: Random and representative measurements using a hand micrometer must be made throughout the coil length. Measurements may be made at any location across the coil width except within 1 in. from the mill trimmed edge. The hand micrometers are assumed to be accurate to  $\pm 0.0001$  in. No measurements are to be made within 3 ft of a weld.

9.1.2 *Thickness Tolerances* shall conform to those prescribed in Table 5 (also see Table 6).

9.1.3 *Transverse Thickness Profile* is the change in sheet thickness from strip center to edge at right angles to the rolling direction. Thickness measured near the edge is normally less than the center thickness. The gage measured 1/4 in. in from the mill trimmed edge shall be no more than either 13 % below the ordered thickness or 10 % less than the center thickness of the individual sheet being measured. Common components of transverse thickness profile are crown and feather edge.

#### TABLE 4 Mechanical Designations Double-Reduced Tin Mill Products

NOTE 1—Thinner plate (0.0083 in. ordered thickness and lighter) is normally tested using Rockwell 15T scale and the results converted to the Rockwell 30T scale (see Annex A2 and Table A2.1).

Designa- tion	Nominal Longitudinal Ultimate Tensile Strengh psi	Nominal Rockwell Hardness HR30-T <sup>4</sup>	Examples of Usage
DR-7.5	75 000	71	can bodies
DR-8	80 000	72	can bodies and ends
DR-8.5	85 000	73	can bodies and ends
DR-9	90 000	75	can bodies and ends
DR-9.5	95 000	76	can ends

<sup>A</sup> These values are based on the use of the diamond spot anvil and a 1/16 in. hardened steel ball indenter. Testing will be in accordance with Test Methods and Definitions A 370. Rockwell values are too varied to permit establishment of ranges. For details see *AISI Contributions to the Metallurgy of Steel*, "Survey of Mechanical Properties of Double Reduced Tin Plate," January 1966.

#### TABLE 5 Thickness Tolerances

NOTE 1—When coils are specified, this does not afford the supplier the opportunity to discard all off-gage product and for that reason the following thickness tolerances are applicable for various lot sizes.

Lot Size, Ib	Tolerance
0 to 12 000	95 % of the product of the coils shall be within the tolerances stated in Table 6
Over 12 000 to 30 000	97.5 % of the product of the coils shall be within the tolerances stated in Table 6
Over 30 000 to 150 000	99.0 % of the product of the coils shall be within the tolerances stated in Table 6
Over 150 000	99.5 % of the product of the coils shall be within the tolerances stated in Table 6

#### TABLE 6 Ordered Thickness and Thickness Tolerances

Note 1—Thickness tolerances are +5 % and –8 % from the ordered thickness.

Ordered	Thickness	Thickness
Thickness,	Tolerance,	Tolerances
in.	Over, in.	Under, in.
0.0050	0.0003	0.0004
0.0055	0.0003	0.0004
0.0061	0.0003	0.0005
0.0066	0.0003	0.0005
0.0072	0.0004	0.0006
0.0077	0.0004	0.0006
0.0083	0.0004	0.0007
0.0088	0.0004	0.0007
0.0094	0.0005	0.0008
0.0099	0.0005	0.0008
0.0105	0.0005	0.0008
0.0110	0.0006	0.0009
0.0113	0.0006	0.0009
0.0118	0.0006	0.0009
0.0123	0.0006	0.0010
0.0130	0.0007	0.0010
0.0141	0.0007	0.0011
0.0149	0.0007	0.0012

#### 0-42ce-4197-99e7-8c1b68cc67ff/astm-a623-03

9.1.4 *Crown* is the difference in strip thickness from the center of roll width and the locations 1 in. in from both mill-trimmed edges.

9.1.5 *Feather Edge* is the maximum difference in thickness across the strip width between points measured at  $\frac{1}{4}$  in. and 1 in. from both mill-trimmed edges. The thickness  $\frac{1}{4}$  in. from an edge is usually less than the thickness measured 1 in. or more from the same edge.

9.1.6 *Width*—Coils are trimmed to  $\frac{1}{4}$  in. over the ordered width. The slit dimension shall not vary over the designated overrun by more than -0,  $+\frac{1}{8}$  in.

9.1.7 Burr-A maximum of 0.002 in. is permissible.

9.1.8 *Coil Length*—Variation between the measured length by the purchaser versus the supplier's billed length shall not exceed the limits prescribed in Table 7.

9.1.8.1 Since it is a common practice for each consumer's shearing operation to keep a running measurement of their supplier's coil shipments, any length variation in small lots (1

TABLE 7 Coil Length Variation

No. of Coils	Variation, ±, %
1	3
100	0.1

to 5 coils) for a given period will automatically be included in this summary. Before concluding there is a length variation in these small lots the total length received from the supplier, regardless of base weight, over periods of one month or one quarter, or both should be checked.

9.1.9 *Camber* is limited to a maximum of  $\frac{1}{4}$  in. in 20 ft of length, in accordance with the latest revision of measuring methods and definitions in Test Method A 987.

9.1.10 *Inside Coil Diameters*—The standard inside diameter produced is approximately 16 in.

9.2 Dimensional Characteristics, Cut Sizes:

9.2.1 Thickness, Method for Determination—Random measurements must be made at least 1 in. from the edge of the sheet using a hand micrometer. The hand micrometers are assumed to be accurate to  $\pm 0.0001$  in.

9.2.2 *Thickness Tolerances*—Tin mill products in cut sizes are produced within thickness tolerances of +5 %, -8 % of the ordered thickness (see Table 6). Any sheets not meeting this requirement are subject to rejection.

9.2.3 Transverse Thickness Profile is the change in sheet thickness from strip center to edge at right angles to the rolling direction. Thickness measured near the edge is normally less than the center thickness. The gage measured  $\frac{1}{4}$  in. in from the mill trimmed edge shall be no more than either 13 % below the ordered thickness or 10 % less than the center thickness of the individual sheet being measured. Common components of transverse thickness profile are crown and feather edge.

9.2.4 *Crown* is the difference in strip thickness from the center of roll width and the locations 1 in. in from both mill-trimmed edges.

9.2.5 *Feather Edge* is the maximum difference in thickness across the strip width between points measured at  $\frac{1}{4}$  in. and 1 in. from both mill-trimmed edges. The thickness  $\frac{1}{4}$  in. from an edge is usually less than the thickness measured 1 in. or more from the same edge.

9.2.6 Burr-A maximum of 0.002 in. is permissible.

9.2.7 *Camber*—The maximum permissible deviation is  $\frac{1}{16}$  in. for each 48 in. of length or fraction thereof, in accordance with the latest revision of measuring methods and definitions in Test Method A 987.

9.2.8 *Out-of-Square* is the deviation of an end edge from a straight line which is placed at a right angle to the side of the plate, touching one corner and extending to the opposite side. The amount of deviation is customarily limited to  $\frac{1}{16}$  in. for any edge measurement, except that a bundle may contain a maximum of four sheets with a deviation up to  $\frac{1}{8}$  in.

9.2.9 Shearing Practice—Tin mill products are sheared to  $\frac{1}{8}$  in. over the ordered width and  $\frac{1}{4}$  in. over the ordered length. The greater dimension is considered length. The slit dimension shall not vary over the designated overrun by more than -0,  $+\frac{1}{8}$  in. and the drum cut dimension shall not vary over the designated overrun by more than -0,  $+\frac{1}{4}$  in.

#### **10. Special Requirements**

10.1 *Welds*—Coils may contain lap or mash welds, the locations of which are marked. A hole may be punched adjacent to the weld for automatic rejection of the weld during shearing. The leading ends of lap welds shall not exceed 1 in.

10.2 *Cores*—If coil centers must be supported to minimize damage, this requirement should be so stated on the order as a special requirement.

#### 11. Sheet Count—Cut Sizes

11.1 Small variations in sheet count/bundle should average out to at least the proper exact count in quantities of 400 packages or more.

#### **12. Retest Procedure**

12.1 In the event the material fails to meet the specified requirements, two further series of samples are to be selected by the purchaser in accordance with the applicable procedures. Both retests must meet the specification limits to qualify as meeting the requirements.

#### 13. Conditions of Manufacture

13.1 The purchaser should be informed of any alterations in the method of manufacture which will significantly affect the properties of the purchased product. Similarly, the purchaser should inform the manufacturer of modifications in their fabrication methods which will significantly affect the way in which the purchased product is used.

#### 14. Inspection

14.1 The inspector representing the purchaser shall have entry, at all times while work on the contract of the purchaser is being performed, to all parts of the manufacturer's works that concern the manufacture of the material ordered. The supplier shall afford the inspector all reasonable facilities to satisfy him that the material is being furnished in accordance with this specification. Unless otherwise specified, all inspection and tests shall be made prior to shipment at the supplier's works and such inspection or sampling shall be made in conjunction with and to the extent of the manufacturer's regular inspection operations.

#### 15. Rejection

15.1 Material that shows excessive number of injurious imperfections subsequent to its acceptance at the manufacturer's works, except as noted in the basis of purchase of the applicable specification, shall be rejected and the supplier notified.

#### 16. Packaging

16.1 Unless otherwise specified, the tin plate shall be packaged and loaded in accordance with Practices A 700.

16.2 When specified in the contract or order, and for direct procurement by or direct shipment to the Government, when Level A is specified, preservation, packaging and packing shall be in accordance with the Level A requirements of MIL-STD-163.

16.3 The standard method of shipping coils is with the eye of the coil vertical.

### A 623 – 03

#### 17. Marking

17.1 As a minimum requirement, the material shall be identified by having the manufacturer's name, ASTM designation, weight, purchaser's order number, and material identification legibly stenciled on top of each lift or shown on a tag attached to each coil or shipping unit.

17.2 When specified in the contract or order, and for direct procurement by or direct shipment to the Government, marking

for shipment, in addition to requirements specified in the contract or order, shall be in accordance with MIL-STD-129 for military agencies and in accordance with Federal Std. No. 123 for civil agencies.

#### 18. Keywords

18.1 tin mill products

### ANNEXES

#### (Mandatory Information)

#### A1. ABBREVIATED RATIO TABLES FOR TIN MILL PRODUCTS

A1.1 The base box is the unit of area of 112 sheets 14 by 20 in. or 31 360 in. $^{2}(217.78 \text{ ft}^{2})$ .

A1.2 To determine the number of base boxes represented by 112 sheets of any other dimensions, a computation is necessary. The computation is carried out using ratio tables.

A1.2.1 Tables A1.1-A1.6<sup>8</sup> are an abbreviated set of such ratio tables which can be used to determine the number of base boxes represented by 112 and 1000 sheets in sizes from  $\frac{1}{16}$  in. square to 50 in. square.

A1.2.2 The following example demonstrates the use of these tables. The example applies to various sheet dimensions as follows:

A1.2.2.1 Sheet with No Fractional Dimensions—Step 1 only.

A1.2.2.2 Sheet with Fractional Dimensions on Only One Dimension—Steps 1 and 2.

A1.2.2.3 Sheet with Fractional Dimensions on Both Dimensions—Steps 1, 2, 3, and 4.

A1.2.3 An example of the use of abbreviated ratio tables to develop the number of base boxes represented by 112 and 1000 sheets with specified dimensions  $28\frac{1}{16}$  by  $34\frac{1}{2}$  in. is given in Table A1.7.

<u>ASTM A623-03</u>

https://standards.iteh.ai/catalog/standards/sist/aaccc2a9-42ce-4197-99e7-8c1b68cc67fl/astm-a623-03

<sup>&</sup>lt;sup>8</sup> These tables are reproduced, by permission of the American Iron and Steel Institute, from "Tin Mill Products," *Steel Products Manual*, AISI, 1963.

# ₩ A 623 – 03

Full-Inch Lengths	0	1	2	3	4	5	6	7	8	0
										9
1 2 3 4 5	.0000	.0036	.0071	.0107	.0143	.0179	.0214	.0250	.0286	.0321
2	.0000 .0000 .0000 .0000	.0071 .0107 .0143 .0179	.0143 .0214 .0286	.0214	.0143 .0286 .0429 .0571 .0714	.0357	.0429 .0643 .0857 .1071	.0500 .0750 .1000 .1250	.0571	.0643
4	0000	.0107	.0214	.0321 .0429 .0536	0571	.0536 .0714 .0893	.0643	.0750	.0857	.0964
5	0000	0179	.0280 .0357	.0429	0714	.0714	1071	.1000	.1143 $.1429$	.1286 .1607
		.0110			.0714					
6 7 9 10	.0000	.0214 .0250 .0286 .0321 .0357	.0429 .0500 .0571 .0643	.0643	.0857	.1071	.1286 .1500 .1714	.1500	.1714	.1929
7	.0000 .0000 .0000 .0000	.0250	.0500	.0750	.1000	.1250	.1500	.1750	.2000	.2250
8	.0000	.0286	.0571	.0857	.1143	.1429	.1714	.2000	.2286	.2571
-9	.0000	.0321	.0643	.0964	.1286	.1607	.1929 .2143	.2250	.2571	.2893
10			.0714	.0643 .0750 .0857 .0964 .1071	.0857 .1000 .1143 .1286 .1429	.1071 .1250 .1429 .1607 .1786		$.1500 \\ .1750 \\ .2000 \\ .2250 \\ .2500 \\$	.1714 .2000 .2286 .2571 .2857	.1323 .2250 .2571 .2893 .3214
11 12 13 14 15	.0000 .0000 .0000 .0000	.0393 .0429 .0464 .0500	.0786	.1179	.1571	$.1964 \\ .2143 \\ .2321 \\ .2500$	.2357	.2750	.3143 .3429 .3714 .4000	.3536
12	.0000	.0429	.0857 .0929 .1000	.1286	.1714	.2143	.2571	.3000	.3429	.3857
13	.0000	.0464	.0929	.1393	.1857	.2321	.2786	.3250	.3714	.4179
14	.0000	.0500	.1000	.1500	.2000	.2500	.3000	.3500	.4000	.4500
15	.0000	.0536	.1071	.1179 .1286 .1393 .1500 .1607	.1571 .1714 .1857 .2000 .2143	.2679	$\begin{array}{r} .2357\\ .2571\\ .2786\\ .3000\\ .3214\end{array}$	$\begin{array}{r} .2750\\ .3000\\ .3250\\ .3500\\ .3750\end{array}$	.4286	.4500 .4821
16	.0000	.0571	.1143 .1214 .1286 .1357		2286	2857	3429		4571	.5143
17	.0000	.0607	.1214	.1821	.2429	3036	3643	4250	4857	.5464
18	.0000	.0643	.1286	.1929	.2571	.3214	.3857	.4500	.4571 .4857 .5143 .5429	.5786
19	.0000	.0679	.1357	.2036	.2714	.3393	.4071	.4750	.5429	.5786 .6107
16 17 18 19 20	.0000 .0000 .0000 .0000 .0000	.0571 .0607 .0643 .0679 .0714	.1429	$\begin{array}{r} .1714\\ .1821\\ .1929\\ .2036\\ .2143\end{array}$	$\begin{array}{r} .2286\\ .2429\\ .2571\\ .2714\\ .2857\end{array}$	$\begin{array}{r} .2857\\ .3036\\ .3214\\ .3393\\ .3571 \end{array}$	.3429 .3643 .3857 .4071 .4286	$\begin{array}{r} .4000\\ .4250\\ .4500\\ .4750\\ .5000\end{array}$	.5714	.6429
21		0750	.1500		2000	9750				.6750
22	.0000 .0000 .0000 .0000	0786	1571	2257	31/12	2020	.4500 .4714 .4929 .5143	.5200	.6000 .6286 .6571 .6857	.7071
23	.0000	0821	1643	2464	3286	4107	1920	5750	.0280	.7393
24	.0000	.0857	1714	2571	3429	4286	5143	6000	6857	.7714
21 22 23 24 25	.0000	.0750 .0786 .0821 .0857 .0893	$.1571 \\ .1643 \\ .1714 \\ .1786$	$\begin{array}{r} .2250\\ .2357\\ .2464\\ .2571\\ .2679\end{array}$	$\begin{array}{r} .3000\\ .3143\\ .3286\\ .3429\\ .3571 \end{array}$	$\begin{array}{r} .3750\\ .3929\\ .4107\\ .4286\\ .4464\end{array}$	.5357	.5250 .5500 .5750 .6000 .6250	.7143	.8036
		0090		0700		4040		CE00		
20	.0000	.0929	1020	.2780	.3714	.4043	.0071	.6500	.7429	.8357 .8679
28	0000	1000	2000	2000	.3001	5000	.5160	.0150	8000	.0019
29	.0000 .0000 .0000 .0000	1036	2071	3107	4143	5179	6214	7250	8286	9321
26 27 28 29 30	.0000	.0929 .0964 .1000 .1036 .1071	.1857 .1929 .2000 .2071 .2143	.2786 .2893 .3000 .3107 .3214	.3714 .3857 .4000 .4143 .4286	$\begin{array}{r}.4643\\.4821\\.5000\\.5179\\.5357\end{array}$	$\begin{array}{r} .5571 \\ .5786 \\ .6000 \\ .6214 \\ .6429 \end{array}$	.6500 .6750 .7000 .7250 .7500	.7429 .7714 .8000 .8286 .8571	.9000 .9321 .9643
		1105	0014	0001	1100					
31 32 33 34 35	.0000 .0000 .0000 .0000	.1107 .1143 .1179 .1214 .1250	.2214 .2286 .2357 .2429	$\begin{array}{r} .3321\\ .3429\\ .3536\\ .3643\\ .3750\end{array}$	.4429 .4571 .4714 .4857 .5000	.5536 .5714 .5893 .6071 .6250	.6643 .6857 .7071 .7286 .7500	.7750 .8000 .8250 .8500 .8750	.8857 .9143 .9429 .9714 1.0000	$\begin{array}{r} .9964 \\ 1.0286 \\ 1.0607 \\ 1.0929 \\ 1.1250 \end{array}$
32	.0000	.1143	.2286	.3429	.45/1	.5714	.6857	.8000	.9143	1.0286
37	.0000	1914	.2357	.3536	4714	.5893	7071	.8250	.9429	1.0607
35	.0000	1250	.2429	3043	.4897	6950	7500	8750	.9714	1.0929
-		.1200		.0100				.0100	1.0000	1.1290
36 37 38	.0000 .0000 .0000 .0000	$\begin{array}{r} .1286\\ .1321\\ .1357\\ .1393\\ .1429\end{array}$	$\begin{array}{r} .2571 \\ .2643 \\ .2714 \\ .2786 \\ .2857 \end{array}$	.3857 .3964 .4071 .4179	.5143 .5286 .5429 .5571	$\begin{array}{r} .6429\\ .6607\\ .6786\\ .6964\end{array}$	.7714 .7929 .8143	.9000 .9250 .9500 .9750 1.0000	$1.0286 \\ 1.0571 \\ 1.0857 \\ 1.1143 \\ 1.1429$	$1.1571 \\ 1.1893 \\ 1.2214 \\ 1.2536 \\ 1.2857$
37	.0000	.1321	.2643	.3964	.5286	.6607	.7929	.9250	1.0571	1.1893
38	.0000	.1357	.2714	.4071	.5429	6786	.8143	.9500	1.0857	1.2214
39	.0000	.1393	.2786	.4179	.5571	.6964	.8357	9750	1.1143	1.2536
40	.0000			.4286	.5714	.7143	.8571	1.0000	1.1429	1.2857
41 42 43 44 45	.0000 .0000 .0000 .0000	$.1464 \\ .1500 \\ .1536 \\ .1571 \\ .1607$	.2929 .3000	.4393 .4500 .4607 .4714	.5857 .6000 .6143 .6286 .6429	.7321	$.8786 \\ .9000 \\ .9214 \\ .9429 \\ .9643$	1.0250	$\begin{array}{r} 1.1714 \\ 1.2000 \\ 1.2286 \\ 1.2571 \\ 1.2857 \end{array}$	1.3179
42	.0000	.1500	.3000	.4500	.6000	.7500	.9000	1.0500	1.2000	1.3500
43	.0000	.1536	.3071	.4607	.6143	.7679	.9214	1.0750	1.2286	1.3821
44	.0000	.1571	.3143	.4714	.6286	.7857	.9429	1.1000	1.2571	1.4143
45	.0000	.1607	.3071 .3143 .3214	.4821	.6429	.7321 .7500 .7679 .7857 .8036	.9643	$\begin{array}{c} 1.0250\\ 1.0500\\ 1.0750\\ 1.1000\\ 1.1250\end{array}$	1.2857	$\begin{array}{r} 1.3179 \\ 1.3500 \\ 1.3821 \\ 1.4143 \\ 1.4464 \end{array}$
45	.0000	.1643 .1679 .1714 .1750 .1786	.3286 .3357 .3429 .3500 .3571	.4929		.8214 .8393 .8571 .8750 .8929	.9857 1.0071 1.0286 1.0500 1.0714	$\begin{array}{r} 1.1500\\ 1.1750\\ 1.2000\\ 1.2250\\ 1.2500\end{array}$	$\begin{array}{r} 1.3143 \\ 1.3429 \\ 1.3714 \\ 1.4000 \\ 1.4286 \end{array}$	
45 47 48 49 50	.0000 .0000 .0000	.1679	.3357	.4929 .5036 .5143 .5250 .5357	.6571 .6714 .6857 .7000 .7143	.8393	1.0071	1.1750	1.3429	$1.4786 \\ 1.5107 \\ 1.5429 \\ 1.5750 \\ 1$
48	.0000	.1714	.3429	.5143	.6857	.8571	1.0286	1.2000	1.3714	1.5429
49	.0000	.1750	.3500	.5250	.7000	.8750	1.0500	1.2250	1.4000	1.5750
	.0000	1 = 0.0	05.54							1.6071

TABLE A1.1 Tin Plate Ratios—Base Boxes per 112 Sheets Full-Inch Widths

TABLE A1.1 Continued

Full-Inch Lengths										
Fel	10	11	12	13	14	15	16	17	18	19
10	.3571	.3929	.4286	.4643	.5000	.5357	.5714	.6071	.6429	.6786
11 12 13 14 15	$\begin{array}{r} .3929 \\ .4286 \\ .4643 \\ .5000 \\ .5357 \end{array}$	$\begin{array}{r} .4321\\ .4714\\ .5107\\ .5500\\ .5893\end{array}$	.4714 .5143 .5571 .6000 .6429	.5107 .5571 .6036 .6500 .6964	.5500 .6000 .6500 .7000 .7500	.5893 .6429 .6964 .7500 .8036	.6286 .6857 .7429 .8000 .8571	.6679 .7286 .7893 .8500 .9107	.7071 .7714 .8357 .9000 .9643	.7464 .8143 .8821 .9500 1.0179
16 17 18 19 20	.5714 .6071 .6429 .6786 .7143	$\begin{array}{r} .6286\\ .6679\\ .7071\\ .7464\\ .7857\end{array}$	.6857 .7286 .7714 .8143 .8571	.7429 .7893 .8357 .8821 .9286	$\begin{array}{r} .8000\\ .8500\\ .9000\\ .9500\\ 1.0000\end{array}$	$.8571 \\ .9107 \\ .9643 \\ 1.0179 \\ 1.0714$	$\begin{array}{r} .9143\\ .9714\\ 1.0286\\ 1.0857\\ 1.1429\end{array}$	$\begin{array}{r} .9714\\ 1.0321\\ 1.0929\\ 1.1536\\ 1.2143\end{array}$	$\begin{array}{c} 1.0286\\ 1.0929\\ 1.1571\\ 1.2214\\ 1.2857\end{array}$	$\begin{array}{r} 1.0857\\ 1.1536\\ 1.2214\\ 1.2893\\ 1.3571 \end{array}$
21 22 23 24 25	.7500 .7857 .8214 .8571 .8929	.8250 .8643 .9036 .9429 .9821	$\begin{array}{r} .9000\\ .9429\\ .9857\\ 1.0286\\ 1.0714\end{array}$	$\begin{array}{r} .9750\\ 1.0214\\ 1.0679\\ 1.1143\\ 1.1607\end{array}$	$\begin{array}{c} 1.0500\\ 1.1000\\ 1.1500\\ 1.2000\\ 1.2500 \end{array}$	$\begin{array}{c} 1.1250\\ 1.1786\\ 1.2321\\ 1.2857\\ 1.3393 \end{array}$	$\begin{array}{c} 1.2000\\ 1.2571\\ 1.3143\\ 1.3714\\ 1.4286\end{array}$	$\begin{array}{r} 1.2750 \\ 1.3357 \\ 1.3964 \\ 1.4571 \\ 1.5179 \end{array}$	$\begin{array}{r} 1.3500 \\ 1.4143 \\ 1.4786 \\ 1.5429 \\ 1.6071 \end{array}$	$\begin{array}{r} 1.4250\\ 1.4929\\ 1.5607\\ 1.6286\\ 1.6964 \end{array}$
26 27 28 29 30	$\begin{array}{r} .9286\\ .9643\\ 1.0000\\ 1.0357\\ 1.0714\end{array}$	$\begin{array}{r} 1.0214 \\ 1.0607 \\ 1.1000 \\ 1.1393 \\ 1.1786 \end{array}$	$\begin{array}{c} 1.1143 \\ 1.1571 \\ 1.2000 \\ 1.2429 \\ 1.2857 \end{array}$	$\begin{array}{r} 1.2071 \\ 1.2536 \\ 1.3000 \\ 1.3464 \\ 1.3929 \end{array}$	$\begin{array}{c} 1.3000\\ 1.3500\\ 1.4000\\ 1.4500\\ 1.5000\end{array}$	$\begin{array}{r} 1.3929 \\ 1.4464 \\ 1.5000 \\ 1.5536 \\ 1.6071 \end{array}$	$\begin{array}{r} 1.4857 \\ 1.5429 \\ 1.6000 \\ 1.6571 \\ 1.7143 \end{array}$	$\begin{array}{r} 1.5786 \\ 1.6393 \\ 1.7000 \\ 1.7607 \\ 1.8214 \end{array}$	$\begin{array}{r} 1.6714 \\ 1.7357 \\ 1.8000 \\ 1.8643 \\ 1.9286 \end{array}$	$\begin{array}{c} 1.7643 \\ 1.8321 \\ 1.9000 \\ 1.9679 \\ 2.0357 \end{array}$
31 32 33 34 35	$\begin{array}{r} 1.1071 \\ 1.1429 \\ 1.1786 \\ 1.2143 \\ 1.2500 \end{array}$	$\begin{array}{r} 1.2179 \\ 1.2571 \\ 1.2964 \\ 1.3357 \\ 1.3750 \end{array}$	$\begin{array}{c} 1.3286\\ 1.3714\\ 1.4143\\ 1.4571\\ 1.5000 \end{array}$	$\begin{array}{r} 1.4393 \\ 1.4857 \\ 1.5321 \\ 1.5786 \\ 1.6250 \end{array}$	$\begin{array}{c} 1.5500 \\ 1.6000 \\ 1.6500 \\ 1.7000 \\ 1.7500 \end{array}$	$\begin{array}{r} 1.6607 \\ 1.7143 \\ 1.7679 \\ 1.8214 \\ 1.8750 \end{array}$	$\begin{array}{r} 1.7714\\ 1.8286\\ 1.8857\\ 1.9429\\ 2.0000\end{array}$	$\begin{array}{r} 1.8821 \\ 1.9429 \\ 2.0036 \\ 2.0643 \\ 2.1250 \end{array}$	$\begin{array}{r} 1.9929 \\ 2.0571 \\ 2.1214 \\ 2.1857 \\ 2.2500 \end{array}$	$\begin{array}{r} 2.1036\\ 2.1714\\ 2.2393\\ 2.3071\\ 2.3750\end{array}$
36 37 38 39 40	$\begin{array}{r} 1.2857 \\ 1.3214 \\ 1.3571 \\ 1.3929 \\ 1.4286 \end{array}$	$\begin{array}{c} 1.4143 \\ 1.4536 \\ 1.4929 \\ 1.5321 \\ 1.5714 \end{array}$	$\begin{array}{r} 1.5429 \\ 1.5857 \\ 1.6286 \\ 1.6714 \\ 1.7143 \end{array}$	$\begin{array}{r} 1.6714 \\ 1.7179 \\ 1.7643 \\ 1.8107 \\ 1.8571 \end{array}$	$\begin{array}{c} 1.8000 \\ 1.8500 \\ 1.9000 \\ 1.9500 \\ 2.0000 \end{array}$	$\begin{array}{c} 1.9286 \\ 1.9821 \\ 2.0357 \\ 2.0893 \\ 2.1429 \end{array}$	$\begin{array}{r} 2.0571 \\ 2.1143 \\ 2.1714 \\ 2.2286 \\ 2.2857 \end{array}$	$\begin{array}{r} 2.1857 \\ 2.2464 \\ 2.3071 \\ 2.3679 \\ 2.4286 \end{array}$	$\begin{array}{r} \textbf{2.3143} \\ \textbf{2.3786} \\ \textbf{2.4429} \\ \textbf{2.5071} \\ \textbf{2.5714} \end{array}$	$\begin{array}{r} 2.4429 \\ 2.5107 \\ 2.5786 \\ 2.6464 \\ 2.7143 \end{array}$
41 42 43 44 45	$\begin{array}{c} 1.4643 \\ 1.5000 \\ 1.5357 \\ 1.5714 \\ 1.6071 \end{array}$	$\begin{array}{c} 1.6107 \\ 1.6500 \\ 1.6893 \\ 1.7286 \\ 1.7679 \end{array}$	$\begin{array}{r} 1.7571 \\ 1.8000 \\ 1.8429 \\ 1.8857 \\ 1.9286 \end{array}$	$\begin{array}{c} 1.9036 \\ 1.9500 \\ 1.9964 \\ 2.0429 \\ 2.0893 \end{array}$	$\begin{array}{r} 2.0500\\ 2.1000\\ 2.1500\\ 2.2000\\ 2.2500 \end{array}$	$\begin{array}{r} 2.1964 \\ 2.2500 \\ 2.3036 \\ 2.3571 \\ 2.4107 \end{array}$	$\begin{array}{r} 2.3429 \\ 2.4000 \\ 2.4571 \\ 2.5143 \\ 2.5714 \end{array}$	$\begin{array}{r} 2.4893 \\ 2.5500 \\ 2.6107 \\ 2.6714 \\ 2.7321 \end{array}$	$\begin{array}{c} 2.6357\\ 2.7000\\ 2.7643\\ 2.8286\\ 2.8929\end{array}$	$\begin{array}{r} 2.7821 \\ 2.8500 \\ 2.9179 \\ 2.9857 \\ 3.0536 \end{array}$
46 47 48 49 50	$1.6429 \\ 1.6786 \\ 1.7143 \\ 1.7500 \\ 1.7857$	$\begin{array}{c} 1.8071 \\ 1.8464 \\ 1.8857 \\ 1.9250 \\ 1.9643 \end{array}$	$\begin{array}{c} 1.9714 \\ 2.0143 \\ 2.0571 \\ 2.1000 \\ 2.1429 \end{array}$	$\begin{array}{r} 2.1357 \\ 2.1821 \\ 2.2286 \\ 2.2750 \\ 2.3214 \end{array}$	$\begin{array}{r} 2.3000 \\ 2.3500 \\ 2.4000 \\ 2.4500 \\ 2.5000 \end{array}$	$\begin{array}{r} 2.4643\\ 2.5179\\ 2.5714\\ 2.6250\\ 2.6786\end{array}$	$\begin{array}{r} 2.6286\\ 2.6857\\ 2.7429\\ 2.8000\\ 2.8571 \end{array}$	$\begin{array}{r} 2.7929 \\ 2.8536 \\ 2.9143 \\ 2.9750 \\ 3.0357 \end{array}$	$\begin{array}{r} 2.9571 \\ 3.0214 \\ 3.0857 \\ 3.1500 \\ 3.2143 \end{array}$	$\begin{array}{r} 3.1214\\ 3.1893\\ 3.2571\\ 3.3250\\ 3.3929\end{array}$

## A 623 – 03

TABLE A1.1 Continued

-

Fuil-Inch Lengths										
Fen	20	21	22	23	24	25	26	27	28	29
20	1.4286	1.5000	1.5714	1.6429	1.7143	1.7857	1.8571	1.9286	2.0000	2.0714
21 22	$1.5000 \\ 1.5714$	$1.5750 \\ 1.6500$	$1.6500 \\ 1.7286$	$1.7250 \\ 1.8071$	$1.8000 \\ 1.8857$	$1.8750 \\ 1.9643$	$1.9500 \\ 2.0429$	$\begin{array}{c} 2.0250\\ 2.1214 \end{array}$	$2.1000 \\ 2.2000$	$2.1750 \\ 2.2786$
23	1.6429	1.7250	1.8071	1.8893	1.9714	2.0536	2.1357	2.2179	2.3000	2.3821
24 25	$1.7143 \\ 1.7857$	$1.8000 \\ 1.8750$	$1.8857 \\ 1.9643$	$\begin{array}{c} 1.9714 \\ 2.0536 \end{array}$	$\begin{array}{c} 2.0571 \\ 2.1429 \end{array}$	$\begin{array}{c} 2.1429 \\ 2.2321 \end{array}$	$\begin{array}{c} 2.2286\\ 2.3214\end{array}$	$\begin{array}{c} 2.3143 \\ 2.4107 \end{array}$	$\begin{array}{c} 2.4000 \\ 2.5000 \end{array}$	$2.4857 \\ 2.5893$
26	1.8571	$1.9500 \\ 2.0250$	$2.0429 \\ 2.1214$	$2.1357 \\ 2.2179$	$2.2286 \\ 2.3143$	$2.3214 \\ 2.4107$	$2.4143 \\ 2.5071$	$2.5071 \\ 2.6036$	$2.6000 \\ 2.7000$	$2.6929 \\ 2.7964$
27 28	$\begin{array}{c} 1.9286\\ 2.0000 \end{array}$	2.0250 2.1000	2.1214 2.2000	2.2179 2.3000	2.3143 2.4000	2.5000	2.5071 2.6000	2.0030 2.7000	2.8000	2.9000
29	2.0714	2.1750	2.2786	2.3821	2.4857	2.5893	2.6929	2.7964	2.9000	3.0036
30	2.1429	2.2500	2.3571	2.4643	2.5714	2.6786	2.7857	2.8929	3.0000	3.1071
31	2.2143	2.3250	2.4357	2.5464	2.6571	2.7679	2.8786	2.9893	3.1000	3.2107
32	2.2857	2.4000	$2.5143 \\ 2.5929$	$2.6286 \\ 2.7107$	$2.7429 \\ 2.8286$	$2.8571 \\ 2.9464$	$2.9714 \\ 3.0643$	$3.0857 \\ 3.1821$	$3.2000 \\ 3.3000$	$3.3143 \\ 3.4179$
33 34	$\begin{array}{c} 2.3571 \\ 2.4286 \end{array}$	$2.4750 \\ 2.5500$	2.5929 2.6714	2.7929	2.8280 2.9143	2.9464 3.0357	3.0643 3.1571	3.1821 3.2786	3.3000 3.4000	3.4179 3.5214
35	2.4280 2.5000	2.6250	2.7500	2.8750	3.0000	3.1250	3.2500	3.3750	3.5000	3.6250
36	2.5714	2.7000	2.8286	2.9571	3.0857	3.2143	3.3429	3.4714	3.6000	3.7286
37	2.6429	2.7750	2.9071	3.0393	3.1714	3.3036	3.4357	3.5679	3.7000	3.8321
38	2.7143	2.8500	$2.9857 \\ 3.0643$	$3.1214 \\ 3.2036$	$3.2571 \\ 3.3429$	$3.3929 \\ 3.4821$	$3.5286 \\ 3.6214$	$3.6643 \\ 3.7607$	$3.8000 \\ 3.9000$	$\begin{array}{c} 3.9357\\ 4.0393\end{array}$
39 40	$2.7857 \\ 2.8571$	$2.9250 \\ 3.0000$	3.0643 3.1429	3.2036 3.2857	3.3429 3.4286	3.4821 3.5714	3.7143	3.8571	4.0000	4.0393 4.1429
41 42	$2.9286 \\ 3.0000$	$3.0750 \\ 3.1500$	$\frac{3.2214}{3.3000}$	$3.3679 \\ 3.4500$	$3.5143 \\ 3.6000$	$3.6607 \\ 3.7500$	$3.8071 \\ 3.9000$	$3.9536 \\ 4.0500$	$4.1000 \\ 4.2000$	$4.2464 \\ 4.3500$
43	3.0000	3.1500 3.2250	3.3786	3.4300 3.5321	3.6857	3.8393	3.9929	4.0300 4.1464	4.3000	4.4536
44	3.1429	3.3000	3.4571	3.6143	3.7714	3.9286	4.0857	4.2429	4.4000	4.5571
<b>15</b>	3.2143	3.3750	3.5357	3.6964	3.8571	4.0179	4.1786	4.3393	4.5000	4.6607
46	3.2857	3.4500	3.6143	3.7786	3.9429	4.1071	4.2714	4.4357	4.6000	4.7643
47	3.3571	3.5250	3.6929	3.8607	4.0286	4.1964	4.3643	4.5321	4.7000	4.8679
48	3.4286	3.6000	3.7714	3.9429	4.1143	4.2857	4.4571	4.6286	4.8000	4.9714
49 50	3.5000	3.6750	3.8500	$4.0250 \\ 4.1071$	$4.2000 \\ 4.2857$	$4.3750 \\ 4.4643$	$4.5500 \\ 4.6429$	$4.7250 \\ 4.8214$	$4.9000 \\ 5.0000$	$5.0750 \\ 5.1786$
າບ	3.5714	3.7500	3.9286	4.1071	4.2007	4.4040	4.0443	4.0414	0.0000	0.1100

**Document Preview** 

### <u>ASTM A623-03</u>

https://standards.iteh.ai/catalog/standards/sist/aaccc2a9-42ce-4197-99e7-8c1b68cc67fl/astm-a623-03

	<b>A 623</b>	- 03
--	--------------	------

 TABLE A1.1
 Continued

Full-Inch Lengths											
23	30	31	32	33	34	35	36	37	38	39	
30	3.2143	3.3214	3.4286	3.5357	3.6429	3.7500	3.8571	3.9643	4.0714	4.1786	
31 32 33 34 35	3.3214 3.4286 3.5357 3.6429 3.7500	3.4321 3.5429 3.6536 3.7643 3.8750	$3.5429 \\ 3.6571 \\ 3.7714 \\ 3.8857 \\ 4.0000$	$\begin{array}{r} 3.6536 \\ 3.7714 \\ 3.8893 \\ 4.0071 \\ 4.1250 \end{array}$	3.7643 3.8857 4.0071 4.1286 4.2500	$\begin{array}{c} 3.8750 \\ 4.0000 \\ 4.1250 \\ 4.2500 \\ 4.3750 \end{array}$	$\begin{array}{c} 3.9857 \\ 4.1143 \\ 4.2429 \\ 4.3714 \\ 4.5000 \end{array}$	$\begin{array}{r} 4.0964 \\ 4.2286 \\ 4.3607 \\ 4.4929 \\ 4.6250 \end{array}$	$\begin{array}{r} 4.2071 \\ 4.3429 \\ 4.4786 \\ 4.6143 \\ 4.7500 \end{array}$	$\begin{array}{r} 4.3179 \\ 4.4571 \\ 4.5964 \\ 4.7357 \\ 4.8750 \end{array}$	
36 37 38 39 40	$\begin{array}{r} 3.8571 \\ 3.9643 \\ 4.0714 \\ 4.1786 \\ 4.2857 \end{array}$	$\begin{array}{r} 3.9857 \\ 4.0964 \\ 4.2071 \\ 4.3179 \\ 4.4286 \end{array}$	$\begin{array}{r} 4.1143 \\ 4.2286 \\ 4.3429 \\ 4.4571 \\ 4.5714 \end{array}$	$\begin{array}{r} 4.2429\\ 4.3607\\ 4.4786\\ 4.5964\\ 4.7143\end{array}$	$\begin{array}{r} 4.3714\\ 4.4929\\ 4.6143\\ 4.7357\\ 4.8571\end{array}$	$\begin{array}{r} 4.5000 \\ 4.6250 \\ 4.7500 \\ 4.8750 \\ 5.0000 \end{array}$	$\begin{array}{r} 4.6286\\ 4.7571\\ 4.8857\\ 5.0143\\ 5.1429\end{array}$	$\begin{array}{r} 4.7571 \\ 4.8893 \\ 5.0214 \\ 5.1536 \\ 5.2857 \end{array}$	$\begin{array}{r} 4.8857\\ 5.0214\\ 5.1571\\ 5.2929\\ 5.4286\end{array}$	$\begin{array}{c} 5.0143 \\ 5.1536 \\ 5.2929 \\ 5.4321 \\ 5.5714 \end{array}$	
41 42 43 44 45	$\begin{array}{r} 4.3929\\ 4.5000\\ 4.6071\\ 4.7143\\ 4.8214\end{array}$	$\begin{array}{r} 4.5393 \\ 4.6500 \\ 4.7607 \\ 4.8714 \\ 4.9821 \end{array}$	$\begin{array}{r} 4.6857\\ 4.8000\\ 4.9143\\ 5.0286\\ 5.1429\end{array}$	$\begin{array}{r} 4.8321 \\ 4.9500 \\ 5.0679 \\ 5.1857 \\ 5.3036 \end{array}$	$\begin{array}{r} 4.9786\\ 5.1000\\ 5.2214\\ 5.3429\\ 5.4643\end{array}$	$\begin{array}{c} 5.1250 \\ 5.2500 \\ 5.3750 \\ 5.5000 \\ 5.6250 \end{array}$	$\begin{array}{c} 5.2714 \\ 5.4000 \\ 5.5286 \\ 5.6571 \\ 5.7857 \end{array}$	$\begin{array}{r} 5.4179 \\ 5.5500 \\ 5.6821 \\ 5.8143 \\ 5.9464 \end{array}$	$5.5643 \\ 5.7000 \\ 5.8357 \\ 5.9714 \\ 6.1071$	$\begin{array}{c} 5.7107 \\ 5.8500 \\ 5.9893 \\ 6.1286 \\ 6.2679 \end{array}$	
46 47 48 49 50	$\begin{array}{r} 4.9286\\ 5.0357\\ 5.1429\\ 5.2500\\ 5.3571\end{array}$	$\begin{array}{c} 5.0929\\ 5.2036\\ 5.3143\\ 5.4250\\ 5.5357\end{array}$	$\begin{array}{c} 5.2571 \\ 5.3714 \\ 5.4857 \\ 5.6000 \\ 5.7143 \end{array}$	$5.4214 \\ 5.5393 \\ 5.6571 \\ 5.7750 \\ 5.8929$	$5.5857 \\ 5.7071 \\ 5.8286 \\ 5.9500 \\ 6.0714$	$5.7500 \\ 5.8750 \\ 6.0000 \\ 6.1250 \\ 6.2500$	$\begin{array}{c} 5.9143 \\ 6.0429 \\ 6.1714 \\ 6.3000 \\ 6.4286 \end{array}$	$\begin{array}{c} 6.0786\\ 6.2107\\ 6.3429\\ 6.4750\\ 6.6071 \end{array}$	$\begin{array}{c} 6.2429\\ 6.3786\\ 6.5143\\ 6.6500\\ 6.7857\end{array}$	$\begin{array}{c} 6.4071 \\ 6.5464 \\ 6.6857 \\ 6.8250 \\ 6.9643 \end{array}$	

#### Full-Inch Lengths 40 43 44 45 46 41 42 47 48 49 40 5.7143 5.8571 6.0000 6.1429 6.2857 6.4286 6.5714 6.7143 6.8571 7.0000 41 5.85716.0036 6.1500 6.29646.4429 6<mark>.58</mark>93 6.73576.8821 7.02867.175042 6.0000 $6.1500 \\ 6.2964 \\ 6.4429$ 6.3000 6.4500 6.6000 6.7500 6.9000 7.0500 $7.3500 \\ 7.5250$ 7.200043 44 45 7.06437.2286 $6.1429 \\ 6.2857$ $6.4500 \\ 6.6000$ $6.6036 \\ 6.7571$ $6.7571 \\ 6.9143$ 7.21797.38576.9107 7.37147.07147.54297.7000 7.55366.42866.58936.7500 6.91077.23217.39297.71437.07147.8750 $\begin{array}{c} 7.2286 \\ 7.3857 \\ 7.5429 \\ 7.7000 \\ 7.8571 \end{array}$ $6.5714 \\ 6.7143 \\ 6.8571 \\ 6.8571$ $\begin{array}{c} 6.7357\\ 6.8821\\ 7.0286\\ 7.1750\\ 7.3214\end{array}$ $\begin{array}{r} 7.0643 \\ 7.2179 \\ 7.3714 \\ 7.5250 \\ 7.6786 \end{array}$ $7.5571 \\ 7.7214 \\ 7.8857$ $\begin{array}{c} 7.7214 \\ 7.8893 \\ 8.0571 \\ 8.2250 \\ 8.3929 \end{array}$ 7.39297.553646 6.9000 7.8857 8.0500 7.0500 7.2000 7.3500 7.5000 $\begin{array}{c} 8.0571 \\ 8.2286 \\ 8.4000 \\ 8.5714 \end{array}$ 47 48 49 50 8.2250 8.4000 $\begin{array}{c} 7.7143 \\ 7.8750 \\ 8.0357 \end{array}$ 8.0500 8.2143 7.00007.14298.5750 8.7500

	50
50	8.9286

# ₩ A 623 – 03

TABLE A1.2 Tin Plate Ratios—Base Boxes per 112 Sheets Full-Inch Widths

Fuil-Inch Lengths	1/16	1/8	3/16	4[1	5/16	3/8	7/16	2 1	ol. /	5/8	11/16	3/4	13/16	7/8	15/16
53 			-118		3/16	<del></del>	116		9/16				13/16		
1 2 3 4	.0002	.0004	.0007	.0009	.0011	.0013	.0016	.0018	.0020	.0022	.0025	.0027 .0054 .0080 .0107 .0134	.0029	.0031	.0033 .0067 .0100 .0134
2	.0004 0007 .0009	.0009 .0013	.0013 .0020 .0027 .0033	.0018 .0027 .0036	.0022 .0033 .0045	.0013 .0027 .0040 .0054 .0067	.0031 .0047 .0063	$.0036 \\ 0054$	.0020 .0040 .0060 .0080 .0100	$.0045 \\ .0067$	.0049	.0054	$.0058 \\ .0087$	.0063 .0094 .0125 .0156	.0067
4	.0009	.0018	.0027	.0036	.0045	.0054	.0063	.0054 .0071 .0089	.0080	.0089	.0074 .0098 .0123	.0107	.0116	.0125	.0134
5	.0011	.0022		.0045	.0056		.0078	.0089		.0112			.0145		.0167
6 7	.0013 .0016 .0018 .0020 .0022	.0027 .0031 .0036 .0040 .0045	$\begin{array}{r} .0040\\ .0047\\ .0054\\ .0060\\ .0067\end{array}$	.0054 .0063 .0071 .0080	.0067 .0078 .0089	.0080 .0094 .0107 .0121 .0134	.0094	.0107	.0121 .0141 .0161 .0181 .0201	.0134	.0147 .0172 .0196 .0221 .0246	$\begin{array}{r} .0161\\ .0188\\ .0214\\ .0241\\ .0268\end{array}$	.0174 .0203 .0232 .0261 .0290	.0188 .0219 .0250 .0281 .0313	.0201 .0234 .0268 .0301 .0335
7 8	.0016	.0031	.0047	.0063	.0078	.0094	.0109 .0125 .0141	.0125 .0143	.0141	.0156	.0172	.0188	.0203	.0219	.0234
9	.0018	.0030	.0054	.0080	.0100	.0107	.0125	.0143	.0181	.0201	.0190	.0214 .0241	.0252 .0261	.0250 .0281	.0208
10	.0022	.0045	.0067	.0089	.0112	.0134	$.015\overline{6}$	.0179	.0201	$.0154 \\ .0156 \\ .0179 \\ .0201 \\ .0223$	.0246	.0268	.0290	.0313	.0335
11	.0025	$.0049 \\ .0054$	.0074	.0098	.0123	.0147	.0172	.0196	.0221	.0246	.0270	.0295	.0319	.0344	.0368
11 12 13	.0027	.0054	.0080	.0107	.0134	.0161	.0188	.0214	.0241	.0246 .0268 .0290 .0313	.0295	.0321	.0319 .0348 .0377	.0375	.0402
13	.0029	.0058	.0087 0094	.0116	.0145	.0174	.0203	.0232	.0261	.0290	.0319 0344	.0348	.0377.0406	.0406	.0435
14 15	.0025 .0027 .0029 .0031 .0033	.0063 .0067	.0074 .0080 .0087 .0094 .0100	.0098 .0107 .0116 .0125 .0134	.0123 .0134 .0145 .0156 .0167	.0147 .0161 .0174 .0188 .0201	.0172 .0188 .0203 .0219 .0234	.0196 .0214 .0232 .0250 .0268	$\begin{array}{c} .0221\\ .0241\\ .0261\\ .0281\\ .0301 \end{array}$	.0335	$\begin{array}{r} .0270\\ .0295\\ .0319\\ .0344\\ .0368\end{array}$	.0295 .0321 .0348 .0375 .0402	.0435	$\begin{array}{c} .0344\\ .0375\\ .0406\\ .0438\\ .0469\end{array}$	.0368 .0402 .0435 .0469 .0502
16 17	.0036 .0038 .0040 .0042 .0045	.0071 .0076 .0080 .0085	.0107 .0114 .0121 .0127 .0134	.0143 .0152 .0161 .0170 .0179	.0179 .0190 .0201 .0212 .0223	.0214 .0228 .0241 .0254 .0268	.0250 .0266 .0281 .0297 .0313	.0286 .0304 .0321 .0339 .0357	.0321 .0342 .0362 .0382 .0402	.0357 .0379 .0402 .0424	.0393 .0417 .0442 .0467 .0491	.0429 .0455 .0482 .0509 .0536	.0464 .0493 .0522 .0551	.0500 .0531 .0563 .0594 .0625	.0536 .0569 .0603 .0636 .0670
17	.0038	.0076	.0114	.0152	.0190	.0228	.0266	.0304	.0342	.0379	.0417	.0455	.0493	.0531	.0569
18 19	.0040	.0085	.0121	.0170	.0201	.0241 .0254	.0281	.0321	.0362	.0402	.0442 .0467	.0482	.0522	.0594	.0603
20	.0045	.0089	.0134	.0179	.0223	.0268	.0313	.0357	.0402	.0446	.0491	.0536	.0580	.0625	.0670
21	.0047 .0049 .0051 .0054	.0094	.0141 .0147 .0154 .0161 .0167	.0188 .0196 .0205 .0214 .0223	$.0234 \\ .0246$	.0281 .0295 .0308 .0321 .0335	.0328 .0344 .0359 .0375	.0375 .0393 .0411 .0429 .0446	$\begin{array}{c} .0422\\ .0442\\ .0462\\ .0482\\ .0502\end{array}$	.0469 .0491 .0513 .0536 .0558	.0516 .0540 .0565 .0589 .0614	.0563 .0589 .0616 .0643 .0670	.0609	$.0656 \\ .0688 \\ .0719 \\ .0750 \\ .0781$	.0703 .0737 .0770
22 23	.0049	.0098 .0103	.0147	.0196	$.0246 \\ .0257$	.0295	.0344	.0393	.0442	.0491	.0540	.0589	.0638 .0667	.0688	.0737
24	.0051	.0103	.0161	.0203	.0268	.0303	.0375	.0429	.0402 .0482	.0515	.0589	.0610	.0696	.0750	.0804
25	.0056	.0107 .0112			.0268 .0279		.0391	.0446					$.0696 \\ .0725$		.0804 .0837
26	.0058 .0060 .0063 .0065 .0067	.0116 .0121 .0125 .0129	.0174 .0181 .0188 .0194 .0201	.0232 .0241 .0250 .0259 .0268	.0290 .0301 .0313 .0324 .0335	.0348 .0362 .0375 .0388 .0402	.0406 .0422 .0438 .0453	.0464 .0482 .0500	.0522 .0542 .0563 .0583 .0603	$S^{.0580}_{.0603}_{.0625}_{.0647}$	.0638 .0663 .0688 .0712 .0737	.0696 .0723 .0750 .0777 .0804	.0754 .0783 .0813 .0842	$.0813 \\ .0844 \\ .0875 \\ .0906 \\ .0938$	.0871 .0904 .0938 .0971 .1004
26 27 28 29 30	.0060	.0121	.0181	.0241	.0301 -	.0362	.0422	.0482	.0542	$\sim .0603$	.0663	.0723	.0783	.0844 $.0875$	.0904
29	.0065	.0129	.0194	.0259	.0324	.0388	.0453	.0518	.0583	.0647	.0712	.0777	.0842	.0906	.0971
30	.0067	.0134	.0201	.0268	.0335	.0402	.0469	.0536		.0670	.0737	.0804	.0871	.0938	.1004
31 32	.0069 .0071 .0074 .0076 .0078	.0138 .0143 .0147 .0152 .0156	$.0208 \\ .0214 \\ .0221 \\ .0228 \\ .0234$	.0277 .0286 .0295 .0304	.0346 .0357 .0368 .0379	$\begin{array}{r} .0415 \\ .0429 \\ .0442 \\ .0455 \\ .0469 \end{array}$	.0484 .0500 .0516	.0554 .0571 .0589 .0607 .0625	.0623 .0643 .0663 .0683 .0703	$\begin{array}{r} .0692 \\ 0.0714 \\ .0737 \\ .0737 \end{array}$	.0761 .0786 .0810 .0835 .0859	.0830 .0857 .0884 .0911 .0938	.0900 .0929 .0958	$\begin{array}{r} .0969\\ .1000\\ .1031\\ .1063\\ .1094 \end{array}$	.1038 .1071 .1105 .1138 .1172
32 33	.0071	.0143	.0214	.0286	.0357	.0429	.0500	.0571	.0643	0.0714	.0786	.0857	.0929	.1000	.1071
33 34	.0074	.0147	.0221	.0295	.0308 .0379	.0442 .0455	.0518 .0531	.0589	.0663	.0759	.0810	.0884	.0987	.1051	.1105
35	.0078	.0156	.0234	.0313	.0391	.0469	.0547	.0625	.0703	.0759 .0781	.0859		.1016	.1094	
36	.0080	.0161	.0241	.0321 .0330 .0339 .0348	.0402 .0413 .0424 .0435	.0482	S.0563	.0643	.0723	.0804 -0826 -0848 .0871	.0884	.0964 .0991 .1018 .1045 .1071	.1045 .1074 .1103 .1132	.1125	.1205
37	.0083	.0165	.0248	.0330	.0413	.0496	.0578 .0594 .0609	.0661	.0743	.0826	.0908	.0991	.1074	.1156	.1239
38	.0085	.0170	.0254 .0261	.0339	.0424 .0435	.0509	.0609	.0679	.0783	.0848	.0933	.1018	.1103	.1219	.1272
37 38 39 40	.0080 .0083 .0085 .0085 .0087 .0089	.0161 .0165 ta.0170 .0174 .0179	.0241 .0248 .0254 .0261 .0261 .0268	.0357	.0446	.0482 .0496 .0509 .0522 .0536	.0625	.0643 .0661 .0679 .0696 .0714	.0723 .0743 .0763 .0763 .0783 .0804	.0893	.0884 .0908 .0933 .0958 .0982	.1071	.1161	$.1125 \\ 2.1156 \\ 2.1188 \\ .1219 \\ .1250$	$.1205 \\ .1239 \\ .1272 \\ .1272 \\ .1306 \\ .1339$
41				.0366	.0458		.0641			.0915			.1190		
41 42 43 44	.0092 .0094 .0096 .0098	.0183 .0188 .0192 .0196	.0281	$.0366 \\ .0375$	.0458 .0469 .0480 .0491	.0563	.0656	.0750	.0844	.0915 .0938 .0960 .0982	.1031	.1098 .1125	.1190 .1219	.1313	.1373 $.1406$
43	.0096	.0192	.0288	.0384 .0393	.0480	.0576	.0672	.0768	.0864	.0960	.1056	.1152	.1248 .1277	.1344	.1440
44 45	.0100	.0198	.0275 .0281 .0288 .0295 .0301	.0393	.0491	.0549 .0563 .0576 .0589 .0603	$\begin{array}{r} .0641 \\ .0656 \\ .0672 \\ .0688 \\ .0703 \end{array}$	.0732 .0750 .0768 .0786 .0804	.0824 .0844 .0864 .0884 .0904	.10982	$.1007 \\ .1031 \\ .1056 \\ .1080 \\ .1105$	.1120 .1152 .1179 .1205	.1277.1306	$.1281\\.1313\\.1344\\.1375\\.1406$	.1440 .1473 .1507
46	.0103	.0205		.0411	.0513		0719			.1027			.1335		
47	.0103 .0105	.0210 .0214 .0219 .0223	.0308 .0315 .0321 .0328 .0335	.0411 .0420 .0429 .0438	.0513 .0525 .0536 .0547 .0558	.0616 .0629 .0643 .0656 .0670	.0734 .0750 .0766 .0781	.0821 .0839 .0857 .0875 .0893	.0924 .0944 .0964 .0984 .1004	.1027 .1049 .1071 .1094	$.1129 \\ .1154 \\ .1179 \\ .1203 \\ .1228$	$\begin{array}{r} .1232\\ .1259\\ .1286\\ .1313\end{array}$	$.1364 \\ .1393$	$.1438\\.1469\\.1500\\.1531\\.1563$	.1574
48 49 50	.0107 .0109	.0214	.0321	.0429	.0536	.0643	.0750 0766	.0857	.0964	.1071	.1179	.1286 1212	.1393 .1422	.1500	.1540 .1574 .1607 .1641 .1674
50	.0103	.0223	.0335	.0438	.0558	.0670	0781	0893	1004	.1116	1228	.1313	.1422	1569	1674