# NOTICE: This standard has either been superseded and replaced by a new version or discontinued. Contact ASTM International (www.astm.org) for the latest information.



Designation: D 1298 – 99

An American National Standard



MPMS Chapter 9.1

160/99

# Standard Test Method for Density, Relative Density (Specific Gravity), or API Gravity of Crude Petroleum and Liquid Petroleum Products by Hydrometer Method<sup>1</sup>

This standard is issued under the fixed designation D 1298; the number immediately following the designation indicates the year of original adoption or, in the case of revision, the year of last revision. A number in parentheses indicates the year of last reapproval. A superscript epsilon ( $\epsilon$ ) indicates an editorial change since the last revision or reapproval.

This standard has been approved for use by agencies of the Department of Defense.

## 1. Scope

- 1.1 This test method covers the laboratory determination using a glass hydrometer, of the density, relative density (specific gravity), or API gravity of crude petroleum, petroleum products, or mixtures of petroleum and nonpetroleum products normally handled as liquids, and having a Reid vapor pressure of 101.325 kPa (14.696 psi) or less.
- 1.2 Values are measured on a hydrometer at either the reference temperature or at another convenient temperature, and readings corrected to the reference temperature by means of the Petroleum Measurement Tables; values obtained at other than the reference temperature being hydrometer readings and not density measurements.
- 1.3 Values determined as density, relative density, or API gravity can be converted to equivalent values in the other units at alternate reference temperatures by means of the Petroleum Measurement Tables.
- 1.4 Annex A1 contains a procedure for verifying or certifying the equipment for this test method.
- 1.5 This standard does not purport to address all of the safety concerns, if any, associated with its use. It is the responsibility of the user of this standard to establish appropriate safety and health practices and determine the applicability of regulatory limitations prior to use.

## 2. Referenced Documents

- 2.1 ASTM Standards:
- D 97 Test Method for Pour Point of Petroleum Products<sup>2</sup> D 323 Test Method for Vapor Pressure of Petroleum Products (Reid Method)<sup>2</sup>
- <sup>1</sup> This test method is under the jurisdiction of ASTM Committee D02 on Petroleum Products and Lubricants and is the direct responsibility of Subcommittee D02.02.A0 on Temperature, Density, Physical Properties.
- Current edition approved June 10, 1999. Published August 1999. Originally published as D 1298–53. Last previous edition D 1298–85 (1990)<sup>e1</sup>.
  - <sup>2</sup> Annual Book of ASTM Standards, Vol 05.01.

- D 1250 Guide for Petroleum Measurement Tables<sup>2</sup>
- D 2500 Test Method for Cloud Point of Petroleum Oils<sup>2</sup>
- D 3117 Test Method for Wax Appearance Point of Distillate Fuels<sup>3</sup>
- D 4057 Practice for Manual Sampling of Petroleum and Petroleum Products<sup>3</sup>
- D 4177 Practice for Automatic Sampling of Petroleum and Petroleum Products<sup>3</sup>
- D 5854 Practice for Mixing and Handling of Liquid Samples of Petroleum and Petroleum Products<sup>4</sup>
- E 1 Specification for ASTM Thermometers<sup>5</sup>
- E 100 Specification for ASTM Hydrometers<sup>5</sup>
- 2.2 Institute of Petroleum Standards<sup>6</sup>
- IP 389 Determination of wax appearance temperature (WAT) of middle distillate fuels by differential thermal analysis (DTA) or differential scanning calorimetry (DSC)
- IP Standard Methods Book, Appendix A, Specifications IP Standard Thermometers
- 2.3 ISO Standards<sup>7</sup>
- ISO 649-1 Laboratory glassware Density hydrometers for general purpose Part 1: Specification

## 3. Terminology

- 3.1 Definitions of Terms Specific to This Standard:
- 3.1.1 *density*, *n*—the mass of liquid per unit volume at 15°C and 101.325 kPa with the standard unit of measurement being kilograms per cubic metre.
- 3.1.1.1 *Discussion*—Other reference temperatures, such as 20°C may be used for some products or in some locations. Less

<sup>&</sup>lt;sup>3</sup> Annual Book of ASTM Standards, Vol 05.02.

<sup>&</sup>lt;sup>4</sup> Annual Book of ASTM Standards, Vol 05.03.

<sup>&</sup>lt;sup>5</sup> Annual Book of ASTM Standards, Vol 14.03.

<sup>&</sup>lt;sup>6</sup> Available from Institute of Petroleum, 61 New Cavendish St., London, W1M 8AR, UK.

<sup>&</sup>lt;sup>7</sup> Available from American National Standards Institute, 11 W 42<sup>nd</sup> St., 13<sup>th</sup> floor, New York, NY 10036.

# NOTICE: This standard has either been superseded and replaced by a new version or discontinued. Contact ASTM International (www.astm.org) for the latest information.



preferred units of measurement; for example, kg/L or g/mL are still in use.

- 3.1.2 relative density (specific gravity), n—the ratio of the mass of a given volume of liquid at a specific temperature to the mass of an equal volume of pure water at the same or different temperature. Both reference temperatures shall be explicitly stated.
- 3.1.2.1 *Discussion*—Common reference temperatures include 60/60°F, 20/20°C, 20/4°C. The historic deprecated term specific gravity may still be found.
- 3.1.3 *API gravity*, *n*—a special function of relative density (specific gravity) 60/60°F, represented by:

$$^{\circ}$$
 API = 141.5/(sp gr 60/60°F) - 131.5 (1)

- 3.1.3.1 *Discussion*—No statement of reference temperature is required, as 60°F is included in the definition.
- 3.1.4 *observed values*, *n*—values observed at temperatures other than the specified reference temperature. These values are only hydrometer readings and not density, relative density (specific gravity), or API gravity at that other temperature.
- 3.1.5 *cloud point*, *n*—temperature at which a cloud of wax crystals first appears in a liquid when it is cooled under specific conditions.
- 3.1.6 *pour point*, *n*—lowest temperature at which a test portion of crude petroleum or petroleum product will continue to flow when it is cooled under specified conditions.
- 3.1.7 wax appearance temperature (WAT), n—temperature at which waxy solids form when a crude petroleum or petroleum product is cooled under specified conditions.

# 4. Summary of Test Method

4.1 The sample is brought to a specified temperature and a test portion is transferred to a hydrometer cylinder that has been brought to approximately the same temperature. The appropriate hydrometer, also at a similar temperature, is lowered into the test portion and allowed to settle. After temperature equilibrium has been reached, the hydrometer scale is read, and the temperature of the test portion is taken. The observed hydrometer reading is reduced to the reference temperature by means of the Petroleum Measurement Tables. If necessary, the hydrometer cylinder and its contents are placed in a constant temperature bath to avoid excessive temperature variation during the test.

# 5. Significance and Use

- 5.1 Accurate determination of the density, relative density (specific gravity), or API gravity of petroleum and its products is necessary for the conversion of measured volumes to volumes or masses, or both, at the standard reference temperatures during custody transfer.
- 5.2 This test method is most suitable for determining the density, relative density (specific gravity), or API gravity of low viscosity transparent liquids. This test method can also be used for viscous liquids by allowing sufficient time for the hydrometer to reach equilibrium, and for opaque liquids by employing a suitable meniscus correction.
- 5.3 When used in connection with bulk oil measurements, volume correction errors are minimized by observing the hydrometer reading at a temperature close to that of the bulk oil temperature.

- 5.4 Density, relative density (specific gravity), or API gravity is a factor governing the quality and pricing of crude petroleum. However, this property of petroleum is an uncertain indication of its quality unless correlated with other properties.
- 5.5 Density is an important quality indicator for automotive, aviation and marine fuels, where it affects storage, handling and combustion.

# 6. Apparatus

- 6.1 *Hydrometers*, of glass, graduated in units of density, relative density, or API gravity as required, conforming to Specification E 100 or ISO 649-1, and the requirements given in Table 1.
- 6.1.1 The user should ascertain that the instruments used for this test conform to the requirements set out above with respect to materials, dimensions, and scale errors. In cases where the instrument is provided with a calibration certificate issued by a recognized standardizing body, the instrument is classed as certified and the appropriate corrections listed shall be applied to the observed readings. Instruments that satisfy the requirements of this test method, but are not provided with a recognized calibration certificate, are classed as uncertified.
- 6.2 *Thermometers*, having range, graduation intervals and maximum permitted scale error shown in Table 2 and conforming to Specification E 1 or IP Appendix A.
- 6.2.1 Alternate measuring devices or systems may be used, provided that the total uncertainty of the calibrated system is no greater than when using liquid-in-glass thermometers.
- 6.3 Hydrometer Cylinder, clear glass, plastic (see 6.3.1), or metal. The inside diameter of the cylinder shall be at least 25 mm greater than the outside diameter of the hydrometer and the height shall be such that the appropriate hydrometer floats in the test portion with at least 25 mm clearance between the bottom of the hydrometer and the bottom of the cylinder.
- 6.3.1 Hydrometer cylinders constructed of plastic materials shall be resistant to discoloration or attack by oil samples and shall not affect the material being tested. They shall not become opaque under prolonged exposure to sunlight.
- 6.4 Constant-Temperature Bath, if required, of dimensions such that it can accommodate the hydrometer cylinder with the test portion fully immersed below the test portion liquid surface, and a temperature control system capable of maintaining the bath temperature within 0.25°C of the test temperature throughout the duration of the test.
- 6.5 Stirring Rod, optional, of glass or plastic, approximately 400 mm in length.

**TABLE 1 Recommended Hydrometers** 

Units	Range		Scale <sup>A</sup>		Meniscus
	Total	Each Unit	Interval <sup>A</sup>	Error <sup>A</sup>	Correction
Density, kg/m3 at 15°C	600 - 1100	20	0.2	± 0.2	+0.3
	600 - 1100	50	0.5	$\pm~0.3$	+0.7
	600 - 1100	50	1.0	$\pm~0.6$	+1.4
Relative density (specific	0.600 - 1.100	0.020	0.0002	± 0.0002	+0.0003
gravity) 60/60°F		0.050	0.0005	$\pm 0.0003$	+0.0007
	0.600 - 1.100	0.050	0.001	± 0.0006	+0.0014
	0.600 - 1.100				
Relative density (specific					
gravity), 60/60°F	0.650 - 1.100	0.050	0.0005	$\pm 0.0005$	
API	-1 - +101	12	0.1	± 0.1	

<sup>&</sup>lt;sup>A</sup>Interval and Error relate to Scale.

**TABLE 2 Recommended Thermometers** 

Scale	Range	Graduation Interval	Scale Error
°C	-1 - +38	0.1	± 0.1
°C	-20 - +102	0.2	± 0.15
°F	-5 <b>-</b> +215	0.5	± 0.25

#### 7. Sampling

- 7.1 Unless otherwise specified, samples of non-volatile petroleum and petroleum products shall be taken by the procedures described in Practices D 4057 and D 4177.
- 7.2 Samples of volatile crude petroleum or petroleum products are preferably taken by Practice D 4177, using a variable volume (floating piston) sample receiver to minimize any loss of light components which may affect the accuracy of the density measurement. In the absence of this facility, extreme care shall be taken to minimize these losses, including the transfer of the sample to a chilled container immediately after sampling.
- 7.3 Sample Mixing—may be necessary to obtain a test portion representative of the bulk sample to be tested, but precautions shall be taken to maintain the integrity of the sample during this operation. Mixing of volatile crude petroleum or petroleum products containing water or sediments, or both, or the heating of waxy volatile crude petroleum or petroleum products may result in the loss of light components. The following sections (7.3.1 to 7.3.4) will give some guidance on sample integrity maintenance.
- 7.3.1 Volatile Crude Petroleum and Petroleum Products Having an RVP Greater than 50 kPa—Mix the sample in its original closed container in order to minimize the loss of light components.
- Note 1—Mixing volatile samples in open containers will lead to loss of light components and consequently affect the value of the density obtained.
- 7.3.2 Waxy Crude Petroleum—If the petroleum has a pour point above 10°C, or a cloud point or WAT above 15°C, warm the sample to 9°C above the pour point, or 3°C above the cloud point or WAT, prior to mixing. Whenever possible, mix the sample in its original closed container in order to minimize the loss of light components.
- 7.3.3 *Waxy Distillate*—Warm the sample to 3°C above its cloud point or WAT prior to mixing.
- 7.3.4 *Residual Fuel Oils*—Heat the sample to the test temperature prior to mixing (see 8.1.1 and Note 4).
- 7.4 Additional information on the mixing and handling of liquid samples will be found in Practice D 5854.

# 8. Procedure

- 8.1 *Temperature of Test*:
- 8.1.1 Bring the sample to the test temperature which shall be such that the sample is sufficiently fluid but not so high as to cause the loss of light components, nor so low as to result in the appearance of wax in the test portion.
- Note 2—The density, relative density or API gravity determined by the hydrometer is most accurate at or near the reference temperature.
- Note 3—The volume and density, the relative density, and the API corrections in the Petroleum Measurement Tables are based on the average

- expansions of a number of typical materials. Since the same coefficients were used in compiling each set of tables, corrections made over the same temperature interval minimize errors arising from possible differences between the coefficient of the material under test and the standard coefficients. This effect becomes more important as temperatures diverge from the reference temperature.
- Note 4—The hydrometer reading is obtained at a temperature appropriate to the physico-chemical characteristics of the material under test. This temperature is preferably close to the reference temperature, or when the value is used in conjunction with bulk oil measurements, within 3°C of the bulk temperature (see 5.3).
- 8.1.2 For crude petroleum, bring the sample close to the reference temperature or, if wax is present, to 9°C above its pour point or 3°C above its cloud point or WAT, whichever is higher.
- Note 5—For crude petroleum an indication of the WAT can be found using IP 389, with the modification of using 50  $\mu L \pm 5~\mu L$  of sample. The precision of WAT for crude petroleum using this technique has not been determined

# 9. Apparatus Verification or Certification

9.1 Hydrometers and thermometers shall be verified in accordance with the procedures in Annex A1.

## 10. Procedure

- 10.1 Bring the hydrometer cylinder and thermometer to within approximately 5°C of the test temperature.
- 10.2 Transfer the sample to the clean, temperaturestabilized hydrometer cylinder without splashing, to avoid the formation of air bubbles, and minimize evaporation of the lower boiling constituents of more volatile samples.
- Note 6—Warning: Extremely flammable. Vapors may cause flash fire!
- 10.3 Transfer highly volatile samples by siphoning or water displacement.
- Note 7—Warning: Siphoning by mouth could result in ingestion of sample!
- 10.3.1 Samples containing alcohol or other water-soluble materials should be placed into the cylinder by siphoning.
- 10.4 Remove any air bubbles formed after they have collected on the surface of the test portion, by touching them with a piece of clean filter paper before inserting the hydrometer.
- 10.5 Place the cylinder containing the test portion in a vertical position in a location free from air currents and where the temperature of the surrounding medium does not change more than 2°C during the time taken to complete the test. When the temperature of the test portion differs by more than 2°C from ambient, use a constant temperature bath to maintain an even temperature throughout the test duration.
- 10.6 Insert the appropriate thermometer or temperature measurement device and stir the test portion with a stirring rod, using a combination of vertical and rotational motions to ensure uniform temperature and density throughout the hydrometer cylinder. Record the temperature of the sample to the nearest 0.1°C and remove the thermometer/temperature measuring device and stirring rod from the hydrometer cylinder.
- Note 8—If a liquid-in-glass thermometer is used, this is commonly used as the stirring rod.
- 10.7 Lower the appropriate hydrometer into the liquid and release when in a position of equilibrium, taking care to avoid