# SLOVENSKI STANDARD

## SIST ISO 31-13:1995

prva izdaja maj 1995

Veličine in enote - 13. del: Fizika trdnega stanja

Quantities and units - Part 13: Solid state physics

## iTeh STANDARD PREVIEW (standards.iteh.ai)

<u>SIST ISO 31-13+A1:2008</u> https://standards.iteh.ai/catalog/standards/sist/1bb081c6-1ffd-4770-b3af-7b478c2e1bf1/sist-iso-31-13a1-2008

ICS 01.060; 07.030

Referenčna številka SIST ISO 31-13:1995(en)

© Standard je založil in izdal Slovenski inštitut za standardizacijo. Razmnoževanje ali kopiranje celote ali delov tega dokumenta ni dovoljeno

## iTeh STANDARD PREVIEW (standards.iteh.ai)

<u>SIST ISO 31-13+A1:2008</u> https://standards.iteh.ai/catalog/standards/sist/1bb081c6-1ffd-4770-b3af-7b478c2e1bf1/sist-iso-31-13a1-2008

# INTERNATIONAL STANDARD

ISO 31-13

> Third edition 1992-09-01

## Quantities and units —

## Part 13: Solid state physics iTeh STANDARD PREVIEW (standards.iteh.ai) Grandeurs et unités —

Parties 133 Physique deol'état solide https://standards.iteh.ai/catalog/standards/sist/1bb081c6-1ffd-4770-b3af-7b478c2e1bfl/sist-iso-31-13a1-2008



## Foreword

ISO (the International Organization for Standardization) is a worldwide federation of national standards bodies (ISO member bodies). The work of preparing International Standards is normally carried out through ISO technical committees. Each member body interested in a subject for which a technical committee has been established has the right to be represented on that committee. International organizations, governmental and non-governmental, in liaison with ISO, also take part in the work. ISO collaborates closely with the International Electrotechnical Commission (IEC) on all matters of electrotechnical standardization.

Draft International Standards adopted by the technical committees are circulated to the member bodies for voting. Publication as an International Standard requires approval by at least 75 % of the member bodies casting VIEW a vote.

International Standard ISO 31-13 was prepared by Technical Committee ) ISO/TC 12, Quantities, units, symbols, conversion factors.

This third edition cancels and and replaces (cathe second ist/edition.6-1ftd-4770-b3af-(ISO 31-13:1981). The major technical changes from the second edition are the following:

- the decision by the International Committee for Weights and Measures (Comité International des Poids et Mesures, CIPM) in 1980 concerning the status of supplementary units has been incorporated;
- the quantity affinity has been included in the list of quantities;
- the unit angström, Å, in use temporarily, has been transferred to the "Conversion factors and remarks" column.

The scope of Technical Committee ISO/TC 12 is standardization of units and symbols for quantities and units (and mathematical symbols) used within the different fields of science and technology, giving, where necessary, definitions of these quantities and units. Standard conversion factors for converting between the various units also come under the scope of the TC. In fulfilment of this responsibility, ISO/TC 12 has prepared ISO 31.

<sup>©</sup> ISO 1992

All rights reserved. Unless otherwise specified, no part of this publication may be reproduced or utilized in any form or by any means, electronic or mechanical, including photocopying and microfilm, without permission in writing from the publisher.

International Organization for Standardization

Case Postale 56 • CH-1211 Genève 20 • Switzerland

Printed in Switzerland

ISO 31 consists of the following parts, under the general title *Quantities* and units:

- Part 0: General principles
- Part 1: Space and time
- Part 2: Periodic and related phenomena
- Part 3: Mechanics
- Part 4: Heat
- Part 5: Electricity and magnetism
- Part 6: Light and related electromagnetic radiations
- Part 7: Acoustics
- Part 8: Physical chemistry and molecular physics
- Part 9: Atomic and nuclear physics
- Part 10: Nuclear reactions and ionizing radiations

iTeh STAN Part 11: Mathematical signs and symbols for use in the physical sciences and technology (stan part 12: Characteristic numbers

Sts Part 13: Solid state physics https://standards.iteh.ai/catalog/standards/sist/16081c6-1ffd-4770-b3af. Annex A forms an integral part of this part of ISO 31. 76478c2e16f1/sist-iso-31-13a1-2008

## Introduction

### 0.1 Arrangement of the tables

The tables of quantities and units in ISO 31 are arranged so that the quantities are presented on the left-hand pages and the units on the corresponding right-hand pages.

All units between two full lines belong to the quantities between the corresponding full lines on the left-hand pages.

Where the numbering of an item has been changed in the revision of a part of ISO 31, the number in the preceding edition is shown in parentheses on the left-hand page under the new number for the quantity; a dash is used to indicate that the item in question did not appear in the preceding RVIRW edition.

## (standards.iteh.ai)

## 0.2 Tables of quantities

The most important quantities within the field of this document are given c6-1ffd-4770-b3aftogether with their symbols and, in most cases, definitions. These definitions are given merely for identification; they are not intended to be complete.

The vectorial character of some quantities is pointed out, especially when this is needed for the definitions, but no attempt is made to be complete or consistent.

In most cases only one name and only one symbol for the quantity are given; where two or more names or two or more symbols are given for one quantity and no special distinction is made, they are on an equal footing. When two types of italic (sloping) letter exist (for example as with  $\vartheta$ ,  $\theta$ ;  $\varphi$ ,  $\phi$ ; g, g) only one of these is given. This does not mean that the other is not equally acceptable. In general it is recommended that such variants should not be given different meanings. A symbol within parentheses implies that it is a "reserve symbol", to be used when, in a particular context, the main symbol is in use with a different meaning.

#### Tables of units 0.3

### 0.3.1 General

Units for the corresponding quantities are given together with the international symbols and the definitions. For further information, see ISO 31-0.

The units are arranged in the following way:

a) The names of the SI units are given in large print (larger than text size). The SI units have been adopted by the General Conference on Weights and Measures (Conférence Générale des Poids et Mesures, CGPM). The SI units and their decimal multiples and sub-multiples are recommended, although the decimal multiples and sub-multiples are not explicitly mentioned.

b) The names of non-SI units which may be used together with SI units because of their practical importance or because of their use in specialized fields are given in normal print (text size).

These units are separated by a broken line from the SI units for the quantities concerned.

- c) The names of non-SI units which may be used temporarily together with SI units are given in small print (smaller than text size) in the "Conversion factors and remarks" column.
- d) The names of non-SI units which should not be combined with SI units are given only in annexes in some parts of ISO 31. These annexes are informative and not integral parts of the standard. They are arranged in three groups:
  - 1) special names of units in the CGS system;
  - 2) names of units based on the foot, pound and second and some other related units;

## 3) names of other units. **iTeh STANDARD PREVIEW** 0.3.2 Remark on units for quantities of dimension one (standards.iteh.ai)

The coherent unit for any quantity of dimension one is the number one (1). When the value of such a quantity is expressed, the unit 1 is generally not written out explicitly. Prefixes shall not be used to form multiples or subnultiples of this unit. Instead of prefixes, powers of 10 may be used.

### **EXAMPLES**

Refractive index  $n = 1,53 \times 1 = 1,53$ 

Reynolds number  $Re = 1.32 \times 10^3$ 

Considering that plane angle is generally expressed as the ratio between two lengths, and solid angle as the ratio between an area and the square of a length, the CIPM specified in 1980 that, in the International System of Units, the radian and steradian are dimensionless derived units. This implies that the quantities plane angle and solid angle are considered as dimensionless derived quantities. The units radian and steradian may be used in expressions for derived units to facilitate distinction between quantities of different nature but having the same dimension.

### 0.4 Numerical statements

All numbers in the "Definition" column are exact.

When numbers in the "Conversion factors and remarks" column are exact, the word "exactly" is added in parentheses after the number.

### 0.5 Special remark

In this part of ISO 31, vector notation is explicity used for vector quantities.

## iTeh STANDARD PREVIEW (standards iteh ai) This page intentionally left blank

<u>SIST ISO 31-13+A1:2008</u> https://standards.iteh.ai/catalog/standards/sist/1bb081c6-1ffd-4770-b3af-7b478c2e1bf1/sist-iso-31-13a1-2008

## Quantities and units —

## **Part 13:** Solid state physics

#### 1 Scope

This part of ISO 31 gives names and symbols for quantities and units of solid state physics. Where appropriate, conversion factors are also given.

## 2 Normative references

maintain registers of currently valid International Standards.

ISO 31-5:1992, Quantities and units - Part 5: Electricity and magnetism.

The names and symbols for quantities and units of

solid state physics are given on the following pages.

Names and symbols

NDARD ileh Sl ISO 31-8:1992, Quantities and units — Part 8: Phys-(standards.itical chem)istry and molecular physics.

3

The following standards contain provisions which, ISO 31-10:1992, Quantities and units - Part 10: Nuof this part of ISO 31. At the time of publication, the ds/sist/100081co-1fd-47/0-b atthrough reference in this text, constitute provisions13+A

editions indicated were valid. All standards are subjectiso-31-13a1-2008 to revision, and parties to agreements based on this part of ISO 31 are encouraged to investigate the possibility of applying the most recent editions of the standards indicated below. Members of IEC and ISO

1

SOLID STATE PHYSICS Quantities						
ltem No.	Quantity	Symbol	Definition	Remarks		
13-1.1	lattice vector	<b>R</b> , <b>R</b> <sub>0</sub> , <b>T</b>	Translation vector which maps the crystal lattice on itself			
13-1.2	fundamental lattice vector	a <sub>1</sub> , a <sub>2</sub> , a <sub>3</sub> a, b, c	Fundamental translation vectors for the crystal lattice	$\mathbf{R} = n_1 \mathbf{a}_1 + n_2 \mathbf{a}_2 + n_3 \mathbf{a}_3$ where $n_1$ , $n_2$ and $n_3$ are integers.		
13-2.1	angular reciprocal lattice vector	G	Vector whose scalar products with all fundamental lattice vectors are integral multiples of 2π	In crystallography, however, the quantity $G/(2\pi)$ is commonly used.		
13-2.2	fundamental reciprocal lattice vectors	b <sub>1</sub> , b <sub>2</sub> , b <sub>3</sub> a*, b*, c*	The fundamental translation vectors for the reciprocal lattice	$\boldsymbol{a}_i \cdot \boldsymbol{b}_k = 2\pi\delta_{ik}$ In crystallography, however, the quantities $\boldsymbol{b}_k/(2\pi)$ are also often used.		
13-3	lattice plane spacing	d iTeh S	Distance between successive	TEW		
13-4	Bragg angle	9	2d sin $\vartheta$ = $n\lambda$ cds. iteh.ai) where $\lambda$ is the wavelength of the radiation in question and $n$ is an integer	6L4770-b3af		
13-5	order of reflexion	n	7b478c2e1bf1/sist-iso-31-13a1-2008	a, o osa		
13-6.1	short-range order parameter	σ	Fraction of nearest-neighbour atom pairs in an Ising ferromagnet having parallel magnetic moments, minus the fraction having antiparallel mag- netic moments	Similar definitions apply to other order-disorder phenom- ena.		
13-6.2	long-range order parameter	5	Fraction of atoms in an Ising ferromagnet having their mag- netic moments directed in one direction, minus the fraction with magnetic moments in the opposition direction			
13-7	Burgers vector	Ь	Vector characterizing a dislo- cation, i.e. the closing vector in a Burgers circuit encircling a dislocation line			

Units				SOLID STATE PHYSICS
ltem No.	Name of unit	International symbol for unit	Definition	Conversion factors and remarks
13-1.a	metre	m		ångström (Å), 1 Å = 10 <sup>-10</sup> m
13-2.a	reciprocal metre, metre to the power minus one	m <sup>-1</sup>		
13-3.a	metre	m		ångström (Å), 1 Å = 10 <sup>-10</sup> m
	iTe	h STAN	DARD PREVI	W
13-4.a	radian	rad(stand	lards.iteh.ai)	
13-4.b	degree	• <u>SIST</u>	ISO 31-13+A1:2008	$1^{\circ} = (\pi/180)$ rad = 0,017 453 29 rad
13-5.a	one	dards.iten.a/catak 1 7b478c2e1	bg/standards/sist/166081c6-1ftd-4, bf1/sist-iso-31-13a1-2008	See the introduction, subclause 0.3.2.
13-6.a	one	1		See the introduction, subclause 0.3.2.
13-7.a	metre	m		ångström (Å), 1 Å = 10 <sup>-10</sup> m