



SLOVENSKI STANDARD
SIST ISO 307:1996

01-junij-1996

Polimerni materiali - Poliamidi - Določanje viskoznostnega števila

Plastics -- Polyamides -- Determination of viscosity number

Plastiques -- Polyamides -- Détermination de l'indice de viscosité

Ta slovenski standard je istoveten z: ISO 307:1994

[SIST ISO 307:1996](https://standards.iteh.ai/catalog/standards/sist/5e4b4dfc-c987-482f-bbc0-0cdc1a781000/sist-iso-307-1996)

<https://standards.iteh.ai/catalog/standards/sist/5e4b4dfc-c987-482f-bbc0-0cdc1a781000/sist-iso-307-1996>

ICS:

83.080.20 Plastomeri Thermoplastic materials

SIST ISO 307:1996

en

iTeh STANDARD PREVIEW
(standards.iteh.ai)

SIST ISO 307:1996

<https://standards.iteh.ai/catalog/standards/sist/5e4b4dfc-c987-482f-bbc0-0cdc1a781000/sist-iso-307-1996>

INTERNATIONAL
STANDARD

ISO
307

Third edition
1994-09-01

**Plastics — Polyamides — Determination
of viscosity number**

iTeh STANDARD PREVIEW
Plastiques — Polyamides — Détermination de l'indice de viscosité
(standards.iteh.ai)

[SIST ISO 307:1996](https://standards.iteh.ai/catalog/standards/sist/5e4b4dfc-c987-482f-bbc0-0cdc1a781000/sist-iso-307-1996)

<https://standards.iteh.ai/catalog/standards/sist/5e4b4dfc-c987-482f-bbc0-0cdc1a781000/sist-iso-307-1996>



Reference number
ISO 307:1994(E)

Foreword

ISO (the International Organization for Standardization) is a worldwide federation of national standards bodies (ISO member bodies). The work of preparing International Standards is normally carried out through ISO technical committees. Each member body interested in a subject for which a technical committee has been established has the right to be represented on that committee. International organizations, governmental and non-governmental, in liaison with ISO, also take part in the work. ISO collaborates closely with the International Electrotechnical Commission (IEC) on all matters of electrotechnical standardization.

Draft International Standards adopted by the technical committees are circulated to the member bodies for voting. Publication as an International Standard requires approval by at least 75 % of the member bodies casting a vote.

International Standard ISO 307 was prepared by Technical Committee ISO/TC 61, *Plastics*, Subcommittee SC 9, *Thermoplastic materials*.

This third edition cancels and replaces the second edition (ISO 307:1984), of which it constitutes a technical revision.

Annex A forms an integral part of this International Standard.

© ISO 1994

All rights reserved. Unless otherwise specified, no part of this publication may be reproduced or utilized in any form or by any means, electronic or mechanical, including photocopying and microfilm, without permission in writing from the publisher.

International Organization for Standardization
Case Postale 56 • CH-1211 Genève 20 • Switzerland

Printed in Switzerland

Plastics — Polyamides — Determination of viscosity number

1 Scope

This International Standard specifies a method for the determination of the viscosity number of dilute solutions of polyamides in certain specified solvents.

The method is applicable to the polyamides designated PA 6, PA 66, PA 69, PA 610, PA 612, PA 11, PA 12 and PA MXD6 as defined in ISO 1874-1, as well as to copolyamides and other polyamides that are soluble in one of the specified solvents under the specified conditions.

The method is not applicable to polyamides produced by anionic polymerization of lactams or produced with crosslinking agents; such polyamides are normally insoluble in the specified solvents.

The viscosity number is determined by the general procedure specified in ISO 1628-1, observing the particular conditions specified in this International Standard.

The determination of the viscosity number of a polyamide provides a measure of the relative molecular mass of the polymer.

2 Normative references

The following standards contain provisions which, through reference in this text, constitute provisions of this International Standard. At the time of publication, the editions indicated were valid. All standards are subject to revision, and parties to agreements based on this International Standard are encouraged to investigate the possibility of applying the most recent editions of the standards indicated below. Members of IEC and ISO maintain registers of currently valid International Standards.

ISO 472:1988, *Plastics — Vocabulary*.

ISO 599:1985, *Plastics — Polyamide homopolymers — Determination of matter extractable by boiling methanol*.

ISO 960:1988, *Plastics — Polyamides (PA) — Determination of water content*.

ISO 1042:1983, *Laboratory glassware — One-mark volumetric flasks*.

ISO 1628-1:1984, *Guidelines for the standardization of methods for the determination of viscosity number and limiting viscosity number of polymers in dilute solution — Part 1: General conditions*.

ISO 1874-1:1992, *Plastics — Polyamide (PA) moulding and extrusion materials — Part 1: Designation*.

ISO 3105:—¹⁾, *Glass capillary kinematic viscometers — Specifications and operating instructions*.

ISO 3451-4:1986, *Plastics — Determination of ash — Part 4: Polyamides*.

ISO 6427:1992, *Plastics — Determination of matter extractable by organic solvents (conventional methods)*.

ASTM D 789:1986, *Standard test methods for determination of relative viscosity, melting point, and moisture content of polyamide (PA)*.

3 Definitions

For the purposes of this International Standard, the definitions given in ISO 1628-1 and the following definition apply.

1) To be published. (Revision of ISO 3105:1976)

3.1 viscosity number (of a polymer): The value given by the formula

$$\left(\frac{\eta}{\eta_0} - 1 \right) \frac{1}{\rho_P}$$

where

- η is the viscosity of a solution of the polymer in a specified solvent;
- η_0 is the viscosity of the solvent, expressed in the same units as η ;
- ρ_P is the concentration, in grams per millilitre, of the polymer in the solution.

The viscosity number is usually expressed in millilitres per gram.

4 Principle

The times of flow of a solvent and a solution of the polyamide at a concentration of 0,005 g/ml in the solvent are measured at 25 °C, the same viscometer being used for both measurements. The viscosity number is calculated from these measurements and from the known concentration of the solution.

5 Reagents and materials

Use only reagents of recognized analytical grade and only distilled water or water of equivalent purity.

WARNING — Avoid contact with the skin and inhalation of any vapours of the solvents and cleaning liquids.

5.1 Solvents

5.1.1 Sulfuric acid, 96 % (*m/m*) \pm 0,15 % (*m/m*) solution.

For the determination of the concentration of commercial sulfuric acid (95 % to 97 %) and adjustment to 96,0 %, see annex A.

5.1.2 Formic acid, 90 % (*m/m*) \pm 0,15 % (*m/m*) solution.

The solvent shall be stored in a brown glass bottle. Its concentration shall be checked at least every 2 weeks. It shall not contain more than 0,2 % acetic acid or methyl formate.

5.1.3 *m*-Cresol, meeting the following specifications:

appearance: clear and colourless

m-cresol content: 99 % (*m/m*) min.

o-cresol content: 0,3 % (*m/m*) max.

water content: 0,13 % (*m/m*) max.

m-Cresol of the required purity can be obtained by distillation of chemically pure *m*-cresol, preferably *in vacuo*.

To avoid oxidation, nitrogen shall preferably be used for pressure compensation. Its purity may be checked by gas chromatography. The solvent shall be stored in a brown glass bottle.

5.2 Cleaning liquids

5.2.1 Chromic acid solution, prepared by mixing equal volumes of sulfuric acid ($\rho = 1,84$ g/ml) and a saturated solution of potassium dichromate. If required, the chromic acid solution may be replaced by other, equally effective cleaning liquids.

5.2.2 Acetone, freshly distilled.

6 Apparatus

6.1 Vacuum drying cabinet, pressure less than 100 kPa.

6.2 Balance, accurate to 0,1 mg.

6.3 Volumetric flask, capacity 50 ml, complying with the requirements of ISO 1042, fitted with a ground-glass stopper.

6.4 Shaking apparatus or magnetic stirrer.

6.5 Sintered-glass filter, with a pore size between 40 μm and 100 μm (grade P 100), or **stainless-steel sieve**, with apertures of about 0,075 mm².

6.6 Viscometer, of the suspended-level Ubbelohde type, complying with the requirements of ISO 3105. The essential dimensions of the viscometer are shown in figure 1. For use with the formic acid solution (5.1.2), the inside diameter of the capillary shall be 0,58 mm \pm 2 % (complying with the requirements of size No. 1 of ISO 3105). For use with the sulfuric acid solution (5.1.1) or *m*-cresol (5.1.3), the inside diameter of the capillary shall be 1,03 mm \pm 2 %

(complying with the requirements of size No. 2 of ISO 3105).

Other types of viscometer listed in ISO 3105 may be used, provided that the results are equivalent to those of the Ubbelohde viscometers specified above. However, in cases of dispute, an Ubbelohde viscometer shall be used.

6.7 Thermostatic bath, capable of being maintained at $25\text{ °C} \pm 0,05\text{ °C}$.

6.8 Stop-watch, accurate to 0,1 s.

6.9 Centrifuge.

7 Preparation of test samples

7.1 General

Polyamide test samples for the determination of the viscosity number shall be completely soluble in the solvents mentioned, and the additives contained in them (reinforcement fibres, flame-retardants and modifiers) shall not interfere with the viscosity measurement, or it shall be possible to separate the additives quantitatively from the solution as with glass and carbon fibres, for instance.

If the content of these additives is greater than 2 % (*m/m*), it shall be determined quantitatively to allow the exact test portion size to be calculated (see table 1).

Exception: an extracted sample if it contains extractable additives (see 7.2).

7.2 Samples with extractable ingredients

The ground polymer remaining after extraction in accordance with ISO 6427 or ISO 599 shall be dried by heating for 3 h at 100 °C under vacuum and used as the test sample.

7.3 Samples with auxiliaries (non-hydrolyzable and without ash) that are insoluble in hydrochloric acid, e.g. polymer modifiers, carbon fibres and certain flame-retardants

Preliminary tests shall be carried out to determine whether the sample is completely soluble in the sol-

vent to be used, i.e. that it does not form particles of gel.

The fraction of polymer modifier and other additives that are insoluble in hydrochloric acid is determined from the hydrolysis residue (this method will form the subject of a future International Standard) and the correct amount of polyamide sample to be weighed out is calculated using equation 8.2.

NOTE 1 Experience indicates that the usual polymer modifiers for polyamides, e.g. ethylene copolymers and EP rubber, are so finely dispersed in the solution of the sample that the solution viscosity is practically unaffected, provided that the solution is free from gel particles.

If carbon fibres that can be detected in the hydrolysis residue under an optical microscope are present, they shall be filtered off from the solution of the polyamide sample by means of a filter crucible with a glass frit.

7.4 Samples with auxiliaries that are soluble in dilute hydrochloric acid and/or cannot be determined from the ash owing to oxide formation, e.g. carbonates, metal powders and certain pigments

The residue on dissolution in 90 % formic acid is determined as follows:

Shake or stir the polyamide sample for several hours at room temperature in about 10 times its own volume of 90 % formic acid using the procedure described in 10.2.

Separate off the solid residue by filtration.

Carefully wash the residue with 90 % formic acid and then with acetone. Subsequently dry for 3 h at 100 °C under a vacuum. Weigh.

7.5 Samples with auxiliaries with determinable ash, e.g. glass fibres and silicates

The ash is determined by the method specified in ISO 3451-4, and the amount of polyamide sample to be weighed out is calculated using equation 8.2. When necessary, filter the solution of the sample through a filter crucible with a glass frit before making the measurement.

NOTE 2 Any glass fibres of the usual dimensions contained in the sample will sediment completely after 3 h to 4 h. In such cases, the test solution can be decanted for the measurement and thus does not need to be filtered.

Table 1 — Determination of additives in polyamide samples in order to be able to calculate the correct test portion size

Property determined	Test method	Additives determinable	Remarks	See subclause
Extractable-matter content	ISO 6427; ISO 599	Low-molecular-weight fractions Plasticizers Stabilizers Slip agents	Extract sample before measurement (thus no correction necessary to size of test portion)	7.2
Hydrolysis residue (no ash)	—	Polymer modifiers (e.g. ethylene and E/P copolymers) Carbon fibres Organic flame-retardants	Check solubility (if necessary, also determine ash and residue on dissolution)	7.3
Residue in 90 % formic acid solution (no ash)	—	Carbonates Metal powders Pigments Organic flame-retardants		7.4
Ash (no oxide conversion)	ISO 3451-4	Glass fibres Silicates Inorganic flame-retardants	If necessary, increase size of test portion	7.5

8 Calculation of mass of test portion

8.1 Polyamides with extractable matter content not greater than 2,00 % (m/m)

Calculate the mass m_c , in milligrams, of the test portion as follows:

$$m_c = \frac{250}{1 - \frac{w(\%)_1 + w(\%)_2 + w(\%)_3}{100}}$$

where

$w(\%)_1$ is the water content of the sample, expressed as a percentage by mass, determined in accordance with ISO 960;

$w(\%)_2$ is the content of inorganic materials (for example fillers or glass fibres) of the sample, expressed as a percentage by mass, determined in accordance with ISO 3451-4;

$w(\%)_3$ is the content of other materials (for example other polymers such as polyolefins, or additives, such as flame-retardants), expressed as a percentage by mass, determined by appropriate methods.

The corrections for $w(\%)_1$, $w(\%)_2$ and $w(\%)_3$ need only be applied if they exceed 0,5 % (m/m) each.

8.2 Polyamides with extractable matter content greater than 2,00 % (m/m)

Use the material extracted and dried according to 7.3 as the test sample. Calculate the mass m_c , in milligrams, of the test portion as follows:

$$m_c = \frac{250}{1 - \frac{w(\%)_2 + w(\%)_3}{100 - w(\%)_4}}$$

where

m_c , $w(\%)_2$ and $w(\%)_3$ have the same meanings as in 8.1;

$w(\%)_4$ is the content of extractable matter of the sample, expressed as a percentage by mass.

It has been assumed in this calculation that $w(\%)_2$ and $w(\%)_3$ have been determined on the unextracted sample and that the extracted and dried material will be kept dry, so that no correction for moisture in the test sample is required.

NOTE 3 When dissolved in 50 ml of solvent, a test portion weighing exactly m_c mg will give a solution containing (almost) exactly 5 mg of polymer per millilitre. For practical reasons, test portion masses of $(m_c \pm 5)$ mg are allowed. The resulting actual polymer concentration is taken into account in the calculation of the viscosity number.

9 Selection of solvent

9.1 The value of the viscosity number of a polyamide depends on the solvent used.

Three different solvents are described in this International Standard: sulfuric acid solution (5.1.1), formic acid solution (5.1.2) and *m*-cresol (5.1.3). The flow times of the solvents shall be determined at least once each day that they are used (see 10.3). If the flow time of a solvent differs by more than 1 % from the initial value at the time of preparation, the solvent shall be discarded and fresh solvent prepared.

The solvent or solvents to be used for a particular polyamide are specified below.

9.2 For PA 6, PA 66, PA 69, PA 610, PA MXD6 and corresponding copolyamides, the sulfuric acid or formic acid solution shall be used as solvent, unless these polyamides contain additives that liberate gases in acidic solvents, in which case *m*-cresol shall be used as the solvent.

NOTE 4 Graphs for interconversion of the viscosity numbers determined in sulfuric acid and in formic acid as solvent are presented in figure 2. The reliability of the conversion is discussed in 13.1.

9.3 For PA 612 and corresponding copolyamides, the sulfuric acid solution or *m*-cresol shall be used as solvent.

NOTE 5 Graphs for interconversion of the viscosity numbers determined in these two solvents are presented in

figure 3. The reliability of the conversion is discussed in 13.2.

9.4 For PA 11, PA 12 and PA 11/12 copolymers, *m*-cresol shall be used as solvent.

9.5 For other polyamides, any of the three solvents may be used.

10 Procedure

10.1 Cleaning of viscometer

Clean the viscometer (6.6) prior to the first use, again after discordant readings (for example when two successive determinations of the efflux time of the solvent differ more than 0,4 s) and, further, at intervals during regular use. For this purpose allow it to stand for at least 12 h filled with a cleaning agent (5.2), for example chromic acid solution (5.2.1). Remove the cleaning agent, rinse the viscometer with water, then with acetone (5.2.2) and dry, for example by a slow stream of filtered air or in the vacuum drying cabinet (6.1).

After each determination, drain the viscometer, rinse with the solvent, then with water, followed by acetone (5.2.2) and dry as described above.

However, if the next solution to be measured is of a polyamide of the same type and of a similar viscosity, it is permissible to drain the viscometer, wash it with the solution to be measured, and then fill it with this solution.

10.2 Preparation of test solution

Weigh, to the nearest 0,2 mg, a test portion of $(m_c \pm 5)$ mg, where m_c is the mass calculated in accordance with clause 8, working rapidly to minimize moisture pick-up by the polymer. If the weighing takes more than 2 min, reject the material and begin another weighing.

Transfer the test portion to the 50 ml volumetric flask (6.3) and add about 40 ml of the solvent selected in accordance with clause 9. Close the flask and shake, or stir with the magnetic stirrer (6.4), the contents until the polymer has dissolved. This may take from approximately 0,5 h to several hours, depending on the type of polyamide and the particle size of the test portion. When the sulfuric acid or formic acid solution is used as the solvent, the temperature shall not exceed 30 °C. When *m*-cresol is used as the solvent, the temperature may be raised to 95 °C to 100 °C. If, in the latter case, dissolution takes more than 2 h, this shall be reported.