



DRAFT INTERNATIONAL STANDARD ISO/DIS 17701

ISO/TC 216

Secretariat: AENOR

Voting begins on
2013-02-14

Voting terminates on
2013-07-14

INTERNATIONAL ORGANIZATION FOR STANDARDIZATION • МЕЖДУНАРОДНАЯ ОРГАНИЗАЦИЯ ПО СТАНДАРТИЗАЦИИ • ORGANISATION INTERNATIONALE DE NORMALISATION

Footwear — Test methods for uppers, lining and insoles — Colour migration

Chaussures — Méthodes d'essai des tiges, de la doublure et des garnitures intérieures — Migration de la couleur

[Revision of first edition (ISO 17701:2003)]

ICS 61.060

ISO/CEN PARALLEL PROCESSING

This draft has been developed within the European Committee for Standardization (CEN), and processed under the **CEN-lead** mode of collaboration as defined in the Vienna Agreement.

This draft is hereby submitted to the ISO member bodies and to the CEN member bodies for a parallel five-month enquiry.

Should this draft be accepted, a final draft, established on the basis of comments received, will be submitted to a parallel two-month approval vote in ISO and formal vote in CEN.

To expedite distribution, this document is circulated as received from the committee secretariat. ISO Central Secretariat work of editing and text composition will be undertaken at publication stage.

Pour accélérer la distribution, le présent document est distribué tel qu'il est parvenu du secrétariat du comité. Le travail de rédaction et de composition de texte sera effectué au Secrétariat central de l'ISO au stade de publication.

THIS DOCUMENT IS A DRAFT CIRCULATED FOR COMMENT AND APPROVAL. IT IS THEREFORE SUBJECT TO CHANGE AND MAY NOT BE REFERRED TO AS AN INTERNATIONAL STANDARD UNTIL PUBLISHED AS SUCH.

IN ADDITION TO THEIR EVALUATION AS BEING ACCEPTABLE FOR INDUSTRIAL, TECHNOLOGICAL, COMMERCIAL AND USER PURPOSES, DRAFT INTERNATIONAL STANDARDS MAY ON OCCASION HAVE TO BE CONSIDERED IN THE LIGHT OF THEIR POTENTIAL TO BECOME STANDARDS TO WHICH REFERENCE MAY BE MADE IN NATIONAL REGULATIONS.

RECIPIENTS OF THIS DRAFT ARE INVITED TO SUBMIT, WITH THEIR COMMENTS, NOTIFICATION OF ANY RELEVANT PATENT RIGHTS OF WHICH THEY ARE AWARE AND TO PROVIDE SUPPORTING DOCUMENTATION.

iTeh STANDARD PREVIEW
(standards.iteh.ai)

Full standard:
<https://standards.iteh.ai/catalog/standards/sist/470a2a3b-83f7-411e-b0c-7e803a751371/iso-17701-2016>

Copyright notice

This ISO document is a Draft International Standard and is copyright-protected by ISO. Except as permitted under the applicable laws of the user's country, neither this ISO draft nor any extract from it may be reproduced, stored in a retrieval system or transmitted in any form or by any means, electronic, photocopying, recording or otherwise, without prior written permission being secured.

Requests for permission to reproduce should be addressed to either ISO at the address below or ISO's member body in the country of the requester.

ISO copyright office
Case postale 56 • CH-1211 Geneva 20
Tel. + 41 22 749 01 11
Fax + 41 22 749 09 47
E-mail copyright@iso.org
Web www.iso.org

Reproduction may be subject to royalty payments or a licensing agreement.

Violators may be prosecuted.

Foreword

ISO (the International Organization for Standardization) is a worldwide federation of national standards bodies (ISO member bodies). The work of preparing International Standards is normally carried out through ISO technical committees. Each member body interested in a subject for which a technical committee has been established has the right to be represented on that committee. International organizations, governmental and non-governmental, in liaison with ISO, also take part in the work. ISO collaborates closely with the International Electrotechnical Commission (IEC) on all matters of electrotechnical standardization.

International Standards are drafted in accordance with the rules given in the ISO/IEC Directives, Part 2.

The main task of technical committees is to prepare International Standards. Draft International Standards adopted by the technical committees are circulated to the member bodies for voting. Publication as an International Standard requires approval by at least 75 % of the member bodies casting a vote.

Attention is drawn to the possibility that some of the elements of this document may be the subject of patent rights. ISO shall not be held responsible for identifying any or all such patent rights.

ISO 17701 was prepared by Technical Committee ISO/TC 216, *Footwear*, and by Technical Committee CEN/TC 309, *Footwear* in collaboration.

This second edition cancels and replaces the first edition (ISO 17701:2003), which has been technically revised.

iTeh STANDARD PREVIEW
(standards.iteh.ai)

Full standard:
<https://standards.iteh.ai/catalog/standards/sist/470a2a3b-83f7-411e-bf0c-7e803a751371/iso-17701-2016>

Footwear — Test methods for uppers, lining and insoles — Colour migration

1 Scope

This European standard specifies a test method for determining the propensity of a material to cause discolouration of another material when stored in close contact. This method is applicable to all materials which are used in intimate contact, and to adhesives which are used to bond them.

2 Normative references

The following referenced documents are indispensable for the application of this document. For dated references, only the edition cited applies. For undated references, the latest edition of the referenced document (including any amendments) applies.

ISO 18454 Footwear - Standard atmospheres for conditioning and testing of footwear and components for footwear

EN ISO 105-A01, Textiles - Tests for colour fastness - Part A01: General principles of testing

EN ISO 105-A02, Textiles - Tests for colour fastness - Part A02: Grey scale for assessing change in colour

EN ISO 105-A03, Textiles - Tests for colour fastness - Part A03: Grey scale for assessing staining

EN ISO 1995; Footwear - Vocabulary

CIE 15; Colorimetry

3 Terms and definitions

For the purposes of this document, the following terms and definitions given in EN ISO 1995:2005, and the following apply

3.1

colour migration

Discolouration caused by movement of colour from one material to another

4 Apparatus and material

The following apparatus and material shall be used:

4.1 Knife to cut the test specimen

4.2 Two smooth and even glass plates at least 70 mm x 70 mm and a mass of $50 \text{ g} \pm 5 \text{ g}$

4.3 Mass of sufficient size that when combined with the mass of the glass plate will exert a pressure of $5,2 \text{ kPa} \pm 0,5 \text{ kPa}$

NOTE The necessary mass depends of the area of the test specimen to get the same pressure.

Example:

Area of test specimen = 30 x 20 mm = 600 mm²

Mass = pressure x area

Mass = 5,2 kPa x 600 mm² = 5 200 Pa x 600 mm² = 5 200 kg x m⁻¹ * s⁻² x 6 x 10⁻⁴ m²

Mass = 3,12 kg x m x s⁻² = 3,12 N

A mass of 3,12 N (these are 0,318 kg) is necessary to get a pressure of 5,2 kPa.

Please note that the mass of one glass plate has to be subtracted: mass = 318 g – 50 g = 268g.

If the area of the test specimen is 50 x 40 mm, a mass of 1,060 kg is necessary to get the same pressure. Please note that the mass of one glass plate has to be subtracted: mass = 1 060 g – 50 g = 1 010 g.

4.4 Oven with a temperature of 60 °C ± 2 °C

NOTE The oven must not have a door or window of glass.

4.5 Colorimeter to measure the colour of the test specimen and the reference specimen to convert the results in CIE- colour values and to calculate automatically the CIELAB- colour differences concerning CIE 15: 2004

The colorimeter has to be calibrated with a white standard (normal light D 65, normal observer 10°, measure geometry d18°).

4.6 Grey scales with half step rating for assessing change in colour and degree of staining complying with EN ISO 105-A02 and EN ISO 105-A03, respectively.

4.7 Artificial lighting conditions as specified in EN ISO 105-A01 or north daylight.

5 Sampling and conditioning

Store the test materials in a conditioned standard atmosphere as specified in EN 18454 for a minimum of 24 h prior to testing.

5.1 Testing for colour migration between materials

Cut two test specimens from each material, the dark coloured material and the light coloured material with a size of 30 x 20 mm (± 2 mm) as minimum. One of each type of test specimen is the reference sample.

If there are insufficient materials, smaller samples may be used and a proportionally lower mass than 1 000 g ± 10 g to maintain the same contact pressure.

5.2 Testing for the effect of adhesives

Cut two samples of the test material with a size of (50 ± 2) mm x (50 ± 2) mm. One of the test specimens is the reference sample.

Coat the centre of the surface, to which the adhesive would be applied in production with the adhesive under test, so that the coating covers approximately 75% of the area of the test specimen. Use a quantity of adhesive that is judged to be representative of that to be used in production. Allow the adhesive to dry at room temperature.

5.3 Testing for the effect of adhesives in laminate

Cut two samples from each material to be laminated together with a size of (50 ± 2) mm x (50 ± 2) mm, when testing for the effect of an adhesive within a laminate. One of each type of test specimen is the reference sample.

5.3.1 When testing for the effect of adhesives within a laminate, where a wet bond is used in production, place the two materials together and press by hand to form a bonded assembly and allow the adhesive to dry at room temperature.

5.3.2 When testing for the effect of adhesives within a laminate where the bond is formed with dry adhesive films, join the two materials using a technique similar to that used in production.

5.4 Testing components such as soling

5.4.1 Prepare by suitable means, a test specimen of uniform thickness from the sole or other component.

5.4.2 Cut a test specimen from the material and two pieces of the second test material (5.1 – one as reference sample).

NOTE Specimens can be taken either from materials likely to be used for uppers or from made up uppers or finished footwear.

6 Test method

6.1 Principle

Either two dissimilar materials are placed in intimate contact, or a single piece of material, coated with a product such as an adhesive, or laminated materials are placed between glass plates. The assembly is stored in the dark for a prescribed period at an elevated temperature. The test specimens are then examined for any discolouration compared to unexposed reference samples. Discolouration indicates that the materials are likely to discolour under normal service conditions.

6.2 Procedure

The CIE values of the colour of all test specimens have to be measured with the colorimeter (including the reference samples). Store the reference samples darkly in standard conditioned atmosphere as specified in ISO 18454.

6.2.1 For assemblies of two materials not joined together with adhesive.

6.2.1.1 Place the first test specimen centrally on a glass plate (see 4.2) with its contact face uppermost.

6.2.1.2 Place the other test specimen with its contact face lowermost on the first specimen.

6.2.1.3 Place the remaining glass plate (see 4.1) centrally on top of the specimens.

6.2.2 For adhesive coated single materials and laminates, place the test specimen between the two glass plates.

6.2.3 Place the mass (see 4.3) symmetrically on the top glass plate (see 4.2).

6.2.4 Place the assembly (see 6.2.1 or 6.2.2) in the dark test environment at $(60 \pm 2) ^\circ\text{C}$ (see 4.3).

6.2.5 After 24 h remove the assembly from the test environment.

6.2.6 For assemblies of two not joined materials; separate the two materials and compare their contact faces to the reference samples. Assess in accordance with 6.2.8.

6.2.7 For adhesive coated single materials and laminates, remove the test specimen and compare the face not coated with adhesive to unexposed material. Assess in accordance with 6.2.8.

6.2.8 Measure the CIE values (concerning CIE 15:2004) of the colour with the colorimeter (see 4.5). The use of the artificial lighting or north daylight is an other method (0). Assess any loss of colour by comparing the contrast in colour between tested and non-tested material with the ratings on the grey scale.

6.2.8.1 Measure any loss of colour by comparing the colour between tested and non-tested material for assessing the change in colour.

- 6.2.8.2 Measure any transfer of colour by comparing the colour between tested and non-tested material for assessing the staining.
- 6.2.8.3 In all cases assess the area showing the most marked contrast.
- 6.2.8.4 Record a description of the loss of colour or transfer of colour alongside the numerical ratings obtained in 6.2.8.1 and 6.2.8.2 in terms of colour, intensity and uniformity of the change.
- 6.2.9 Repeat the procedure from 6.2.1 to 6.2.8. Remove the assembly from the test environments after every $24\text{ h} \pm 1\text{ h}$ until a total exposure time of 7 days has been reached.

7 Test report

The test report shall include the following information:

- a) for each inspection carried out, a description of any loss of colour or transfer of colour of each test specimen as determined in 6.2.8 and the corresponding cumulative contact time;
- b) method used for the measurement of colour changes
- c) description of the materials or samples that were tested, including commercial references (style codes etc.);
- d) reference to this standard;
- e) date of testing;
- f) date of analysis;
- g) any deviation from this test method.

DR
AW
ST
AND
AR
D

PREVIEW
(standards.iteh.ai)
Full standard:
<https://standards.iteh.ai/catalog/standards/sist/470a2a3b-8317-411e-b00c-7c803a751371/iso-17701-2016>