ISO TC 147/SC 3

Date: 2018-<u>07</u> ISO,13169:2018(E) ISO TC 147/SC 3/WG 4 Secretariat: AFNOR



Water quality — Uranium — Test method using alpha liquid scintillation counting

Qualité de l'eau — Uranium — Méthode d'essai par comptage des scintillations alpha en milieu liquide

## iTeh STANDARD PREVIEW (standards.iteh.ai)

<u>ISO 13169:2018</u> https://standards.iteh.ai/catalog/standards/sist/43cac5df-24a0-46e2-97ae-c099<mark>e0edeb26/iso-</mark> 13169-2018

### iTeh STANDARD PREVIEW (standards.iteh.ai)

ISO 13169:2018

https://standards.iteh.ai/catalog/standards/sist/43cac5df-24a0-46e2-97ae-c099e0edeb26/iso-13169-2018

#### Contents

Introduction       vi         1       Scope       1         2       Normative references       1         3       Terms, definitions, symbols and units       1         4       Principle       2         5       Reagents and equipment       3         5.1       Reagents       3         5.2       Equipment       3         6       Sampling       4         7       Instrument set up and calibration       4         7.1       Preparation of extractant scintillation cocktail       4         7.2       Preparation of counting conditions       4         7.4       Optimization of counting conditions       4         7.5       Detection efficiency       5         7.6       Blank sample preparation and measurement       5         8       Procedure       5         8.1       Without pre-concentration       6         8.2       Pre-concentration by evaporation       6         8.3       Sample measurement       6         9.4       Detection limit       7         9.5       Confidence limits       7         9.4       Detection limit       7         9.5       <	Fo	orev	word	v
2       Normative references       1         3       Terms, definitions, symbols and units       1         4       Principle       2         5       Reagents and equipment       3         5.1       Reagents       3         5.2       Equipment       3         6       Sampling       4         7       Instrument set up and calibration       4         7.1       Preparation of extractant scintillation cocktail       4         7.2       Preparation of alpha emitter calibration source       4         7.3       Preparation of counting conditions       4         7.4       Optimization of counting conditions       4         7.5       Detection efficiency       5         8       Procedure       5         8.1       Without pre-concentration       6         8.2       Pre-concentration by evaporation       6         8.3       Sample measurement       6         9       Expression of results       6         9.1       Calculation of activity per unit of mass.       6         9.2       Standard uncertainty.       7         9.4       Detection limit       7         9.5       Confidenc	In	tro	duction	vi
3       Terms, definitions, symbols and units       1         4       Principle       2         5       Reagents and equipment       3         5.1       Reagents       3         5.2       Equipment       3         6       Sampling       4         7       Instrument set up and calibration       4         7.1       Preparation of extractant scintillation cocktail       4         7.2       Preparation of beta emitter calibration source       4         7.3       Preparation of beta emitter calibration source       4         7.4       Optimization of counting conditions       4         7.5       Detection efficiency       5         7.6       Blank sample preparation and measurement       5         8       Procedure       5         8.1       Without pre-concentration       6         8.3       Sample measurement       6         9.4       Sauperement       6         9.1       Calculation of activity per unit of mass       6         9.2       Standard uncertainty       6         9.3       Decision threshold       7         9.4       Detection limit       7         9.5	1	5	Scope	1
4       Principle       2         5       Reagents and equipment       3         5.1       Reagents       3         5.2       Equipment       3         6       Sampling       4         7       Instrument set up and calibration       4         7.1       Preparation of extractant scintillation cocktail       4         7.2       Preparation of alpha emitter calibration source       4         7.3       Preparation of beta emitter calibration source       4         7.4       Optimization of conting conditions       4         7.5       Detection efficiency       5         7.6       Blank sample preparation and measurement       5         8       Procedure       5         8.1       Without pre-concentration       6         8.2       Pre-concentration by evaporation       6         8.3       Sample preparation       6         8.4       Sample measurement       6         9.1       Calculation of activity per unit of mass       6         9.2       Standard uncertainty       6         9.3       Decision threshold       7         9.4       Detection limit       7         9.5	2	ľ	Normative references	1
5       Reagents and equipment       3         5.1       Reagents       3         5.2       Equipment       3         6       Sampling       4         7       Instrument set up and calibration       4         7.1       Preparation of extractant scintillation cocktail       4         7.1       Preparation of extractant scintillation source       4         7.2       Preparation of beta emitter calibration source       4         7.3       Preparation of counting conditions       4         7.4       Optimization of counting conditions       4         7.5       Detection efficiency       5         7.6       Blank sample preparation and measurement       5         8       Procedure       5         8.1       Without pre-concentration       5         8.2       Pre-concentration by evaporation       6         8.3       Sample measurement       6         8.4       Sample measurement       6         9.1       Calculation of activity per unit of mass       6         9.2       Standard uncertainty       6         9.3       Decision threshold       7         9.4       Detection limit       7 <tr< th=""><th>3</th><th>1</th><th>Геrms, definitions, symbols and units</th><th>1</th></tr<>	3	1	Геrms, definitions, symbols and units	1
5.1       Reagents       3         5.2       Equipment       3         6       Sampling       4         7       Instrument set up and calibration       4         7.1       Preparation of extractant scintillation cocktail       4         7.2       Preparation of alpha emitter calibration source       4         7.3       Preparation of beta emitter calibration source       4         7.4       Optimization of counting conditions       4         7.5       Detection efficiency.       5         7.6       Blank sample preparation and measurement       5         8       Procedure       5         8.1       Without pre-concentration       5         8.2       Pre-concentration by evaporation       6         8.3       Sample preparation       6         8.4       Sample measurement       6         9.1       Calculation of activity per unit of mass       6         9.2       Standard uncertainty       6         9.3       Decision threshold       7         9.4       Detection limit       7         9.5       Confidence limits       7         9.6       Calculations using the concentration activity       7 <th>4</th> <th>I</th> <th>Principle</th> <th>2</th>	4	I	Principle	2
5.2       Equipment       3         6       Sampling       4         7       Instrument set up and calibration       4         7.1       Preparation of extractant scintillation cocktail       4         7.2       Preparation of alpha emitter calibration source       4         7.3       Preparation of beta emitter calibration source       4         7.4       Optimization of counting conditions.       4         7.5       Detection efficiency       5         7.6       Blank sample preparation and measurement       5         8       Procedure       5         8.1       Without pre-concentration       5         8.2       Pre-concentration by evaporation       6         8.4       Sample measurement       6         9.1       Calculation of activity per unit of mass       6         9.2       Standard uncertainty       6         9.3       Decision threshold       7         9.4       Detection limit       7         9.5       Confidence limits       7         9.6       Calculations using the concentration activity       7         10       Interference control       8         11       Quality control       8	5	I	Reagents and equipment	3
6       Sampling		5.1	Reagents	3
7       Instrument set up and calibration       4         7.1       Preparation of extractant scintillation cocktail       4         7.2       Preparation of alpha emitter calibration source       4         7.3       Preparation of beta emitter calibration source       4         7.4       Optimization of counting conditions       4         7.5       Detection efficiency       5         7.6       Blank sample preparation and measurement       5         8       Procedure       5         8.1       Without pre-concentration       6         8.3       Sample preparation       6         8.4       Sample measurement       6         9.1       Calculation of activity per unit of mass       6         9.2       Standard uncertainty       6         9.3       Decision threshold       7         9.4       Detection limit       7         9.5       Confidence limits       7         9.6       Calculations using the concentration activity       7         10       Interference control       8         11       Quality control       8         12       Test report       8 <th></th> <th>5.2</th> <th>Equipment</th> <th>3</th>		5.2	Equipment	3
7.1       Preparation of extractant scintillation cocktail       4         7.2       Preparation of alpha emitter calibration source       4         7.3       Preparation of beta emitter calibration source       4         7.4       Optimization of counting conditions       4         7.5       Detection efficiency       5         7.6       Blank sample preparation and measurement       5         8       Procedure       5         8.1       Without pre-concentration       6         8.2       Pre-concentration by evaporation       6         8.3       Sample preparation       6         8.4       Sample preparation       6         9       Expression of results       6         9.1       Calculation of activity per unit of mass       6         9.2       Standard uncertainty       6         9.3       Decision threshold       7         9.4       Detection limit       7         9.5       Confidence limits       7         9.6       Calculations using the concentration activity       7         10       Interference control       8         11       Quality control       8         12       Test report       8	6	9	Sampling	4
7.2       Preparation of alpha emitter calibration source       4         7.3       Preparation of beta emitter calibration source       4         7.4       Optimization of counting conditions       4         7.5       Detection efficiency       5         7.6       Blank sample preparation and measurement       5         8       Procedure       5         8.1       Without pre-concentration       5         8.2       Pre-concentration by evaporation       6         8.3       Sample preparation       6         8.4       Sample measurement       6         9       Expression of results       6         9.1       Calculation of activity per unit of mass       6         9.2       Standard uncertainty       6         9.3       Decision threshold       7         9.4       Detection limit       7         9.5       Confidence limits       7         9.6       Calculations using the concentration activity       7         10       Interference control       8         11       Quality control       8         12       Test report       8         13       Latereport       8         14	7	Ι	Instrument set up and calibration	4
7.3       Preparation of beta emitter calibration source       4         7.4       Optimization of counting conditions       4         7.5       Detection efficiency       5         7.6       Blank sample preparation and measurement       5         8       Procedure       5         8.1       Without pre-concentration       5         8.2       Pre-concentration by evaporation       6         8.3       Sample preparation       6         8.4       Sample measurement       6         9       Expression of results       6         9.1       Calculation of activity per unit of mass       6         9.2       Standard uncertainty       6         9.3       Decision threshold       7         9.4       Detection limit       7         9.5       Confidence limits       7         9.6       Calculations using the concentration activity       8		7.1	Preparation of extractant scintillation cocktail	4
7.4       Optimization of counting conditions.       4         7.5       Detection efficiency		7.2	Preparation of alpha emitter calibration source	4
7.5       Detection efficiency		7.3		
7.5       Detection efficiency		7.4	Optimization of counting conditions	4
8       Procedure       5         8.1       Without pre-concentration       5         8.2       Pre-concentration by evaporation       6         8.3       Sample preparation       6         8.4       Sample measurement       6         9       Expression of results       6         9.1       Calculation of activity per unit of mass       6         9.2       Standard uncertainty       6         9.3       Decision threshold       7         9.4       Detection limit       7         9.5       Confidence limits       7         9.6       Calculations using the concentration activity       7         10       Interference control       8         11       Quality control       8         12       Test report       8         Annex A (informative) Set-up parameters and validation data       10		7.5	Detection efficiency	5
8       Procedure       5         8.1       Without pre-concentration       5         8.2       Pre-concentration by evaporation       6         8.3       Sample preparation       6         8.4       Sample measurement       6         9       Expression of results       6         9.1       Calculation of activity per unit of mass       6         9.2       Standard uncertainty       6         9.3       Decision threshold       7         9.4       Detection limit       7         9.5       Confidence limits       7         9.6       Calculations using the concentration activity       7         10       Interference control       8         11       Quality control       8         12       Test report       8         Annex A (informative) Set-up parameters and validation data       10		7.6	Blank sample preparation and measurement	5
8.2       Pre-concentration by evaporation	8	ł		
8.3       Sample preparation		8.1	Without pre-concentration	5
8.3       Sample preparation		8.2	Pre-concentration by evaporation	69e0edeb26/isc
9Expression of results69.1Calculation of activity per unit of mass69.2Standard uncertainty69.3Decision threshold79.4Detection limit79.5Confidence limits79.6Calculations using the concentration activity710Interference control811Quality control812Test report8Annex A (informative) Set-up parameters and validation data10		8.3	Sample preparation	6
9.1Calculation of activity per unit of mass		8.4	Sample measurement	6
9.2       Standard uncertainty	9	ł	Expression of results	6
9.3Decision threshold		9.1	Calculation of activity per unit of mass	6
9.4Detection limit		9.2	Standard uncertainty	6
9.5Confidence limits		9.3	Decision threshold	7
9.6       Calculations using the concentration activity		9.4	Detection limit	7
10 Interference control		9.5	Confidence limits	7
11 Quality control       8         12 Test report       8         Annex A (informative) Set-up parameters and validation data       10		9.6	Calculations using the concentration activity	7
12 Test report	1	DI	Interference control	8
Annex A (informative) Set-up parameters and validation data	1	1 (	Quality control	8
	12	2 7	Гest report	8
Bibliography14	A	nne	ex A (informative) Set-up parameters and validation data1	0
	Bi	ibli	ography1	4

### iTeh STANDARD PREVIEW (standards.iteh.ai)

ISO 13169:2018

https://standards.iteh.ai/catalog/standards/sist/43cac5df-24a0-46e2-97ae-c099e0edeb26/iso-13169-2018

#### Foreword

ISO (the International Organization for Standardization) is a worldwide federation of national standards bodies (ISO member bodies). The work of preparing International Standards is normally carried out through ISO technical committees. Each member body interested in a subject for which a technical committee has been established has the right to be represented on that committee. International organizations, governmental and non-governmental, in liaison with ISO, also take part in the work. ISO collaborates closely with the International Electrotechnical Commission (IEC) on all matters of electrotechnical standardization.

The procedures used to develop this document and those intended for its further maintenance are described in the ISO/IEC Directives, Part 1. In particular, the different approval criteria needed for the different types of ISO documents should be noted. This document was drafted in accordance with the editorial rules of the ISO/IEC Directives, Part 2 (see www.iso.org/directives).

Attention is drawn to the possibility that some of the elements of this document may be the subject of patent rights. ISO shall not be held responsible for identifying any or all such patent rights. Details of any patent rights identified during the development of the document will be in the Introduction and/or on the ISO list of patent declarations received (see <a href="https://www.iso.org/patents">www.iso.org/patents</a>).

Any trade name used in this document is information given for the convenience of users and does not constitute an endorsement.

For an explanation <u>of</u> the voluntary nature of standards, the meaning of ISO specific terms and expressions related to conformity assessment, as well as information about ISO's adherence to the World Trade Organization (WTO) principles in the Technical Barriers to Trade (TBT) see <u>www.iso.org/iso/foreword.html</u>.

This document was prepared by Technical Committee ISO/TC 147, *Water quality*, Subcommittee SC 3, *Radioactivity measurements*.

Any feedback or questions on this document should be directed to the user's national standards body. A complete listing of these bodies can be found at www.iso.org/members.html.

- Deleted: on

#### Introduction

Radioactivity from several naturally-occurring and anthropogenic sources is present throughout the environment. Thus, water bodies (e.g. surface waters, ground waters, sea waters) can contain radionuclides of natural, human-made, or both origins.

- Natural radionuclides, including 40K, 3H, 14C, and those originating from the thorium and uranium decay series, in particular 226Ra, 228Ra, 234U, 238U, 210Po and 210Pb can be found in water for natural reasons (e.g. desorption from the soil and washoff by rain water) or can be released from technological processes involving naturally occurring radioactive materials (e.g. the mining and processing of mineral sands or phosphate fertilizers production and use).
- Human-made radionuclides such as transuranium elements (americium, plutonium, neptunium, curium), 3H, 14C, 90Sr and gamma emitting radionuclides can also be found in natural waters. Small quantities of these radionuclides are discharged from nuclear fuel cycle facilities into the environment as a result of authorized routine releases. Some of these radionuclides used for medical and industrial applications are also released into the environment after use. Anthropogenic radionuclides are also found in waters as a result of past fallout contaminations resulting from the explosion in the atmosphere of nuclear devices and accidents such as those that occurred in Chernobyl and Fukushima.

Radionuclide activity concentration in water bodies can vary according to local geological characteristics and climatic conditions and can be locally and temporally enhanced by releases from nuclear installation during planned, existing and emergency exposure situations<sup>[1]</sup>. Drinking-water may thus contain radionuclides at activity concentrations which could present a risk to human health.

The radionuclides present in liquid effluents are usually controlled before being discharged into the environment<sup>[2]</sup> and water bodies. Drinking waters are monitored for their radioactivity as recommended by the World Health Organization (WHO)<sup>[3]</sup>, so that proper actions can be taken to ensure that there is no adverse health effect to the public. Following these international recommendations, national regulations usually specify radionuclide authorized concentration limits for liquid effluent discharged to the environment and radionuclide guidance levels for waterbodies and drinking waters for planned, existing, and emergency exposure situations. Compliance with these limits can be assessed using measurement results with their associated uncertainties as specified by ISO/IEC Guide 98-3 and ISO 5667-20<sup>[4]</sup>.

Depending on the exposure situation, there are different limits and guidance levels that would result in an action to reduce health risk. As an example, during a planned or existing situation, the WHO guidelines for guidance level for uranium 238 and uranium 234 in drinking water is 10 Bq/l and 1 Bq/l, respectively. The provisional guideline value for total content of uranium in drinking water is  $30 \mu g/l$  based on its chemical toxicity, which is predominant compared with its radiological toxicity.

NOTE 1 The guidance level is the activity concentration with an intake of 2 l/d of drinking water for one year that results in an effective dose of 0,1 mSv/a for members of the public. This is an effective dose that represents a very low level of risk and which is not expected to give rise to any detectable adverse health effects<sup>[3]</sup>.

In the event of a nuclear emergency, the WHO Codex Guideline Levels<sup>[6]</sup> state that the activity concentration might not be greater than 100 Bq/l for uranium 235.

NOTE 2 The Codex guidelines levels (GLs) apply to radionuclides contained in foods destined for human consumption and traded internationally, which have been contaminated following a nuclear or radiological emergency. These GLs apply to food after reconstitution or as prepared for consumption, i.e. not to dried or concentrated foods, and are based on an intervention exemption level of 1 mSv in a year for members of the public (infant and adult)<sup>[6]</sup>.

Thus, the test method can be adapted so that the characteristic limits, decision threshold, detection limit and uncertainties ensure that the radionuclide activity concentrations test results can be verified to be below the guidance levels required by a national authority for either planned/existing situations or for an emergency situation<sup>[5][6][7]</sup>.

e0edeb26/iso-

Usually, the test methods can be adjusted to measure the activity concentration of the radionuclide(s) in either wastewaters before storage or in liquid effluents before being discharged to the environment. The test results will enable the plant/installation operator to verify that, before their discharge, wastewaters/liquid effluent radioactive activity concentrations do not exceed authorized limits.

The test method(s) described in this document may be used during planned, existing and emergency exposure situations as well as for wastewaters and liquid effluents with specific modifications that could increase the overall uncertainty, detection limit and threshold.

The test method(s) may be used for water samples after proper sampling, sample handling and test sample preparation (see the relevant part of the ISO 5667 series).

An International Standard on a test method <u>for total</u> activity <u>concentration of uranium isotopes</u> in water samples is justified for test laboratories carrying out these measurements, required sometimes by national authorities, as laboratories may have to obtain a specific accreditation for radionuclide measurement in drinking water samples.

This document is one of a set of International Standards on test methods dealing with the measurement of the activity concentration of radionuclides in water samples.

### iTeh STANDARD PREVIEW (standards.iteh.ai)

<u>ISO 13169:2018</u>

https://standards.iteh.ai/catalog/standards/sist/43cac5df-24a0-46e2-97ae-c099e0edeb26/iso-13169-2018

Deleted: of gross alpha and gross beta
Deleted: concentrations

### iTeh STANDARD PREVIEW (standards.iteh.ai)

ISO 13169:2018

https://standards.iteh.ai/catalog/standards/sist/43cac5df-24a0-46e2-97ae-c099e0edeb26/iso-13169-2018

# Water quality — Uranium — Test method using alpha liquid scintillation counting

WARNING — Persons using this document should be familiar with normal laboratory practice. This document does not purport to address all of the safety problems, if any, associated with its use. It is the responsibility of the user to establish appropriate safety and health practices.

IMPORTANT — It is absolutely essential that tests conducted in accordance with this document be carried out by suitably qualified staff.

#### 1 Scope

This document specifies the measurement method for the determination of total activity concentration of uranium isotopes in non-saline waters by extraction and liquid scintillation counting.

This method covers the measurement of soluble uranium isotopes in water in activity concentrations between approximately  $2 \cdot 10^{-3}$  Bq/kg and 10 Bq/kg when analysing a 11 test sample volume with a 60 000 s counting time with a typical alpha LSC instrument.

The ratio  ${}^{234}\text{U}/{}^{238}\text{U}$  can also be determined. This method has not been tested for the measurement of other uranium isotopes.

#### 2 Normative references

The following documents are referred to in the text in such a way that some or all of their content constitutes requirements of this document. For dated references, only the edition cited applies. For undated references, the latest edition of the referenced document (including any amendments) applies.

ISO 3696, Water for analytical laboratory use - Specification and test methods

https://standards.iteh.ai/catalog/standards/sist/43cac5df-24a0-46e2-9/ae-c099e0edeb26/iso

ISO 5667-1, Water quality — Sampling — Part 1: Guidance on the design of sampling programmes and sampling techniques

ISO 5667-3, Water quality — Sampling — Part 3: Guidance on the preservation and handling of water samples

ISO 80000-10, Quantities and units - Part 10: Atomic and nuclear physics

ISO 11929, Determination of the characteristic limits (decision threshold, detection limit and limits of the confidence interval) for measurements of ionizing radiation — Fundamentals and application

ISO/IEC 17025, General requirements for the competence of testing and calibration laboratories

ISO/IEC Guide 98-3, Uncertainty of measurement — Part 3: Guide to the expression of uncertainty in measurement (GUM:1995)

#### 3 Terms, definitions, symbols and units

For the purposes of this document, the terms, definitions, symbols and units given in ISO 80000-10, ISO/IEC Guide 98-3 and the following apply.

ISO and IEC maintain terminological databases for use in standardization at the following addresses:

- ISO Online browsing platform: available at <a href="http://www.iso.org/obp">http://www.iso.org/obp</a>
- IEC Electropedia: available at <u>http://www.electropedia.org/</u>

m	mass of the test sample, in grams	
m <sub>S(U)</sub>	mass of <sup>236</sup> U standard solution used for the preparation of the calibration sample, in grams	
m <sub>S(Sr)</sub>	mass of <sup>90</sup> Sr standard solution used for the preparation of the calibration sample, in grams	
4s	activity per unit of mass of the $^{236}$ U standard solution at the measuring time, in becquerel per gram	
rs	count rate of the calibration sample in the alpha window, per second	
r <sub>0</sub>	blank sample count rate in the alpha window, per second	
rg	sample gross count rate in the alpha window, per second	
E	alpha efficiency	
а	activity per unit of mass, in <u>becquerel</u> per gram	<b>Deleted:</b> becquerels
CA	activity concentration, in <u>becguerel</u> per litre	Deleted: becquerels
0	blank sample counting time, in seconds	
rg	sample counting time, in seconds	
ts	calibration sample counting time, in seconds	
u(a)	standard uncertainty associated with the measurement result; in becquerel per gram	
U(a)	expanded uncertainty, calculated by $U = k u (c_A)$ with k= 1, 2,, in becquerel per gram	
a*	decision threshold for the alpha activity, in becquerel per gram	
a#	detection limit for the alpha activity, in becquerel per gram	
a< ,a>	lower and upper limits of the confidence interval, in becquerel per gram	
r sα,β	alpha emitter count rate in beta window ISO 13169:2018	
rs0,	htt blank count rate in beta window standards/sist/43cac5df-24a0-46e2-97ae-c09	
sα,Τ	alpha emitter count rate in total (alpha+beta) window 2018	
sβ,α	beta emitter count rate in alpha window	
s0,α	blank count rate in alpha window	
sβ,T	beta emitter count rate in total (alpha+beta) window	
Γα	alpha spillover parameter	
τ <sub>β</sub>	beta spillover parameter	

The water sample is first acidified with a fixed amount of nitric acid and then, if lower detection limits are required, concentrated by evaporation. Uranium isotopes are then extracted (liquid-liquid extraction) by a scintillation cocktail containing a complexing agent [bis(2-ethylhexyl) hydrogen phosphate, HDEHP] and counted by liquid scintillation. The total activity of uranium isotopes can be thus determined. <sup>236</sup>U standard solution is used for calibration (external standard).

Spectral deconvolution can be performed using a suitable software to assess the  ${}^{234}\text{U}/{}^{238}\text{U}$  ratio.

#### 5 Reagents and equipment

#### 5.1 Reagents

All reagents shall be of recognised analytical grade and shall not contain any detectable alpha and beta activity.

**5.1.1** Nitric acid, c(HNO<sub>3</sub>) = 15,8 mol/l,  $\rho$  = 1,42 g/ml, mass fraction w(HNO<sub>3</sub>) = 70 %.

**5.1.2** Nitric acid, c(HNO<sub>3</sub>) = 0,7 mol/l, obtained by dilution of concentrated nitric acid.

#### 5.1.3 Laboratory water, distilled or deionized (complying with grade 3 of ISO 3696).

Deionized water can contain detectable amounts of <sup>222</sup>Rn and short lived daughters. It is therefore strongly recommended to boil the water under vigorous stirring and let it stand for one day before its use. An alternative option is to purge it with nitrogen for about 1 h for 2 l volume.

- 5.1.4 Scintillation cocktail, to be prepared (see 7.1).
- 5.1.5 Ethanol, 95 %.
- 5.1.6 p-Xylene, 99 %, for spectroscopy or scintillation grade.
- 5.1.7 Bis(2-ethylhexyl) hydrogen phosphate (HDEHP), 95 %.
- 5.1.8 Naphthalene, 99 %, scintillation grade.
- 5.1.9 2-(4-Biphenylyl)-6-phenyl benzoxazole (PBBO), scintillation grade.

#### 5.1.10 Radioactive standard solution.

Alpha and beta emitter standard solutions (respectively <sup>236</sup>U and <sup>90</sup>Sr/<sup>90</sup>Y or other suitable beta emitter radionuclide) shall be provided with calibration certificates containing at least the activity concentration, measurement uncertainty and/or statement of compliance with an identified metrological specification.

#### **5.2 Equipment**

- 5.2.1 Balance.
- 5.2.2 Hot plate with magnetic stirrer and stirring bar.
- 5.2.3 pH meter.

**5.2.4** Wide-mouth HDPE sample bottles, volumes between 100 ml and 500 ml.

**5.2.5** Liquid scintillation counter, with  $\alpha/\beta$  discrimination option, with thermostated counting chamber and preferably a commercially available low background counter to achieve better detection limits.

5.2.6 Polyethylene scintillation vials, PTFE coated, 20 ml.

PTFE coated polyethylene vials are the best choice since they prevent both the diffusion of the cocktail into the wall of the vial and the absorption of radon from the outer environment. Glass vials exhibit a considerably higher background and generally degrade both  $\alpha/\beta$  discrimination and  $\alpha$  peaks resolution.

e0edeb26/iso-