# INTERNATIONAL STANDARD

Second edition 2018-05

# Self adhesive tapes — Measurement of static shear adhesion

Rubans auto-adhésifs — Mesurage de la résistance au cisaillement statique

# iTeh STANDARD PREVIEW (standards.iteh.ai)

<u>ISO 29863:2018</u> https://standards.iteh.ai/catalog/standards/sist/55d5d640-0d91-4ce2-b593-8f08b1ac82fd/iso-29863-2018



Reference number ISO 29863:2018(E)

# iTeh STANDARD PREVIEW (standards.iteh.ai)

<u>ISO 29863:2018</u> https://standards.iteh.ai/catalog/standards/sist/55d5d640-0d91-4ce2-b593-8f08b1ac82fd/iso-29863-2018



## **COPYRIGHT PROTECTED DOCUMENT**

#### © ISO 2018

All rights reserved. Unless otherwise specified, or required in the context of its implementation, no part of this publication may be reproduced or utilized otherwise in any form or by any means, electronic or mechanical, including photocopying, or posting on the internet or an intranet, without prior written permission. Permission can be requested from either ISO at the address below or ISO's member body in the country of the requester.

ISO copyright office CP 401 • Ch. de Blandonnet 8 CH-1214 Vernier, Geneva Phone: +41 22 749 01 11 Fax: +41 22 749 09 47 Email: copyright@iso.org Website: www.iso.org

Published in Switzerland

## Contents

Page

Fore	word		<b>v</b>			
Intro	oductio	n	vi			
1	Scop	e				
2	Norr	native references				
3	Terms and definitions					
4	Significance and use					
т г						
5		IOG A: Measurement of snear adnesion to a vertical standard steel panel	<u>Z</u>			
	5.1	Principle	Z			
	5.2	Malel Idis.	Z			
	5.5	5 3 1 Typical shear adhesion tester				
		5.3.2 Test niece cutter				
		5.3.3 Stainless steel nanels	3			
		5.3.4 Roller mechanically or hand operated	3			
	5.4	Test samples and test piece.				
	5.5	Procedure				
		5.5.1 Standard test conditions	4			
		5.5.2 Preparation of the panel	4			
		5.5.3 Shear adhesion	4			
	5.6	Expression of results.	5			
	5.7	Test report	5			
6	Method B: Measurement of shear adhesion to a vertical nanel covered with NIST					
0	SRM	1810A standard fibreboard so 200622018	6			
	6.1	Principle/ctandarde.itch.ai/oataloo/standarde/sist/55d5d640u0d01u4co2ub502u				
	6.2	Materials	6			
	6.3	Apparatus	6			
		6.3.1 Test piece cutter	6			
		6.3.2 Suitable panels	6			
		6.3.3 Roller mechanically or hand operated	6			
		6.3.4 Test stands and ancillary apparatus				
	6.4	Test samples and test piece				
	6.5	Procedure				
		6.5.1 Standard test conditions				
		6.5.2 Preparation of the panel	6			
	( (	6.5.3 Shear adhesion				
	0.0 6 7	Expression of results				
	0.7	Test TepoTt				
7	Method C: Measurement of shear adhesion to a vertical panel covered with a					
	fibre	board agreed upon by the buyer and the seller	7			
	7.1	Principle				
	1.2	Procedure				
8	Meth	od D: Measurement of shear adhesion of filament reinforced tape applied to a				
	hori	zontal standard steel panel	7			
	8.1	Principle	7			
	8.2	Materials	7			
	8.3	Apparatus				
		8.3.1 Test piece cutter				
		8.3.2 Stainless steel panels				
		0.5.5 Koller mechanically or nand operated	ð			
	Q /	0.5.4 Test statius and test piece	ປັ ດ			
	0.7	rest sumples and test prece	0			

	8.5	Procedure	8		
		8.5.1 Standard test conditions	8		
		8.5.2 Preparation of the panel	8		
		8.5.3 Shear adhesion			
	8.6	Expression of results	9		
	8.7	Test report	9		
9	Method E: Measurement of shear adhesion of filament reinforced tape applied to a				
	horizo	ontal panel covered with NIST SRM 1810A standard fibreboard			
	9.1	Principle	10		
	9.2	Procedure	10		
10	Method F: Measurement of shear adhesion of filament reinforced tape applied to a				
	horizo	ontal panel covered with a fibreboard agreed upon by the buyer and the seller			
	10.1	Principle	10		
	10.2	Procedure	10		
11	Method G: Measurement of shear adhesion to a vertical standard steel panel at an				
	elevated temperature after 10 min dwell time				
	11.1	Principle	10		
	11.2	Procedure	11		
Biblio	graphy	۲	14		

# iTeh STANDARD PREVIEW (standards.iteh.ai)

ISO 29863:2018

https://standards.iteh.ai/catalog/standards/sist/55d5d640-0d91-4ce2-b593-8f08b1ac82fd/iso-29863-2018

## Foreword

ISO (the International Organization for Standardization) is a worldwide federation of national standards bodies (ISO member bodies). The work of preparing International Standards is normally carried out through ISO technical committees. Each member body interested in a subject for which a technical committee has been established has the right to be represented on that committee. International organizations, governmental and non-governmental, in liaison with ISO, also take part in the work. ISO collaborates closely with the International Electrotechnical Commission (IEC) on all matters of electrotechnical standardization.

The procedures used to develop this document and those intended for its further maintenance are described in the ISO/IEC Directives, Part 1. In particular the different approval criteria needed for the different types of ISO documents should be noted. This document was drafted in accordance with the editorial rules of the ISO/IEC Directives, Part 2 (see <a href="https://www.iso.org/directives">www.iso.org/directives</a>).

Attention is drawn to the possibility that some of the elements of this document may be the subject of patent rights. ISO shall not be held responsible for identifying any or all such patent rights. Details of any patent rights identified during the development of the document will be in the Introduction and/or on the ISO list of patent declarations received (see <a href="https://www.iso.org/patents">www.iso.org/patents</a>).

Any trade name used in this document is information given for the convenience of users and does not constitute an endorsement.

For an explanation on the voluntary nature of standards, the meaning of ISO specific terms and expressions related to conformity assessment, as well as information about ISO's adherence to the World Trade Organization (WTO) principles in the Technical Barriers to Trade (TBT) see the following URL: <a href="https://www.iso.org/iso/foreword.html">www.iso.org/iso/foreword.html</a>.

This document was prepared by Technical Committee ISO/TC 61, *Plastics*, Subcommittee SC 11, *Products*.

https://standards.iteh.ai/catalog/standards/sist/55d5d640-0d91-4ce2-b593-

This second edition cancels and replaces the first edition (ISO 29863:2007) of which it constitutes a minor revision.

The changes compared to the previous edition are as follows:

- the Introduction has been revised to remove outdated information;
- the normative references in <u>Clause 2</u> have been updated;
- the definition of "shear adhesion" has been revised and a definition has been added for "self adhesive tape" in <u>Clause 3</u>;
- a Bibliography has been added;
- the text has been editorially revised to comply with the most recent editing rules.

## Introduction

This document has been prepared in conjunction with AFERA (International Association for the Self Adhesive Tape Industry) in Europe and PSTC (Pressure Sensitive Tape Council) in USA.

## iTeh STANDARD PREVIEW (standards.iteh.ai)

<u>ISO 29863:2018</u> https://standards.iteh.ai/catalog/standards/sist/55d5d640-0d91-4ce2-b593-8f08b1ac82fd/iso-29863-2018

# Self adhesive tapes — Measurement of static shear adhesion

### 1 Scope

This document specifies a series of methods for the determination of the ability of a pressure sensitive tape to remain adhered under a constant load applied parallel to the surfaces of the tape and substrate.

This document contains:

- method A: Self adhesive tapes Measurement of shear adhesion to a vertical standard steel panel;
- method B: Self adhesive tapes Measurement of shear adhesion to a vertical panel covered with NIST SRM 1810A<sup>1</sup> standard fibreboard;
- method C: Self adhesive tapes Measurement of shear adhesion to a vertical panel covered with a fibreboard agreed upon by the buyer and seller;
- method D: Self adhesive tapes Measurement of shear adhesion of filament reinforced tape applied to a horizontal standard steel panel;
- method E: Self adhesive tapes Measurement of shear adhesion of filament reinforced tape applied to a horizontal panel covered with NIST SRM 1810A<sup>1</sup>) standard fibreboard;
- method F: Self adhesive tapes Measurement of shear adhesion of filament reinforced tape applied to a horizontal panel covered with a fibreboard agreed upon by the buyer and seller;
- method G: Self adhesive tapes Measurement of shear adhesion to a vertical standard steel panel at elevated temperature after a 10 min dwell time.

## 2 Normative references

The following documents are referred to in the text in such a way that some or all of their content constitutes requirements of this document. For dated references, only the edition cited applies. For undated references, the latest edition of the referenced document (including any amendments) applies.

EN 12481, Self adhesive tapes — Terminology

### 3 Terms and definitions

For the purposes of this document, the terms and definitions given in EN 12481 and the following apply.

ISO and IEC maintain terminological databases for use in standardization at the following addresses:

- IEC Electropedia: available at http://www.electropedia.org/
- ISO Online browsing platform: available at <a href="https://www.iso.org/obp">https://www.iso.org/obp</a>

<sup>1)</sup> NIST SRM 1810A is National Institute of Standards and Technology – Standard Reference Material 1810A and is available from the Institute at Gaithersburg, Maryland MD 20899, USA.

#### 3.1

#### shear adhesion

resistance of the pressure sensitive adhesive against shear when static forces are exerted parallel to the bonding surface

Note 1 to entry: It is expressed as the time to failure under constant load.

#### 3.2

#### self adhesive tape

pressure sensitive adhesive

adhesive which in a dry state is permanently tacky at room temperature and adheres readily to surfaces under brief and light pressure

### 4 Significance and use

These test methods are tools for quality control use. Given specific self adhesive tape and a requirement in terms of the minimum or maximum value expected for this tape, the data from the test can be used in conjunction with acceptance criteria.

These methods provide a means of assessing the uniformity of the adhesive of a given type of pressuresensitive tape (an example are tapes used for packaging applications). The assessment may be within a roll of tape, between rolls or production lots.

Variations in the tape backing and adhesive affect the results, therefore, these methods cannot be used to pinpoint the specific cause s) of non-uniformity DARD PREVIEW

These test methods may not provide design information as there is usually no direct relationship between shear adhesion and any functional requirement.

#### ISO 29863:2018

#### 5 Method A: Measurement of shear adhesion to a vertical standard steel panel

8f08b1ac82fd/iso-29863-2018

#### 5.1 Principle

Method A measures the shear adhesion of a self adhesive tape to a standard steel panel by its time to failure at 23 °C and 50 % relative humidity (RH) under constant load.

Shear adhesion to standard steel panel – A strip of tape is applied to a standard steel panel under controlled roll down. The panel is mounted vertically, a standard mass is attached to the free end of the tape and the time to failure is determined.

#### 5.2 Materials

**5.2.1 Absorbent cleaning material**, surgical gauze, cotton wool or tissue. To be suitable, materials shall be lint free during use, absorbent, contain no additives that are soluble in the solvents listed in <u>5.2.2</u> and made exclusively from virgin materials.

#### 5.2.2 One or more of the following solvents:

- diacetone alcohol (4-hydroxy-4-methyl-2-pentanone) non–residual grade;
- methanol;
- methyl ethyl ketone;
- acetone;
- *n*-heptane;

 a mixture of *n*-heptane and a fluorinated hydrocarbon such as refrigerant (suitable when toxicity or flammability restrictions apply).

Solvents shall be of general purpose chemical grade and held in a suitable dispensing system.

#### 5.3 Apparatus

#### 5.3.1 Typical shear adhesion tester

See <u>Figure 1</u> for a typical shear adhesion tester.

#### 5.3.2 Test piece cutter

A test piece cutter shall hold two single edge razor blades in parallel planes a precise distance apart, to form a cutter of exact specimen width; two cutters, 12 mm and 24 mm cutting width, shall be available or appropriate alternatives which will not cause edge damage. The precision of the razor blade separation shall be the nominal width ±0,1 mm.

#### 5.3.3 Stainless steel panels

These shall be perfectly flat, at least 125 mm long and 50 mm wide and at least 1,1 mm thick, stainless steel type 1.4301 in accordance with the 2 R quality defined in EN 10088-2, having a bright annealed finish with a surface roughness of 50 nm  $\pm$  25 nm. Panels showing stains, discoloration or many scratches are not acceptable. New panels shall be cleaned prior to use as described in 5.5.2 except with ten washes of the final solvent. Between uses the panel test surface shall be protected from scratches and contamination and the panels shall be stored in the conditions described in 5.5.2.

#### 5.3.4 Roller mechanically or hand operated ISO 29863:2018

**5.3.4.1** A steel roller 85 mm  $\pm$  2,5 mm in diameter and 45 mm  $\pm$  1,5 mm in width, covered with rubber approximately 6 mm in thickness, having a Shore A durometer hardness of 80  $\pm$  5. The surface shall be a true cylinder, void of any convex or concave deviations. The mass of the roller shall be 2 kg  $\pm$  0,1 kg.

**5.3.4.2** No part of the apparatus shall increase the mass of the roller during use. The roller shall move either mechanically or by hand at the rate of  $10 \text{ mm/s} \pm 0.5 \text{ mm/s}$ .

#### 5.3.5 Test stands and ancillary apparatus

#### 5.3.5.1 Test stand

A test stand that shall hold the test panel, with tape applied, at an angle between  $0^{\circ}$  and  $2^{\circ}$  from the vertical, so that when the mass is acting on the test specimen, no peel force will be exerted on the tape.

#### 5.3.5.2 Clamps

Clamps that will allow the attachment of the mass to the specimen, distributing the load equally across the tape specimen width.

#### 5.3.5.3 Test masses

The test mass shall be 1 000 g  $\pm$  5 g or other mass as specified. The mass of the clamp described in 5.3.5.2 shall be included as part of the total mass.

#### 5.3.5.4 Timing system

A timing system to measure the interval between the application of the load to the specimen and its separation from the panel.

#### 5.4 Test samples and test piece

**5.4.1** Condition the sample rolls of tape in the standard conditions of 23 °C  $\pm$  1 °C and 50 %  $\pm$  5 % RH. Test at these conditions unless otherwise specified [see 5.7 h)].

If these tolerances cannot be maintained, the closest possible tolerances shall be used and these revised tolerances quoted in the report.

The test requires three test pieces, each shall be  $12 \text{ mm} \pm 0.5 \text{ mm}$  wide by approximately 150 mm 5.4.2 long. Alternatively test pieces of 24 mm  $\pm$  0,5 mm or other widths may be used specifying the contact area used with the results.

**5.4.3** Discard at least three but no more than six outer wraps of tape from the sample roll before taking the test pieces for testing.

**5.4.4** Remove three test pieces for each test to be performed. Remove each test piece from a freely rotating roll at the rate of 500 mm/s to 750 mm/s. Where high unwind force makes it impossible to remove the test piece at the prescribed rate, remove it at a rate as close to 500 mm/s as possible. ILEN STANDARD PRE

**5.4.5** When the tape is wider than 12 mm, test pieces of the specified width are to be cut with an apparatus as described in 5.3.2 from the centre of a strip removed from the roll in accordance with 5.4.4.

**5.4.6** Apply the test pieces within 5 min after unwinding. https://standards.iteh.ai/catalog/standards/sist/55d5d640-0d91-4ce2-b593-8f08b1ac82fd/iso-29863-2018

#### 5.5 Procedure

#### 5.5.1 Standard test conditions

Standard test conditions shall be the same as <u>5.4.1</u> for test pieces and test samples conditioning.

#### 5.5.2 **Preparation of the panel**

Dispense one of the solvents listed in 5.2.2 on to the panel, wiping it to dryness with fresh absorbent cleaning material. Repeat for a total of three washes with this solvent.

Final wipe shall be with methyl ethyl ketone or acetone. The panel should be allowed to dry for at least 10 min. Panels not used within 10 h should be recleaned.

In order to obtain consistent results a new panel shall be wiped at least 10 times with final solvent before use.

Discard plates showing stains, discoloration, or many scratches. Avoid contacting panel surface with fingers. During storage panel should, be protected from damage or contamination.

#### 5.5.3 **Shear adhesion**

#### 5.5.3.1 Test piece preparation

Centre the test piece at one end of the test panel and apply without added pressure to cover an area of 12 mm  $\pm$  0,5 mm by 12 mm  $\pm$  0,5 mm, unless other dimensions are specified. The exposed adhesive of the free area of the test piece may be masked.

To prevent damaging the test piece by the end of the panel during roll down, place another panel of the same or slightly lesser thickness under the free masked end of the test piece, and in contact with the end of the panel prior to roll down. Roll down the applied test area twice, once in each lengthwise direction.

Individually prepare each specimen and begin test within 1 min. For tapes other than packaging tapes, other dwell times may be used but shall be reported.

The tester should know that by prolonged handling, heat is transmitted to the stainless steel test panel. Therefore during and after application of the adhesive tape to the test panel, the panel should be handled as little as possible.

#### 5.5.3.2 Shear adhesion test

The following action shall be completed within 1 min of rolling the sample in <u>5.5.3.1</u>.

Place the clamp on the free end of the test piece, ensuring that the clamp extends completely across the width of the test piece and is aligned to uniformly distribute the load.

Place the test assembly in the test stand so that the free end of the test piece is vertical, ensuring that no peel force acts on the test piece.

Apply the mass to the clamp gently so as to cause no shear impact force on the test piece. Record the time elapsed until the test piece has completely separated from the test panel.

## 5.6 Expression of results STANDARD PREVIEW

To determine the test result, convert each of the test piece results (times to failure) to its common or natural logarithm. Obtain the arithmetic mean of all logarithms and then convert back to time by obtaining the appropriate antilogarithm. ISO 29863:2018

https://standards.iteh.ai/catalog/standards/sist/55d5d640-0d91-4ce2-b593t 8f08b1ac82fd/iso-29863-2018

#### 5.7 Test report

The test report shall include the following information:

- a) a reference to this document;
- b) statement that this test method was used and indicating any deviations from the method as written;
- c) identification of each roll of tape tested;
- d) the time to separate completely from the panel as calculated in <u>5.6</u>;
- e) the dwell time, if other than 1 min;
- f) test contact area if other than  $12 \text{ mm} \pm 0.5 \text{ mm}$  by  $12 \text{ mm} \pm 0.5 \text{ mm}$ ;
- g) mode of failure, cohesive or adhesive failure or other observation:
  - cohesive failure: failure of an adhesive bond such that the separation is within the adhesive,
  - adhesive failure: failure of an adhesive bond such that the separation is at the interface of adhesive and substrate leaving negligible residue;
- h) conditions of test if other than 23 °C  $\pm$  1 °C and 50 %  $\pm$  5 % RH.