

Designation: E 889 – 82 (Reapproved 1996)

# Standard Test Method for Composition or Purity of a Solid Waste Materials Stream<sup>1</sup>

This standard is issued under the fixed designation E 889; the number immediately following the designation indicates the year of original adoption or, in the case of revision, the year of last revision. A number in parentheses indicates the year of last reapproval. A superscript epsilon  $(\epsilon)$  indicates an editorial change since the last revision or reapproval.

#### 1. Scope

- 1.1 This test method covers the determination of the composition of a materials stream in a solid waste resource recovery processing facility. The composition is determined with respect to one or more defined components. The results are used for determining the purity resulting from the operation of one or more separators, and in conjunction with Test Method E 1108 used to measure the efficiency of a materials separation device.
- 1.2 The values stated in SI units are to be regarded as the standard. The values given in parentheses are for information only.
- 1.3 This standard does not purport to address all of the safety concerns, if any, associated with its use. It is the responsibility of the user of this standard to establish appropriate safety and health practices and determine the applicability of regulatory limitations prior to use. For hazard statements, see Section 7.

## 2. Referenced Documents

2.1 ASTM Standards:

C 566 Test Method for Total Moisture Content of Aggregate by Drying<sup>2</sup>

C 702 Practice for Reducing Field Samples of Aggregates to Testing Size<sup>2</sup>

D 75 Practice for Sampling Aggregates<sup>3</sup>

D 644 Test Method for Moisture Content of Paper and Paperboard by Oven Drying<sup>4</sup>

D 2013 Method of Preparing Coal Samples for Analysis<sup>5</sup>

D 2234 Test Methods for Collection of a Gross Sample of Coal<sup>5</sup>

E 380 Practice for Use of the International System of Units (SI) (the Modernized Metric System)<sup>6</sup>

Current edition approved July 30, 1982. Published May 1983.

- E 1107 Method for Measuring the Throughput of Resource-Recovery Unit Operations<sup>7</sup>
- E 1108 Test Method for Determination of the Recovery of a Product in a Materials Separation Device<sup>7</sup>

## 3. Terminology Definitions

- 3.1 *binary separator*—a device that separates a single input feed stream into two output or product streams.
- 3.2 *gross sample*—a sample representing one lot and composed of a number of increments on which neither reduction nor division has been performed.
- 3.3 *laboratory sample or analysis sample*—a portion of one gross sample representative of a lot and taken at random from the gross sample.
- 3.4 polynary separator—a device that separates a single input feed stream into three or more output product streams.
- 3.5 purity—The purity of a stream is defined in terms of one or more identifiable components, x, y, z, etc. The purity for any component such as x is the mass of x in a stream divided by the total mass of that stream. In some cases, the mass of x must be defined in practical terms that relate to the origin of the feed. For example, the purity of a ferrous product magnetically recovered from refuse can be expressed as the purity of ferrous by proximate analysis. Alternatively, it can be expressed as the purity by manual sorting, with all nonferrous materials that cannot readily be removed by hand as the contaminants. In any case, purity must be defined for each application.

#### 4. Summary of Test Method

- 4.1 A gross sample of a preselected process stream is taken, and subdivided into four laboratory samples. Two of the laboratory samples are analyzed for composition of the component(s) or item(s) of interest by hand-picking and weighing. The third sample is used if the results of the first two do not agree within specified limits. The composition is computed as the weight ratio of the component(s) of interest to the weight of the sample.
- 4.2 The composition is expressed as the purity of the stream with respect to the component(s) indicated.

<sup>&</sup>lt;sup>1</sup> This test method is under the jurisdiction of ASTM Committee D34 on Waste Management and is the direct responsibility of Subcommittee D34.087 on Municipal Solid Waste.

<sup>&</sup>lt;sup>2</sup> Annual Book of ASTM Standards, Vol 04.02.

<sup>&</sup>lt;sup>3</sup> Annual Book of ASTM Standards, Vol 04.03.

<sup>&</sup>lt;sup>4</sup> Annual Book of ASTM Standards, Vol 15.09.

<sup>&</sup>lt;sup>5</sup> Annual Book of ASTM Standards, Vol 15.09.

<sup>&</sup>lt;sup>6</sup> Annual Book of ASTM Standards, Vol 14.02.

<sup>&</sup>lt;sup>7</sup> Annual Book of ASTM Standards, Vol 11.04.



#### 5. Significance and Use

- 5.1 This method is used to document the ability of solid waste resource recovery separators to concentrate or classify a particular component (or components) present in solid waste.
- 5.2 The purity determined in this way is used to calculate the recovery achieved by a separator as another measure of its performance, according to Test Method E 1108.

#### 6. Apparatus

- 6.1 Scales—Several size scales must be available to weigh gross samples and laboratory samples that will range in size from less than 1 kg (2.2 lb) to more than 100 kg (220 lb). All scales should have a precision and accuracy of  $\pm 0.1$  %.
- 6.2 Sorting Apparatus—This may be any convenient work surface, such as a table and bins as decribed by Kaiser et al.<sup>8</sup>
- 6.3 *Polyethylene Bags*, used to store laboratory and sometimes gross samples as the means of preserving their moisture content. These bags should be 0.10 to 0.15 mm (0.004 to 0.006 in.) thick and supplied with metal ties.
- 6.4 Laboratory Drying Oven, and general associated equipment are required.

#### 7. Hazards

- 7.1 This procedure calls for the hand-picking of solid waste and its processed fractions. Because the origin of all of the materials is generally unknown, workers must use proper safety precautions when handling samples. Workers shall wear gloves and safety glasses. When appropriate, dust masks shall be worn. Workers must be cautioned to wash their hands thoroughly before eating or smoking.
- 7.2 Particular caution shall be exercised when collecting samples near moving equipment.

#### 8. Sampling

- 8.1 Samples are taken from processor streams, or separator output or input streams, according to the procedures outlined in Method E 1107.
- 8.2 The purity is determined with respect to a particular component in the stream, such as steel cans or glass. Hence, sampling and containment of samples must be done in a manner to preserve the integrity of the components being analyzed and the mass of the entire sample. As an example, if a stream is to be analyzed for the purity with respect to pieces of glass larger than 10 mm (0.4 in.) in size, the sample must be handled and stored in a manner in which pieces of glass larger than 10 mm are not broken.

# 9. Test Specimen and Samples

- 9.1 The size of sample is determined by the particle size of the material in accordance with Practice D 75. The size of sample specified constitutes the gross sample.
- 9.1.1 For particle sizes greater than 90 mm ( $3\frac{1}{2}$  in.), not included in Table 1, Size of Samples, of Practice D 75, the size of sample shall be 250 kg (550 lb).
- <sup>8</sup> Kaiser, E. R., "Sampling and Analysis of Solid-Incinerator Refuse and Residue," *Proceedings of 1970 National Incineration Conference*, Am. Soc. Mechanical Engrs., pp. 25–31.

- 9.1.2 Gross samples shall be weighed, without subdivision.
- 9.1.3 A gross sample may be sized in accordance with the section on Test Specimen and Samples of Method E 1107 in circumstances where Practice D 75 cannot be practiced.
- 9.2 Gross samples shall be subdivided in accordance with Practice C 702 to form four laboratory samples. Each is weighed and labeled. This is recorded as "as-received weight."
- 9.3 Samples from wet processing steps, for example, wet screening, spiral classification, jigging, etc., are to be weighed after draining the water, in accordance with 11.3. The weight of such samples is recorded as the "drained weight."

#### 10. Conditioning

- 10.1 Weigh the samples immediately after being taken with due precaution so that they neither gain nor lose weight from natural drying or from being left uncovered in wet or dusty areas. This is known as" as-received weight."
- 10.2 Condition wet samples by draining in accordance with 11.8. This is known as "drained weight."
- 10.3 The weight of dry samples, either of gross or laboratory samples, must exclude the contained moisture. Dry samples in accordance with 11.10. This is known as "dry weight."

#### 11. Procedure

- 11.1 Take a gross sample in accordance with the section on Procedures, in Method E 1107.
- 11.1.1 Contain the gross sample in a moisture barrier container in accordance with 11.8.1 if the moisture content is to be preserved.
  - 11.1.2 Record the weight of the gross sample.
- 11.2 Subdivide the gross sample into four near equal parts in accordance with Practice C 702 to form four laboratory samples.
- 11.2.1 Place the laboratory samples in moisture barrier containers, in accordance with 11.10 if the moisture content is to be preserved.
  - 11.2.2 Record the weight of each laboratory sample.
- 11.3 Choose two of the laboratory samples at random for analysis; retain the other two, if needed, in accordance with 11.5.1.
- 11.4 Perform the analysis by spreading a laboratory sample on a clean, flat surface, and hand-picking the component(s) of interest.
- 11.4.1 Place the component(s) of interest in a clean, tared container. If the moisture content is to be preserved, this must be a moisture barrier container in accordance with 11.8.1.
- 11.4.2 Carefully remove adhering tramp substances from the component(s) of interest. Do not remove tramp substances that are physically attached so as not to be readily removed by hand and classify the entire piece as either components of interest (accept) or not of interest (reject). Record this decision on the data sheet.
- 11.4.3 Record the weights of component(s) picked from each laboratory sample as "as-received weight."
- 11.5 Compute the purity of the stream in regard to the component(s) of interest in accordance with Section 12.
- 11.5.1 The computed values of the purity of the two laboratory samples must agree within 10 % to be accepted. If