DRAFT INTERNATIONAL STANDARD ISO/DIS 8529-3

ISO/TC 85/SC 2

Voting begins on: **2022-10-11**

Secretariat: AFNOR

Voting terminates on: 2023-01-03

Neutron reference radiation fields -

Part 3: Calibration of area and personal dosemeters and determination of their response as a function of neutron energy and angle of incidence

ICS: 17.240

iTeh STANDARD PREVIEW (standards.iteh.ai)

ISO/FDIS 8529-3

https://standards.iteh.ai/catalog/standards/sist/a976497c-cd1f-4de1-a648-b917f9e32d85/iso-fdis-8529-3

THIS DOCUMENT IS A DRAFT CIRCULATED FOR COMMENT AND APPROVAL. IT IS THEREFORE SUBJECT TO CHANGE AND MAY NOT BE REFERRED TO AS AN INTERNATIONAL STANDARD UNTIL PUBLISHED AS SUCH.

IN ADDITION TO THEIR EVALUATION AS BEING ACCEPTABLE FOR INDUSTRIAL, TECHNOLOGICAL, COMMERCIAL AND USER PURPOSES, DRAFT INTERNATIONAL STANDARDS MAY ON OCCASION HAVE TO BE CONSIDERED IN THE LIGHT OF THEIR POTENTIAL TO BECOME STANDARDS TO WHICH REFERENCE MAY BE MADE IN NATIONAL REGULATIONS.

RECIPIENTS OF THIS DRAFT ARE INVITED TO SUBMIT, WITH THEIR COMMENTS, NOTIFICATION OF ANY RELEVANT PATENT RIGHTS OF WHICH THEY ARE AWARE AND TO PROVIDE SUPPORTING DOCUMENTATION. This document is circulated as received from the committee secretariat.



Reference number ISO/DIS 8529-3:2022(E)

iTeh STANDARD PREVIEW (standards.iteh.ai)

<u>ISO/FDIS 8529-3</u>

https://standards.iteh.ai/catalog/standards/sist/a976497c-cd1f-4de1-a648-b917f9e32d85/isofdis-8529-3



COPYRIGHT PROTECTED DOCUMENT

© ISO 2022

All rights reserved. Unless otherwise specified, or required in the context of its implementation, no part of this publication may be reproduced or utilized otherwise in any form or by any means, electronic or mechanical, including photocopying, or posting on the internet or an intranet, without prior written permission. Permission can be requested from either ISO at the address below or ISO's member body in the country of the requester.

ISO copyright office CP 401 • Ch. de Blandonnet 8 CH-1214 Vernier, Geneva Phone: +41 22 749 01 11 Email: copyright@iso.org Website: www.iso.org

Published in Switzerland

Contents

Forew	rord	iv
Introduction v		
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Procedures applicable to area and personal dosemeters4.1Neutron fields4.2Conversion coefficients4.3Determination of the response4.4Calibration procedures	2 2 2 3 3
5	Procedures for calibrating and determining the ambient dose equivalent responseof area dosemeters5.15.1Quantity to be measured and conversion coefficients5.2Required response characteristics5.3Dosemeter conditions5.4Irradiation geometry5.5Evaluation of measurement	3 3 4 4 4
6 https:	Procedures for calibrating and determining the personal dose equivalent response of personal dosemeters 6.1 Quantity to be measured and conversion coefficients 6.2 Required response characteristics 6.3 Calibration phantom 6.4 Dosemeter conditions 6.5 Irradiation geometry 6.6 Evaluation of measurement	5
7	Uncertainty fdis-8529-3	8
Annex A (informative) List of reference conditions and standard test conditions		9
Bibliography		

Foreword

ISO (the International Organization for Standardization) is a worldwide federation of national standards bodies (ISO member bodies). The work of preparing International Standards is normally carried out through ISO technical committees. Each member body interested in a subject for which a technical committee has been established has the right to be represented on that committee. International organizations, governmental and non-governmental, in liaison with ISO, also take part in the work. ISO collaborates closely with the International Electrotechnical Commission (IEC) on all matters of electrotechnical standardization.

The procedures used to develop this document and those intended for its further maintenance are described in the ISO/IEC Directives, Part 1. In particular the different approval criteria needed for the different types of ISO documents should be noted. This document was drafted in accordance with the editorial rules of the ISO/IEC Directives, Part 2 (see www.iso.org/directives).

Attention is drawn to the possibility that some of the elements of this document may be the subject of patent rights. ISO shall not be held responsible for identifying any or all such patent rights. Details of any patent rights identified during the development of the document will be in the Introduction and/or on the ISO list of patent declarations received (see www.iso.org/patents).

Any trade name used in this document is information given for the convenience of users and does not constitute an endorsement.

For an explanation on the voluntary nature of standards, the meaning of ISO specific terms and expressions related to conformity assessment, as well as information about ISO's adherence to the World Trade Organization (WTO) principles in the Technical Barriers to Trade (TBT) see the following URL: www.iso.org/iso/foreword.html.

This document was prepared by Technical Committee ISO/TC 85, *Nuclear energy*, Subcommittee SC 2, *Radiation protection*.

ISO 8529 consists of the following parts, under the general title *Neutron Reference radiation fields*

- Part 1: Characteristics and methods of production
- Part 2: Calibration fundamentals related to the basic quantities characterizing the radiation field
- Part 3: Calibration of area and personal dosemeters and determination of their response as a function of neutron energy and angle of incidence

Introduction

This part of ISO 8529 is closely related to two other standards concerning the calibration of dosemeters and doserate meters for neutron radiation. The first standard, ISO 8529-1, specifies the reference neutron radiation fields, in the energy range from thermal up to 20 MeV, and their production methods. ISO 8529-2 describes the calibration fundamentals of radiation protection devices related to basic quantities characterising the radiation field and specifies the procedures to be used for realising the calibration conditions of radiation protection devices produced by calibration sources with emphasis on correction for extraneous effects.

This part of ISO 8529 deals with dosemeters for area and individual monitoring. Area dosemeters are often called area monitors or area survey meters, and dosemeters for individual monitoring are often called personal dosemeters or personal dosimeters. This part of ISO 8529 describes procedures for calibrating and determining the response in terms of the International Commission on Radiation Units and Measurements (ICRU) operational quantities. These are defined in ICRU Reports 39 and 51 (^[1] and^[2]). For radiation protection purposes, these operational quantities are considered to be a sufficiently accurate approximation to the protection quantities. For the purposes of this part of ISO 8529, the emphasis will be on the evaluation of the operational quantities at 10 mm depth defined in the body using conversion coefficients in the appropriate phantom. Cold neutrons may present special problems in dosimetry and are outside the scope of this part of ISO 8529, as are the photon calibrations of instruments designed to measure both photons and neutrons.

The determination of the response of dosemeters is essentially a three-step process. Firstly, a primary quantity such as the neutron fluence is determined at the point of test. Secondly, the reference point of the device being calibrated is then placed at the point of test to determine the fluence response. Thirdly, the response of the device with respect to the appropriate operational quantity is then determined by the application of conversion coefficients that relate the physical quantity (the fluence) to the operational quantity (the dose equivalent). This part of ISO 8529 will describe the methods and the conversion coefficients to be used for the determination of the response of area and personal dosemeters in terms of the respective ICRU operational quantities for neutrons.

103/https://standards.iteh.ai/catalog/standards/sist/a976497c-cd1f-4de1-a648-b917f9e32d85/iso

fdis-8529-3

iTeh STANDARD PREVIEW (standards.iteh.ai)

ISO/FDIS 8529-3

https://standards.iteh.ai/catalog/standards/sist/a976497c-cd1f-4de1-a648-b917f9e32d85/isofdis-8529-3

Neutron reference radiation fields —

Part 3: Calibration of area and personal dosemeters and determination of their response as a function of neutron energy and angle of incidence

1 Scope

This part of ISO 8529 provides guidance for those who calibrate protection-level dosemeters and doserate meters for area and individual monitoring with reference neutron radiation fields. This includes the determination of the response as a function of neutron energy and angle of incidence. The operational quantities recommended in ICRU Report 51 ^[2] are considered. In addition to the description of procedures, this part of ISO 8529 includes appropriate definitions and conversion coefficients and provides guidance on the statement of measurement uncertainties.

2 Normative references

The following documents are referred to in the text in such a way that some or all of their content constitutes requirements of this document. For dated references, only the edition cited applies. For undated references, the latest edition of the referenced document (including any amendments) applies.

ISO 29661, Reference radiation fields for radiation protection — Definitions and fundamental concepts

ISO/IEC Guide 98-3, Uncertainty of measurement — Part 3: Guide to the expression of uncertainty in measurement (GUM:1995)

ISO 8529-1, Neutron reference radiations fields — Part 1: Characteristics and methods of production

ISO 8529-2, Reference neutron radiations — Part 2: Calibration fundamentals of radiation protection devices related to the basic quantities characterizing the radiation field

ISO 12789-1, Reference radiation fields — Simulated workplace neutron fields — Part 1: Characteristics and methods of production

ISO 12789-2, Reference radiation fields — Simulated workplace neutron fields — Part 2: Calibration fundamentals related to the basic quantities

3 Terms and definitions

For the purposes of this document, the terms and definitions of ISO 29661 and the following apply.

ISO and IEC maintain terminological databases for use in standardization at the following addresses:

— ISO Online browsing platform: available at <u>https://www.iso.org/obp</u>

— IEC Electropedia: available at https://www.electropedia.org/

3.1

free-field neutron fluence

Φ

the fluence that would be present at the point in absence of any dosemeter, calibration phantom if present, and scattering from the room and the air

3.2

uniform irradiation

a field can be regarded as providing a uniform irradiation if the uncertainty component introduced by the non uniformity does not significantly impact the overall uncertainty of the calibration procedure

4 Procedures applicable to area and personal dosemeters

4.1 Neutron fields

This part of ISO 8529 deals with neutron reference radiation fields chosen from and produced in accordance with ISO 8529-1 and characterized using the techniques of ISO 8529-2. In general, when selecting an appropriate neutron field, it will be useful to take into account the specified energy and dose or doserate ranges of the dosemeter to be tested. The basic quantities characterizing the radiation fields (energy and direction distribution of the neutron fluence) should be determined and all necessary corrections should be considered in accordance with ISO 8529-2 to allow the use of the recommended conversion coefficients

4.2 Conversion coefficients

The conversion coefficients given in this part of ISO 8529 refer to the monoenergetic energies or the continuous energy distributions given in ISO 8529-1 and were derived from those recommended by ICRU $^{[3]}$.

All of the conversion coefficients given in <u>Tables 1</u> to <u>4</u> have been determined assuming broad parallel neutron beams or fields composed of such beams. If these coefficients are used for calibration and test purposes, the neutron fields used should be uniform over a broad area, i.e., extending over the whole item to be calibrated (area dosemeter or phantom with personal dosemeter) and also should be almost parallel or composed of almost-parallel beams. For calibrations of large devices in divergent beams as described in detail in ISO 8529-2, geometric corrections are needed to correct for non uniform irradiation of the item at close distances from point sources.

The fluence to which the conversion coefficients refer should be measured at the point of test.

If the fluence is uniform on the whole front face of the dosemeter or phantom the fluence-to-dose equivalent conversion coefficient can be applied without any further considerations.

If not, corrections should be applied for all influencing factors, especially for calibrations of multiple personal dosemeters:

- the calibration of multiple personal dosemeters in broad spectrum reference neutron fields, where the fluence and direction vary across the face of the phantom ^[4];
- the calibration of multiple personal dosemeters in monoenergetic reference neutron fields, where the fluence, energy, and direction distributions vary across the face of the phantom ^[5].

Numerical values of fluence-to-dose-equivalent conversion coefficients for various irradiation conditions are given in <u>Clauses 5</u> and <u>6</u>.

If the calibration field differs in energy distribution from the reference fields given in ISO 8529-1, the average fluence to dose equivalent conversion coefficient h_{ϕ} should be derived from the energy distribution of the neutron fluence, Φ_E , and the energy-dependent fluence to dose equivalent conversion coefficients h_{ϕ} (*E*) ^[3] using Formula (1).

$$h_{\Phi} = \frac{1}{\Phi} \int h_{\Phi} (E) \Phi_E dE$$

where Φ is the neutron fluence

(1)

4.3 Determination of the response

The response or calibration factor of a dosemeter is a unique property of the dosemeter, and will, in general, depend on the energy and direction distributions of the radiation field, but should not be a function of other characteristics of the calibration facility or of the experimental techniques employed. Hence, the procedures for calibration or determining the response should ensure that the results are independent of the technique, and other factors such as the source-to-device distance and room size. For determining their response or calibration factor, dosemeters are placed with their reference point at the point of test of a reference radiation field with known energy distribution and free-field fluence value. Personal dosemeters should be positioned on the appropriate phantom.

In accordance with the above, the dosemeter indication shall be corrected for all extraneous effects, including neutrons scattered by the air and by the calibration room (see ISO 8529-2) and neutrons having other than the desired energies, such as the target-scattered neutrons in accelerator-based reference monoenergetic neutron fields. These are type-S influence quantities for which corrections need to be applied when deriving the "corrected indication" defined in ISO 29661.

Once the free-field fluence and the corrected indication are obtained, the response or calibration factor can be calculated. If the calibration is performed in terms of the ICRU-recommended operational quantities, the operational quantities are obtained by multiplying the free-field fluence and the corresponding fluence-to-dose-equivalent conversion coefficients.

Since the dose equivalent response of neutron dosemeters is generally energy dependent, it will often be useful to obtain a calibration factor that is not in one of the reference fields specified in ISO 8529-1, but is in a field that closely simulates the field that exist in the workplace. These are called simulated workplace neutron fields. The ISO 12789 Series describes how simulated workplace neutron fields are produced and the related calibration fundamentals. This is especially the case for the albedo neutron personal dosemeter, for which a calibration factor may only be valid for a field identical to the calibration field and may depend on parameters such as the source-detector distance or the room size. An investigation of this kind serves to test the suitability of the dosemeter in these workplace neutron fields rather than to determine a unique calibration factor or response.

https://standards.iteh.ai/catalog/standards/sist/a976497c-cd1f-4de1-a648-b917f9e32d85/iso-

4.4 Calibration procedures

Different calibration procedures are applied in radionuclide or reactor- and accelerator-based reference neutron fields.

For radionuclide reference neutron fields the quantities characterizing the field (fluence and its energy and direction distribution) should be known from previous investigations of the radiation source characteristics and be predictable with time. In other cases, additional measurements are needed such as monitoring variations in fluence or dose equivalent rate during the calibration procedure.

As explained in ISO 29661, the calibration procedure can rely on the usage of a standard instrument, either sequentially or simultaneously exposed with respect to the dosemeter to be calibrated.

Calibrations at reactor- or accelerator-based reference neutron fields require the use of a monitor to transfer the quantity value and to monitor variations of the fluence or dose equivalent rate during the calibration procedure. The monitor and the dosemeter are simultaneously exposed. The monitor and dosemeter should be placed such that each does not influence the response of the other.

5 Procedures for calibrating and determining the ambient dose equivalent response of area dosemeters

5.1 Quantity to be measured and conversion coefficients

The quantity to be measured in area monitoring is the ambient dose equivalent, $H^*(10)$. Tables 1 and 2 contain conversion coefficients, h^*_{ϕ} , converting neutron fluence to ambient dose equivalent for the reference fields recommended in ISO 8529-1.

5.2 Required response characteristics

Ideally, the response of area dosemeters should be isotropic. Under this assumption the fluence response R_{ϕ} only depends on the energy distribution of the incident field, Φ_E , and can be derived using Formula (2)

$$R_{\Phi} = \frac{1}{\Phi} \int R_{\Phi} \left(E \right) \Phi_E dE \tag{2}$$

where

 Φ is the incident neutron fluence;

 $R_{\phi}(E)$ is the response to monoenergetic neutrons of energy *E*, usually derived via simulation.

To properly measure the ambient dose equivalent, the energy dependence of $R_{\phi}(E)$ should be similar to that of the fluence-to-ambient dose equivalent conversion coefficient ^[3].

5.3 Dosemeter conditions

The measurement should be performed under a controlled set of conditions required by the manufacturer in the accompanying documents or by a product standard. <u>Annex A</u> lists standard test conditions and reference conditions for an electronic direct-reading area dosemeter.

5.4 Irradiation geometry STANDARD PREVIEW

Calibrations or determinations of the response are ideally performed in broad, parallel beams providing a uniform irradiation of the total area of the dosemeter or, more precisely, of the parts to be irradiated, i.e. ideally, the dose rate is constant across the beam diameter.

With the use of point sources (accelerator targets, radionuclide neutron sources), this can, in general, only be achieved by having a sufficient distance between source and dosemeter, the minimum distance being dependent on the size of the dosemeter. For spherical devices, a geometry correction has been developed allowing smaller distances between source and dosemeter (ISO 8529-2). If a narrow, collimated beam of neutrons is used, such as is usually found at reactors, a broad-beam irradiation shall be simulated by moving the dosemeter appropriately across the beam ^[6].

5.5 Evaluation of measurement

The response (or calibration factor) of the area dosemeter under the conditions specified above is obtained by determining

- the dosemeter corrected indication. The influence of the scattering from the room and the air on the dosemeter indication should be considered as indicated in ISO 8529-2;
- the free-field neutron fluence Φ ;

and applying the appropriate fluence-to-ambient-dose-equivalent conversion coefficient referred to in 4.2 and given in Tables 1 and 2 for the ISO-recommended neutron reference fields.