NOTICE: This standard has either been superseded and replaced by a new version or withdrawn. Contact ASTM International (www.astm.org) for the latest information.



AMERICAN SOCIETY FOR TESTING AND MATERIALS 100 Barr Harbor Dr., West Conshohocken, PA 19428 Reprinted from the Annual Book of ASTM Standards. Copyright ASTM

Standard Test Method for Adhesion of Gasket Materials to Metal Surfaces¹

This standard is issued under the fixed designation F 607; the number immediately following the designation indicates the year of original adoption or, in the case of revision, the year of last revision. A number in parentheses indicates the year of last reapproval. A superscript epsilon (ϵ) indicates an editorial change since the last revision or reapproval.

This standard has been approved for use by agencies of the Department of Defense.

1. Scope

1.1 This test method provides a means of determining the degree to which gasket materials under compressive load adhere to metal surfaces. The test conditions described are indicative of those frequently encountered in gasket applications. Test conditions may also be modified in accordance with the needs of specific applications as agreed upon between the user and the producer. The maximum temperature recommended for this test method is $205^{\circ}C$ ($400^{\circ}F$).

1.2 The values stated in SI units are to be regarded as standard. The values in parentheses are for information only.

1.3 This standard does not purport to address all of the safety concerns, if any, associated with its use. It is the responsibility of the user of this standard to establish appropriate safety and health practices and determine the applicability of regulatory limitations prior to use.

2. Referenced Documents

2.1 ASTM Standards:

F 38 Test Methods for Creep Relaxation of a Gasket Material²

F 104 Classification System for Nonmetallic Gasket Materials²

https://standards.iteh.ai/catalog/standards/sist///35

3. Summary of Test Method

3.1 The procedure described in this test method involves placing a specimen of a gasket material between flat platens of the desired metal, loading the assembly, and subjecting it to a specified set of conditions. The tensile force required to part the platen is measured in newtons or pounds-force. The force is recorded in newtons or pounds-force, and the stress (force per unit area) in megapascals or pounds-force per square inch of gasket surface.

Note 1—This tensile force required to separate the platens may be in excess of 8896 N (2000 lbf).

NOTE 2—This fixturing also provides for the measurement of creep relaxation in accordance with Method B of Test Methods F 38.

4. Significance and Use

4.1 This test method provides terms such as megapascals or pounds-force per square inch of gasket surface for expressing the extent of adhesion applicable to all materials within the scope of Classification System F104. Under certain conditions, adhesion develops when gasket materials are confined in a compressed state between metal flanges. Adhesion is important as an index of ease of removal of a gasket material. Since other variables may enter into the performance in an application, the results obtained should be correlated with field results. A typical set of conditions is described in this test method. This test method may be used as an acceptance test when agreed upon between the user and the producer.

5. Apparatus

5.1 *Circulating Air Oven*, capable of maintaining $100 \pm 2^{\circ}$ C (212 $\pm 3.6^{\circ}$ F) or other specified temperature as agreed upon between the user and the producer.

5.2 *Test Fixture*, ³ composed of two platens with holes 180° apart on the side of each platen, a calibrated bolt, washer, nut, (in accordance with the fixture in Test Method B of Test Methods F 38) a dial indicator assembly, steel dowel pins, and a steel yoke or similar device to grip the dowel pins. The yoke, in turn, is attached to the grips of a test machine that will provide the capability of applying a tensile force perpendicular to the plane of the platen surface. See Fig. 1.

5.3 9/16 in. Box End Wrench.

5.4 *Tension Tester*, capable of a rate of separation of grips of 1.3 mm (0.05 in.)/min equipped with a recording or a maximum indicating device.

5.5 Tension Adapters, that is, upper and lower yokes.

5.6 % Dry Garnet Paper.

5.7 Molybdenum Disulfide, in powder or spray form.

6. Test Specimens

6.1 Three circular test specimens of material shall be tested. Care should be taken to cut cleanly, with minimum burrs or loose fibers. The surface of the material shall be kept clean, free of oil deposits or foreign material. No substances shall be used during the cutting operation for lubrication of the die or for any other purpose where they may come in contact with the

¹ This test method is under the jurisdiction of ASTM Committee F-3 on Gaskets and is the direct responsibility of Subcommittee F03.40 on Chemical Test Methods. Test apparatus prints are available at ASTM Headquarters.

Current edition approved April 10, 1996. Published May 1996. Originally published as F 607 - 79. Last previous edition F 607 - 90.

² Annual Book of ASTM Standards, Vol 09.02.

³ Composite test fixture including yokes available from Metal Samples Co. Inc., P.O. Box 8, Munford, AL 36268, have been found suitable.