



Designation: ~~D6656~~—14a D6656 – 14b

Standard Test Method for Determination of Chromic Oxide in Wet Blue (Perchloric Acid Oxidation)¹

This standard is issued under the fixed designation D6656; the number immediately following the designation indicates the year of original adoption or, in the case of revision, the year of last revision. A number in parentheses indicates the year of last reapproval. A superscript epsilon (ϵ) indicates an editorial change since the last revision or reapproval.

1. Scope

1.1 This test method covers the determination of chromic oxide in wet blue that has been partly or completely tanned with chromium compounds. In general, the samples will contain chromium content between 1 % and 5 % when calculated as chromic oxide expressed upon a dry basis otherwise referred to as moisture-free basis (mfb).

1.2 The values stated in SI units are to be regarded as standard. No other units of measurement are included in this standard.

1.3 *This standard does not purport to address all of the safety concerns, if any, associated with its use. It is the responsibility of the user of this standard to establish appropriate safety and health practices and determine the applicability of regulatory limitations prior to use.* See Section 9 for specific safety hazards.

2. Referenced Documents

2.1 *ASTM Standards:*²

[D6658 Test Method for Volatile Matter \(Moisture\) of Wet Blue by Oven Drying](#)

[D6659 Practice for Sampling and Preparation of Wet Blue for Physical and Chemical Tests](#)

[E180 Practice for Determining the Precision of ASTM Methods for Analysis and Testing of Industrial and Specialty Chemicals \(Withdrawn 2009\)](#)³

[E177 Practice for Use of the Terms Precision and Bias in ASTM Test Methods](#)

[E691 Practice for Conducting an Interlaboratory Study to Determine the Precision of a Test Method](#)

3. Terminology

3.1 *Definitions*—The terms and definitions employed within this method are commonly used in normal laboratory practice and require no special comment.

4. Summary of Test Method

4.1 The perchloric acid method may be applied to wet blue. Accurately weighed wet blue samples are digested in a blend of concentrated nitric acid and a prepared “oxidation mixture” consisting of sulfuric and perchloric acids. Once completed, oxidation of all tri-valent to hexavalent chrome is executed by controlled heating. Upon dilution, the chromium is indirectly (back) titrated volumetrically with standardized thiosulfate using released iodine as the titrate. The perchloric acid method requires less manipulation than procedures based upon fusion of the ash. However, care must be taken because of potential hazards in the use of this reagent.

5. Significance and Use

5.1 The procedure described is specific for chromium in wet blue. Vanadium is the only common interfering element and is rarely present in quantity. The precision and accuracy of the methods are usually, at least, as good as the sampling of wet blue itself.

5.2 The chromium content of wet blue is related to the degree of tannage obtained, and hence may be a matter for specification in the purchase of wet blue. The procedure described provides adequate accuracy for this purpose.

¹ This test method is under the jurisdiction of ASTM Committee D31 on Leather and is the direct responsibility of Subcommittee D31.02 on Wet Blue. Current edition approved May 1, 2014. Published November 1, 2014. Originally approved in 1996. Last previous edition approved in 2014 as ~~D6656-14~~D6656 - 14a. DOI: ~~10.1520/D6656-14A~~10.1520/D6656-14B.

² For referenced ASTM standards, visit the ASTM website, www.astm.org, or contact ASTM Customer Service at service@astm.org. For *Annual Book of ASTM Standards* volume information, refer to the standard's Document Summary page on the ASTM website.

³ The last approved version of this historical standard is referenced on www.astm.org.

6. Apparatus

- 6.1 *Analytical Balance*—accurate and calibrated to 0.001 g.
- 6.2 *Erlenmeyer Flasks*—250 mL capacity or equivalent.
- 6.3 *Burette*—50 mL capacity of suitable calibration grade, minimum calibration of 0.1 mL.
- 6.4 *Glass Anti-Bumping Beads*—or equivalent.
- 6.5 *Measuring Cylinders*—of 50 mL capacity or equivalent.
- 6.6 *Small Glass Filter Funnel*.
- 6.7 *Dessicator*—of suitable size and design and charged with fresh dessicant.
- 6.8 *Weighing Vessels*—of suitable size and design.
- 6.9 *Drying Oven*—with accurate variable temperature controls.

7. Reagents and Materials

7.1 *Purity of Reagents*—Analytical Reagent (AR) grade shall be used in all tests. Unless otherwise indicated, it is intended that all reagents shall conform to specifications of the Committee on Analytical Reagents of the American Chemical Society, where such specifications are available.⁴ Other grades may be used, provided it is first ascertained that the reagent is of sufficiently high purity to permit its use without lessening the accuracy of the determination.

7.2 *Purity of Water*—Unless otherwise indicated, reference to water shall be understood to mean distilled water or water of equal purity.

7.3 *Commercial Reagents*—The use of commercially available pre-standardized analytical reagents and solutions is appropriate, providing those reagents and solutions have been prepared according to and conform to the previously mentioned specifications (see 7.1).

7.4 *Nitric Acid*—(HNO₃), 70 % w/w.

7.5 *Perchloric Acid*—(HClO₄), 60-62 % w/w. 70 % or 72 % w/w perchloric acid may be substituted; however, storage is somewhat more hazardous.

7.6 *Sulfuric Acid*—(H₂SO₄), 96-98 % w/w.

7.7 *Potassium Iodide*—(KI), 99-100 % purity.

7.8 *Potassium Iodide Solution*—(KI), 10 % w/w. Dissolve 10 g (\pm 0.1 g) of potassium iodide into 100 ml of water.

7.9 *Starch Indicator Solution*—2 % or equivalent. Prepared according to accepted procedures available in analytical handbooks.

7.10 *Oxidizing Mixture*—Mix 1666 mL of concentrated sulfuric acid into an appropriate glass container that contains 2500 mL of perchloric acid using extreme caution while adding. Cool the mixture to room temperature before use.

NOTE 1—The reagents may be added individually according to 11.3.1.

7.11 *Phosphoric Acid*—(H₃PO₄), 40 % w/w. Dilute 45 mL of 85 % phosphoric acid with water to 100 ml.

7.12 *Hydrochloric Acid*—(HCl, 1:1 dilution of 37 %, w/w). Used in standardization of thiosulfate solution.

7.13 *Potassium Dichromate*—(K₂Cr₂O₇). Used in standardization of thiosulfate solution.

7.14 *Sodium Carbonate*—(Na₂CO₃). Used in preparation of thiosulfate solution.

7.15 *Sodium Thiosulfate*—(Na₂S₂O₃ · 5H₂O). Used to prepare thiosulfate solution.

7.16 *Sodium Thiosulfate Standard Solution*—(Na₂S₂O₃), 0.1N (\pm 0.0002). Dissolve 24.85 g of sodium thiosulfate (Na₂S₂O₃ · 5H₂O) in previously boiled water, add 1.00 g of sodium carbonate (Na₂CO₃) and dilute to 1000 mL.

8. Standardization

8.1 Dry potassium dichromate (K₂Cr₂O₇) in an oven at 130 °C for 2 h and cool in a dessicator. Once cool, weigh about 0.2 g (\pm 0.0001 g) of this dry potassium dichromate into a clean 250 ml, glass-stoppered Erlenmeyer flask. Dissolve in 50 mL water; add 4 ml of hydrochloric acid (HCl, 1:1) and 20 ml of KI solution. Stopper the flask and allow to stand for 5 min. in the dark. Titrate with the thiosulfate solution that is to be standardized. When the solution color has faded to brownish-green, add 2 ml of 2 % starch solution and continue titrating until the deep blue color changes to a clear green. Record the volume of titrant used. Calculate the Normality of the thiosulfate solution as follows:

⁴ *Reagent Chemicals, American Chemical Society Specifications*, American Chemical Society, Washington, DC. For suggestions on the testing of reagents not listed by the American Chemical Society, see *Analar Standards for Laboratory Chemicals*, BDH Ltd. Poole, Dorset, UK and the *United States Pharmacopoeia and National Formulary*, U.S. Pharmacopoeial Convention, Inc. (USPC), Rockville, MD.