



Designation: **D2208 – 00 (Reapproved 2010) D2208 – 16**

## Standard Test Method for Breaking Strength of Leather by the Grab Method<sup>1</sup>

This standard is issued under the fixed designation D2208; the number immediately following the designation indicates the year of original adoption or, in the case of revision, the year of last revision. A number in parentheses indicates the year of last reapproval. A superscript epsilon ( $\epsilon$ ) indicates an editorial change since the last revision or reapproval.

*This standard has been approved for use by agencies of the U.S. Department of Defense.*

### 1. Scope

1.1 This test method covers the determination of the breaking strength of leather by the grab method. It is intended for use on light, soft leathers; boarded, sueded, or embossed leathers tested on a specimen in the form of a rectangle piece; narrow strap, welt, lace, and round belt leathers; or other leathers that cannot be accurately tested by Test Method **D2209**. This test method does not apply to wet blue.

1.2 The test method is not recommended for breaking loads over 500 lbf (2200 N) because of slippage of the specimen in the jaws.

1.3 The values stated in inch-pound units are to be regarded as the standard. The values given in parentheses are for information only.

1.4 *This standard does not purport to address all of the safety concerns, if any, associated with its use. It is the responsibility of the user of this standard to establish appropriate safety and health practices and determine the applicability of regulatory limitations prior to use.*

### 2. Referenced Documents

2.1 *ASTM Standards:*<sup>2</sup>

**D1517** Terminology Relating to Leather

**D1610** Practice for Conditioning Leather and Leather Products for Testing

**D1813** Test Method for Measuring Thickness of Leather Test Specimens

**D2209** Test Method for Tensile Strength of Leather

**D2211** Test Method for Elongation of Leather

### 3. Terminology

3.1 For definitions of leather terms used in this standard, refer to Terminology **D1517**.

### 4. Summary of Test Method

4.1 The leather specimen is clamped in the test machine as described in Test Method **D2209**. The force required to rupture the leather at a jaw separation of  $10 \pm 2$  in./min is measured, along with the percent elongation at rupture.

### 5. Significance and Use

5.1 The measurement of the strength of leather is often necessary in order to determine its suitability for its intended application. This test method is recommended for use on light, soft leathers, narrow strap, welt, lace and round belt leathers as well as others that cannot be accurately tested by Test Method **D2209**.

### 6. Apparatus

6.1 *Testing Machine*, as described in Test Method **D2209**.

NOTE 1—The face of one jaw of each clamp shall measure 1 by 1 in. (25.4 by 25.4 mm) and that of the other shall measure 1 by 1½ (25.4 by 38 mm)

<sup>1</sup> This test method is under the jurisdiction of ASTM Committee **D31** on Leather and is the direct responsibility of **D31.05** on Upholstery. This test method was developed in cooperation with the American Leather Chemists Assn. (Standards Method E16–1965).

Current edition approved April 1, 2010; Sept. 1, 2016. Published May 2010; October 2016. Originally approved in 1963. Last previous edition approved in 2005 as **D2208–00 (2005)**; (2016). DOI: 10.1520/D2208-00R10; 10.1520/D2208-16.

<sup>2</sup> For referenced ASTM standards, visit the ASTM website, www.astm.org, or contact ASTM Customer Service at service@astm.org. For *Annual Book of ASTM Standards* volume information, refer to the standard's Document Summary page on the ASTM website.

or more for testing specimens wider than the jaws only.

6.2 *Thickness Gage*—A dead-mass type of thickness gage as described in Test Method **D1813**.

6.3 *Steel Scale*, graduated to read in 0.02 in. (0.5 mm).

## 7. Sampling, Test Specimens, and Test Units

7.1 For testing specimens wider than the jaws, the specimen for wide, flat leathers shall be a small piece of leather 6 in. (152 mm) long and 3 in. (76 mm) wide. The direction of the long dimension relative to the backbone shall be noted.

7.2 For testing specimens cut from narrow strip, the specimen for narrow strap, welting, lace, and round belt leathers shall be a piece of leather 6 in. (152 mm) long.

## 8. Conditioning

8.1 ~~All samples shall be conditioned for 48 h in standard atmospheric conditioning and tested under these conditions~~ Conditions as described in Practice **D1610**.

## 9. Procedure

9.1 *For Testing Specimens Wider than the Jaws:*

9.1.1 Measure the thickness of the specimen to the nearest 0.001 in. (0.025 mm) in three places: at the center and on the long axis 1 in. (25.4 mm) each side of the center.

9.1.2 The distance between the grips at the start of the test shall be  $3 \pm \frac{1}{8}$  in. ( $76 \pm 3.2$  mm).

9.1.3 The face of one jaw of each clamp shall measure 1 by 1 in. (25.4 by 25.4 mm).

9.1.4 Place the specimen in the testing machine with its long axis parallel to the direction of the applied force, and clamp lightly. Distribute the material of the specimen uniformly and hang flat between the jaws before tightly clamping the specimen.

9.1.5 Determine the elongation of the specimen in accordance with Test Method **D2211**.

9.1.6 Operate the machine so that the movable clamp travels at a uniform speed of  $10 \pm 2$  in./min ( $254 \pm 50$  mm/min) when running free.

9.1.7 Record the load required to rupture the specimen as the breaking strength.

NOTE 2—In a test of this type, many of the specimens will rupture at the jaws of the testing machines. The load should be recorded regardless of the place of rupture.

9.2 *For Testing Specimens Cut from Narrow Strips:*

9.2.1 Measure the thickness of a flat specimen or the diameter of a round specimen to the nearest 0.001 in. (0.025 mm) in three places: at the center and 1 in. (25.4 mm) each side of the center.

9.2.2 Place the specimen in the testing machine with its long axis parallel to the direction of the applied force.

9.2.3 The distance between the grips at the start of the test shall be  $3 \pm \frac{1}{8}$  in. ( $76 \pm 3.2$  mm).

9.2.4 Determine the elongation of the specimen in accordance with Test Method **D2211**.

9.2.5 Operate the machine so that the movable clamp travels at a uniform speed of  $10 \pm 2$  in./min ( $254 \pm 50$  mm/min) when running free.

9.2.6 Record the load required to rupture the specimen as the breaking strength.

## 10. Report

10.1 The report shall include the following:

10.1.1 Thickness to the nearest 0.001 in. (0.025 mm), reported for each specimen or averaged and reported as the thickness of the sample, and

10.1.2 Breaking strength to the nearest 1 lbf (or 1 N), reported for each specimen or averaged and reported as the breaking strength of the sample.

## 11. Precision and Bias

11.1 The following criteria may be used to judge the acceptability of the results if at least 15 units have been tested:

11.1.1 *One Operator, Duplicate Specimens, Same Skin*—Results by the same operator on duplicate adjacent specimens in a skin taken from the official sampling position should not be considered suspect unless the coefficient of variation exceeds:

	Specimens Wider than Jaws	
Upholstery		16 %
Garment		11 %
	Specimens Narrower than Jaws	
Laces (Note 3)		27 %
Welting (Note 4)		24 %

NOTE 3—Lace samples are taken at random from the bundles of finished laces. The location of die and direction of testing is unknown, so the comparisons should be between and within bundles.

NOTE 4—Welting samples are taken at random from the hanks of the finished welting. The location of side and direction of testing is unknown, so the comparison should be between and within hanks.