
**Metallic coatings — Measurement of
coating thickness — Profilometric
method**

*Revêtements métalliques — Mesurage de l'épaisseur de revêtement —
Méthode profilométrique*

iTeh Standards
(<https://standards.iteh.ai>)
Document Preview

[ISO 4518:2021](https://standards.iteh.ai/catalog/standards/iso/ff4dbaad-b20c-4d86-b895-45f28dc1133d/iso-4518-2021)

<https://standards.iteh.ai/catalog/standards/iso/ff4dbaad-b20c-4d86-b895-45f28dc1133d/iso-4518-2021>



iTeh Standards
(<https://standards.iteh.ai>)
Document Preview

[ISO 4518:2021](https://standards.iteh.ai/catalog/standards/iso/ff4dbaad-b20c-4d86-b895-45f28dc1133d/iso-4518-2021)

<https://standards.iteh.ai/catalog/standards/iso/ff4dbaad-b20c-4d86-b895-45f28dc1133d/iso-4518-2021>



COPYRIGHT PROTECTED DOCUMENT

© ISO 2021

All rights reserved. Unless otherwise specified, or required in the context of its implementation, no part of this publication may be reproduced or utilized otherwise in any form or by any means, electronic or mechanical, including photocopying, or posting on the internet or an intranet, without prior written permission. Permission can be requested from either ISO at the address below or ISO's member body in the country of the requester.

ISO copyright office
CP 401 • Ch. de Blandonnet 8
CH-1214 Vernier, Geneva
Phone: +41 22 749 01 11
Email: copyright@iso.org
Website: www.iso.org

Published in Switzerland

Contents

Page

Foreword	iv
1 Scope	1
2 Normative references	1
3 Terms and definitions	1
4 Principle	1
5 Instrumentation — Operational parameters and measurement characteristics	1
5.1 Types of profile recording instruments.....	1
5.2 Stylus instruments.....	2
5.3 Inductive measuring probes or displacement sensors.....	2
5.4 Optical profilometers.....	3
6 Factors relating to accuracy	4
6.1 Profile record.....	4
6.2 Vertical magnification (only for instruments with chart recorders).....	4
6.3 Graphical measurements.....	4
6.4 Applied force (only for profilometers with stylus).....	4
6.5 Stylus diameter and surface roughness.....	4
6.6 Surface roughness.....	4
6.7 Vibrations.....	5
6.8 Surface curvature.....	5
6.9 Cleanliness.....	5
6.10 Temperature.....	5
6.11 Step configuration.....	5
6.12 Datum reference (only for profilometers with stylus).....	5
6.13 Calibration.....	5
7 Calibration	5
8 Measuring procedure	6
8.1 Preparation of step.....	6
8.2 Recording of profiles.....	7
8.3 Measurement of thickness.....	7
8.4 Measurement accuracy.....	7
9 Test report	7
Bibliography	8