
**Binders for paints and varnishes —
Determination of softening point —**

**Part 1:
Ring-and-ball method**

Liants pour peintures et vernis — Détermination du point de ramollissement —

Partie 1: Méthode de l'anneau et de la bille

iteh Standards
(<https://standards.iteh.ai>)
Document Preview

[ISO 4625-1:2020](https://standards.iteh.ai/catalog/standards/iso/fb4fbd65-cfec-4529-b566-72fd38c7b697/iso-4625-1-2020)

<https://standards.iteh.ai/catalog/standards/iso/fb4fbd65-cfec-4529-b566-72fd38c7b697/iso-4625-1-2020>



iTeh Standards
(<https://standards.iteh.ai>)
Document Preview

[ISO 4625-1:2020](https://standards.iteh.ai/catalog/standards/iso/fb4fbd65-cfec-4529-b566-72fd38c7b697/iso-4625-1-2020)

<https://standards.iteh.ai/catalog/standards/iso/fb4fbd65-cfec-4529-b566-72fd38c7b697/iso-4625-1-2020>



COPYRIGHT PROTECTED DOCUMENT

© ISO 2020

All rights reserved. Unless otherwise specified, or required in the context of its implementation, no part of this publication may be reproduced or utilized otherwise in any form or by any means, electronic or mechanical, including photocopying, or posting on the internet or an intranet, without prior written permission. Permission can be requested from either ISO at the address below or ISO's member body in the country of the requester.

ISO copyright office
CP 401 • Ch. de Blandonnet 8
CH-1214 Vernier, Geneva
Phone: +41 22 749 01 11
Email: copyright@iso.org
Website: www.iso.org

Published in Switzerland

Contents

Page

Foreword	iv
Introduction	v
1 Scope	1
2 Normative references	1
3 Terms and definitions	1
4 Principle	1
5 Sampling and preparation of test pieces	2
5.1 Sampling.....	2
5.2 Preparation of test pieces by the pour method.....	2
5.2.1 Field of application.....	2
5.2.2 Apparatus.....	2
5.2.3 Procedure.....	2
5.3 Preparation of test pieces from samples with a low softening point (up to 35 °C).....	2
5.3.1 Apparatus.....	2
5.3.2 Procedure.....	3
6 Materials (heating-bath liquids)	3
7 Automated ring-and-ball method (reference method)	3
7.1 Apparatus.....	3
7.2 Calibration.....	4
7.3 Procedure for materials with a softening point between 35 °C and 80 °C.....	4
7.4 Procedure for materials with a softening point between 80 °C and 150 °C.....	4
7.5 Procedure for materials with a softening point above 150 °C.....	4
8 Manual ring-and-ball method (alternate method)	4
8.1 Apparatus.....	4
8.2 Calibration.....	7
8.3 Procedure.....	7
8.3.1 Procedure for materials with a softening point between 35 °C and 80 °C.....	7
8.3.2 Procedure for materials with a softening point between 80 °C and 150 °C.....	8
8.3.3 Procedure for materials with a softening point above 150 °C.....	8
8.3.4 Procedure for materials with a softening point below 35 °C.....	8
9 Expression of results	8
10 Precision and bias	8
10.1 Precision of the automated method.....	8
10.1.1 General.....	8
10.1.2 Precision data.....	8
10.2 Precision of the manual method.....	9
10.2.1 General.....	9
10.2.2 Precision data.....	9
10.3 Bias.....	9
11 Test report	10
Bibliography	11