



International
Standard

ISO 9350

**Corrosion of metals and alloys —
Testing method of corrosion
resistance for hafnium at high
temperature and pressure**

*Corrosion des métaux et alliages — Méthode d'essai de la
résistance à la corrosion du hafnium à haute température et
pression*

First edition
2025-08

Document Preview

[ISO 9350:2025](#)

<https://standards.iteh.ai/catalog/standards/iso/ab334774-38e2-40b7-8084-9fd2874d5588/iso-9350-2025>

iTeh Standards
(<https://standards.iteh.ai>)
Document Preview

[ISO 9350:2025](#)

<https://standards.iteh.ai/catalog/standards/iso/ab334774-38e2-40b7-8084-9fd2874d5588/iso-9350-2025>



COPYRIGHT PROTECTED DOCUMENT

© ISO 2025

All rights reserved. Unless otherwise specified, or required in the context of its implementation, no part of this publication may be reproduced or utilized otherwise in any form or by any means, electronic or mechanical, including photocopying, or posting on the internet or an intranet, without prior written permission. Permission can be requested from either ISO at the address below or ISO's member body in the country of the requester.

ISO copyright office
CP 401 • Ch. de Blandonnet 8
CH-1214 Vernier, Geneva
Phone: +41 22 749 01 11
Email: copyright@iso.org
Website: www.iso.org

Published in Switzerland

Contents

	Page
Foreword	iv
Introduction	v
1 Scope	1
2 Normative references	1
3 Terms and definitions	1
4 Principle	1
5 Significance	2
6 Reagents and materials	2
7 Apparatus	2
8 Hazards	3
9 Sampling, test specimens and test units	3
10 Preparation of apparatus	3
11 Calibration and standardization	3
11.1 Coupon preparation	3
11.2 Autoclaves	4
11.3 Use of control coupons	4
11.4 Calibration	5
12 Conditioning	5
12.1 Test water quality	5
12.2 Autoclave load restrictions	5
12.3 Test conditions	5
12.3.1 Temperature	5
12.3.2 Pressure	5
12.3.3 Time	5
12.3.4 Tests	5
12.4 Specimen preparation	6
12.4.1 Etched specimens	6
12.4.2 As-manufacturer specimens	6
13 Procedure	6
13.1 Inspection of specimens	6
13.2 Dimensions, weight and inspection	6
13.3 Autoclaving	6
13.3.1 Placing of test specimens	6
13.3.2 Venting method A	6
13.3.3 Refreshed autoclaving, method B	7
13.4 Post-test measurements and inspection	7
14 Calculation or interpretation of results	7
14.1 Calculation of mass gain	7
14.2 Visual interpretation of surface appearance	8
14.3 Invalid tests	8
15 Test report	8
Annex A (informative) Guide to specimen preparation	9
Bibliography	11